Appendix F:

Hazards and Hazardous Materials Supporting Information

THIS PAGE INTENTIONALLY LEFT BLANK

CAMERON-COLE
AN ADEC INNOVATION

WEST/CENTRAL

California
2236 Mariner Square Drive
Suite 500
Alameda, CA 94501
T 510 777 1870

250 Commerce
Suite 250
Irvine, CA 92602
T 714 508 4100

1350 Treat Boulevard
Suite 380
Walnut Creek, CA 94597
T 888 826 5814

Colorado
5777 Central Avenue
Suite 200
Boulder, CO 80301
T 303 938 5500

Tennessee
670 Buck Mountain Road
Roan Mountain, TN 37687
T 423 772 3029
F 423 772 3678

EAST/GULF COAST

Florida
200 East Government Street
Suite 100
Pensacola, FL 32502
T 850 434 1011
F 850 434 2168

2282 Killearn Center Boulevard
Tallahassee, FL 32309
T 850 444 4860

Northern Virginia/Washington, D.C.
T 781 881 0271

February 23, 2024

Ms. Elizabeth Johnson
Senior Project Manager
2999 Oak Road, Suite 250
Walnut Creek, CA 94597

RE: PHASE I EVIRONMENTAL SITE ASSESSMENT 71 CAMARITAS AVENUE, SOUTH SAN FRANCISCO, CA.

Dear Ms. Johnson,

This letter summarizes the findings of a Phase I Environmental Site Assessment (ESA) for the above referenced property and provides recommendations for future actions.

The Phase I ESA prepared by Cameron-Cole on December 20th, 2023, identified the presence of a Recognized Environmental Condition (REC) at the Subject Property This condition was identified via the review of a Phase II ESA published by Ninyo & Moore Inc. (Ninyo & Moore) on October 6th, 2021. In this Phase II ESA Ninyo & Moore details the collection and analysis of soil and soil gas samples to determine the level of impact, if any, of petroleum hydrocarbons on the property as a result of a former fuel station which historically operated on the adjacent parcel currently occupied by the Citibank at 101 Arroyo Drive.

Analysis of two soil gas samples collected by Ninyo & Moore identified chloroform and benzene in one sample above their respective residential screening levels. In the Ninyo & Moore report, these concentrations were compared to the State of California Water Resources Control Board Low-Threat Underground Storage Tank Closure Policy (LTCP). Based on this comparison Ninyo & Moore determined the presence of these compounds in the subsurface of the property constitutes *de minimis* conditions and was unlikely to pose a significant risk to the current building occupants.

It is the opinion of Cameron-Cole that the detection of chloroform and benzene in soil gas on the property constitutes a REC, and the limited number (i.e. two) samples are insufficient to fully characterize the extent of the soil gas impacts. Cameron-Cole recommends that additional soil gas testing be performed prior to development to determine the lateral extent of VOCs in excess of screening criteria and to determine if mitigation of potential vapor intrusion into the new building is warranted.

Considering the potential for subsurface conditions to change during redevelopment, Cameron-Cole recommends that a limited soil gas sampling event be performed following completion of any demolition and grading activity on the

WEST/CENTRAL

California
2236 Mariner Square Drive
Suite 500
Alameda, CA 94501
T 510 777 1870

250 Commerce
Suite 250
Irvine, CA 92602
T 714 508 4100

1350 Treat Boulevard
Suite 380
Walnut Creek, CA 94597
T 888 826 5814

Colorado
5777 Central Avenue
Suite 200
Boulder, CO 80301
T 303 938 5500

Tennessee
670 Buck Mountain Road
Roan Mountain, TN 37687
T 423 772 3029
F 423 772 3678

EAST/GULF COAST

Florida
200 East Government Street
Suite 100
Pensacola, FL 32502
T 850 434 1011
F 850 434 2168

2282 Killearn Center Boulevard
Tallahassee, FL 32309
T 850 444 4860

Northern Virginia/Washington, D.C.
T 781 881 0271

Site and prior to construction of the building slab. Soil gas sample points should be located within the new building footprint where the potential for vapor forming chemicals to accumulate is the highest.

Should you have any questions regarding the recommendations and opinions provided in this letter, or any other concern or question, please contact Michael Stephenson at (510) 777-1864.

Sincerely,

Michael Stephenson
Principal Scientist

PHASE I ENVIRONMENTAL SITE ASSESSMENT

71 CAMARITAS AVENUE

SOUTH SAN FRANCISCO FIRE STATION #63

SOUTH SAN FRANCISCO, CALIFORNIA

PREPARED FOR:

The City of South San Francisco

AND

First Carbon Solutions

2999 Oak Road, Suite 250

Walnut Creek, California 94597

PREPARED BY:

2336 Mariner Square Drive Suite 500

Alameda, California 95401

December 20th, 2023

TABLE OF CONTENTS

1.0 SUMMARY 5

2.0 INTRODUCTION 5

2.1 Purpose 5

2.2 Detailed Scope of Services 6

2.3 Significant Assumptions 6

2.4 Limitations and Exceptions of Assessment 6

3.0 SUBJECT PROPERTY DESCRIPTION 9

3.1 Location and Legal Description 9

3.2 Site and Vicinity Characteristics 9

3.3 Current Uses of the Property 9

3.4 Descriptions of Structures, Roads, and Other Improvements to the Site 9

4.0 USER PROVIDED INFORMATION 10

4.1 Title Records 10

4.2 Environmental Liens or Activity and Use Limitations 10

4.3 Specialized Knowledge 10

4.4 Commonly Known or Reasonably Ascertainable Information 10

4.5 Valuation Reduction for Environmental Issues 10

4.6 Owner, Property Manager, and Occupant Information 10

4.7 Proceedings Involving the Property 11

4.8 Reason for Performing Phase I ESA 11

5.0 RECORDS REVIEW 12

5.1 Standard Environmental Record Sources and Other Ascertainable Records Sources 12

5.2 Standard Environmental Record and Other Ascertainable Records Review 17

5.3 Unmappable Sites 28

5.4 Additional Environmental Record Sources 28

5.5 Physical Setting Sources 29

5.6 Historical Use Information 29

5.7 Historical Use Summary 36

6.0 SITE RECONNAISSANCE 38

6.1 Methodology and Limiting Conditions 38

6.2 General Site Setting 38

6.3 Subject Property Observations 39

7.0 INTERVIEWS 40

7.1 Site Owner/Occupants 40

7.2 Past Owners, Operators, Occupants 40

7.3 User 40

7.4 State and/or Local Government 40

8.0 FINDINGS AND CONCLUSIONS 42

9.0 DEVIATIONS 43

10.0 REFERENCES 44

11.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONAL 45

12.0 ENVIRONMENTAL PROFESSIONAL STATEMENT 46

FIGURES

FIGURE 1: Site Vicinity Map

FIGURE 2: Regional Vicinity Map

FIGURE 3: Ninyo & Moore Soil Vapor Results Above ESLs

FIGURE 4: Ninyo & Moore Shallow Soil Results Above ESLs

APPENDICES

APPENDIX A: Photographs

APPENDIX B: Government Records Report

APPENDIX C: Historical Research Documentation

APPENDIX D : Interview Documentation

APPENDIX E : Professional Qualifications

1.0 SUMMARY

Cameron-Cole, LLC (Cameron-Cole) has completed a Phase I Environmental Site Assessment (ESA) for an approximately 1.07-acre property located in South San Francisco, San Mateo County, California, hereinafter referred to as the "property", "subject property", "site", or "SP" (Figure 2). The assessment was performed in accordance with the Master Environmental Services Agreement between Cameron-Cole and First Carbon Solutions (FCS). The scope of services conforms to the scope and limitations of the American Society for Testing and Materials International (ASTM International) Standard Practice for Environmental Site Assessments, Designation: E1527-21. The purpose of this Phase I ESA is to identify, to the extent feasible pursuant to the ASTM International Standard E1527-21, recognized environmental conditions (RECs) in connection with the subject property.

According to records maintained by the San Mateo County Assessors' office, the subject property is associated with assessor parcel numbers (APN) 010-402-240 which is identified by street address 71 Camaritas Avenue, South San Francisco, San Mateo County California.

The subject property consists of one structure, an approximately 7-560-ft^2 commercial building which is currently operated as a Filipino restaurant under the name Ongpin. To the west of the structure there is an open landscape area which does not currently have any structures. According to information provided to Cameron-Cole this area is utilized as an easement by the San Francisco Public Utilities Commission (SFPUC). This easement includes two buried pipelines which appear to be used for the conveyance of water and or sewage. Above ground Infrastructure associated with the pipeline easement is present in this area of the SP, photos of the above ground utilities are provided in the photograph log included as Appendix A. The remainder of the SP consists of paved areas directly surrounding the structure which is used for vehicle parking.

The goal of this Phase I ESA is to identify the presence or likely presence of hazardous substances or petroleum products on the subject property under conditions that indicate an existing release, a past release, or a material threat of release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water on the property. The findings of this report are summarized below and may include known or suspected Recognized Environmental Conditions (RECs), Controlled Recognized Environmental Conditions (CRECs), or Historical Recognized Environmental Conditions (HRECs) identified during the performance of this Phase I ESA.

It is the opinion of the EP that there are no CRECs or HRECs, there is one condition which constitutes a REC. The known presence of benzene, chloroform, and antimony in the subsurface of SP above residential screening levels as discussed in section 5.6.8 constitutes a recognized environmental condition.

2.0 INTRODUCTION

2.1 Purpose

Cameron-Cole performed a Phase I ESA for a an approximately 1.07-acre property located at 71 Camaritas Avenue, South San Francisco, San Mateo County, California in accordance with the Master Environmental Services Agreement between Cameron-Cole and FCS (the Client) on behalf of the City of South San Francisco (the User). The assessment was conducted in general conformance with the ASTM International Standard E1527-21 Standard Practice for Environmental Site Assessments. This ESA was designed to

identify, to the extent feasible, the presence or likely presence of RECs in connection with the property.

This ESA allows the "User" to benefit from one of the defenses referenced in the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) liability: the innocent landowner defense, the contiguous property owner defense, or bona fide prospective purchaser defense. These defenses are collectively referred to as the "landowner liability protections," or "LLPs". ASTM International Standard E1527-21 constitutes "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined at 42 U.S.C. §9601(35)(B). Cameron-Cole considers FCS to be the Client and the City of South San Francisco to be the "User" of this report.

The goal of this Phase I ESA is to identify RECs, CRECs, or HRECs in connection with the subject property consistent with ASTM International Standard E1527-21.

A REC is defined as:

> *"1) the presence of hazardous substances or petroleum products in, on, or at the subject property due to a release to the environment ; 2) the likely presence of hazardous substances or petroleum products in, on, or at the subject property due to a release or likely release to the environment; or 3) the presence of hazardous substances or petroleum products in, on, or at the subject property under conditions that pose a material threat of a future release to the environment."*

A CREC is defined as:

> *"a recognized environmental condition affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities with hazardous substances or petroleum products allowed to remain in place subject to implementation of required controls."*

A HREC is defined as:

> "*a previous release of hazardous substances or petroleum products affecting the subject property that has been addressed to the satisfaction of the applicable regulatory authority or authorities and meeting unrestricted use criteria established by the applicable regulatory authority without subjecting the subject property to any controls."*

2.2 Detailed Scope of Services

This Phase I ESA was conducted in accordance with the Master Environmental Services Agreement between Cameron-Cole and FCS. The scope of services consists of completing a Phase I ESA in general accordance with ASTM International Standard E1527-21 and the Scope of Services specified in the Master Agreement.

2.3 Significant Assumptions

Historical resources, personal interviews, and federal and state agency files regarding site operations and past historical use have been considered when presenting Cameron-Cole's findings and opinions. Cameron-Cole considers all information provided by our environmental database subcontractor regarding regulatory status of facilities to be current, accurate, and complete. Although Cameron-Cole made no independent investigation as to the accuracy and completeness of other information derived from secondary sources, Cameron-Cole assumes such information is reliable and representative of site conditions.

2.4 Limitations and Exceptions of Assessment

2.4.1 Site-Specific Limitations

Select portions of the interior of the structure are not considered part of this ESA and thus were not considered or assessed during the in-person site walk. These areas include sections of the building not typically accessible to the public, this includes kitchens, offices, and storage rooms. Subsurface investigations were not conducted as part of this assessment.

2.4.2 Data Gaps

A data gap is a lack of, or inability to, obtain information required by ASTM International Standard E1527-21 despite good faith efforts to gather such information. Data gaps may result from incompleteness in any of the activities required by ASTM International Standard E1527-21. According to the ASTM International Standard Practice E1527-21, data gaps are only significant if "other information and/or professional experience raise reasonable concerns involving the data gap". As of the date of this Phase I ESA, Cameron-Cole has not received completed copies of the pre-site visit questionnaire and the user questionnaire. The lack of these documents is considered a data gap; however, it is the opinion of the EP that due to the availability of historical records including previous assessments for the subject property, this data gap is not considered "significant".

2.4.3 General Limitations and Exceptions

The Phase I ESA is produced in accordance with customary principles and practices in the applicable fields of environmental science and engineering. Cameron-Cole is not responsible for conclusions, opinions, or recommendations made by others based upon the information presented herein.

Although industry standard practices are employed, Phase I ESAs are inherently limited, given that findings and conclusions are developed from limited site evaluation and research. In performing a Phase I ESA, Cameron-Cole can only rely upon those records regarding the subject property and surrounding properties which are available to the public, and which can reasonably be obtained by Cameron-Cole. Cameron-Cole's opinions, conclusions and recommendations are therefore limited to those which can be derived from such available and reasonably obtainable records. It is often necessary for Cameron-Cole to rely on information prepared or obtained by others to complete the Phase I ESA. Cameron-Cole makes no warranty or representation as to the accuracy or completeness of information obtained from third parties. Additionally, changes may result with the passage of time with respect to characteristics of the subject property and those of surrounding properties. Cameron-Cole and its representatives do not warrant for or against future changes in operations or conditions, nor do they warrant for or against conditions present of a type or at a location not specifically addressed in the Phase I ESA.

Subject to the limitations stated herein, the opinions presented in Phase I ESA are valid for a period of 180 days from the date of issuance.

Air, soil, and groundwater testing are not part of the Phase I ESA Report. This Phase I ESA is not intended to establish whether air, soil, or groundwater contamination, or waste disposal is present or not present on the subject property or on surrounding properties. Knowledge of actual environmental conditions on the subject property or on any surrounding properties can only be obtained from air, soil, and groundwater testing, the installation of groundwater monitoring wells, and possible additional testing, all of which are outside the scope of the Phase I ESA.

Reasonable efforts were made within the scope of the Phase I ESA to identify the presence of underground

storage tanks (USTs), aboveground storage tanks (ASTs), and ancillary equipment on or near the subject property. Limitations to the Phase I ESA exist regarding USTs and ASTs, in as much as information was obtained by Cameron-Cole solely through its review of unobstructed and readily accessible areas, database information, and interviews. Such methods (which are considered industry standard) do not preclude the actual presence of subsurface equipment (including USTs) or regulated materials that are hidden from view due to historical activity such as site paving, re-grading, construction, or debris pile storage. Similarly, it is possible that additional UST facilities not listed in regulatory database files may exist at the subject property or on properties adjacent to the subject property related to owner/operator registration negligence, filing errors with the state regulatory agency, or other reasons over which Cameron-Cole has no control or ability to determine.

Conclusions in the Phase I ESA regarding potential environmental impact of properties and facilities surrounding the subject property are based upon reasonably available information obtained from environmental databases and inferred groundwater flow direction.

No environmental assessment can wholly eliminate uncertainty regarding the potential for RECs in connection with a property. Performance of a Phase I ESA is solely intended to reduce, but not eliminate, uncertainty regarding the potential for RECs in connection with the subject property, and this practice recognizes reasonable limits of time and cost. The Phase I ESA has been prepared for the exclusive use and benefit of FCS subject to the terms and conditions specified in the Master Environmental Services Agreement between Cameron-Cole, LLC. and FCS. The Phase I ESA is for the sole and exclusive use and benefit of FCS, our client. Cameron-Cole makes no warranty as to the Phase I ESA except as to FCS's exclusive use of the Phase I ESA. The Client bears the sole responsibility for ensuring that the Phase I ESA is distributed or disseminated to only those third parties to whom FCS is strictly obligated by contract, law, regulation, or ordinance to provide it. Cameron-Cole disclaims any and all liability to any person or entity other than FCS who uses or relies on the Phase I ESA in any way whatsoever without the express written consent of both FCS and Cameron-Cole.

Third-party reliance letters may be issued upon request and upon payment of the then current fee for such letters, and only if Cameron-Cole, FCS, and the User provide express written consent for any such reliance letters.

3.0 SUBJECT PROPERTY DESCRIPTION

3.1 Location and Legal Description

The subject property is located at the addresses 71 and 73 Camaritas Avenue, in the city of South San Francisco, San Mateo County, CA. A Site Map is provided as Figure 1 and a regional vicinity map as Figure 2. According to records maintained by the San Mateo County Assessor's office, the subject property is associated with APN 010-402-240.

3.2 Site and Vicinity Characteristics

The subject property consists of one parcel with surface area totaling approximately 1.07-acres. The SP is bordered by a Citi Bank branch located at 101 Arroyo Drive to the north, Westborough Boulevard and the California Golf Club of San Francisco to the south, commercial properties to the east, and residential properties to the west. Vehicle access to the SP is provided by Camaritas Avenue, the major throughfare Westborough boulevard borders the SP immediately to the south. Arroyo drive borders the area of the SP which is operated an an easement by the SFPUC.

3.3 Current Uses of the Property

The SP is commercial in nature, the structure present on the SP has previously hosted several businesses. However, at the time of this ESA only one business, a Philippine restaurant named Ongpin is currently operating at 71 Camaritas Avenue. The remainder of this structure was vacant at the time of this ESA. An open landscape section to the west of the structure is also utilized as an easement by the SFPUC for the operation of subsurface pipelines.

3.4 Descriptions of Structures, Roads, and Other Improvements to the Site

The SP can be accessed via the driveway located on Camaritas Avenue which intersects with Arroyo Drive to the northwest and Westborough Boulevard to the southeast. The structure on the SP is built as slab-on-grade and largely composed of masonry building materials. Improvements to the SP include impervious surfaces in the form of parking areas, fencing along property boundaries, landscape architecture, infrastructure associated with the SFPUC easement, and an electrical transformer located southwestern most corner of the building.

4.0 USER PROVIDED INFORMATION

For the User to qualify for one of the LLPs offered by the Small Business Liability Relief and Brownfields Revitalization Act of 2001, Section 6 of ASTM International Standard E1527-21 requires the User to provide the environmental professional (EP) the following information:

- The existence of environmental cleanup liens;
- Activity and Use Limitations (AULs) recorded against the subject property;
- Specialized knowledge or experience of the User;
- Relationship of the purchase price to the fair market value of the property if it were not contaminated;
- Commonly known or reasonably ascertainable information about the subject property; and
- The degree of obviousness of the presence of contamination at the subject property.

Cameron-Cole made reasonable efforts to obtain the above-described information from the User of this report via distribution of a *User Questionnaire* to representatives of Kitchell Development as well as the City of South San Francisco on October 10th, 2023. As of the date of this ESA, a completed copy of this questionnaire has not been received, the extent to which the EP considers this to be a data gap is discussed in section 2.4.2.

4.1 Title Records

A historical chain-of-title report and an environmental lien report were not provided by the User or obtained and reviewed by Cameron-Cole as part of the approved scope of services for this project. According to information obtained from the San Mateo County Assessor's office this property is currently owned by the City of South San Francisco.

4.2 Environmental Liens or Activity and Use Limitations

Cameron-Cole did not receive information from the User regarding environmental liens and use limitations.

4.3 Specialized Knowledge

Cameron-Cole did not receive any specialized knowledge regarding the property from the User.

4.4 Commonly Known or Reasonably Ascertainable Information

Cameron-Cole did not receive any commonly known or reasonably ascertainable information from the User.

4.5 Valuation Reduction for Environmental Issues

Cameron-Cole did not receive any information regarding a value reduction from the User.

4.6 Owner, Property Manager, and Occupant Information

Cameron-Cole did not receive any occupant information from the User.

4.7 Proceedings Involving the Property

Cameron-Cole did not receive any information regarding proceedings involving the property.

4.8 Reason for Performing Phase I ESA

Cameron-Cole did not receive any information regarding the reason for performing a Phase I ESA from the User.

5.0 RECORDS REVIEW

5.1 Standard Environmental Record Sources and Other Ascertainable Records Sources

Envirosite provided Cameron-Cole with a comprehensive government agency information search in accordance with ASTM International Standard E1527-21. Regulatory search details as well as maps depicting the properties identified in the databases searched by Envirosite are provided in Appendix B. The table below provides a summary of the identified standard (ASTM required) federal, state, tribal, and local environmental database records reviewed along with each record's approximate minimum search distance (AMSD) from the subject property.

STANDARD ENVIRONMENTAL DATABASE RECORD SUMMARY

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (Miles)	<1/8 Mile	1/8-1/4 Mile	1/4-1/2 Mile	1/2-1 Mile	>1 Mile	TOTAL MAPPED
FEDERAL RCRA NON-CORRACTS TSD FACILITIES LIST								
ARCHIVED RCRA TSDF		0.500	0	0	0	--	--	0
RCRA_TSDF		0.500	0	0	0	--	--	0
FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS								
FEMA UST		0.250	0	0	--	--	--	0
INDIAN UST R9		0.250	0	0	--	--	--	0
AST - CA		0.250	2	1	--	--	--	3
FID UST - CA		0.250	0	1	--	--	--	1
HIST AST - CA		0.250	1	0	--	--	--	1
HIST UST - CA		0.250	2	4	--	--	--	6
FEDERAL CERCLIS LIST								
CERCLIS NFRAP		0.500	0	0	0	--	--	0
CERCLIS-HIST		0.500	0	0	0	--	--	0
FEDERAL FACILITY		1.000	0	0	0	0	--	0
FEDERAL RCRA CORRACTS FACILITIES LIST								
CORRACTS		1.000	0	0	0	0	--	0
HIST CORRACTS 2		1.000	0	0	0	0	--	0
FEDERAL DELISTED NPL SITE LIST								
DELISTED NPL		1.000	0	0	0	0	--	0
FEDERAL ERNS LIST								
ERNS		SP	0	--	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (Miles)	<1/8 Mile	1/8-1/4 Mile	1/4-1/2 Mile	1/2-1 Mile	>1 Mile	TOTAL MAPPED
FEDERAL INSTITUTIONAL CONTROLS / ENGINEERING CONTROLS REGISTRIES								
FED E C		0.500	0	0	0	--	--	0
FED I C		0.500	0	0	0	--	--	0
RCRA IC_EC		0.250	0	0	--	--	--	0
FEDERAL RCRA GENERATORS LIST								
HIST RCRA_CESQG		0.250	0	0	--	--	--	0
HIST RCRA_LQG		0.250	0	0	--	--	--	0
HIST RCRA_NONGEN		0.250	0	0	--	--	--	0
HIST RCRA_SQG		0.250	0	0	--	--	--	0
RCRA_NONGEN		0.250	7	10	--	--	--	17
RCRA_SQG		0.250	0	1	--	--	--	1
RCRA_VSQG		0.250	0	0	--	--	--	0
FEDERAL, STATE, and TRIBAL LEAKING STORAGE TANK LISTS								
INDIAN LUST R9		0.500	0	0	0	--	--	0
LUST REG 2 – CA		0.500	1	3	7	--	--	11
LUST_SAN MATEO COUNTY – CA		0.500	1	3	8	--	--	12
SLIC REG 2 – CA		0.500	1	4	1	--	--	6
FEDERAL NPL SITE LIST								
NPL		1.000	0	0	0	0	--	0
NPL EPA R9 GIS		1.000	0	0	0	0	--	0
SEMS_FINAL NPL		1.000	0	0	0	0	--	0
SEMS_PROPOSED NPL		1.000	0	0	0	0	--	0
STATE AND TRIBAL – EQUIVALENT CERCLIS								
ENIROSTOR – CA		1.000	0	0	0	1	--	1
OIL & GAS CLEANUP - CA		0.500	0	0	0	--	--	0
SWRCB CLEANUP-CA		0.500	0	0	1	--	--	1
TOXIC PITS – CA		1.000	0	0	0	0	--	0
STATE RCRA GENERATOR LIST								

HWG – CA	0.250	16	31	--	--	--	--	47

STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

SWF/LF – CA		0.500	0	0	0	--	--	0

STATE AND TRIBAL BROWNFIELD SITES

TRIBAL BROWNFIELDS		0.500	0	0	0	--	--	0

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES

CDL – CA		SP	0	--	--	--	--	0
SCH – CA		0.250	0	0	--	--	--	0

LOCAL BROWNFIELD LISTS

FED BROWNFIELDS		0.500	0	0	0	--	--	0

LOCAL LAND RECORDS

LIENS 2		SP	0	--	--	--	--	0
HIST LIENS – CA		SP	0	--	--	--	--	0
LIENS – CA		SP	0	--	--	--	--	0

RECORDS OF EMERGENCY RELEASE REPORTS

HMIRS (DOT)		SP	0	--	--	--	--	0

LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES

TRIBAL ODI		0.500	0	0	0	--	--	0
SWRCY – CA		0.500	1	0	0	--	--	1

SP = Subject property

Cameron-Cole also conducted a search of other ascertainable records related to the subject property and surrounding properties, where applicable. The table below provides a summary of the other ascertainable records reviewed along with each record AMSD from the subject property:

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (Miles)	<1/8 Mile	1/8-1/4 Mile	1/4-1/2 Mile	1/2-1 Mile	>1 Mile	TOTAL MAPPED
COAL GAS		1.000	0	0	0	0	--	0
CORRECTIVE ACTIONS_2020		0.500	0	0	0	0	--	0
DOD		1.000	0	0	0	0	--	0
ECHO		SP	0	--	--	--	--	0
FUDS		1.000	0	0	0	0	--	0
HIST DOD		1.000	0	0	0	0	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (Miles)	<1/8 Mile	1/8-1/4 Mile	1/4-1/2 Mile	1/2-1 Mile	>1 Mile	TOTAL MAPPED
HIST PCS ENF		SP	0	--	--	--	--	0
ICIS		SP	0	--	--	--	--	0
LUCIS		0.500	0	0	0	--	--	0
LUCIS 2		0.500	0	0	0	--	--	0
NPL AOC		1.000	0	0	0	0	--	0
NPL LIENS		SP	0	--	--	--	--	0
PADS		SP	0	--	--	--	--	0
PCB TRANSFORMER		SP	0	--	--	--	--	0
PFAS NPL		0.500	0	0	0	--	--	0
PFAS TRIS		0.500	0	0	0	--	--	0
CALEPA SITES – CA		0.250	8	14	--	--	--	22
CIWQS - CA		SP	0	--	--	--	--	0
CIWQS 2 - CA		SP	0	--	--	--	--	0
DRYCLEANERS - CA		0.250	0	1	--	--	--	1
DRYCLEANERS_BAY AREA = CA		0.250	0	0	--	--	--	0
FA - CA		SP	0	--	--	--	--	0
HAZNET - CA		0.250	13	27	--	--	--	40
HIST HAZNET - CA		0.250	1	2	--	--	--	3
HIST HWP - CA		1.000	0	0	0	0	--	0
HIST LDS - CA		0.500	0	0	0	--	--	0
HIST MCS - CA		1.000	0	0	0	0	--	0
HIST NFA - CA		0.500	0	0	0	--	--	0
HWM-COMMERCIAL FACILITIES - CA		0.250	0	0	--	--	--	0
HWP - CA		1.000	0	0	0	0	--	0
HWT - CA		0.250	0	0	--	--	--	0
LDS - CA		0.500	0	0	0	--	--	0
MCS - CA		1.000	0	0	1	0	--	0
MWMP - CA		0.250	0	0	--	--	--	0
MWMP 2 - CA		0.250	0	0	--	--	--	0
NFA - CA		0.500	0	0	0	--	--	0
NFE - CA		0.500	0	0	0	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (Miles)	<1/8 Mile	1/8-1/4 Mile	1/4-1/2 Mile	1/2-1 Mile	>1 Mile	TOTAL MAPPED
NPDES - CA		SP	0	--	--	--	--	0
PERCHLORATE 2 - CA		0.500	0	0	0	--	--	0
PFAS - CA		0.500	0	0	0	--	--	0
PFAS DOD - CA		0.500	0	0	0	--	--	0
PFAS GAMA - CA		0.500	0	1	9	--	--	10
RFR – CA		SP	0	--	--	--	--	0
WDR - CA		SP	0	--	--	--	--	0
WDS - CA	X	SP	0	--	--	--	--	1

SP = Subject property

5.1.1 Database Descriptions

BUSINESS INVENTORY_SAN MATEO COUNTY – CA: San Mateo County listings of underground storage tanks, hazardous materials, business plans, and hazardous waste generators.

CALEPA SITES – CA: CalEPA regulated sites from the Certified Unified Program Agencies (CUPA).

CHMIRS: California hazardous material incident reporting system's reported accidental hazardous material incident release or spills.

DRYCLEANERS – CA: Listing drycleaning facilities.

ENVIROSTOR: Department of toxic substances controls.

EPA UST: Facilities listed in the EPA UST finder databases.

EPA LUST: Releases listed in the EPA UST finder database.

FID UST – CA: The State Water Resource Control Board's Facility Inventory Database underground storage tank locations listings.

FIRE AREAS – CA: The Multi-agency statewide database of fire perimeters.

HAZNET – CA: Listing of hazardous waste manifest from when hazardous waste is transported from generators to permitted recycling, treatment, storage, or disposal facilities by registered hazardous waste transporters.

HIGH FIRE – CA: Fire hazard severity zones mapped as areas of significant fire hazard based on fuels, terrain, weather, and other factors.

HIST HAZNET – CA: List of hazardous waste manifest from when hazardous waste is transported from generators to permitted recycling, treatment, storage, or disposal facilities by registered hazardous waste transporters that are no longer in current agency list.

HIST UST – CA: Historical listings of underground storage tank facilities.

HWG – CA: Hazardous waste generator listings.

LUST_SAN MATEO COUNTY – CA: San Mateo County leaking underground storage tank listing.

UST – CA: Listing of active underground storage tank facilities.

LUST REG 2 – CA: Leaking underground storage tanks in region 2: Alameda, Contra Costa, San Francisco, Santa Clara (north of Morgan Hill), San Mateo, Marin, Sonoma, Napa, and Solano counties.

MANIFEST EPA: EPA Hazardous waste electronic manifest system (e-Manifest).

PFAS GAMA – CA: PFOS & PFAS GAMA wells sampling program.

SEISMIC – CA: Earthquake zones of required investigation, shows the location of both seismic hazard zones and earthquake fault zones.

SLIC REG 2 – CA: List of Region 2 sites from GeoTracker Site Cleanup Program.

SWRCB CLEANUP – CA: List of SWRCB cleanups from GeoTraker including CAF, Sampling points, and projects.

SWRCB NON_CASE: List of SWRCB Non-Case Sites from the GeoTracker site cleanup program database.

SWRCY – CA: Listing of facilities which perform recycling material processing activities.

RCRA_ LQG, RCRA_NONGEN, RCRA_SQG, RCRA_VSQG: Resource Conservation and Recovery Act listing of licensed large quantity generators (LQG), non-generators (NONGEN), small quantity generators (SQG), and very small quantity generators (VSQG).

WDS – CA: Listing of waste discharge system reporting facilities.

5.2 Standard Environmental Record and Other Ascertainable Records Review

The following discussion provides a review of results from the standard environmental records and other ascertainable records search with respect to the subject property as well as the adjacent or nearby properties. Per the discretion of the EP, some results may be omitted from this review if they are interpreted to be not of environmental significance based on threat of a material release, distance from the subject property, lower topographic elevations, and interpreted groundwater flow direction. The complete Envirosite report is included as Appendix B and contains all points of interest that were identified within the AMSD.

SUBJECT PROPERTY

ONGPIN RESTURAUNT, 73 Camaritas Avenue, located on the subject property was identified in the **CHMIRS - CA** and **WDS – CA** databases.

- The **CHMIRS – CA** and **WDS – CA** identifies the Ongpin restaurant which currently operates on the SP, the reason for listing is due to a leak of sewage on 01/09/2018. It is reported that grease deposits clogged a gravity mainline resulting in 5,000-gallons of sewage to spill onto the ground surface from a sewer lateral clean-out. The reporting party and the property owner are identified as being responsible for cleanup actions, corrective actions taken include containment, disposal, and a change in preventative maintenance to prevent a reoccurrence.

Based upon the age of release, type of material released, and the remediation efforts taken, it is the EP's opinion that this incident at the SP **does not represent a REC, HREC,** or **CREC** to the subject property at

this time.

Note: The above listing provides a summary of information obtained from two separate listings in the Envirosite report. Based upon the date of release, material released, and corrective actions, we have determined that these two listings are detailing the same release.

Adjacent and Nearby Off-Site Properties within the AMSD

The following provides a summary of relevant identified off-site points of interest with respect to interpreted groundwater flow direction which is inferred to flow south-southeasterly in the shallow perched unit below the site (Weiss, 2020) (see Sections 5.5.3 and 6.2.1).

North (up-gradient)

OFFICE OF MORRIS WONG DDS, TONI A AMBUS DDS, EPITACIO SISON JR SISON DENTAL CARE, 100 Arroyo Drive, located 129-ft north from the SP, is listed in the **BUSSINESS INVENTORY_SAN MATEO COUNTY- CA, HAZNET – CA,** and **HWG - CA** databases.

- The **HAZNET - CA**, **HWG - CA,** and **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA** databases identify this facility as an inactive hazardous waste generator. Based upon the name of the business this appears to have formerly been a dental office which produced medical waste. Manifest information detailing the disposition of hazardous waste to appropriate facilities is present. No records indicating a release to the environment or misuse of hazardous materials are shown in the database listings.

CITY OF SSF FIRE STATION #63 | SO SAN FRAN POLICE DEPT-DISP PRG | STATION 63, 33 Arroyo Drive, located 326-ft northeast of the SP is identified in **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, AST – CA, CALEPA SITES – CA, HAZNET – CA, HIST AST - CA,** and **HWG – CA** databases.

- **AST – CA, CALEPA SITES – CA, HIST AST – CA, AND HWG – CA** identify this facility as hosting multiple storage tanks for hazardous materials. Materials stored on this facility include diesel fuel in a tank holding between 1,200-2,999-gal and liquid oxygen in quantity 0-2,599 cubic feet. Multiple violations are noted by the San Mateo Conty Environmental Health Department. These violations include the presence of a small amount of liquid being present in the containment basin and significant absorbent material present below the generator on 10/03/2022. It is noted that the liquid present within the containment pad was not confirmed to be a hazardous substance and no evidence of a leak or spill was observed. Other violations resulting from the 10/03/2022 inspection include administrative failures such as the failure to prepare a spill prevention control and countermeasures plan (SPCC), failure to provide initial and annual training to employees on safety procedures in the event of a release or threatened release, and failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date. All violations are shown as having been returned to compliance.

GRAND AUTO | PACCAR AUTMOTIVE INC | CSK AUTO INC | KRAGEN AUTO PARTS #4047, 1103 El Camino Real, located 548-feet north-northeast from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, HAZNET – CA, AND HWG – CA** databases.

- The above listed databases identify this facility as a former hazardous waste generator which produces and recycles waste oils/solvents. Records detail the disposition of hazardous materials to approved facilities between 1995 and 1999.

CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER), 112 El Camino Real, located 646-feet north-northeast from the SP was identified in **BUSSINESS INVENTORY_SAN MATEO COUNTY, CALEPA SITES - CA, HAZNET – CA, HWG – CA,** and **SLIC REG 2 – CA** databases.

- This facility operated as a dry cleaner from approximately the 1960's to 2002 (ICES, 2016). In a letter dated 1/9/2013, the San Mateo County Health System notified the Pauline Tsiplakos Trust that Tetrachlrooethene (PCE) had been detected in a groundwater sample near the facility. A document dated 1/16/2014 indicated that the Pauline Tsiplakos Trust entered into a voluntary remedial action agreement with the SMCHS. Over the following years investigatory activities took place to characterize the vertical and lateral extent of PCE contamination in groundwater at and near the facility. A site investigation work plan was given conditional approval on 3/31/2015 and subsequently implemented. Following implementation, a site characterization report was submitted on 6/13/2016 which detailed activities including the installation and sampling of soil vapor wells, and the collection of soil samples. ICES found that "… the investigation indicated very low levels of PCE in the subsurface underlying the former dry-cleaning machines and chemical storage area at the southwest portion of the building. Based on the findings of the investigation and our experience with similar project it does not appear the PCE detected by SFPUC in the deeper aquifer could have originated from the former dry-cleaning operations at the site." (ICES, 2016). In a letter dated July 28th, 2016, the SMCHS determined that further activity was needed to delineate the extent if any, of groundwater contamination. The responsible party was requested to advance one boring and collect a groundwater sample from the suspected source area. A work plan to conduct these activities was submitted on 8/17/2021. On 9/7/2021 a new voluntary remedial action agreement was filed with a new owner which assumes the position of responsible party. Notice of concurrence with conditions of the 2021 workplan was given in a letter on 10/14/2021. Following concurrence of the workplan a sampling activities report was submitted on 8/11/2023. This report details investigation activities performed including sapling of soil, soil vapor and groundwater. Following sampling the "results of the investigation indicated that the two highest concentrations of PCE of 2.2 mg/kg and 1.1mg/kg were encountered at depths of 4 feet and 6 feet bgs at the southwestern portion of building." Following sampling a supplemental workplan was submitted which detailed activities which will be undertaken to collect a groundwater sample at the form of the building… remove and dispose of underlying sediments at the southwestern portion of the site and along the sanitary sewer, installation of vapor mitigation measures, and monitoring of soil vapor and indoor air levels for a minimum of one season. This workplan was submitted on 8/30/23, a response was filed on 9/14/23 which requested a further addendum to the workplan. A revised remedial action workplan was submitted on 9/28/23 and subsequently given conditional approval on 11/1/2023. As of the date of this Phase I, remedial action is underway at the site.

MYINT SWE DDS INC | REDENCION U J JAOCHICO, DMD, 1133 El Camino Real, located 730-feet north from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUTNY – CA** database.

- Based on information found in the above identified database this facility is a dentist's office which produces medical waste.

LEUNG & ABAYA DENTAL OFFICE | MARILYN SY DDS | DR. EDEN JAOCHICO DENTAL SERVICES INC, 1133 El Camino Real, located 7310-feet north from the SP was identified in the **HAZNET – CA** and **HWG – CA** databases.

- Based on information found in the above-listed databases this facility is a dental office which produces medical waste. Records detail the disposition of hazardous waste to the appropriate facilities.

NORGE VILLAGE CLEANERS (FORMER), 1155 El Camino Real, located 806-feet north of the SP was identified in the **CALEPA – SITES** and **SLIC REG 2 – CA** databases.

- Based on information found in the above listed databases this facility is a former dry cleaner which is open for site assessment as of 5/28/2015. Constituents of concern are identified as PCE and TCE, substances commonly associated with former drycleaning facilities. Indoor air sampling was conducted at the facility in September 2023, PCE was detected in all three samples taken. Air purifiers were installed as a temporary mitigation measure, follow up indoor air sampling showed "PCE concentrations have dropped by approximately one order of magnitude with active mitigation measures installed in both restrooms." (EKI, 2023). As of the date of this Phase I, this property remains under investigation and further sampling events are currently underway.

GENIUS LEARNING | EDWARD V FOUCRAULT | GUARDIAN ABULANCE SVC, 1165 El Camino Real, located 857-feet north-northwest from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY - CA, HAZNET – CA,** and **HWG – CA** databases.

- Based upon information attained from the above identified databases, this facility was formerly a storage location of hazardous waste. Waste details include the production of organic solids, contaminated soil from site cleanup, off specification or aged surplus organic, and other organic solids. Records show the waste as having been transported to appropriate facilities for disposal.

PACIFIC GAS AND ELECTRIC, 950 Antoinette Lane, located 1,197-feet northeast from the SP, was identified in the **HAZNET – CA** and **HWG – CA** databases.

- Based on information obtained from the above listed databases, this facility is a former hazardous waste generator which produced inorganic solid waste. Records show the disposal of waste to approved off-site facilities.

Grand Avenue Gas | Grand Ave Olympic | Liouse Brusco, 1086 Grand Avenue, located 2,028-ft north from the SP was identified in the **EPA LUST, LUST REG 2 – CA,** and **LUST_SAN MATEO COUNTY – CA** databases.

- Based upon information obtained in the above listed databases this facility is a former gas station which underwent assessment and cleanup actions relating to LUSTs and was ultimately granted closure status on 6/24/2022. The case was opened on 7/5/2011 because of soil sampling finding TPHg concentrations in soil as high as 10,000 parts per million. A significant number of records regarding the history of this site are available in GeoTracker including, monitoring reports, workplans, UST removal reports, vapor intrusion assessment reports, and agency responses. Based upon the distance from the SP and considering inferred groundwater flow direction, the EP has determined this facility poses little environmental risk to the SP. Therefore, the summary of this facility has been truncated.

Contreras Painting, 1090 Grand Avenue, located 2,067-ft north of the SP was identified in the **SLIC REG 2 – CA** database.

- Based upon information obtained from the above identified databases this facility is a closed cleanup

site where the contaminants of concern are solvents, mineral spirits, or distillates. The site underwent various assessment reports and cleanup actions and was ultimately granted clsaoure in 2011. Based upon the distance from the SP and considering inferred regional flow patterns, the EP has determined this site poses little environmental risk to the SP and therefore the summary for this facility has been truncated.

Based upon review of available materials such as monitoring reports and analytical results for samples collected at the SP, as well as considering inferred regional groundwater flow direction and distance from the SP, it is the opinion of the EP that none of the above discussed up-gradient sites pose significant environmental risk to the subject property at this time.

South (down-gradient)

ACCESS PROPERTIES LLC, 91 Westborough Boulevard, located 300-ft east-southeast from the SP, was identified in the **CALEPA SITES – CA** database.

- **CALEPA – SITES** identifies this facility as a non-residential property manager. It is identified as being listed in the US EPA Emission Inventory System (EIS), no details of the type of air pollutants released are provided.

CLUBVIEW APTS 2004 | KORET FOUNDATION, DBA CLUB VIEW APARTMENTS, 849 Orange Avenue, located 536-feet southeast from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, HAZNET – CA, HWG – CA, MANIFEST EPA,** and **RCRA_NONGEN** databases.

- The **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, HAZNET – CA, HWG – CA, MANIFEST EPA,** and **RCRA_NONGEN** databases identify this facility as formerly being a temporary hazardous waste generator. It is shown as having been the generator of various quantities of asbestos containing materials between 2000 and 2019.

CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO – MAINTINENCE. 95 Westborough boulevard located 536-ft southwest of the SP is identified in the **AST – CA, CALEPA SITES – CA, HWG – CA** and **RCRA_NONGEN** databases.

- According to the **AST- CA** database this facility is part of the above ground petroleum storage, chemical storage facility, and hazardous waste generator programs. It has above ground storage tanks which hold 600-1,199 gallons of diesel fuel, 600-1,199 of gasoline,

TOMMY'S CLEANERS | WALGREEN #3346 | CENTENNIAL VILLAGE, El Camino Real, located 544-ft south-southwest from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA** and **MANIFEST EPA** databases.

- **MANIFEST EPA** identifies this facility as a hazardous waste generator which generates less than 27 gallons/year. Records identify the disposal of hazardous waste to an approved facility. The type of waste disposed of is identified as "non-RCRA hazardous waste, solid (consumer products)".

WEST ORGANE LIBRARY | CLUB VIEW APARTMENTS, 840 W Orange Avenue, located 642-ft south-southeast from the SP was identified in the **CALEPA SITES – CA, EPA LUST, HAZNET – CA, HIST UST – CA, HWG – CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY – CA, MANIFEST EPA,** and **RCRA_NONGEN** databases.

- The above listed databases identify this facility as formerly being a leaking underground storage tank cleanup site. Constituents of concern are identified as being diesel fuel which leaked from a UST. The leak was first reported on 06/24/1999, the case has been closed and was given notice of no further action as of 8/09/2001. The facility was also identified as a former hazardous waste generator which produced and disposed of asbestos containing material at various times between 1996 and 2014. Available manifest records show hazardous asbestos containing materials was disposed of via treatment and transfer to an approved landfill facility.

Based upon review of available materials such as monitoring reports and analytical results for samples collected at the SP as well as the identified facilities and considering inferred regional groundwater flow direction and distance from the SP, it is the opinion of the SP that not of the above discussed down-gradient sites pose significant environmental risk to the subject property at this time.

West (cross-gradient)

BILL STAVROULAKIS, 112 Arroyo Drive, located 281-ft from the SP was identified in the **HWG – CA, MANIFEST EPA,** and **RCRA_NONGEN** databases.

- The **HWG – CA, MANIFEST EPA, AND RCRA_NONGEN** identify this facility as the originator of <1 ton of asbestos containing waste. Records indicate the asbestos containing material was treated and stabilized prior to being transported to an approved landfill facility.

Based upon review of available materials such as monitoring reports and analytical results for samples collected at the SP, as well as considering inferred regional groundwater flow direction and distance from the SP, it is the opinion of the SP that none of the above discussed cross-gradient sites pose significant environmental risk to the subject property at this time.

East (cross-gradient)

SOUTH SAN FRANCISOC AT HOME, 74 Camaritas Avenue, located 164-ft was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA** database.

- The **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA** identifies this facility as a producer of medical waste. This facility appears to be a dialysis center which produces >200 lbs/month of medical waste. Records identify the waste as being transported off site for disposal.

PENINSULA DIALYSIS ACCESS | T MOBILE WEST CORPORATION SF03183A, 91 Westborough Avenue, located 303-ft east-southeast from the SP was identified in the **BUESSINES INVENTORY_SAN MATEO CONTY – CA** database.

- The **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA** identifies the program category for this facility as medical waste.

O'REILLY AUTO PARTS STORE 2743 | 1X BLOCKBUSTER VIDEO, INC., 1059 El Camino Real, located 469-feet east-northeasterly was identified in **BUSSINESS INVENTORY_SAN MATEO COUNTY, CALEPA SITES – CA, HAZNET – CA, HIST HAZNET – CA. HWG – CA, MANIFEST EPA, RCRA_NONGEN,** and **SWRCY – CA** databases.

- The **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA** database identifies this facility as a member of the county hazardous waste program which generates and recycles waste oil/solvent.

- The **CALEPA SITES – CA, HAZNET – CA** and **MANIFEST EPA** databases identify this facility as a chemical storage facility and a hazardous waste generator. Types of waste generated and stored are listed as used motor oil, used oil filters, and used absorbent containing oil. Multiple violations are noted by the certified unified program agency (CUPA) during inspections performed dating back to 09/12/2012 and as recently as 12/14/2022. Violations include failure to provide required training to employees, failure to accurately maintain hazardous waste manifests, improper storage and labeling of hazardous materials including used lightbulbs and brake shavings, and failure obtain permit to accumulate waste longer than ninety days. All violations are listed as having been rectified and the facility returned to compliance. Manifest records showing disposition of hazardous waste to approved facilities is provided.

WESTBOROUGH KIWK SERV | WESTBOROUGH LLC | WESTBOROUGH PETROLEUM INC, 1 Westborough Boulevard, located 666-feet east from the SP was identified in the **CALEPA SITES – CA, EPA LUST, FID UST – CA, HAZNET – CA, HIST UST – CA, HWG – CA, MANIFEST EPA, RCRA_NONGEN, SWRCB NON_CASE – CA,** and **UST – CA** databases**.**

- Based upon information found in the above-listed databases this facility is a fuel station which operates several USTs. Records identify three USTs at this facility, a 10,000-gallon tank with diesel, a 10,000-gallon tank with premium unleaded gasoline, and a 10,000-gallon tank with regular unleaded gasoline. No records identify any leak or release from any of the identified tanks. The facility is also identified as a hazardous waste generator which disposed of various types of hazarfous waste to approved facilities between 1995 and 2019. This facility historically had multiple other USTs all used for the storage of motor vehicle fuels.

MY CELANERS (FORMER) | MY CLEANERS | DON NHAN, 1053 El Camino Real, located 610-feet east-northeast from the SP was identifein the the **BUSSINESS INVENTORY_SAN MATEO COUNTY, CALEPA SITES – CA, HAZNET – CA, HWG – CA,** and **SLIC REG 2 – CA** databases**.**

- The above listed database indicates this facility was formerly a dry cleaner which operated from approximately 1960 and 2010 (Weiss, 2020). The property is currently under investigation and mitigation for the known presence of VOCs. Weiss Associates Inc. has submitted various monitoring reports which were accessed and reviewed by Cameron-Cole through the California State Water Quality Control Board's GeoTracker web application. Assessment and remediation activities undertaken at the property include excavation and characterization of contaminated soil, destruction of the former building, installation of bore holes, groundwater sampling, soil sampling, soil vapor sampling, and indoor air sampling of adjacent structures. Monitoring reports for the site as recently as the second quarter of 2020 were reviewed to establish the most recent subsurface conditions. Weiss' 2020 monitoring report indicates that "The results for this sampling event are consistent with the post-remediation monitoring data collected in 2019. The groundwater flow direction in the perched unit was to the south-southeast, consistent with the second, third and fourth quarter 2019. The analytical data for the samples collected in May 2020 support that the VOC concentrations in groundwater downgradient of the former source area are stable or declining." (Weiss Inc., 2020). Indoor and sub-slab vapor sampling was undertaken at the adjacent O'Reilly's auto parts store as well as Gunter's restaurant. Results from this sampling found that "…the sub-slab soil gas sampling identified PCE beneath the adjacent building at concentrations of up to 560 ug/m3. However, no PCE was detected above commercial/industrial ESLs at O'Reilly or Gunter's… Thus, it appears that, based

on two opposite season sampling events, there is not a significant vapor intrusion risk to the building." (Weiss Inc., 2020).

CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS | LIBRARY PARKS & REC, 1010 El Camino Real, located 746-feet east-northeast from the SP was identified in the **CALEPA – SITES, HAZNET – CA, HWG – CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 2 – CA,** and **SWRB NON_CASE – CA** databases.

- Based on information found in the above listed database as well as in a Phase II investigation accessed via GeoTracker, this facility was an unoccupied property which was investigated for environmental contamination by Ninyo and Moore. The facility is approximately 400-feet downgradient from the former MyCleaners site and 350-feet downgradient from the former Carriage Cleaners site. A Phase I identified the potential presence of lead in surface soils due to aerially deposition from leaded gaoline used in vehicles traversing El Camino Real. In response Ninyo and Moore prepared a Phase II which identified two soil samples which exceeded residential ESLS for TPHd, nine samples containing vanadium more than the tier 1 ESL, one sample containing zinc more than the tier 1 ESL, and three samples containing lead more than the tier 1 ESL. In response to these samples multiple remdial actions agreements and work plans were submitted. The most recent document available details a request for an operations and maintenance plan. As of the date of this document, the site remains open for long term monitoring.

SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR, 998 El Camino Real, located 876-feet east from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, CALEPA SITES – CA, HAZNET – CA, HIST UST – CA, HWG – CA,** and **UST – CA** databases.

- Based on information obtained from the above-listed databases, this facility is a former gas station which previously had four USTs on site. Records from 1988 gives details for three tanks which were installed in 1950, these tanks include a 7,500-gallon tank used for unleaded motor vehicle fuel, a 6,000-gallon tank used for waste oil, a 6,000-gallon tank used for premium motor vehicle fuel, and a 550-gallon tank used for waste oil. This facility was also a hazardous waste generator which disposed of various types of material to approved facilities in 2007. No record of a leak, spill, or other release was identified.

PACIFIC BELL | PACIFIC BELL TELEPHONE CO DBA AT&T CALIF, 965 El Camino Real, located 892-feet from the SP was identified in the **HAZNET – CA, HWG -CA,** and **RCRA_LQG** databases.

- Based upon information obtained from the above identified databases this facility was a large quantity hazardous waste generator. No details regarding the type of exact quantity of waste generated were identified.

VISTA DENTAL CARE | COHEN DENTAL CARE | COHEN DENTAL GROUP, 931 El Camino Rela, located 915-feet east-southeast from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, HAZNET – CA,** and **HWG – CA** databases.

- Based upon information obtained from the above-listed databases this facility is a dental office which is a registered small quantity generator, the type of waste is identified as medical waste. Records detail the disposition of hazardous waste to approved off-site facilities.

BUILDING KIDZ | MILLS OENINSULA HLTH SVC LAB & IMAG, 935 El Camino Real, located 916-feet east-southeast from the SP was identified in the **BUESSINESS INVENTORY_SAN MATEO COUNTY – CA** database.

- Based upon information obtained from the above-described database this facility is a small quantity generator which produced medical waste.

SOUTHWOOD CHIROPRACTIC, 943 El Camino Real, located 916-feet east-southeast of the SP was identified in the **HAZNET – CA** and **HWG – CA** databases.

- Based upon information obtained from the above-described databases this facility operated as a chiropractic office which produced photochemical/photo processing waste. Records detail the disposition of waste to approved, off-site facilities.

SHAC 988 ECR APARTMENTS, LLC, 998 El Camino Real, located 956-feet east from the SP was identified in the **BUSSINES INVENTORY_SAN MATEO COUTNY – CA, CALEPA SITES – CA, HAZNET – CA, HIST HAZNET – CA, HWG – CA, MANIFEST EPA – CA,** and **RCRA_NONGEN** databases.

- Based upon information obtained from the above listed databases this property previously operated a car wash under the name South City Car Wash which produced and disposed of various types of waste including soil, unspecified liquid waste, and photochemical/photo processing materials. Records indicate that all hazardous was transported and disposed to approved facilities.

SOUTH SAN FRANCISCO FOOT CLINIC, 927 El Camino Real, located 1,097-feet east-southeast from the SP was identified in the **HAZNET – CA** and **HWG – CA** databases.

- Based upon information obtained from the above-listed databases this facility is now inactive but was previously a medical clinic which produced photochemical/photo processing waste which was disposed of at authorized facilities.

CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE, 1 Chestnut Avenue, located 1,116-feet eath-northeast from the SP was identifieid in the **AST – CA, CALEPA SITES – CA, HAZNET – CA, HIST UST – CA, HWG – CA, MANIFEST EPA, RCRA_NONGEN,** and **SLIC REG 2 – CA** databases.

Based upon information obtained from the above-listed databases this property is currently used by the City of South San Francisco police department and was previously occupied by a facility named Ron Price Motors. During this time the facility utilized several USTs and ASTs on the property, these tanks were used for the storage of diesel, waste oil, and gasoline. The facility also hosted a service area as well as a part washing and hazardous material storage area. USTs and ASTs were removed from the property in 1991. In 1996 the San Mateo County Health Services Agency granted site closure to the site regarding the USTs at Ron Price Motors. In a 2007 Phase I ESA, Basics Environmental Inc. (Basics) recommended further investigation of the property. As a result, CSS Environmental Inc. (CSS) performed a peer review of Basics' Phase I as well as performed a limited Phase II. During this Phase II, CSS advanced six soil borings and collected samples from these borings. These samples did not return results above environmental screening levels of any of compounds tested for. In 2017, Ninyo & Moore performed a Phase II for the site which included various field activities including the installation of additional borings, soil-gas wells, and sub-slab vapor pins within the structure on the property. Ninyo & Moore concluded in part, that "elevated

concentrations of benzene and PCE, exceed their respective Tier 1 ESLs. The location of the benzene and PCE detections are near the areas formerly used by Ron Price Motors for parts washing, former storage area of hazardous materials, and former waste oil ASTs which are potential sources of the impacts." (Ninyo and Moore, 2019). Over the next four years Ninyo & Morre proceeded with various investigatory and mitigation actions including additional soil vapor surveys, a PCB and asbestos assessment, development of a remedial action plan, the design of a vapor intrusion mitigation system (VIMS), and the development of operations and maintenance procedures. Ultimately, in a memorandum dated 9/15/2023 the San Mateo County Groundwater Protection Program recommended to close the case due to post-construction sub-slab monitoring indicating that "construction activities have likely removed vapor sources and that ongoing mitigation is not required." (SMCGPP, 2023)

CHEVRON | FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION, 972 El Camino Real. Located 1,141-feet east from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, CALEPA SITES – CA, EPA LUST, LUST REG 2 – CA,** and **LUST_SAN MATEO COUNTY – CA** databases.

- Based on information obtained from the above-listed databases this facility is currently operating as a Burger King restaurant, records indicate that it was previously a fuel station which operated under various names. The property is listed as a leaking underground storage tank (LUST) cleanup site which was closed as of 3/30/2012. Investigatory activities at the site began in 2007 when Professional Service Industries (PSI) advanced soil borings to approximately 20-ftbgs to investigate potential RECs identified in a Phase I performed by PSI in early 2007. Petroleum hydrocarbons including TPHd, TPGg, and benzene were detected in two of four samples taken. A remedial action agreement was reached between the San Mateo County Health System and the former property owner, the SMCHS requested further characterization based upon the 2007 PSI report. In February of 2008 PSI removed one undocumented 800-gallon UST, soil samples collected during the removal of this tank did not find any analyte above the respective ESL. In July of 2008 on behalf of Chevron, CRA submitted a subsurface investigation workplan which involved the installation of additional borings to investigate hydrocarbon contamination. This work plan was subsequently approved and implemented in March of 2009. Additional borings were advanced adjacent to and downgradient from the location of the former ASTs to determine lateral and vertical extent of hydrocarbon contamination. The results of these samples found the presence of various constituents consistent with the established contamination at the site including TPHg, TPHd, and bezene. Subsequently additional groundwater monitoring wells were installed at the site and continual monitoring was undertaken. Based upon the results of continued monitoring, CRA, on behalf of Chevron, applied for case closure in 2011. A final notice of case closure was provided by the San Mateo County Health System on March 30th, of 2012.

SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY | SOUTHWOD DR WELL & TREATMENT FACILITY, 608 Southwood drive, located 1,254-ft east-southeast from the SP was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, CALEPA SITES – CA, HWG – C, MANIFEST EPA – CA, HWG, CA,** and **RCRA_SWG** databases.

- Based upon information obtained from the above listed databases, this facility is related to

infrastructure operated and maintained by the San Francisco Public Utilities Commission (SFPUC), This facility is identified as a hazardous waste generator which produced hypochlorite solutions, ammonium sulfate, sodium hydroxide, and alkaline solutions. This facility appears to be a public infrastructure which involves injection wells.

ACUTECH AUTO | WESTBOROUGH PET HOSPOTAL | AUTO STUDIO, 45 Chesnut Avenue, located 1,317-ft from the SP, was identified in the **BUSSINESS INVENTORY_SAN MATEO COUNTY – CA, HIST UST – CA, CALEPA SITES – CA, EPA LUST, HAZNET – CA, HWG – CA, LUST REG 2 0 CA, LUST_SAN** and **MATEO COUNTY - CA** databases.

- Based on information this property has been operated as multiple facilities. During the time which a pet hospital was operated the facility was identified as a generator of medical waste. Similarly, during its time operating as an auto shop there were USTs present on the site. As a result of leaks detected from these USTs, this site is identified as a LUST cleanup site which was granted closure in 2003. Based upon information obtained from GeoTracker the property was granted closure with site management requirements including a prohibition on excavation of contaminated soils without agency approval, no groundwater extraction without agency approval, notification requirements prior to development, and notification prior to any subsurface work. Constituents of concern for the site include gasoline relating to the identified leaking USTs which were removed in 1991.

Chesnut Cleaners | Eun Young Kim, 26 Chesnut Avenue, located 1,409-ft east-northeast from the SP was identified in the **SWRCB NON_CASE – CA** database.

- Based on information obtained in the above listed database, this facility is a former dry cleaner which underwent informational review by the RWQCB as of 4/23/2018. Due to its history as a former dry cleaner a site history report was prepared in 2018. Similarly, a site assessment report was prepared in 2018 and indicated that PCE contamination in the vicinity of the site was not related to the activities at the property. The site was granted non-case status as of 9/27/2018.

South SF Groundwater Investigation, East of El Camino Real, located 1,504-ft east of the SP was identified in the **LUST_SAN MATEO COUNTY – CA, SWRCB CLENAUP – CA,** and **SWRCB NON_CASE – CA** databases.

- Based upon information obtained from the above listed databases this property is associated with an active cleanup case where the constituents of concern are gasoline, MTBE, TBA, other fuel oxygenates, tetrachloroethylene, and TPH. Limited information about the source of the contamination is provided, based upon available records it appears the site is a LUST cleanup site which is currently undergoing assessment.

STAN THE ROOF MAN, 103 1ST Street, located 1,548-ft east from the SP was identified in the **EPA LUST, LUST REG 2 – CA,** and **LUST_SAN MATEO COUNTY – CA** databases.

- Based upon information obtained from the above listed databases, this facility is a closed LUST cleanup site as of 8/10/2000. Records indicate that the constituent of concern at the site is gasoline which leaked from a UST previously operated at the facility. The case began in 1992 and underwent assessment, ultimately the case was closed in 2000.

California Water Services Company, 90 Chesnut Avenue, located 1,953-ft east-northeast from the SP was identified the **SWRCB NON _CASE – CA** database.

- Based upon information obtained it the above listed database this facility underwent an informational review in 2018 and was granted non-case status.
  Based upon the records reviewed it is the opinion of the EP that at this time the above-described facility does not pose and increased environmental risk to the SP.

Finley Construction Co., 125 Chesnut Aveune, located 2,215-ft east-northeast from the SP was identified in the **EPA LUST, LUST REG 2 – CA, LUST_SAN MATEO COUNTY – CA** databases.

- Based upon information obtained from the above list databases this facility is closed LUST cleanup site where gasoline is identified as the contaminant of concern. Records indicate the leak was initially discovered in 1989, the site began assessment and remediation activities and ultimately was granted case closure on 7/9/1992.

SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL, 710 El Camino Real, located 2,245-ft east-southeast from the SP was identified in the **EPA LUST, LUST REG 2 – CA, LUST_SAN MATEO COUNTY – CA** databases.

- Based upon information obtained from the above-listed databases this facility is a former Shell gas which is classified as a LUST cleanup site. Contaminants of concern at the facility are identified as waste oil, motor oil, hydraulic oil, and lubricating oil. The case relating to the release of these materials included various assessment and remediation activities. A full account of the activities performed relating to the LUST is available in the government records report. Ongoing activities to other USTs were active as recently as 2022. A report detailing the removal of gasoline USTs in preparation for site development was submitted by AU Energy LLC on June 24th, 2022. Samples taken during the removal of these USTs did not find any evidence of additional release.

Based upon review of available materials such as monitoring reports and analytical results for samples collected at the SP, as well as considering inferred regional groundwater flow direction and distance from the SP, it is the opinion of the SP that not of the above discussed cross-gradient sites pose significant environmental risk to the subject property at this time.

5.3 Unmappable Sites

The Envirosite Report (Appendix B) includes a summary of identified points of intertest that may be in the general area of the subject property; yet do not have adequate location addresses or latitude/longitude coordinates to pinpoint their exact location in relation to the subject property. Five unmappable sites were identified in the Envirosite report. None of the facilities identified as unmappable were observed in the vicinity of the subject property during the site reconnaissance, and research into these facilities through other available materials did not show any reason to believe they have any impact to the SP.

5.4 Additional Environmental Record Sources

5.4.1 County Property Assessor/Appraiser

According to records maintained by the San Mateo County Assessor's office, the subject property is identified by APN 0104-02-240 and is currently owned by the City of South San Francisco.

5.4.2 Fire/Police officials

Cameron-Cole contacted the City of South San Francisco Fire Department as well as the City of South San Francisco Police Department on October 24th, 2023, requesting records pertaining to fires or responses to incidents, spills, or releases of hazardous substances or petroleum products at, or in the immediate vicinity of the property. No response has been received as of the date of this report.

5.5 Physical Setting Sources

5.5.1 Topography

Figure 1 is a Site Map which shows the vicinity of the subject property. Topographic maps furnished by Envirosite were reviewed to establish the physical setting of the subject property and surrounding area. The site lies approximately 50-ft to 70-ft above mean sea level and generally slopes southeasterly.

5.5.2 Soils/Geology

The Envirosite report provides a summary of the United States Department of Agriculture (USDA) Soil Survey of the subject property's general area. The USDA soil conservation service identifies the general area of the SP to be urban land, therefore no further soil type data is available.

5.5.3 Hydrology

Based on topographic maps, and review of groundwater monitoring reports prepared for nearby sites, there are two hydrologic units beneath the site. A deep groundwater unit is inferred to flow east to north easterly, and a shallow perched groundwater unit in a south to southeasterly direction (Weiss, 2020).

5.6 Historical Use Information

Available historical resources were consulted to develop a history of the previous uses of the property to help identify the likelihood of past uses having led to RECs in connection with the subject property. Copies of the aerial photographs, historical topographic maps, Fire Insurance Maps, and City Directory Report are provided in Appendix C.

5.6.1 Aerial Photographs

The aerial photographs described below furnished by Envirosite were reviewed to assess the general physical conditions of the property over time. Copies of the 1941, 1943, 1946, 1947, 1956, 1960, 1965, 1968, 1969, 1971, 1972, 1974, 1975, 1982, 1983, 1985, 1987, 1988, 1991, 1993, 1995, 1998, 2000, 2001, 2005, 2009, 2010, 2012, 2014, 2016, 2018, 2020, 2022 aerial photographs are provided in Appendix C. Property descriptions may be truncated if little to no change in the physical conditions were observed for a given time period.

Date: 1941-1943

Scale: 1" = 500'

> **Description of Subject Property:** What appears to largely be agricultural land, an area cleared of vegetation appears to traverse the SP. The exact nature of this cleared area is not discernable.

Adjoining North: What appears to be agricultural land. A road appears to traverse west to east.

Adjoining East: What appears to agricultural land.

Adjoining South: What appears to be part of the California Golf Club of San Francisco.

Adjoining West: What appears to agricultural land.

Surrounding Area: The surrounding area appears to be generally undeveloped with a majority of the vicinity being used for what appears to be agriculture. Limited structures are visible approximately 1,000-ft to the north of the SP. Cleared areas which appear to be part of the Golf Club of San Francisco can be seen to the south of the SP.

Date: 1946-1947

Scale: 1" = 500'

Description of Subject Property: The SP has been cleared of vegetation in relation to the development activity occurring directly to the north.

Adjoining North: A residential development can now be seen directly to the north of the SP. Multiple completed structures as well as activity indicative of active development can be observed.

Adjoining East: The east of the SP appears to have been cleared of vegetation, activity relating to the development of homes can be seen.

Adjoining South: The south of the SP appears unchanged since the 1943 aerial image.

Adjoining West: Informal dirt roadways can be seen to the west of the SP. It appears these roadways are used for the residential development to the north.

Surrounding Area: The vicinity of the SP is beginning to be developed for use as residential development. Various activities including vegetation clearing, construction of homes and roadways can be seen.

Date: 1956

Scale: 1" = 500'

Description of Subject Property: The subject property now hosts a structure in the northwestern corner along Arroyo Drive. The exact nature of the structure is not ascertainably from the aerial imagery.

Adjoining North: The area to the north of the SP is now significantly developed; significant roadways are now present to the north. Large residential developments have replaced the open space previously observed.

Adjoining East: The east of the SP is now significantly developed. Camaritas avenue can now be seen bordering the SP.

Adjoining South: What appears to be undeveloped land.

Adjoining West: Development has expanded directly to the west of the SP, including homes on Arroyo drive directly boarding the SP which remain present to the modern day.

Surrounding Area: The vicinity of the SP has significantly developed in the time between 1947 and 1956. Nearly the entirety of the area observable in the aerial image is now developed for commercial or residential purposes. Larger throughfares have been installed alongside this development. The San Francisco Golf Club remains bordering the SP directly to the south.

5.6.2 Fire Insurance Maps (Sanborn Maps)

The Fire Insurance Maps Report provided by Envirosite identified coverage of the SP. Through review of these maps, it appears there was formerly a fuel station adjoining the SP at the corner of Camaritas Avenue and Arroyo Drive.

5.6.3 Recorded Land Title Records

A historical chain-of-title report was not provided or obtained as part of this Phase I.

5.6.4 Historic USGS Topographic Maps

The historic topographic maps described below were obtained from Envirosite. Copies of 1892, 1896, 1899, 1915, 1939, 1943, 1947, 1950, 1956, 1993, 1995, 2012, 2015, 2018, and 2021 topographic maps are provided in Appendix C.

Date: 1892 - 1899

Scale: 1:62500

Description of Subject Property: Appears to be undeveloped.

Adjoining North: Largely undeveloped, southern pacific railway is to the north to some distance.

Adjoining East: Undeveloped directly to the east, beyond that is the southern pacific railway.

Adjoining South: Largely undeveloped, a creek appears to flow to the south.

Adjoining West: Undeveloped land.

Surrounding Area: Mostly undeveloped land, a railway operated by Southern Pacific runes to the northeast.

Date: 1915

Scale: 1:24000

Description of Subject Property: Appears to be in similar condition to which was observed in 1899.

Adjoining North: A roadway now traverses to the north of the SP.

Adjoining East: More roadways and rail lines are now to the east.

Adjoining South: The south appears to still be undeveloped.

Adjoining West: Appears to still be undeveloped.

Surrounding Area: The general area remains a mix of undeveloped and rail lines.

Date: 1939 – 1950

Scale: 1:24000

Description of Subject Property: The SP appears unchanged from the previous observation.

Adjoining North: There are now significant roadways typical of a residential development to the north.

Adjoining East: Areas to the east of the SP are significantly developed with roadways.

Adjoining South: A roadway appears to traverse directly to the south of the SP.

Adjoining West: Remains largely unchanged from previous observation.

Date: 1956 – 2021

Scale: 1:24000

Description of Subject Property: Appears to be undeveloped.

Adjoining North: Significant development is now to the north of the SP; roadways are common, and the area is generally developed.

Adjoining East: Roadway directly to the east, open area beyond the roadway.

Adjoining South: Roadway directly to the south.

Adjoining West: No noted structures pr features to the west/.

Surrounding Area: The area surrounding the SP is not significantly developed. All areas are inhabited by some structure or roadway.

5.6.5 Local Street Directories

Historical street directories for the subject property and adjacent property addresses were provided by Envirosite. The primary address for the Subject property is 71 Camaritas Avenue, through review of historical sources we have determined that additional addresses are present on the SP. These additional addresses include 73 and 75 Camaritas Avenue. Due to the large number of residential properties in the vicinity of the SP, some adjacent addresses have been omitted from section 5.7.5 if they were deemed to only have been residential throughout their history. The complete city directory report is provided in Appendix C.

Subject Property

71 Camaritas Avenue

1973, 1978, 1983, 1993, 1998, 2002, 2006, 2010, 2015, 2018 - Buri Buri Liquor

73 Camaritas Avenue

1973, 1978, 1983 - Buri Buri Delicatessen

1998, 2002, 2015, 2018 - Ongpin Noodles

2006, 2010 - Edgas Elazigue

75 Camaritas Avenue

1973 - Armanino Gun Shop

1978 - Buri Buri Realty

1983, 1993 - Frank Cosentino, Affiliated Air Services

1998 - Fantasy Comics

Note: *Additional listings were identified for properties named Buri Buri Liquor, Buri Buri Delicatessen, and Buri Buri Chevron SVC in 1959, 1963, and 1968. However, the addresses provided for these facilities in these years were 13, 11, and 1 Camaritas Avenue, respectively. It is unclear whether the street number or the physical location of these facilities were changed prior to 1973 when they first appear on the SP addresses.*

Adjacent Properties

74 Camaritas Avenue (East of the SP, across Camaritas Avenue)

1959 - Bank of America

1983 - Doherty and Dunne Sporting Goods

1993 - Doherty & Dunne Inc, First National Bank of Daly City

1998, 2002 – Blockbuster Video

2006 – Joseph So

2015, 2018 – Davita South San Francisco

33 Arroyo Drive (Northeast of SP, across Camaritas Avenue)

1983, 1993 – Senior Citizens Nutrition Program

1998 – Police Department, Maintenance Division Administration, South San Francisco Fire Emergency, City of South San Francisco Senior Services, Libraries Grnd Ave, Police Department Anonymous Tip Line, Maintenance Division Garage, Maintenance Division Emer Night and Weekend Service, Police Department Emergency

2002 - S San Francisco Senior SVC, S San Francisco Police Dept, S San Francisco Recreation Svc, S San Francisco Fire Dept, S San Francisco City Empl Fcu

2006 - Sharon Ranals, Mark Raffaelli, Laura Giga, Gus Vellis, Phillip White, Laura Armanino

2010 - Mike Massoni, Sharon Ranals, Laura Giga, Sandi Trembly, Laura Armanino, S San Francisco

Swimming Pool

2015 - S San Francisco Parks & Rec, S San Francisco Police Dept, South San Francisco City FCU, Bruce McPhillips, Great Commission Church

2018 – Great Commission Church, Police Department, S San Francisco Parks Rec, S San Francisco Parks & Rec, S San Francisco Police Dept, South San Francisco City FCU

81 Arroyo Drive (Northeast of SP, across Camaritas Avenue)

1963, 1968, 1973, 1978 – Buri Buri Shell SVC

100 Arroyo Drive (Northwest of SP, across Arroyo Drive)

1959, 1963, - Henriques J A, Julian D E MD, Sanders Realty Co.,

1968 - O Reilly E M, Kenny G Realty, Larry's Barber Shop

1973, 1978, 1983, 1988 – Wong Morris DDS, O Reilly Edward M, Thomassen Paul, Kenny Realty, Bron's Barber Shop

1998 – Dell John B DDS, Kenny Realty, Oreilly Edward M DDS, Wong Morris DDS

2002 – Kenny Realty, Wong Morris DDS, O Reilly Edward M DDS, Bron's Scissors, Ambus Toni DDS

2006 – Bron Loli, Morris Wong, Michael Kenny

2010 – Bron Ioli, Michael Kenny, Maung Naing, Morris Wong

2015 – Bron's Scissors, Kenny Realty, Naing Maung DDS, A D T-Authorized Dealer

2018 – Brons's Scissors, Kenny Realty

101 Arroyo Drive

1959 - Mobilgas SVC Dealers

1963 - ALS Mobile Service

1968, 1973 – Correa Brothers Mobile SVC

1983, 1993 – Glendale Federal S&L ASSN

1998 – Glendale Federal Bank Offices South San Francisco

2006, 2010, 2015 - CitiBank

5.6.6 Building Department Records

Historical use of the subject property was researched using other standard historical sources and was identified as undeveloped; therefore, Building Department records were not reviewed as part of this assessment.

5.6.7 Zoning/Land Use Records

Historical use of the subject property was researched using other standard historical sources and was identified as undeveloped; therefore, historical Zoning/Land Use records were not reviewed as part of this assessment.

5.6.8 Prior Assessment Reports

Cameron-Cole was provided with and reviewed multiple previous assessments for the property located on parcel 010-402-240. The following reports were reviewed to assist in identifying RECs, HRECs, or CRECs,

A Phase I ESA done by Basics Environmental (Basics) on November 7th, 2016, was reviewed by Cameron-Cole. This Phase I included interviews of individuals, a review of federal and state environmental databases, a site reconnaissance, and a review of various historical materials including aerial imagery, Sanborn fire insurance maps, and topographic maps. This ESA did not identify any RECs, CRECs, or HRECs. Basics determined that several conditions present on the SP constitute *de minimis* conditions. These conditions include the use of a select area of the parcel as an easement by the SFPUC and the use of the structure as a restaurant/retail facility.

Cameron-Cole was also provided and reviewed *Phase I Environmental Site Assessment Report Peer Review* authored by Ninyo & Moore Inc. (Ninyo & Moore) on July 15th, 2021. This document is a summary and assessment of the Phase I ESA performed by Basics. Ninyo & Moore concluded that "…the ESA was performed in accordance with ASTM E1527-13 standard and concurs with Basics' conclusions that no RECs, CRECs, or HRECs, were identified at the site based on the findings of the ESA." (Ninyo & Moore, 2021)

Lastly, Cameron-Cole was provided with and reviewed a Phase II Environmental Site Assessment for the property located on parcel 010-402-240 published on October 6th, 2021, by Ninyo & Moore. This Phase II includes site background information, investigatory activities, and results. Investigatory activities undertaken by Ninyo & Moore include the installation and sampling of soil vapor probes, and the sampling of soil media. Results of soil sampling found detections of arsenic above Environmental Screening Levels (ESLs) in all but one sample. Ninyo & Moore notes that while these samples exceeded ESLs, no sample found arsenic above the established regional background level of 11-mg/kg. All soil samples also had detections of antimony which exceeded its residential ESL of 11-mg/kg (Figure 4) in every sample analyzed. Soil gas results found chloroform was in one sample at 6.4-µg/m³, which exceeds the residential ESL of 4.1-µg/m³ but is below the commercial ESL of µg/m³. Similarly, benzene was detected in one sample at a level of 4.3-µg/m³, which exceeds the residential ESL of 3.2-µg/m³ but below the commercial ESL of 14- µg/m³. Ninyo & Moore states that "Given that it is likely the benzene concentrations detected are related to a petroleum fuel release from the former fuel service station on the adjoining property, benzene was also compared to the State of California Water Resources Control Board Low-Threat Underground Storage Tank Case Closure Policy (LTCP), residential and commercial criteria for direct measurement of soil gas concentrations (Appendix 4, Scenario 4, Soil Gas Sampling – No Bioattenuation Zone), effective August 17, 2012." (Ninyo & Moore, 2021). Based upon comparison to the LTCP Ninyo & Moore determined the presence of these substances in the soil gas sample and soil constitute *de minimis* conditions and was unlikely to pose a significant risk to the current site building occupants. Considering the concentration of benzene above the residential ESL was found in the soil vapor probe located further away from the former fuel station than the soil gas sample with no detection (Figure 3), it is the opinion of Cameron-Cole that the two soil vapor samples collected by Ninyo & Moore did

not adequately characterize the potential distribution of contaminants in the subsurface of the SP. Considering Cameron-Cole has not identified any records detailing remediation activities regarding the former adjacent fuel station and based upon the known presence of these substances in the subsurface of the SP as demonstrated by Ninyo & Moore's data, it is the opinion of the EP that this constitutes a recognized environmental condition.

5.7 Historical Use Summary

The following is a summary of the subject and adjacent property historical uses based on a review of the historical records reviewed in Section 5.6.

Adjoining North: The parcel directly to the north of the SP identified by street address 101 Arroyo drive remained undeveloped until approximately the 1950's. The first appearance of development on this property is seen in the 1956 aerial imagery which depicts a structure having been built. Based upon city directory reports as well as local knowledge detailed in documents reviewed including Phase I and Phase II ESAs conducted by Ninyo & Moore Inc., this facility was used as a fuel and mobile service station from approximately 1956 until approximately 1973. City directory reports indicate the property was transitioned to operating as a financial institution in 1983 and continued to operate as a business of this nature under various names until it was purchased and built as a Citi Bank branch in 2008. This bank operates on the property as of the date of this Phase I. The general area to the north of 101 Arroyo was undeveloped prior to 1946 when aerial imagery depicts residential development. Many of the homes built during this period remain present today and the typical land use of much of the area north of the SP remains residential.

Adjoining East: Areas to the east of the SP appear to be generally undeveloped until approximately 1956 when development is first observed in aerial imagery. A commercial shopping lot was built across Camaritas avenue to the northeast and remains the current land use. The general area to the east remains a mix of commercial and residential properties, commercial activities to the east include gas stations, retails stores, a fish market, and limited medical offices.

Adjoining South: The south of the SP appears to have been used as a golf course as late as 1941. This remained the case until approximately 1970 when Westborough Avenue was built along the southern border of the SP and the golf course beyond Westborough Avenue. This remains the present conditions to the south of the SP presently.

Adjoining West: Areas to the west of the SP remained undeveloped until approximately 1946 when residential construction began. A significant number of homes are first observed in 1956 and remain the general land use of areas to the west of SP presently.

Subject Property: The SP was undeveloped land until approximately 1971 when a structure first appears. Based upon city directory information the structure was initially occupied by a liquor store and a delicatessen. The structure has been used for various other purposes throughout its history including as a firearms store, a comic bookstore, an air services facility, and as the office for a realty company. Beginning in 1998 it was used by the Ongpin restaurant, which remains the only occupant of the building as of the date of this ESA.

In accordance with ASTM International E1527-21, 8.3.1, the objective of compiling and analyzing historical property information and developing a history of the previous uses of the subject property, adjoining properties, and surrounding area is to help identify the likelihood of past uses having led to recognized environmental conditions in connection with the subject property. All obvious uses of the subject property must be identified from the present, back to the subject property's first developed use, or back to 1940, whichever is earlier. The report must describe all identified uses, justify the earliest date identified for the subject property's first developed use, and explain the reason for any gaps in the history of use. This task requires reviewing as many of the standard historical resources in 8.3.4.1 through 8.3.4.8 as are necessary and both reasonably ascertainable and likely to be useful. Data failure occurs when all the standard historical sources that are reasonably ascertainable and likely to be useful have been reviewed and yet the objective has not been met. Data failure is not uncommon in trying to identify historical uses at 5-year intervals back to first use or 1940 (whichever is earlier). If the data failure represents a significant data gap to the Environmental Professional (EP), ASTM International Standard E1527-21 requires documentation of the impact of the data gap on the ability of the EP to identify RECs. No significant historical use information data gaps were encountered.

6.0 SITE RECONNAISSANCE

6.1 Methodology and Limiting Conditions

The methodology used by the Cameron-Cole representative during the October 23rd, 2023, site reconnaissance consisted of visual observations of readily accessible areas of the subject property to determine the presence or absence of hazardous substance or petroleum product storage areas or spills as indicated by stressed vegetation, soil staining, storage tanks, drums, etc.

6.2 General Site Setting

The subject property one parcel in South San Francisco with surface area of approximately 1.07-acres and according to the San Mateo County Assessor's office is associated with APN 010-402-240. The subject property currently consists of one approximately 7,650-ftsq structure which is used for commercial operation of a restaurant. This multi-unit structure also occupies the street address 74 Camaritas Avenue and previously hosted various businesses. At the time of site reconnaissance, the only operating business was Ongpin restaurant. The SP also hosts an open landscape area which extends from the boundary of Westborough boulevard to the boundary of Arroyo Drive. This landscape area is operated as an easement by the SFPUC for the operation of two subsurface water/sewage pipelines.

6.2.1 Geologic, Hydrogeologic, and Topographic Conditions

Our site reconnaissance identified the SP to be generally flat with a minor slope toward the southeast. The elevation of the SP ranged from approximately 70-feet above mean sea level in the northwestern corner to approximately 50-feet above mean sea level near the corner of Westborough Avenue and Camaritas Avenue. Based upon review of groundwater monitoring well data obtained from nearby sites, primarily the former MyCleaners site located to the east, there are two identifiable groundwater units beneath the site. A "shallow perched" unit which typically shows groundwater as shallow as 2.9 to 5.2 ft-bgs and typically flowing in a south to southeasterly direction (Weiss, 2021). A deeper unit is also identified with water levels typically ranging between 90 and 110-ftbgs with a flow typical flow direction toward a north-northeasterly orientation. It must be noted that the groundwater flow direction can be influenced by factors such as surface topography, underground structures, seasonal fluctuation, soil and bedrock geology, and production wells, which were not considered in this interpretation. Cameron-Cole has made no independent investigation into the actual groundwater flow under the SP, based upon the topography of the site and review of reports for nearby sites, we infer that the groundwater under the SP typically flows in a south to southeasterly direction.

6.2.2 General Description of Structures

One structure is currently present on the SP. The approximately 7,650-sqft commercial building is currently occupied by the Ongping restaurant. This single-story building is built as slab-on-grade and is in large made of masonry building materials. Certain portions of the interior of this structure were not accessible during our site reconnaissance and thus were not assessed as part of this Phase I.

6.2.3 Roads

The SP is bounded by roadways on three sides, bordering SFPUC easement area is Arroyo Drive, to the northeast of the SP is Camaritas avenue, and to the south is the major thoroughfare Westborough boulevard.

6.2.4 Potable Water Supply

Potable water is supplied to the SP is supplied by the municipal utility organization SFPUC.

6.2.5 Sewage Disposal System

Sewage disposal from the SP appears to be provided by the SFPUC.

6.3 Subject Property Observations

6.3.1 Hazardous Substances and Petroleum Products in Connection with Identified Uses

No hazardous substances or petroleum products were observed on the subject property during our site reconnaissance.

6.3.3 Odors

Noticeable odors were not identified at the subject property at the time of the property reconnaissance.

6.3.4 Pools of Liquid

No pools of liquid were observed on the subject property during the property reconnaissance.

6.3.5 Drums

Cameron-Cole did not observe drums on the subject property during the property reconnaissance.

6.3.6 Pits, Ponds, or Lagoons

There were no pits, ponds, or lagoons noted onsite during the site reconnaissance.

6.3.7 Stained Soil or Pavement

No stained soil or pavement was noted onsite during the site reconnaissance.

6.3.8 Stressed Vegetation

Stressed vegetation was not observed during the site reconnaissance.

6.3.9 Solid Waste

A *de minimus* amount of household waste was noted in the SFPUC easement area during site reconnaissance. Solid waste dumpsters were observed in the rear of the restaurant, based on material observed within these units, they appeared to be used for the disposal of typical restaurant refuse, no hazardous materials were identified within the SP. Also near the rear of the restaurant were multiple storage containers which according to labels present on the outside of the containers, are used to store used cooking oil for future disposal. The containers appeared to be in good condition and showed no signs of leaks and or spills.

6.3.10 Wastewater

Cameron-Cole did not observe any wastewater on site.

6.3.11 Wells

No groundwater wells were observed during the site reconnaissance. Records provided to Cameron-Cole show that there previously were several monitoring wells on the SP. These historic monitoring wells are described further in section 7.4.

6.3.12 Septic Systems

Septic systems were not observed at the time of site reconnaissance and no information was provided to Cameron-Cole which would indicate the presence of a septic system.

7.0 INTERVIEWS

7.1 Site Owner/Occupants

No site owners or occupants were interviewed as part of this ESA.

7.2 Past Owners, Operators, Occupants

Past owners, operators, or occupants were not interviewed for this Phase I ESA.

7.3 User

A completed copy of the User questionnaire was not received by Cameron-Cole; thus, no interview of the user was conducted.

7.4 State and/or Local Government

Cameron-Cole submitted a records request with the City of South San Francisco on October 24th, 2023, requesting records regarding environmental violations, releases, or hazardous material or petroleum product storage, storage tanks or any other environmental concern at, or within the immediate vicinity of the subject property. A response was received on November 14th, 2023, which provided no records regarding hazardous substances or petroleum products.

Cameron-Cole contacted the California Department of Toxic Substances Control on October 24th, 2023, requesting records regarding environmental violations, releases, or hazardous material or petroleum product storage, storage tanks or any other environmental concern at, or within the immediate vicinity of the subject property. A response was received on October 24th indicating that no records pertaining to the subject property were found.

Cameron-Cole contacted the San Mateo County Department of Environmental Health on October 24th, 2023, requesting records regarding environmental violations, releases, or hazardous materials or petroleum product storage, storage tanks or any other environmental concern at, or within the immediate vicinity of the subject property. Documents received from the Department of Environmental health included drilling permits issued for 71 Camaritas avenue. A permit was issued 6/29/2011 to Geotechnical Consultants Inc. for one boring located in the southeast corner of the SFPUC easement located on the SP. Records indicate this boring was to be completed as a groundwater piezometer, and one cone penetration test. Another permit issued to the City of South San Francisco and listing Ninyo & Moore as the consultant. This permit indicates 10 borings were to be advanced on the SP, of these 10, 8 were to be soil borings with names SB-1 through SB-8. Boring depth is

variable per point, the maximum depth is shown as 15-ftbgs at SB-1. Soil samples were to be collected at depths of 1 and 4-ftbgs for points SB-1 through SB-5, and at 1-ftbgs for borings SB-6 through SB-8. The final two borings are identified by names SB/SV/GW-1 and SB-5/SV-2, these were advanced to a depth of 5.5-ftbgs. Soil vapor wells were installed in these borings at a depth of 5-ftbgs. Records indicate that these borings were completed as part of a Phase II ESA performed by Ninyo & Moore. This Phase II was reviewed by Cameron-Cole and is discussed in further detail in section 5.7.8.

8.0 FINDINGS AND CONCLUSIONS

The goal of this Phase I ESA is to identify the presence or likely presence of hazardous substances or petroleum products on the subject property under conditions that indicate an existing release, a past release, or a material threat of release of any hazardous substances or petroleum products into structures on the property or into the ground, groundwater, or surface water on the property. The findings of this report are summarized below and may include known or suspected RECs, CRECs, or HRECs identified during the performance of this Phase I ESA.

It is the opinion of the EP that there are no CRECs or HRECs, there is one condition which constitutes a REC. The known presence of benzene, chloroform, and antimony in the subsurface of SP above residential screening levels as shown in samples collected as part of a Phase II ESA by Ninyo & Moore Inc. constitutes a recognized environmental condition. It is the opinion of Cameron-Cole that the presence of these constituents in the subsurface of the SP has not been adequately characterized due to the spatially variable distribution of these substances in reference to the inferred source at the corner of Arroyo Drive and Camaritas Avenue. Cameron-Cole has not identified nor been provided with any records detailing remediation activities on the SP or on the site of the former fuel station, therefore Cameron-Cole has no reason to believe subsurface conditions have substantially changed since this data was collected. It is for these reasons the EP considers the presence of these substances in the subsurface of SP to constitute a recognized environmental condition.

9.0 DEVIATIONS

There were no contractual excluded elements or deviations from the ASTM International Standard E1527-21.

10.0 REFERENCES

ICES, 2016 – Interactive & Creative Environmental Solutions, Site Characterization Former Carriage Cleaners. 112 El Camino Real, South San Francisco. June 2016.

EKI, 2023 – EKI Environment & Water Inc., Indoor Air Monitoring Report, Former Norge Village Cleaners, 1155 El Camino Real, South San Francisco. January 2023.

Weiss, 2020. – Weiss Associates Inc., Soil Gas and Indoor Air Monitoring Report, Former My Cleaners Dry Cleaners, 1053 El Camino Real, South San Francisco. May 2020.

San Mateo County Department of Environmental Health Groundwater Protection Program, 2023. Notice of Pending Case Closure, Ron Price Motors, 1 Chestnut Avenue, South San Francisco. November 2023.

Ninyo & Moore, 2018. Phase II Environmental Site Assessment and Geophysical Survey, 1 Chestnut Avenue, 1010 El Camino Real, 33 Arroyo Drive, 81 Arroyo Drive, South San Francisco. January 2018.

Basics Inc. 2016, Basics Environmental Inc. Phase I Environmental Site Assessment, 71 – 75 Camaritas Avenue, South San Francisco, California. November 2016.

Ninyo & Moore, 2021. Phase I Environmental Site Assessment Peer Review, 71 – 75 Camaritas Avenue, South San Francisco. July 2021.

Ninyo & Moore, 2021. Phase II Environmental Site Assessment 71 Camaritas Avenue, South San Francisco. October 2021.

Envirosite 1941, 1943, 1946, 1956, 1960, 1965, 1667, 1968, 1970, 1971, 1974, 1975, 1977, 1982, 1983, 1985, 1987, 1988, 1991, 1993, 1995, 1998, 2000, 2001, 2005, 2009, 2010, 2012, 2014, 2016, 2018, 2020, and 2022. Report generated November 25th, 2023.

American Society of Testing and Materials International (ASTM International) Standard Practice Designation E1527-21.

USGS Topographic Maps

Envirosite – 1892, 1896, 1899, 1915, 1939, 1943, 1947, 1950, 1956, 1993, 1995, 2012, 2015, 2018, 2021. Topographic Maps of Mt Diablo, California. Report generated November 22nd, 2023.

Standard Environmental Records Search – Completed by Envirosite for 71 Camaritas Aveue, South San Francisco, San Mateo County, California. Report generated November 22nd, 2023.

Fire Insurance Map Search – Completed by Envirosite for 71 Camaritas Avenue, South San Francisco, San Mateo County, California. Report generated November 27th 2023.

City Directory Abstract – Completed by Envirosite for 71 Camaritas Avenue, South San Francisco, San Mateo County, California. Report generated November 28th, 2023.

11.0 SIGNATURE OF ENVIRONMENTAL PROFESSIONAL

The following Cameron-Cole personnel were involved with the site inspection, records search, regulatory review, and drafting of the Phase I Environmental Site Assessment Report for the property located 71 Camaritas Avenue, South San Francisco, California.

Prepared by:



Ryan Barry
Environmental Scientist I

This is to certify that I have reviewed and approve the contents of the Phase I Environmental Site Assessment Report for the property located at located at 71 Camaritas Avenue, South San Francisco, California. Certification of the environmental professional are provided in Section 14, and professional qualifications are provided in Appendix E.

Reviewed by:



Michael Stephenson
Principal Scientist


12.0 ENVIRONMENTAL PROFESSIONAL STATEMENT

I declare that, to the best of my professional knowledge and belief, I meet the definition of Environmental Professional as defined in 312.10 of 40 CFR 312, and I have the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. I have developed and performed all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.



Michael Stephenson
Principal Scientist

FIGURES




Source: ESRI Aerial Imagery, San Mateo County GIS Portal

CAMERON-COLE
creating sustainable success
AN ADEC INNOVATION

180 90 0 180 Feet

Figure 1: Site Vicinity Map




Source: Census 2000 Data, The California Spatial Information Library (CaSIL).

CAMERON-COLE
creating sustainable success
AN ADEC INNOVATION

5 2.5 0 5
Miles

Figure 2: Regional Vicinity Map




Source: ESRI Aerial Imgaery, San Mateo County GeoPortal, Ninyo & Moore Inc.

CAMERON-COLE
creating sustainable success
AN ADEC INNOVATION

60 30 0 60
Feet

Figure #3

Ninyo & Moore Inc. Soil Vapor Results Above ESLs (Results Provided in µg/m³)



Source: ESRI Aerial Imgaery, San Mateo County GeoPortal, Ninyo & Moore Inc.

CAMERON-COLE
creating sustainable success
AN ADEC INNOVATION

60 30 0 60
Feet

Figure #4

Ninyo & Moore Inc. Shallow Soil Results Above ESLs
(Results Provided in mg/kg)

APPENDICES

APPENDIX A

Photograph Log


	
Photo 1: Southeastern face of 71 Camaritas Avenue. Photo taken facing northwest.	Photo 2: Edge of SP along Westborough Boulevard, photo taken facing roughly west.
	
Photo 3: Boundary of SP along Camaritas Avenue. Photo taken facing northwest.	Photo 4: Rear, loading area of 71 Camaritas avenue. Photo taken facing southeast.
	
Photo 5: Western boundary edge of 71 Camaritas Avenue. Photo taken facing southwest.	Photo 6: Western most boundary the SP. Taken facing north along Arroyo Drive near the edge of SFPUC easement present on the SP.

	
Photo 7: Facing southeast into the SFPUC easement from the boundary along Arroyo Drive.	Photo 8: Infrastructure located in open landscape area used as an easement by the SFPUC.
	
Photo 9: Infrastructure located in open landscape area used as an easement by the SFPUC.	Photo 10: Facing 101 Arroyo Drive from southwestern most corner of SP along SFPUC easement.
	
Photo 11: Southwestern face of 71 Camaritas Avenue. Former location of Buri Buri Liquors.	Photo 12: Dumpster in use by Ongpin restaurant, located in rear of 71 Camaritas Avenue.



Photo 13: Solid waste disposal dumpsters in read of Ongpin restaurant.



Photo 14: Used cooking oil storage bins, in use by Ongpin restaurant. Located in read of 71 Camaritas.



Photo 15: Electrical transformer located in the rear corner of 71 Camaritas Avenue.



Photo 16: Front of 71 Camaritas Avenue. Photo taken from across Camaritas Avenue.



Photo 17: Southeastern face of 71 Camaritas Avenue, photo taken across Camaritas Avenue from northeastern corner of Camaritas and Westborough intersection.



Photo 18: Camaritas avenue, facing northwest.

APPENDIX B

Government Records Report

Government Records Report | 2023

With Platinum Review

Order Number: 92757

Report Generated: 11/22/2023

Project Name: South San Francisco Fire Station #63

Project Number: 3818.0008ES114B

South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA 94080

with Envirosite Atlas

Contact us at:
(866) 211-2028
envirositecorp.com

Table of Contents 2023

Section	Page
Executive Summary	1
Executive Summary by Distance	2
Executive Summary by Database	5
Property Proximity Map	21
Area Map	22
Map Findings Summary	23
Map Findings	27
Unmappable Summary	309
Environmental Records Searched	310
Geological Landscape Section	321
Geological Landscape Section Soil Map	324
Geological Landscape Section Summary	325
Geological Findings Map	329
Geological Landscape Section Map Findings	330
Geological Landscape Section Map Findings Radon	344
Geological Landscape Records Searched	345

Disclaimer - Copyright and Trademark Notice

All information contained in this report are based on data available from various public, government and other sources and are based upon the best data available from those sources. The information available in this report may be available from other sources and is not exclusive or the exclusive property of Envirosite Corporation.

NO WARRANTY EXPRESSED OR IMPLIED, IS MADE IN CONNECTION WITH THIS REPORT, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. ALL RISK IS ASSUMED BY USER AND Envirosite assumes no liability for faulty or inaccurate information. The Reports may utilize a variety of public and other sources reasonably available to Envirosite. Envirosite cannot, and does not assure, warrant, guarantee or assume any liability for the correctness, comprehensiveness, timeliness or completeness of any of such information, nor is the information in any Report to be construed as legal advice with respect to environmental risks associated with any property. Envirosite shall not be liable to anyone for any claims, causes of action, suits, damages, losses, costs and expenses (including, without limitation, attorneys' fees and costs) arising out of or caused by this report regardless of the acts, errors or omissions, or negligence of Envirosite. Any damages shall be limited to the purchase price of the report.

Purchaser of the report accepts the report "As Is". The report is intended only to provide information only and should not be considered as providing any legal advice, prediction, forecast, or fact as to the environmental risk for any specific property. Reports are proprietary to Envirosite, and contain copyrighted material and trademarks of Envirosite. All other trademarks used herein are the property of their respective owners. All rights of Envirosite as to the Reports are reserved.

Envirosite Corporation has conducted a search of all reasonably ascertainable records in accordance with EPA's AAI (40 CFR Part 312) requirements and the ASTM E-1527-21 Environmental Site Assessments standard.

SUBJECT PROPERTY INFORMATION:

ADDRESS:

South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA 94080

COORDINATES:

Latitude (North):	37.654462 - 37°39'16.1"
Longitude (West):	-122.437419 - -122°26'14.7"
Universal Transverse Mercator:	Zone 10N
UTM X (Meters):	549624.19
UTM Y (Meters):	4167626.78
State Plane Coordinates:	0403 - California Zone 3 (US Survey Feet)
X Coordinate (Feet):	6000842.573 E
Y Coordinate (Feet):	2066572.156 N

ELEVATION:

Elevation:	60 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH SUBJECT PROPERTY:

Subject Property Map: 37122-F4 San Francisco South, CA
Most Recent Revision: 2018

MAP ID	SITE NAME	ADDRESS	DATABASE(S)	RELATIVE ELEVATION	DIRECTION / DISTANCE
1	843753	N R	WDS - CA		SP
A2	OFFICE OF MORRIS WONG DDS | TONI...	100 ARROYO DR | 100 ARROY...	HAZNET - CA, HWG - CA	Higher	WNW / 0.024 mi., 128...
B3	BILL STAVROULAKIS	112 ARROYO DRIVE	HWG - CA, RCRA_NONGEN	Higher	WNW / 0.053 mi., 280...
C4	ACCESS PROPERTIES LLC	91 WESTBOROUGH BOULEVARD	CALEPA SITES - CA	Higher	ESE / 0.057 mi., 301 ft.
D5	CITY OF SSF FIRE STATION #63 | SO ...	33 ARROYO	HIST UST - CA	Higher	NNE / 0.061 mi., 325 ft.
D6	CITY OF SSF FIRE STATION #63 | CITY...	33 ARROYO DR	AST - CA, CALEPA SITES - CA, HAZNET - CA, H...	Higher	NNE / 0.063 mi., 331 ft.
B7	ALAN WONG	100 DEL MONTE AVENUE	HWG - CA, RCRA_NONGEN	Higher	WNW / 0.063 mi., 333...
A8	MIKE KENNY	66 ARROYO DR APT 1	HAZNET - CA, HWG - CA	Higher	NNW / 0.064 mi., 336 ft.
D9	PACIFIC SUPERMARKET	1015 EL CAMINO REAL	CALEPA SITES - CA	Lower	ENE / 0.075 mi., 395 ft.
D10	O'REILLY AUTO PARTS STORE 2743 | ...	1059 EL CAMINO REAL	CALEPA SITES - CA, HAZNET - CA, HIST HAZNE...	Higher	NE / 0.089 mi., 469 ft.
C11	SUMMERVILLE SENIOR LIVING | WEST...	89 WESTBOROUGH BLVD	HAZNET - CA, HWG - CA	Lower	ESE / 0.098 mi., 520 ft.
12	CALIFORNIA GOLF CLUB OF SAN FRAN...	95 WESTBOROUGH BLVD	AST - CA, CALEPA SITES - CA, HWG - CA, RCR...	Higher	WSW / 0.102 mi., 537 ft.
E13	CLUBVIEW APTS. 2004 | KORET FOUN...	849 W ORANGE AVE | 849 OR...	HAZNET - CA, HWG - CA, RCRA_NONGEN	Higher	SE / 0.102 mi., 537 ft.
F14	GRAND AUTO | PACCAR AUTOMOTIVE,...	1103 EL CAMINO REAL	HAZNET - CA, HWG - CA	Higher	NNE / 0.107 mi., 565 ft.
D15	MY CLEANERS (FORMER) | MY CLEANE...	1053 EL CAMINO REAL | 105...	CALEPA SITES - CA, HAZNET - CA, HWG - CA, ...	Higher	NE / 0.115 mi., 610 ft.
F16	FIONNOLA VILLAMEJOR	129 ALTA LOMA DR	HAZNET - CA, HWG - CA	Higher	NNW / 0.118 mi., 626 ft.
D17	CALTRANS DISTRICT 4 EA 04-0K6704	RTE 82 PM 19.8	HWG - CA	Lower	ENE / 0.120 mi., 636 ft.
E18	WEST ORANGE LIBRARY | CLUB VIEW ...	840 W ORANGE AVENUE | 840...	CALEPA SITES - CA, HAZNET - CA, HIST UST - ...	Higher	SSE / 0.121 mi., 642 ft.
F19	WALTER & MILLIE 244 INC DBA KFC L...	1111 EL CAMINO REAL	CALEPA SITES - CA	Higher	N / 0.123 mi., 651 ft.
G20	1X G & K MANAGEMENT	77 WEST BOROUGH	HAZNET - CA, HWG - CA	Lower	ESE / 0.124 mi., 657 ft.
G21	GOLDRICH KEST MANAGEMENT | FAI...	77 WESTBOROUGH BLVD	HAZNET - CA, HWG - CA, RCRA_NONGEN	Lower	ESE / 0.125 mi., 660 ft.
H22	WESTBOROUGH KWIK SERV | WESTB...	1 WESTBOROUGH BLVD	CALEPA SITES - CA, FID UST - CA, HAZNET - CA...	Lower	E / 0.126 mi., 665 ft.
F23	CARRIAGE CLEANERS | CARRIAGE CL...	1121 EL CAMINO REAL	CALEPA SITES - CA, HAZNET - CA, HWG - CA, ...	Higher	N / 0.129 mi., 682 ft.
H24	1X 1ST NT'L BANK OF DALY CITY	975 EL CAMINO REAL	HAZNET - CA, HIST HAZNET - CA, HWG - CA	Lower	E / 0.131 mi., 694 ft.
I25	ELIZABETH BARTHE	105 INDIO DR	HAZNET - CA, HWG - CA	Higher	W / 0.135 mi., 713 ft.
D26	CITY OF SOUTH SAN FRANCISCO | CO...	1010 EL CAMINO REAL	CALEPA SITES - CA, HAZNET - CA, HWG - CA, ...	Lower	NE / 0.141 mi., 745 ft.
F27	LEUNG & ABAYA DENTAL OFFICE | MA...	1133 EL CAMINO | 1133 EL ...	HAZNET - CA, HWG - CA	Higher	N / 0.148 mi., 780 ft.
J28	FIKRET ASHKAR	127 CAMARITAS AVE	HAZNET - CA, HWG - CA	Higher	WNW / 0.149 mi., 785...
H29	BANK OF AMERICA	955 EL CAMINO REAL	HAZNET - CA, HWG - CA	Lower	E / 0.155 mi., 820 ft.
I30	WININA MONTERO	102 ALTA MESA DR	HAZNET - CA, HWG - CA	Higher	W / 0.156 mi., 823 ft.
J31	4110009-015	37.655845, -122.44071	PFAS GAMA - CA	Higher	WNW / 0.156 mi., 823...
F32	CARMELA AND ART QUIAMBAO | CAR...	136 ALTA LOMA DRIVE	HAZNET - CA, HWG - CA, RCRA_NONGEN	Higher	NNW / 0.156 mi., 824 ft.
F33	NORGE VILLAGE CLEANERS (FORMER)	1155 EL CAMINO REAL	CALEPA SITES - CA, SLIC REG 2 - CA	Higher	NNW / 0.160 mi., 844 ft.
H34	SO CITY GAS & AUTO REPAIR | SOUTH...	998 EL CAMINO REAL	CALEPA SITES - CA, HAZNET - CA, HIST UST - ...	Lower	E / 0.165 mi., 874 ft.
F35	GENIUS LEARNING | EDWARD V FOUC...	1165 EL CAMINO REAL | 116...	HAZNET - CA, HWG - CA	Higher	NNW / 0.168 mi., 890 ft.
H36	PACIFIC BELL | PACIFIC BELL TELEPHO...	965 EL CAMINO REAL	HAZNET - CA, HWG - CA	Lower	E / 0.169 mi., 891 ft.
G37	MY CLEANERS	1053F EL CAMINO	CALEPA SITES - CA, DRYCLEANERS - CA	Lower	ESE / 0.171 mi., 901 ft.
J38	NANCY LUATHATI	25 DEL PASO DR	HAZNET - CA, HWG - CA	Higher	NW / 0.172 mi., 910 ft.

MAP ID	SITE NAME	ADDRESS	DATABASE(S)	RELATIVE ELEVATION	DIRECTION / DISTANCE
G39	VISTA DENTAL CARE | COHEN DENTAL...	931 EL CAMINO REAL	HAZNET - CA, HWG - CA	Lower	ESE / 0.173 mi., 915 ft.
G40	SOUTHWOOD CHIROPRACTIC	943 EL CAMINO REAL	HAZNET - CA, HWG - CA	Lower	ESE / 0.173 mi., 917 ft.
H41	SHAC 988 ECR APARTMENTS, LLC | S...	988 EL CAMINO REAL	CALEPA SITES - CA, HAZNET - CA, HIST HAZNE...	Lower	E / 0.181 mi., 954 ft.
K42	FORZA TELECOM-PH8 CHESTNUT HEA...	955 ANTOINETTE LANE	CALEPA SITES - CA	Lower	ENE / 0.189 mi., 1000 ft.
43	NICOLETTE CIARDELLA	9 HILLCREST COURT	HWG - CA, RCRA_NONGEN	Higher	SE / 0.193 mi., 1022 ft.
K44	PACIFIC GAS AND ELECTRIC COMPANY...	LAT. 37.656875, LONG. -12...	HAZNET - CA, HWG - CA, RCRA_NONGEN	Lower	NE / 0.202 mi., 1067 ft.
L45	SOUTH SAN FRANCISCO FOOT CLINIC	927 EL CAMINO REAL	HAZNET - CA, HWG - CA	Lower	ESE / 0.208 mi., 1097 ft.
K46	CITY OF SOUTH SAN FRANCISCO | SO...	1 CHESTNUT AVE	AST - CA, CALEPA SITES - CA, HAZNET - CA, H...	Lower	ENE / 0.211 mi., 1115 ft.
K47	RON PRICE MOTORS	1 CHESTNUT	CALEPA SITES - CA, LUST REG 2 - CA, LUST_S...	Lower	ENE / 0.211 mi., 1116 ft.
K48	BART CHESTNUT AVENUE VENTILATI...	995 ANTOINETTE LN	CALEPA SITES - CA	Lower	NE / 0.216 mi., 1139 ft.
H49	CHEVRON, FORMER STANDARD OIL S...	972 EL CAMINO REAL	CALEPA SITES - CA, LUST REG 2 - CA, LUST_S...	Lower	E / 0.216 mi., 1140 ft.
50	COREY HANKS	10 CHESTNUT AVE BE: 19986...	HAZNET - CA, HWG - CA, RCRA_NONGEN	Lower	ENE / 0.222 mi., 1175 ft.
51	DAVID DEZMAN	808 W. ORANGE AVE.	HAZNET - CA, HWG - CA	Higher	SSE / 0.223 mi., 1179 ft.
M52	JUAN FULGENCIO	207 DEL MONTE AVENUE	HAZNET - CA, HWG - CA	Higher	WNW / 0.226 mi., 119...
K53	PACIFIC GAS AND ELECTRIC	950 ANTOINETTE LN	HAZNET - CA, HWG - CA	Lower	NE / 0.227 mi., 1197 ft.
54	KRISTY HARDY	250 EL CAMPO DRIVE	HAZNET - CA, HWG - CA, RCRA_NONGEN	Higher	W / 0.237 mi., 1252 ft.
55	SFPUC SOUTHWOOD DRIVE WELL & T...	608 SOUTHWOOD DRIVE	CALEPA SITES - CA, HWG - CA, RCRA_SQG	Lower	ESE / 0.238 mi., 1255 ft.
M56	EMMA JEAN O'NIELL	208 INDIO DR	HAZNET - CA, HWG - CA	Higher	WNW / 0.239 mi., 126...
L57	ESTATE OF FRANK GIGLEY | HANKS R...	932 EL CAMINO REAL	HAZNET - CA, HWG - CA	Lower	E / 0.245 mi., 1292 ft.
N58	ACUTECH AUTO | WESTBOROUGH PET...	45 CHESTNUT	HIST UST - CA	Lower	ENE / 0.249 mi., 1316 ft.
N59	ACUTEC AUTOS | 1X ACUTECH AUTO ...	45 CHESTNUT AVE	CALEPA SITES - CA, HAZNET - CA, HWG - CA, ...	Lower	ENE / 0.249 mi., 1317 ft.
M60	JOHN LIM | JULIE KHOLMEISTER	210 INDIO DR	HWG - CA, RCRA_NONGEN	Higher	WNW / 0.250 mi., 132...
N61	CA4110009_015_015	37.655849, -122.431968	PFAS GAMA - CA	Lower	ENE / 0.276 mi., 1457 ft.
62	SOUTH SF GROUNDWATER INVESTIGATION	EAST OF EL CAMINO REAL	LUST_SAN MATEO COUNTY - CA, SWRCB CLEA...	Lower	E / 0.284 mi., 1503 ft.
L63	STAN THE ROOF MAN | 1X STAN THE ...	103 1ST | 103 FIRST STREE...	LUST REG 2 - CA, LUST_SAN MATEO COUNTY -...	Lower	E / 0.293 mi., 1548 ft.
N64	100879	N R	PFAS GAMA - CA	Lower	ENE / 0.295 mi., 1559 ft.
N65	CA4110009_014_014 | 4110009-014	37.656342, -122.4318	PFAS GAMA - CA	Lower	ENE / 0.298 mi., 1573 ft.
O66	CA4110009_013_013 | 4110009-013	37.658103, -122.43319	PFAS GAMA - CA	Lower	NE / 0.317 mi., 1673 ft.
N67	CA4110009_007_007 | 4110009-007	37.656582, -122.431481	PFAS GAMA - CA	Lower	ENE / 0.321 mi., 1695 ft.
68	CALIFORNIA GOLF CLUB OF SAN FRAN...	844 WEST ORANGE AVENUE ...	LUST REG 2 - CA, LUST_SAN MATEO COUNTY -...	Higher	SSW / 0.324 mi., 1711...
O69	100883	N R	PFAS GAMA - CA	Lower	NE / 0.334 mi., 1763 ft.
P70	100880	N R	PFAS GAMA - CA	Lower	ENE / 0.391 mi., 2063 ft.
Q71	GRAND AVENUE GAS | GRAND AVE O...	1086 GRAND AVE	LUST REG 2 - CA, LUST_SAN MATEO COUNTY -...	Lower	N / 0.393 mi., 2077 ft.
Q72	CONTRERAS PAINTING	1090 GRAND	SLIC REG 2 - CA	Lower	N / 0.400 mi., 2113 ft.
73	FINLEY CONSTRUCTION CO	125 CHESTNUT	LUST REG 2 - CA, LUST_SAN MATEO COUNTY -...	Higher	ENE / 0.419 mi., 2214 ft.
R74	SOUTH CITY SHELL AUTO SERVICE | O...	710 EL CAMINO REAL	LUST REG 2 - CA, LUST_SAN MATEO COUNTY -...	Higher	ESE / 0.425 mi., 2246 ft.
P75	CA4110009_006_006 | 4110009-006	37.656491, -122.429236	PFAS GAMA - CA	Lower	ENE / 0.431 mi., 2279 ft.
P76	100881	N R	PFAS GAMA - CA	Lower	ENE / 0.436 mi., 2301 ft.

MAP ID	SITE NAME	ADDRESS	DATABASE(S)	RELATIVE ELEVATION	DIRECTION / DISTANCE
R77	CHEVRON 9-0248	687 EL CAMINO REAL	LUST REG 2 - CA, LUST_SAN MATEO COUNTY -...	Higher	SE / 0.448 mi., 2365 ft.
R78	CAMINO PETROLEUM | ANDREW S JU...	698 EL CAMINO REAL	LUST REG 2 - CA, LUST_SAN MATEO COUNTY -...	Higher	ESE / 0.469 mi., 2477 ft.
79	MANTEGANI SITE	735 COMMERCIAL AVENUE	ENVIROSTOR - CA	Lower	E / 0.635 mi., 3351 ft.

SUBJECT PROPERTY SEARCH RESULTS:

The subject property was identified in the following records. For more information on this property, see Map Findings section on page 27.

SITE	DATABASE(S)	EPA ID
843753 N/R CA	WDS - CA	N/R

SEARCH RESULTS:

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS

AST - CA: Listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act **3 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D6	*CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING*	*33 ARROYO DR*	*NNE / 0.063 mi., 331 ft.*	*34*
12	*CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE*	*95 WESTBOROUGH BLVD*	*WSW / 0.102 mi., 537 ft.*	*55*

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
K46	*CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE*	*1 CHESTNUT AVE*	*ENE / 0.211 mi., 1115 ft.*	*161*

FID UST - CA: The State Water Resource Control Board's Facility Inventory Database underground storage tank locations listing **1 SITE FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
H22	*WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC*	*1 WESTBOROUGH BLVD*	*E / 0.126 mi., 665 ft.*	*92*

HIST AST - CA: Historical listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act **1 SITE FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D6	*CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING*	*33 ARROYO DR*	*NNE / 0.063 mi., 331 ft.*	*34*

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS *(cont.)*

HIST UST - CA: Historical UST listing **6 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D5	CITY OF SSF FIRE STATION #63 | SO SAN FRAN POLICE DEPT-DISP PRG | STATION 63	33 ARROYO	NNE / 0.061 mi., 325 ft.	*34*
E18	*WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS*	*840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005*	*SSE / 0.121 mi., 642 ft.*	*76*

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
H22	*WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC*	*1 WESTBOROUGH BLVD*	*E / 0.126 mi., 665 ft.*	*92*
H34	*SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR*	*998 EL CAMINO REAL*	*E / 0.165 mi., 874 ft.*	*135*
K46	*CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE*	*1 CHESTNUT AVE*	*ENE / 0.211 mi., 1115 ft.*	*161*
N58	ACUTECH AUTO | WESTBOROUGH PET HOSPITAL | AUTO STUDIO	45 CHESTNUT	ENE / 0.249 mi., 1316 ft.	*199*

FEDERAL RCRA GENERATORS LIST

RCRA_NONGEN: Resource Conservation and Recovery Act listing of licensed non-generators **17 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
B3	*BILL STAVROULAKIS*	*112 ARROYO DRIVE*	*WNW / 0.053 mi., 280 ft.*	*32*
	- ID: CAC003219023	Status: No Violation/Inspections	Date: N/A	
B7	*ALAN WONG*	*100 DEL MONTE AVENUE*	*WNW / 0.063 mi., 333 ft.*	*44*
	- ID: CAC003246122	Status: No Violation/Inspections	Date: N/A	
D10	*O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.*	*1059 EL CAMINO REAL*	*NE / 0.089 mi., 469 ft.*	*47*
	- ID: CAL000392590	Status: No Violation/Inspections	Date: N/A	
12	*CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE*	*95 WESTBOROUGH BLVD*	*WSW / 0.102 mi., 537 ft.*	*55*
	- ID: CAL000463611	Status: No Violation/Inspections	Date: N/A	
E13	*CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS*	*849 W ORANGE AVE | 849 ORANGE*	*SE / 0.102 mi., 537 ft.*	*59*
	- ID: CAC003076743	Status: No Violation/Inspections	Date: N/A	
	- ID: CAC002997479	Status: No Violation/Inspections	Date: N/A	

FEDERAL RCRA GENERATORS LIST *(cont.)*

RCRA_NONGEN: Resource Conservation and Recovery Act listing of licensed non-generators **17 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
E18	*WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS*	*840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005*	*SSE / 0.121 mi., 642 ft.*	*76*
	- ID: CAC002971555	Status: No Violation/Inspections	Date: N/A	
F32	*CARMELA AND ART QUIAMBAO | CARMELA AND ART QUIAMBAO 45-011217*	*136 ALTA LOMA DRIVE*	*NNW / 0.156 mi., 824 ft.*	*130*
	- ID: CAC003001123	Status: No Violation/Inspections	Date: N/A	
43	*NICOLETTE CIARDELLA*	*9 HILLCREST COURT*	*SE / 0.193 mi., 1022 ft.*	*156*
	- ID: CAC003193552	Status: No Violation/Inspections	Date: N/A	
54	*KRISTY HARDY*	*250 EL CAMPO DRIVE*	*W / 0.237 mi., 1252 ft.*	*192*
	- ID: CAC002964506	Status: No Violation/Inspections	Date: N/A	
M60	*JOHN LIM | JULIE KHOLMEISTER*	*210 INDIO DR*	*WNW / 0.250 mi., 1320 ft.*	*208*
	- ID: CAC003222146	Status: No Violation/Inspections	Date: N/A	
	- ID: CAC003148650	Status: No Violation/Inspections	Date: N/A	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
G21	*GOLDRICH KEST MANAGEMENT | FAIRWAY APARTMENTS*	*77 WESTBOROUGH BLVD*	*ESE / 0.125 mi., 660 ft.*	*89*
	- ID: CAC003214488	Status: No Violation/Inspections	Date: N/A	
H22	*WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC*	*1 WESTBOROUGH BLVD*	*E / 0.126 mi., 665 ft.*	*92*
	- ID: CAR000116624	Status: No Violation/Inspections	Date: N/A	
	- ID: CAL000223419	Status: No Violation/Inspections	Date: N/A	
	- ID: CAL000471177	Status: No Violation/Inspections	Date: N/A	
	- ID: CAC003177208	Status: No Violation/Inspections	Date: N/A	
D26	*CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL*	*1010 EL CAMINO REAL*	*NE / 0.141 mi., 745 ft.*	*114*
	- ID: CAC003113979	Status: No Violation/Inspections	Date: N/A	
H41	*SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL*	*988 EL CAMINO REAL*	*E / 0.181 mi., 954 ft.*	*148*
	- ID: CAC003038917	Status: No Violation/Inspections	Date: N/A	
	- ID: CAC003025607	Status: No Violation/Inspections	Date: N/A	
K44	*PACIFIC GAS AND ELECTRIC COMPANY-I007B*	*LAT. 37.656875, LONG. -122.434623*	*NE / 0.202 mi., 1067 ft.*	*157*
	- ID: CAC003061658	Status: No Violation/Inspections	Date: N/A	

FEDERAL RCRA GENERATORS LIST *(cont.)*

RCRA_NONGEN: Resource Conservation and Recovery Act listing of licensed non-generators **17 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
K46	*CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE*	*1 CHESTNUT AVE*	*ENE / 0.211 mi., 1115 ft.*	*161*
	- ID: CAC003058037	Status: No Violation/Inspections	Date: N/A	
	- ID: CAD981441959	Status: No Violation/Inspections	Date: N/A	
	- ID: CAL000474811	Status: No Violation/Inspections	Date: N/A	
50	*COREY HANKS*	*10 CHESTNUT AVE BE: 199864*	*ENE / 0.222 mi., 1175 ft.*	*186*
	- ID: CAC003017534	Status: No Violation/Inspections	Date: N/A	

RCRA_SQG: Resource Conservation and Recovery Act listing of licensed small quantity generators **1 SITE FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
55	*SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY | SFPUC SOUTHWOOD DR WELL & TREATEMENT FACILITY*	*608 SOUTHWOOD DRIVE*	*ESE / 0.238 mi., 1255 ft.*	*194*
	- ID: CAR000337667	Status: No Violation/Inspections	Date: N/A	

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS

LUST REG 2 - CA: Leaking underground storage tanks in Region 2: Alameda Contra Costa San Francisco Santa Clara (north of Morgan Hill) San Mateo Marin Sonoma Napa Solano counties **11 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
E18	*WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS*	*840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005*	*SSE / 0.121 mi., 642 ft.*	*76*
	- ID: T0608191183	Status: Completed - Case Closed	Date: 2001-08-09	
68	*CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F*	*844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE*	*SSW / 0.324 mi., 1711 ft.*	*245*
	- ID: T0608100653	Status: Completed - Case Closed	Date: 2000-10-04	
	- ID: T0608140024	Status: Completed - Case Closed	Date: 2022-10-11	
73	*FINLEY CONSTRUCTION CO*	*125 CHESTNUT*	*ENE / 0.419 mi., 2214 ft.*	*275*
	- ID: T0608100215	Status: Completed - Case Closed	Date: 1992-07-09	
R74	*SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL*	*710 EL CAMINO REAL*	*ESE / 0.425 mi., 2246 ft.*	*279*
	- ID: T0608100490	Status: Completed - Case Closed	Date: 2005-06-24	
R77	*CHEVRON 9-0248*	*687 EL CAMINO REAL*	*SE / 0.448 mi., 2365 ft.*	*295*
	- ID: T0608100144	Status: Completed - Case Closed	Date: 2001-12-19	

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*

LUST REG 2 - CA: Leaking underground storage tanks in Region 2: Alameda Contra Costa San Francisco Santa Clara (north of Morgan Hill) San Mateo Marin Sonoma Napa Solano counties **11 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
R78	*CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669*	*698 EL CAMINO REAL*	*ESE / 0.469 mi., 2477 ft.*	*299*
	- ID: T0608100145	Status: Completed - Case Closed	Date: 2007-04-09	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
K47	*RON PRICE MOTORS*	*1 CHESTNUT*	*ENE / 0.211 mi., 1116 ft.*	*173*
	- ID: T0608100429	Status: Completed - Case Closed	Date: 1996-01-08	
H49	*CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION*	*972 EL CAMINO REAL*	*E / 0.216 mi., 1140 ft.*	*178*
	- ID: SL0608123509	Status: Completed - Case Closed	Date: 2012-03-30	
N59	*ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC*	*45 CHESTNUT AVE*	*ENE / 0.249 mi., 1317 ft.*	*199*
	- ID: T0608151808	Status: Completed - Case Closed	Date: 2003-05-13	
L63	*STAN THE ROOF MAN | 1X STAN THE ROOF MAN INC*	*103 1ST | 103 FIRST STREET | 103 1ST ST.*	*E / 0.293 mi., 1548 ft.*	*220*
	- ID: T0608100696	Status: Completed - Case Closed	Date: 2000-08-10	
Q71	*GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO*	*1086 GRAND AVE*	*N / 0.393 mi., 2077 ft.*	*266*
	- ID: T10000003112	Status: Completed - Case Closed	Date: 2022-06-24	

LUST_SAN MATEO COUNTY - CA: San Mateo county leaking underground storage tank listing **12 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
E18	*WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS*	*840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005*	*SSE / 0.121 mi., 642 ft.*	*76*
	- ID: T0608191183	Status: COMPLETED - CASE CLOSED	Date: 2001-08-09	
68	*CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F*	*844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE*	*SSW / 0.324 mi., 1711 ft.*	*245*
	- ID: T0608100653	Status: COMPLETED - CASE CLOSED	Date: 2000-10-04	
	- ID: T0608140024	Status: COMPLETED - CASE CLOSED	Date: 2022-10-11	

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*

LUST_SAN MATEO COUNTY - CA: San Mateo county leaking underground storage tank listing **12 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
73	*FINLEY CONSTRUCTION CO*	*125 CHESTNUT*	*ENE / 0.419 mi., 2214 ft.*	*275*
	- ID: T0608100215	Status: COMPLETED - CASE CLOSED	Date: 1992-07-09	
R74	*SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL*	*710 EL CAMINO REAL*	*ESE / 0.425 mi., 2246 ft.*	*279*
	- ID: T0608100490	Status: COMPLETED - CASE CLOSED	Date: 2005-06-24	
R77	*CHEVRON 9-0248*	*687 EL CAMINO REAL*	*SE / 0.448 mi., 2365 ft.*	*295*
	- ID: T0608100144	Status: COMPLETED - CASE CLOSED	Date: 2001-12-19	
R78	*CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669*	*698 EL CAMINO REAL*	*ESE / 0.469 mi., 2477 ft.*	*299*
	- ID: T0608100145	Status: COMPLETED - CASE CLOSED	Date: 2007-04-09	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
K47	*RON PRICE MOTORS*	*1 CHESTNUT*	*ENE / 0.211 mi., 1116 ft.*	*173*
	- ID: T0608100429	Status: COMPLETED - CASE CLOSED	Date: 1996-01-08	
H49	*CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION*	*972 EL CAMINO REAL*	*E / 0.216 mi., 1140 ft.*	*178*
	- ID: SL0608123509	Status: COMPLETED - CASE CLOSED	Date: 2012-03-30	
N59	*ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC*	*45 CHESTNUT AVE*	*ENE / 0.249 mi., 1317 ft.*	*199*
	- ID: T0608151808	Status: COMPLETED - CASE CLOSED	Date: 2003-05-13	
62	*SOUTH SF GROUNDWATER INVESTIGATION*	*EAST OF EL CAMINO REAL*	*E / 0.284 mi., 1503 ft.*	*217*
	- ID: T10000004143	Status: OPEN - SITE ASSESSMENT	Date: N/R	
L63	*STAN THE ROOF MAN | 1X STAN THE ROOF MAN INC*	*103 1ST | 103 FIRST STREET | 103 1ST ST.*	*E / 0.293 mi., 1548 ft.*	*220*
	- ID: T0608100696	Status: COMPLETED - CASE CLOSED	Date: 2000-08-10	
Q71	*GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO*	*1086 GRAND AVE*	*N / 0.393 mi., 2077 ft.*	*266*
	- ID: T10000003112	Status: COMPLETED - CASE CLOSED	Date: 2022-06-24	

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*

SLIC REG 2 - CA: List of Region 2 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database. **6 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D15	*MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN*	*1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F*	*NE / 0.115 mi., 610 ft.*	*70*
	- ID: T10000003589	Status: Open - Site Assessment	Date: 2012-02-29	
F23	*CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)*	*1121 EL CAMINO REAL*	*N / 0.129 mi., 682 ft.*	*105*
	- ID: T10000005163	Status: Open - Site Assessment	Date: 2013-09-19	
F33	*NORGE VILLAGE CLEANERS (FORMER)*	*1155 EL CAMINO REAL*	*NNW / 0.160 mi., 844 ft.*	*133*
	- ID: T10000007001	Status: Open - Site Assessment	Date: 2015-05-28	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D26	*CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL*	*1010 EL CAMINO REAL*	*NE / 0.141 mi., 745 ft.*	*114*
	- ID: T10000014438	Status: Open - Long Term Management	Date: 2020-06-10	
K46	*CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE*	*1 CHESTNUT AVE*	*ENE / 0.211 mi., 1115 ft.*	*161*
	- ID: T10000013692	Status: Open - Site Assessment	Date: 2019-10-08	
Q72	CONTRERAS PAINTING	1090 GRAND	N / 0.400 mi., 2113 ft.	*271*
	- ID: T0608106763	Status: Completed - Case Closed	Date: 2011-06-23	

STATE- AND TRIBAL - EQUIVALENT CERCLIS

ENVIROSTOR - CA: Department of Toxic Substances Controls **1 SITE FOUND WITHIN 1 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
79	MANTEGANI SITE	735 COMMERCIAL AVENUE	E / 0.635 mi., 3351 ft.	*305*
	- ID: 70000073	Status: Certified	Date: Cleanup Date 2007-02-20	

SWRCB CLEANUP - CA: List of SWRCB Cleanups from Geotracker including CAF, Sampling Points, and Projects. **1 SITE FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
62	*SOUTH SF GROUNDWATER INVESTIGATION*	*EAST OF EL CAMINO REAL*	*E / 0.284 mi., 1503 ft.*	*217*
	- ID: T10000004143	Status: Active	Date: 2018-03-28	

STATE RCRA GENERATORS LIST

HWG - CA: Hazardous waste generator listing **47 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
A2	OFFICE OF MORRIS WONG DDS | TONI A AMBUS DDS | EPITACIO SISON JR SISON DENTAL CARE	100 ARROYO DR | 100 ARROYO DR STE C | 100 ARROYO_DR	WNW / 0.024 mi., 128 ft.	28
B3	BILL STAVROULAKIS	112 ARROYO DRIVE	WNW / 0.053 mi., 280 ft.	32
D6	CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING	33 ARROYO DR	NNE / 0.063 mi., 331 ft.	34
B7	ALAN WONG	100 DEL MONTE AVENUE	WNW / 0.063 mi., 333 ft.	44
A8	MIKE KENNY	66 ARROYO DR APT 1	NNW / 0.064 mi., 336 ft.	45
D10	O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.	1059 EL CAMINO REAL	NE / 0.089 mi., 469 ft.	47
12	CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE	95 WESTBOROUGH BLVD	WSW / 0.102 mi., 537 ft.	55
E13	CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS	849 W ORANGE AVE | 849 ORANGE	SE / 0.102 mi., 537 ft.	59
F14	GRAND AUTO | PACCAR AUTOMOTIVE, INC | CSK AUTO INC/KRAGEN AUTO PARTS #4047	1103 EL CAMINO REAL	NNE / 0.107 mi., 565 ft.	67
D15	MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN	1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F	NE / 0.115 mi., 610 ft.	70
F16	FIONNOLA VILLAMEJOR	129 ALTA LOMA DR	NNW / 0.118 mi., 626 ft.	74
E18	WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS	840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005	SSE / 0.121 mi., 642 ft.	76
F23	CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)	1121 EL CAMINO REAL	N / 0.129 mi., 682 ft.	105
I25	ELIZABETH BARTHE	105 INDIO DR	W / 0.135 mi., 713 ft.	112
F27	LEUNG & ABAYA DENTAL OFFICE | MARILYN SY DDS | DR. EDEN JAOCHICO DENTAL SERVICES, INC	1133 EL CAMINO | 1133 EL CAMINO REAL | 1133 EL CAMINO REAL STE 3	N / 0.148 mi., 780 ft.	119
J28	FIKRET ASHKAR	127 CAMARITAS AVE	WNW / 0.149 mi., 785 ft.	122
I30	WININA MONTERO	102 ALTA MESA DR	W / 0.156 mi., 823 ft.	124
F32	CARMELA AND ART QUIAMBAO | CARMELA AND ART QUIAMBAO 45-011217	136 ALTA LOMA DRIVE	NNW / 0.156 mi., 824 ft.	130
F35	GENIUS LEARNING | EDWARD V FOUCRAULT | GUARDIAN AMBULANCE SVC	1165 EL CAMINO REAL | 1165 EL CAMINO REAL STE B | 1165 EL CAMINO	NNW / 0.168 mi., 890 ft.	140
J38	NANCY LUATHATI	25 DEL PASO DR	NW / 0.172 mi., 910 ft.	143
43	NICOLETTE CIARDELLA	9 HILLCREST COURT	SE / 0.193 mi., 1022 ft.	156
51	DAVID DEZMAN	808 W. ORANGE AVE.	SSE / 0.223 mi., 1179 ft.	189
M52	JUAN FULGENCIO	207 DEL MONTE AVENUE	WNW / 0.226 mi., 1194 ft.	190
54	KRISTY HARDY	250 EL CAMPO DRIVE	W / 0.237 mi., 1252 ft.	192
M56	EMMA JEAN O'NIELL	208 INDIO DR	WNW / 0.239 mi., 1261 ft.	196
M60	JOHN LIM | JULIE KHOLMEISTER	210 INDIO DR	WNW / 0.250 mi., 1320 ft.	208

STATE RCRA GENERATORS LIST *(cont.)*

HWG - CA: Hazardous waste generator listing **47 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C11	*SUMMERVILLE SENIOR LIVING | WESTBOROUGH ROYALE INC*	*89 WESTBOROUGH BLVD*	*ESE / 0.098 mi., 520 ft.*	*53*
D17	CALTRANS DISTRICT 4 EA 04-0K6704	RTE 82 PM 19.8	ENE / 0.120 mi., 636 ft.	*75*
G20	*1X G & K MANAGEMENT*	*77 WEST BOROUGH*	*ESE / 0.124 mi., 657 ft.*	*89*
G21	*GOLDRICH KEST MANAGEMENT | FAIRWAY APARTMENTS*	*77 WESTBOROUGH BLVD*	*ESE / 0.125 mi., 660 ft.*	*89*
H22	*WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC*	*1 WESTBOROUGH BLVD*	*E / 0.126 mi., 665 ft.*	*92*
H24	*1X 1ST NT'L BANK OF DALY CITY*	*975 EL CAMINO REAL*	*E / 0.131 mi., 694 ft.*	*111*
D26	*CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL*	*1010 EL CAMINO REAL*	*NE / 0.141 mi., 745 ft.*	*114*
H29	*BANK OF AMERICA*	*955 EL CAMINO REAL*	*E / 0.155 mi., 820 ft.*	*123*
H34	*SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR*	*998 EL CAMINO REAL*	*E / 0.165 mi., 874 ft.*	*135*
H36	*PACIFIC BELL | PACIFIC BELL TELEPHONE CO DBA AT&T CALIF*	*965 EL CAMINO REAL*	*E / 0.169 mi., 891 ft.*	*142*
G39	*VISTA DENTAL CARE | COHEN DENTAL CARE | COHEN DENTAL CORP*	*931 EL CAMINO REAL*	*ESE / 0.173 mi., 915 ft.*	*144*
G40	*SOUTHWOOD CHIROPRACTIC*	*943 EL CAMINO REAL*	*ESE / 0.173 mi., 917 ft.*	*146*
H41	*SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL*	*988 EL CAMINO REAL*	*E / 0.181 mi., 954 ft.*	*148*
K44	*PACIFIC GAS AND ELECTRIC COMPANY-I007B*	*LAT. 37.656875, LONG. -122.434623*	*NE / 0.202 mi., 1067 ft.*	*157*
L45	*SOUTH SAN FRANCISCO FOOT CLINIC*	*927 EL CAMINO REAL*	*ESE / 0.208 mi., 1097 ft.*	*160*
K46	*CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE*	*1 CHESTNUT AVE*	*ENE / 0.211 mi., 1115 ft.*	*161*
50	*COREY HANKS*	*10 CHESTNUT AVE BE: 199864*	*ENE / 0.222 mi., 1175 ft.*	*186*
K53	*PACIFIC GAS AND ELECTRIC*	*950 ANTOINETTE LN*	*NE / 0.227 mi., 1197 ft.*	*191*
55	*SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY | SFPUC SOUTHWOOD DR WELL & TREATEMENT FACILITY*	*608 SOUTHWOOD DRIVE*	*ESE / 0.238 mi., 1255 ft.*	*194*
L57	*ESTATE OF FRANK GIGLEY | HANKS RENTALS*	*932 EL CAMINO REAL*	*E / 0.245 mi., 1292 ft.*	*197*
N59	*ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC*	*45 CHESTNUT AVE*	*ENE / 0.249 mi., 1317 ft.*	*199*

LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES

SWRCY - CA: Listing of facilities which perform recycled material processing activities **1 SITE FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D10	*O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.*	*1059 EL CAMINO REAL*	*NE / 0.089 mi., 469 ft.*	*47*

OTHER ASCERTAINABLE RECORDS

CALEPA SITES - CA: CalEPA Regulated Sites from the Certified Unified Program Agencies (CUPA). **22 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C4	ACCESS PROPERTIES LLC	91 WESTBOROUGH BOULEVARD	ESE / 0.057 mi., 301 ft.	*34*
D6	*CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING*	*33 ARROYO DR*	*NNE / 0.063 mi., 331 ft.*	*34*
D10	*O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.*	*1059 EL CAMINO REAL*	*NE / 0.089 mi., 469 ft.*	*47*
12	*CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE*	*95 WESTBOROUGH BLVD*	*WSW / 0.102 mi., 537 ft.*	*55*
D15	*MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN*	*1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F*	*NE / 0.115 mi., 610 ft.*	*70*
E18	*WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS*	*840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005*	*SSE / 0.121 mi., 642 ft.*	*76*
F19	WALTER & MILLIE 244 INC DBA KFC/LONG JOHN SILVER	1111 EL CAMINO REAL	N / 0.123 mi., 651 ft.	*88*
F23	*CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)*	*1121 EL CAMINO REAL*	*N / 0.129 mi., 682 ft.*	*105*
F33	*NORGE VILLAGE CLEANERS (FORMER)*	*1155 EL CAMINO REAL*	*NNW / 0.160 mi., 844 ft.*	*133*

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D9	PACIFIC SUPERMARKET	1015 EL CAMINO REAL	ENE / 0.075 mi., 395 ft.	*46*
H22	*WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC*	*1 WESTBOROUGH BLVD*	*E / 0.126 mi., 665 ft.*	*92*
D26	*CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL*	*1010 EL CAMINO REAL*	*NE / 0.141 mi., 745 ft.*	*114*
H34	*SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR*	*998 EL CAMINO REAL*	*E / 0.165 mi., 874 ft.*	*135*
G37	*MY CLEANERS*	*1053F EL CAMINO*	*ESE / 0.171 mi., 901 ft.*	*142*

OTHER ASCERTAINABLE RECORDS *(cont.)*

CALEPA SITES - CA: CalEPA Regulated Sites from the Certified Unified Program Agencies (CUPA). **22 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
H41	*SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL*	*988 EL CAMINO REAL*	*E / 0.181 mi., 954 ft.*	*148*
K42	FORZA TELECOM-PH8 CHESTNUT HEAD END	955 ANTOINETTE LANE	ENE / 0.189 mi., 1000 ft.	*155*
K46	*CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE*	*1 CHESTNUT AVE*	*ENE / 0.211 mi., 1115 ft.*	*161*
K47	*RON PRICE MOTORS*	*1 CHESTNUT*	*ENE / 0.211 mi., 1116 ft.*	*173*
K48	BART CHESTNUT AVENUE VENTILATION STRUCTURE (CHS)	995 ANTOINETTE LN	NE / 0.216 mi., 1139 ft.	*178*
H49	*CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION*	*972 EL CAMINO REAL*	*E / 0.216 mi., 1140 ft.*	*178*
55	*SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY | SFPUC SOUTHWOOD DR WELL & TREATEMENT FACILITY*	*608 SOUTHWOOD DRIVE*	*ESE / 0.238 mi., 1255 ft.*	*194*
N59	*ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC*	*45 CHESTNUT AVE*	*ENE / 0.249 mi., 1317 ft.*	*199*

DRYCLEANERS - CA: Listing of drycleaning facilities **1 SITE FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
G37	*MY CLEANERS*	*1053F EL CAMINO*	*ESE / 0.171 mi., 901 ft.*	*142*

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters **40 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
A2	*OFFICE OF MORRIS WONG DDS | TONI A AMBUS DDS | EPITACIO SISON JR SISON DENTAL CARE*	*100 ARROYO DR | 100 ARROYO DR STE C | 100 ARROYO_DR*	*WNW / 0.024 mi., 128 ft.*	*28*
D6	*CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING*	*33 ARROYO DR*	*NNE / 0.063 mi., 331 ft.*	*34*
A8	*MIKE KENNY*	*66 ARROYO DR APT 1*	*NNW / 0.064 mi., 336 ft.*	*45*
D10	*O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.*	*1059 EL CAMINO REAL*	*NE / 0.089 mi., 469 ft.*	*47*
E13	*CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS*	*849 W ORANGE AVE | 849 ORANGE*	*SE / 0.102 mi., 537 ft.*	*59*

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters **40 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
F14	GRAND AUTO | PACCAR AUTOMOTIVE, INC | CSK AUTO INC/KRAGEN AUTO PARTS #4047	1103 EL CAMINO REAL	NNE / 0.107 mi., 565 ft.	67
D15	MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN	1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F	NE / 0.115 mi., 610 ft.	70
F16	FIONNOLA VILLAMEJOR	129 ALTA LOMA DR	NNW / 0.118 mi., 626 ft.	74
E18	WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS	840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005	SSE / 0.121 mi., 642 ft.	76
F23	CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)	1121 EL CAMINO REAL	N / 0.129 mi., 682 ft.	105
I25	ELIZABETH BARTHE	105 INDIO DR	W / 0.135 mi., 713 ft.	112
F27	LEUNG & ABAYA DENTAL OFFICE | MARILYN SY DDS | DR. EDEN JAOCHICO DENTAL SERVICES, INC	1133 EL CAMINO | 1133 EL CAMINO REAL | 1133 EL CAMINO REAL STE 3	N / 0.148 mi., 780 ft.	119
J28	FIKRET ASHKAR	127 CAMARITAS AVE	WNW / 0.149 mi., 785 ft.	122
I30	WININA MONTERO	102 ALTA MESA DR	W / 0.156 mi., 823 ft.	124
F32	CARMELA AND ART QUIAMBAO | CARMELA AND ART QUIAMBAO 45-011217	136 ALTA LOMA DRIVE	NNW / 0.156 mi., 824 ft.	130
F35	GENIUS LEARNING | EDWARD V FOUCRAULT | GUARDIAN AMBULANCE SVC	1165 EL CAMINO REAL | 1165 EL CAMINO REAL STE B | 1165 EL CAMINO	NNW / 0.168 mi., 890 ft.	140
J38	NANCY LUATHATI	25 DEL PASO DR	NW / 0.172 mi., 910 ft.	143
51	DAVID DEZMAN	808 W. ORANGE AVE.	SSE / 0.223 mi., 1179 ft.	189
M52	JUAN FULGENCIO	207 DEL MONTE AVENUE	WNW / 0.226 mi., 1194 ft.	190
54	KRISTY HARDY	250 EL CAMPO DRIVE	W / 0.237 mi., 1252 ft.	192
M56	EMMA JEAN O'NIELL	208 INDIO DR	WNW / 0.239 mi., 1261 ft.	196

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C11	SUMMERVILLE SENIOR LIVING | WESTBOROUGH ROYALE INC	89 WESTBOROUGH BLVD	ESE / 0.098 mi., 520 ft.	53
G20	1X G & K MANAGEMENT	77 WEST BOROUGH	ESE / 0.124 mi., 657 ft.	89
G21	GOLDRICH KEST MANAGEMENT | FAIRWAY APARTMENTS	77 WESTBOROUGH BLVD	ESE / 0.125 mi., 660 ft.	89
H22	WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC	1 WESTBOROUGH BLVD	E / 0.126 mi., 665 ft.	92
H24	1X 1ST NT'L BANK OF DALY CITY	975 EL CAMINO REAL	E / 0.131 mi., 694 ft.	111
D26	CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL	1010 EL CAMINO REAL	NE / 0.141 mi., 745 ft.	114
H29	BANK OF AMERICA	955 EL CAMINO REAL	E / 0.155 mi., 820 ft.	123
H34	SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR	998 EL CAMINO REAL	E / 0.165 mi., 874 ft.	135
H36	PACIFIC BELL | PACIFIC BELL TELEPHONE CO DBA AT&T CALIF	965 EL CAMINO REAL	E / 0.169 mi., 891 ft.	142

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters **40 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
G39	VISTA DENTAL CARE | COHEN DENTAL CARE | COHEN DENTAL CORP	931 EL CAMINO REAL	ESE / 0.173 mi., 915 ft.	144
G40	SOUTHWOOD CHIROPRACTIC	943 EL CAMINO REAL	ESE / 0.173 mi., 917 ft.	146
H41	SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL	988 EL CAMINO REAL	E / 0.181 mi., 954 ft.	148
K44	PACIFIC GAS AND ELECTRIC COMPANY-I007B	LAT. 37.656875, LONG. -122.434623	NE / 0.202 mi., 1067 ft.	157
L45	SOUTH SAN FRANCISCO FOOT CLINIC	927 EL CAMINO REAL	ESE / 0.208 mi., 1097 ft.	160
K46	CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE	1 CHESTNUT AVE	ENE / 0.211 mi., 1115 ft.	161
50	COREY HANKS	10 CHESTNUT AVE BE: 199864	ENE / 0.222 mi., 1175 ft.	186
K53	PACIFIC GAS AND ELECTRIC	950 ANTOINETTE LN	NE / 0.227 mi., 1197 ft.	191
L57	ESTATE OF FRANK GIGLEY | HANKS RENTALS	932 EL CAMINO REAL	E / 0.245 mi., 1292 ft.	197
N59	ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC	45 CHESTNUT AVE	ENE / 0.249 mi., 1317 ft.	199

HIST HAZNET - CA: List of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters that are no longer in current agency list. **3 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D10	O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.	1059 EL CAMINO REAL	NE / 0.089 mi., 469 ft.	47

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
H24	1X 1ST NT'L BANK OF DALY CITY	975 EL CAMINO REAL	E / 0.131 mi., 694 ft.	111
H41	SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL	988 EL CAMINO REAL	E / 0.181 mi., 954 ft.	148

PFAS GAMA - CA: PFOS & PFAS GAMA Well Sampling program **10 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
J31	4110009-015	37.655845, -122.44071	WNW / 0.156 mi., 823 ft.	125

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
N61	CA4110009_015_015	37.655849, -122.431968	ENE / 0.276 mi., 1457 ft.	212
N64	100879	N/R	ENE / 0.295 mi., 1559 ft.	225
N65	CA4110009_014_014 | 4110009-014	37.656342, -122.4318	ENE / 0.298 mi., 1573 ft.	229

OTHER ASCERTAINABLE RECORDS *(cont.)*

PFAS GAMA - CA: PFOS & PFAS GAMA Well Sampling program **10 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O66	CA4110009_013_013 | 4110009-013	37.658103, -122.43319	NE / 0.317 mi., 1673 ft.	*234*
N67	CA4110009_007_007 | 4110009-007	37.656582, -122.431481	ENE / 0.321 mi., 1695 ft.	*239*
O69	100883	N/R	NE / 0.334 mi., 1763 ft.	*256*
P70	100880	N/R	ENE / 0.391 mi., 2063 ft.	*261*
P75	CA4110009_006_006 | 4110009-006	37.656491, -122.429236	ENE / 0.431 mi., 2279 ft.	*284*
P76	100881	N/R	ENE / 0.436 mi., 2301 ft.	*289*

No unmappable sites reported.

DATABASE(S) WITH NO MAPPED SITES:

FEDERAL RCRA NON-CORRACTS TSD FACILITIES LIST

ARCHIVED RCRA TSDF	Archived Resource Conservation and Recovery Act: Treatment Storage and Disposal Facilities
RCRA_TSDF	Resource Conservation and Recovery Act: Treatment Storage and Disposal Facilities

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS

FEMA UST	FEMA Underground Storage Tanks
INDIAN UST R9	Underground Storage Tanks on Indian Land in EPA Region 9

FEDERAL CERCLIS LIST

CERCLIS NFRAP	Comprehensive Environmental Response Compensation and Liability Act No Further Remedial Action Planned
CERCLIS-HIST	Comprehensive Environmental Response Compensation and Liability Act
FEDERAL FACILITY	Federal Facility sites

FEDERAL RCRA CORRACTS FACILITIES LIST

CORRACTS	Hazardous Waste Corrective Action
HIST CORRACTS 2	Historical Hazardous Waste Corrective Action

FEDERAL DELISTED NPL SITE LIST

DELISTED NPL	Delisted National Priority List

FEDERAL ERNS LIST

ERNS	Emergency Response Notification System

FEDERAL INSTITUTIONAL CONTROLS / ENGINEERING CONTROLS REGISTRIES

FED E C	Engineering Controls
FED I C	Institutional Controls
RCRA IC_EC	RCRA sites with Institutional and Engineering Controls

FEDERAL RCRA GENERATORS LIST

HIST RCRA_CESQG	Historical Resource Conservation and Recovery Act_Conditionally Exempt Small Quantity Generators
HIST RCRA_LQG	Historical Resource Conservation and Recovery Act_ Large Quantity Generators
HIST RCRA_NONGEN	Historical Resource Conservation and Recovery Act_Non Generators
HIST RCRA_SQG	Historical Resource Conservation and Recovery Act_Small Quantity Generators
RCRA_VSQG	Resource Conservation and Recovery Act_Very Small Quantity Generator

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS

INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land in EPA Region 9

FEDERAL NPL SITE LIST

NPL	National Priority List
NPL EPA R9 GIS	GIS for EPA Region 9 NPL
SEMS_FINAL NPL	Sites included on the Final National Priorities List
SEMS_PROPOSED NPL	Sites Proposed to be Added to the National Priorities List

STATE- AND TRIBAL - EQUIVALENT CERCLIS

OIL & GAS CLEANUP - CA	SWRCB Oil & Gas Cleanup Sites
TOXIC PITS - CA	Toxic Pits Cleanup Act

STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

SWF/LF - CA	Solid Waste Information System

STATE AND TRIBAL BROWNFIELD SITES

TRIBAL BROWNFIELDS	Tribal Brownfields

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES

CDL - CA	Meth and Clandestine Drug Labs
SCH - CA	School Property Evaluation Program

LOCAL BROWNFIELD LISTS

FED BROWNFIELDS	Federal Brownfields

LOCAL LAND RECORDS

LIENS 2	CERCLA Lien Information
HIST LIENS - CA	Historical Liens
LIENS - CA	Liens

RECORDS OF EMERGENCY RELEASE REPORTS

HMIRS (DOT)	Hazardous Materials Information Reporting Systems

LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES

TRIBAL ODI	Indian Open Dump Inventory Sites

OTHER ASCERTAINABLE RECORDS


COAL GAS	Coal Gas Plants
CORRECTIVE ACTIONS_2020	Wastes - Hazardous Waste - Corrective Action
DOD	Department of Defense
ECHO	EPA Enforcement and Compliance History Online
FUDS	Formerly Used Defense Sites
HIST DOD	Department of Defense historical sites
HIST PCS ENF	Historical Enforced Permit Compliance Facilities
ICIS	Integrated Compliance Information System
LUCIS	Land Use Control Information Systems
LUCIS 2	Land Use Control Information Systems 2
NPL AOC	Areas related to NPL remediation sites
NPL LIENS	National Priority List Liens
PADS	PCB Activity Database Systems
PCB TRANSFORMER	Polychlorinated Biphenyl (PCB) Waste
PFAS NPL	PFAS NPL Sites
PFAS TRIS	PFAS TRIS Sites
CIWQS - CA	California Integrated Water Quality System
CIWQS 2 - CA	California Integrated Water Quality System
FA - CA	Financial Assurance
HIST HWP - CA	Historical EnviroStor Permitted Facilities
HIST LDS - CA	Historical Land Disposal Sites
HIST MCS - CA	Historical Military Cleanup Sites
HIST NFA - CA	Historical No Further Action Sites

OTHER ASCERTAINABLE RECORDS *(cont.)*

HWM COMMERCIAL FACILITIES - CA	Hazardous Waste Management Commercial Facilities
HWP - CA	EnviroStor Permitted Facilities
HWT - CA	Hazardous Waste Transporters
LDS - CA	Land Disposal Sites
MCS - CA	Military Cleanup Sites
MWMP - CA	Medical Waste Management Program
MWMP 2 - CA	Medical Waste Management Program
NFA - CA	No Further Action Sites
NFE - CA	Unconfirmed contaminated properties
NPDES - CA	State Wastewater and NPDES Permits
PERCHLORATE 2 - CA	Perchlorate contaminted sites
PFAS - CA	PFAS Site Listing
PFAS DOD - CA	PFAS Site Listing
RFR - CA	Regulated Facility Report
WDR - CA	Waste Discharge Requirement Sites

SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 9...
LAT/LONG: 37.654462 / -122.437419


PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: November 22, 2023



- Subject Property
- Equal/Higher Elevation
- Lower Elevation
- Department of Defense (No Data)
- DFIRM Floodzone 100
- DFIRM Floodzone 500
- FEMA FloodZone 100
- FEMA FloodZone 500 (No Data)
- Historical DOD (No Data)
- National Priority List (No Data)
- NWI

SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 9...
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: November 22, 2023



- Subject Property
- Equal/Higher Elevation
- Lower Elevation
- Department of Defense (No Data)
- DFIRM Floodzone 100
- DFIRM Floodzone 500
- FEMA FloodZone 100
- FEMA FloodZone 500 (No Data)
- Historical DOD (No Data)
- National Priority List (No Data)
- NWI

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
FEDERAL RCRA NON-CORRACTS TSD FACILITIES LIST								
ARCHIVED RCRA TSDF		0.500	0	0	0	--	--	0
RCRA_TSDF		0.500	0	0	0	--	--	0
FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS								
FEMA UST		0.250	0	0	--	--	--	0
INDIAN UST R9		0.250	0	0	--	--	--	0
AST - CA		0.250	2	1	--	--	--	3
FID UST - CA		0.250	0	1	--	--	--	1
HIST AST - CA		0.250	1	0	--	--	--	1
HIST UST - CA		0.250	2	4	--	--	--	6
FEDERAL CERCLIS LIST								
CERCLIS NFRAP		0.500	0	0	0	--	--	0
CERCLIS-HIST		0.500	0	0	0	--	--	0
FEDERAL FACILITY		1.000	0	0	0	0	--	0
FEDERAL RCRA CORRACTS FACILITIES LIST								
CORRACTS		1.000	0	0	0	0	--	0
HIST CORRACTS 2		1.000	0	0	0	0	--	0
FEDERAL DELISTED NPL SITE LIST								
DELISTED NPL		1.000	0	0	0	0	--	0
FEDERAL ERNS LIST								
ERNS		SP	0	--	--	--	--	0
FEDERAL INSTITUTIONAL CONTROLS / ENGINEERING CONTROLS REGISTRIES								
FED E C		0.500	0	0	0	--	--	0
FED I C		0.500	0	0	0	--	--	0
RCRA IC_EC		0.250	0	0	--	--	--	0
FEDERAL RCRA GENERATORS LIST								
HIST RCRA_CESQG		0.250	0	0	--	--	--	0
HIST RCRA_LQG		0.250	0	0	--	--	--	0
HIST RCRA_NONGEN		0.250	0	0	--	--	--	0
HIST RCRA_SQG		0.250	0	0	--	--	--	0
RCRA_NONGEN		0.250	7	10	--	--	--	17
RCRA_SQG		0.250	0	1	--	--	--	1
RCRA_VSQG		0.250	0	0	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS								
INDIAN LUST R9		0.500	0	0	0	--	--	0
LUST REG 2 - CA		0.500	1	3	7	--	--	11
LUST_SAN MATEO COUNTY - CA		0.500	1	3	8	--	--	12
SLIC REG 2 - CA		0.500	1	4	1	--	--	6
FEDERAL NPL SITE LIST								
NPL		1.000	0	0	0	0	--	0
NPL EPA R9 GIS		1.000	0	0	0	0	--	0
SEMS_FINAL NPL		1.000	0	0	0	0	--	0
SEMS_PROPOSED NPL		1.000	0	0	0	0	--	0
STATE- AND TRIBAL - EQUIVALENT CERCLIS								
ENVIROSTOR - CA		1.000	0	0	0	1	--	1
OIL & GAS CLEANUP - CA		0.500	0	0	0	--	--	0
SWRCB CLEANUP - CA		0.500	0	0	1	--	--	1
TOXIC PITS - CA		1.000	0	0	0	0	--	0
STATE RCRA GENERATORS LIST								
HWG - CA		0.250	16	31	--	--	--	47
STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS								
SWF/LF - CA		0.500	0	0	0	--	--	0
STATE AND TRIBAL BROWNFIELD SITES								
TRIBAL BROWNFIELDS		0.500	0	0	0	--	--	0
LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES								
CDL - CA		SP	0	--	--	--	--	0
SCH - CA		0.250	0	0	--	--	--	0
LOCAL BROWNFIELD LISTS								
FED BROWNFIELDS		0.500	0	0	0	--	--	0
LOCAL LAND RECORDS								
LIENS 2		SP	0	--	--	--	--	0
HIST LIENS - CA		SP	0	--	--	--	--	0
LIENS - CA		SP	0	--	--	--	--	0
RECORDS OF EMERGENCY RELEASE REPORTS								
HMIRS (DOT)		SP	0	--	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES								
TRIBAL ODI		0.500	0	0	0	--	--	0
SWRCY - CA		0.500	1	0	0	--	--	1
OTHER ASCERTAINABLE RECORDS								
COAL GAS		1.000	0	0	0	0	--	0
CORRECTIVE ACTIONS_2020		0.500	0	0	0	--	--	0
DOD		1.000	0	0	0	0	--	0
ECHO		SP	0	--	--	--	--	0
FUDS		1.000	0	0	0	0	--	0
HIST DOD		1.000	0	0	0	0	--	0
HIST PCS ENF		SP	0	--	--	--	--	0
ICIS		SP	0	--	--	--	--	0
LUCIS		0.500	0	0	0	--	--	0
LUCIS 2		0.500	0	0	0	--	--	0
NPL AOC		1.000	0	0	0	0	--	0
NPL LIENS		SP	0	--	--	--	--	0
PADS		SP	0	--	--	--	--	0
PCB TRANSFORMER		SP	0	--	--	--	--	0
PFAS NPL		0.500	0	0	0	--	--	0
PFAS TRIS		0.500	0	0	0	--	--	0
CALEPA SITES - CA		0.250	8	14	--	--	--	22
CIWQS - CA		SP	0	--	--	--	--	0
CIWQS 2 - CA		SP	0	--	--	--	--	0
DRYCLEANERS - CA		0.250	0	1	--	--	--	1
FA - CA		SP	0	--	--	--	--	0
HAZNET - CA		0.250	12	28	--	--	--	40
HIST HAZNET - CA		0.250	1	2	--	--	--	3
HIST HWP - CA		1.000	0	0	0	0	--	0
HIST LDS - CA		0.500	0	0	0	--	--	0
HIST MCS - CA		1.000	0	0	0	0	--	0
HIST NFA - CA		0.500	0	0	0	--	--	0
HWM COMMERCIAL FACILITIES - CA		0.250	0	0	--	--	--	0
HWP - CA		1.000	0	0	0	0	--	0
HWT - CA		0.250	0	0	--	--	--	0
LDS - CA		0.500	0	0	0	--	--	0
MCS - CA		1.000	0	0	0	0	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
OTHER ASCERTAINABLE RECORDS *(cont.)*								
MWMP - CA		0.250	0	0	--	--	--	0
MWMP 2 - CA		0.250	0	0	--	--	--	0
NFA - CA		0.500	0	0	0	--	--	0
NFE - CA		0.500	0	0	0	--	--	0
NPDES - CA		SP	0	--	--	--	--	0
PERCHLORATE 2 - CA		0.500	0	0	0	--	--	0
PFAS - CA		0.500	0	0	0	--	--	0
PFAS DOD - CA		0.500	0	0	0	--	--	0
PFAS GAMA - CA		0.500	0	1	9	--	--	10
RFR - CA		SP	0	--	--	--	--	0
WDR - CA		SP	0	--	--	--	--	0
WDS - CA	X	SP	--	--	--	--	--	1

Map Id: 1
Direction:
Distance:
Elevation:
Relative:

Site Name : 843753
N/R
CA

Database(s) : [WDS - CA]

Envirosite ID: 9459305
EPA ID: N/R

WDS - CA

Facility Address :	N/R
County :	San Mateo
WDID :	2SSO10115
SSS Event ID :	843753
Spill Type :	Category 1
Start Date :	2018.01.08 23.08.00
Spill Address :	N/R
Spill Location Name :	73 Camaritas Ave, South San Francisco, CA 94080
Spill Location Description :	N/R
Agency :	South San Francisco City
Collection System :	South San Francisco City CS
Overall Spill Description :	Grease Deposition (FOG) caused 24499.0 gallons of sewage to spill from Lateral Clean Out (Private) at 73 Camaritas Ave, South San Francisco, CA 94080 to Surface Water;San Francisco Bay. Surface water body affected (Colma Creek).
Spill Cause :	Grease Deposition (FOG)
Spill Cause Explaination :	N/R
Where Failure Occur :	Gravity Mainline
Where Failure Occur Explaination :	N/R
Agency Notification Date :	2018.01.08 23.10.00
Operator Approval Date :	2018.01.08 23.20.00
Estimated End Date :	2018.01.09 00.10.00
Response Activities :	Restored flow
Response Activities Explanation :	N/R
Response Complete Date :	2018.01.09 07.00.00
Appearance Point :	Lateral Clean Out (Private)
Appearance Point Explanation :	N/R
Reach Surface :	Yes
Reach Surface Drainpipe :	Yes
Return to SSS :	No
Private Lateral Spill :	No
Final Spill Destination :	Surface Water
Final Spill Destination Explanation :	San Francisco Bay
Spill Volume Reached Land :	1745
Spill Volume Discharge A :	22754
Spill Volume Discharge B :	0
Spill Volume Discharge C :	0
Spill Volume Discharge D :	0
Spill Volume Discharge E :	0
Spill Volume Discharge F :	0
Spill Volume Discharge G :	1745
Spill Volume Discharge H :	1745
Spill Volume :	24499
Spill Volume Recover :	1745
Spill Volume Reach Surface :	22754
Spill Rate :	1
Region :	2
Certificate Person Name :	Louis Langi
Certificate Person Title :	Interim Program Manager
Certificate Location :	Corporation Yard
Certificate ID :	522074
Certificate Date :	2018.02.09 00.00.00
Diameter of Sewer :	0

Map Id: 1
Direction:
Distance:
Elevation:
Relative:

Site Name : 843753
N/R
CA

Database(s) : [WDS - CA] ***(cont.)***

Envirosite ID: 9459305
EPA ID: N/R

WDS - CA ***(cont.)***

Material of Sewer Pipe :	N/R
Age Sewer Pipe :	0
Visual Inspection Result :	N/R
Health Warning Post :	No
Beach Impact :	N/R
Surface Water Impact :	Colma Creek
Ongoing Investigate :	Yes
Sample Analyzed for :	No water quality samples taken
Sample Analyzed for Explaination :	N/R
Sample Reported to :	No water quality samples taken
Sample Reported to Explaination :	N/R
Corrective Action :	Adjusted schedule/method of preventive maintenance;Enforcement action against FOG source;Inspected Sewer Using CCTV to Determine Cause
Response Correct Action Taken :	NA
OES Control Number :	180169
OES Called Date :	2018.01.09 12.04.00
Latitude :	37.65456
Longitude :	-122.43715
Last Date in Agency List :	2018-11-01

Map Id: A2
Direction: WNW
Distance: 0.024 mi., 128 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : OFFICE OF MORRIS WONG DDS | TONI A AMBUS DDS | EPITACIO SISON JR SISON DENTAL CARE
100 ARROYO DR | 100 ARROYO DR STE C | 100 ARROYO_DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946900
EPA ID: CAL000126358

HAZNET - CA

Facility Name :	EDWARD M O REILLY TRUST DDS
Facility Address :	100 ARROYO_DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000126358
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	100 ARROYO DR, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65505383
Longitude :	-122.43790030

Map Id: A2
Direction: WNW
Distance: 0.024 mi., 128 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : OFFICE OF MORRIS WONG DDS | TONI A AMBUS DDS | EPITACIO SISON JR SISON DENTAL CARE
100 ARROYO DR | 100 ARROYO DR STE C | 100 ARROYO_DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946900
EPA ID: CAL000126358

HAZNET - CA ***(cont.)***

Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : EPITACIO SISON JR SISON DENTAL CARE
Facility Address : 100 ARROYO DR STE C, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

Site Details
Generator EPA ID : CAL000421804
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 100 ARROYO DR STE C, SOUTH SAN FRANCISCO, CA 94080
Latitude : 37.65501900
Longitude : -122.43825450
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : OFFICE OF MORRIS WONG DDS
Facility Address : 100 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

Site Details
Generator EPA ID : CAL000320553
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : PO BOX 464, CORTE MADERA, CA 949760464
Latitude : 37.65505383
Longitude : -122.43790030
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 2011: 541 - Photochemicals/photoprocessing waste, 0.0417 tons to CAD981429673
2008: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.), tons to CAD008252405
2008: 133 - Aqueous solution with total organic residues 10 percent or more, 0.00417 tons to CAD008252405

Map Id: A2
Direction: WNW
Distance: 0.024 mi., 128 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : OFFICE OF MORRIS WONG DDS | TONI A AMBUS DDS | EPITACIO SISON JR SISON DENTAL CARE
100 ARROYO DR | 100 ARROYO DR STE C | 100 ARROYO_DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946900
EPA ID: CAL000126358

HAZNET - CA ***(cont.)***

2008: 541 - Photochemicals/photoprocessing waste, 0.01668 tons to CAD981429673
2007: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.), 0.0165 tons to CAD008252405
2007: 541 - Photochemicals/photoprocessing waste, 0.0417 tons to CAD981429673

Facility Name :	TONI A AMBUS DDS
Facility Address :	100 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000172944
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	773 JENEVEIN AVE, SAN BRUNO, CA 940664231
Latitude :	37.65505383
Longitude :	-122.43790030
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste : 2003: 341 - Organic liquids (nonsolvents) with halogens, 0.02085 tons to CA0000084517

HWG - CA

Facility Name :	EDWARD M O REILLY TRUST DDS
Facility Address :	100 ARROYO_DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL000126358
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	100 ARROYO DR, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	EDWARD M O REILLY TRUST DDS
Owner Address :	100 ARROYO_DR, SOUTH SAN FRANCISCO, CA
Operator Name :	KAREN FUSS OFFICE MANAGER
Operator Address :	INACTIVE PER VQ00 - BMI, SOUTH SAN FRANCISCO, CA

Map Id: A2
Direction: WNW
Distance: 0.024 mi., 128 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : OFFICE OF MORRIS WONG DDS | TONI A AMBUS DDS | EPITACIO SISON JR SISON DENTAL CARE
100 ARROYO DR | 100 ARROYO DR STE C | 100 ARROYO_DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946900
EPA ID: CAL000126358

HWG - CA ***(cont.)***

Latitude :	37.655054
Longitude :	-122.4379
Facility Name :	EPITACIO SISON JR SISON DENTAL CARE
Facility Address :	100 ARROYO DR STE C, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000421804
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	100 ARROYO DR STE C, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	EPITACIO SISON JR
Owner Address :	100 ARROYO DR STE C, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	EPITACIO SISON JR
Operator Address :	100 ARROYO DR STE C, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.655019
Longitude :	-122.438254
Facility Name :	OFFICE OF MORRIS WONG DDS
Facility Address :	100 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000320553
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	PO BOX 464, CORTE MADERA, CA 949760464
Owner Name :	MORRIS WONG DDS
Owner Address :	100 ARROYO DR, SOUTH SAN FRANCISCO, CA 940800000
Operator Name :	MORRIS WONG DDS
Operator Address :	100 ARROYO DR, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.655075
Longitude :	-122.43789
Facility Name :	TONI A AMBUS DDS
Facility Address :	100 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000172944
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	773 JENEVEIN AVE, SAN BRUNO, CA 940664231
Owner Name :	TONI A AMBUS

Map Id: A2
Direction: WNW
Distance: 0.024 mi., 128 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : OFFICE OF MORRIS WONG DDS | TONI A AMBUS DDS | EPITACIO SISON JR SISON DENTAL CARE
100 ARROYO DR | 100 ARROYO DR STE C | 100 ARROYO_DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946900
EPA ID: CAL000126358

HWG - CA ***(cont.)***

Owner Address :	773 JENEVEIN AVE, SAN BRUNO, CA 940664231
Operator Name :	TONI AMBUS/DDS
Operator Address :	773 JENEVEIN AVE, SAN BRUNO, CA 940664231
Latitude :	37.655141
Longitude :	-122.437985

Map Id: B3
Direction: WNW
Distance: 0.053 mi., 280 ft.
Elevation: 73 ft.
Relative: Higher

Site Name : BILL STAVROULAKIS
112 ARROYO DRIVE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN]

Envirosite ID: 53946904
EPA ID: CAC003219023

HWG - CA

Facility Name :	BILL STAVROULAKIS
Facility Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003219023
Status :	Active
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	BILL STAVROULAKIS
Owner Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	BILL STAVROULAKIS
Operator Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.654864
Longitude :	-122.439191

RCRA_NONGEN

Facility Name :	BILL STAVROULAKIS
Facility Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2023-02-22
EPA ID :	CAC003219023
Mailing Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Contact :	BILL STAVROULAKIS
Contact Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	415-872-2872
Contact Email :	BSTAVROULAKIS@GMAIL.COM
EPA Region :	09

Map Id: B3
Direction: WNW
Distance: 0.053 mi., 280 ft.
Elevation: 73 ft.
Relative: Higher

Site Name : BILL STAVROULAKIS
112 ARROYO DRIVE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 53946904
EPA ID: CAC003219023

RCRA_NONGEN ***(cont.)***

Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	BILL STAVROULAKIS
Owner/Operator Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-872-2872
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	BILL STAVROULAKIS
Owner/Operator Address :	112 ARROYO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-872-2872
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: C4
Direction: ESE
Distance: 0.057 mi., 301 ft.
Elevation: 58 ft.
Relative: Higher

Site Name : ACCESS PROPERTIES LLC
91 WESTBOROUGH BOULEVARD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA]

Envirosite ID: 52367910
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	ACCESS PROPERTIES LLC
Facility Address :	91 WESTBOROUGH BOULEVARD, SOUTH SAN FRANCISCO, 94080
Site ID :	449427
EI ID :	110058351402
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	37.653920
Longitude :	-122.435650
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Map Id: D5
Direction: NNE
Distance: 0.061 mi., 325 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | SO SAN FRAN POLICE DEPT-DISP PRG | STATION 63
33 ARROYO
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HIST UST - CA]

Envirosite ID: 52367915
EPA ID: N/R

HIST UST - CA

Facility Name :	MUNICIPAL SERVICES BLDG
Facility Address :	33 ARROYO, SOUTH SAN FRANCISCO, 94080
County :	San Mateo
PDF Link :	Click here for hyperlink provided by the agency.

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA]

Envirosite ID: 52367916
EPA ID: N/R

AST - CA

Facility Name :	City of South San Francisco Fire Station 63
Facility Address :	33 ARROYO DR, S SAN FRANCISCO, CA 94080

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

AST - CA ***(cont.)***

County : San Mateo County

Site Details

Site ID :	30253
Facility Identifer :	FA0008507
EPA Identifier :	N/R
Facility Explorer ID :	30253
Dun and Bradsheet Number :	N/R
Regulatory Programs :	Chemical Storage Facilities, Aboveground Petroleum Storage
SIC :	9224 Fire protection
NAICS :	922160 Fire Protection
Latitude :	37.655621
Longitude :	-122.436610
Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-11-16

Violations

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Violation Date :	2022-10-03
Citation :	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Description :	Failure to prepare a Spill Prevention, Control, and Countermeasures (SPCC) Plan.
Notes :	Returned to compliance on 01/25/2023. OBSERVATION: Facility is subject to the APSA program because more than 1,320 gallons of petroleum product is stored on-site. Facility appears to be storing more than 2,000 gallons of petroleum product on-site. CORRECTIVE ACTION: Please forward the latest copy of the SPCC plan to the CUPA or complete and implement an SPCC plan within 30 days.
Division :	San Mateo County Environmental Health
Program :	APSA
Source :	CERS
Violation Date :	2022-10-03

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

AST - CA ***(cont.)***

Citation :	HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple
Description :	Business Plan Program - Release/Leaks/Spills - General
Notes :	OBSERVATION: A small amount of liquid was observed in the day tank rupture basin. A large amount of absorbent material was on the floor below the generator. CORRECTIVE ACTION: Remove liquid from the secondary containment and properly manage if hazardous waste. Submit proof of correction to the CUPA in 7 days.
Division :	San Mateo County Environmental Health
Program :	HMRRP
Source :	CERS
Violation Date :	2022-10-03
Citation :	HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)
Description :	Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.
Notes :	OBSERVATION: The records of annual employee training were not reviewed during the inspection. CORRECTIVE ACTION: Ensure all employees receive the required training that includes: safe handling hazardous materials, emergency response procedures, and proper use of response equipment. Maintain records of training available for 3 years. Submit evidence of current training to the CUPA in 7 days.
Division :	San Mateo County Environmental Health
Program :	HMRRP
Source :	CERS
Violation Date :	2022-10-03
Citation :	HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2
Description :	Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

AST - CA ***(cont.)***

Notes :

Returned to compliance on 01/25/2023. OBSERVATION: The business failed to electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA on or before the required due date. The last accepted submittal was completed on 9/20/2020. CORRECTIVE ACTION: Electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA within 30 days. On an ongoing basis, electronically submit and certify the business plan annually on or before the required due date.

Division : San Mateo County Environmental Health
Program : HMRRP
Source : CERS

Violation Date : 2022-10-03

Citation : HSC 6.95 25508(a)(3) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3)

Description : Failure to report program data electronically.

Notes :

Returned to compliance on 01/25/2023. OBSERVATION: The business failed to electronically submit the Business Activities Page and/or Business Owner Operator Identification Page, or failed to report complete or accurate information on these forms. The primary emergency contact and environmental contact listed has since retired and requires updating. CORRECTIVE ACTION: Complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Division : San Mateo County Environmental Health
Program : HMRRP
Source : CERS

Enforcements

Enforcement Action Date : 2023-03-20
Type : Notice of Violation (Unified Program)
Description : Notice of Violation Issued by the Inspector at the Time of Inspection
Notes : N/R
Division : San Mateo County Environmental Health
Program : HMRRP
Source : CERS

Chemicals

Chemical Name : DIESEL FUEL NO. 2
CAS Number : 68334-30-5
Hazard Type(s) : -
Max Daily Amount / Unit : 1200-2999 Gallons
Average Daily Amount / Unit : 1200-2999 Gallons

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

AST - CA ***(cont.)***

Days Onsite :	365
Physical State(s) :	Liquid, Pure
Chemical Name :	Oxygen
CAS Number :	7782-44-7
Hazard Type(s) :	-
Max Daily Amount / Unit :	0-2599 Cubic Feet
Average Daily Amount / Unit :	0-2599 Cubic Feet
Days Onsite :	365
Physical State(s) :	Gas, Pure
Facility Name :	CITY OF SSF FIRE STATION #63
Facility Address :	33 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo County

Site Details

Site ID :	30253
Facility Identifer :	200920_008507
EPA Identifier :	N/R
Facility Explorer ID :	30253
Dun and Bradsheet Number :	N/R
Regulatory Programs :	Chemical Storage Facilities, Aboveground Petroleum Storage
SIC :	N/R
NAICS :	922160 Fire Protection
Latitude :	37.655621
Longitude :	-122.436610
Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-02-24

Violations

Violation Date :	2022-10-03
Citation :	HSC 6.67 25270.4.5(a) - California Health and Safety Code, Chapter 6.67, Section(s) 25270.4.5(a)
Description :	Failure to prepare a Spill Prevention, Control, and Countermeasures (SPCC) Plan.

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

AST - CA ***(cont.)***

Notes : OBSERVATION: Facility is subject to the APSA program because more than 1,320 gallons of petroleum product is stored on-site. Facility appears to be storing more than 2,000 gallons of petroleum product on-site. CORRECTIVE ACTION: Please forward the latest copy of the SPCC plan to the CUPA or complete and implement an SPCC plan within 30 days.

Division : San Mateo County Environmental Health
Program : APSA
Source : CERS

Violation Date : 2022-10-03

Citation : HSC 6.95 25508.2 - California Health and Safety Code, Chapter 6.95, Section(s) 25508.2

Description : Failure to annually review and electronically certify that the business plan is complete and accurate on or before the annual due date.

Notes :

OBSERVATION: The business failed to electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA on or before the required due date. The last accepted submittal was completed on 9/20/2020. CORRECTIVE ACTION: Electronically submit and certify that the business plan is complete, accurate, and in compliance with EPCRA within 30 days. On an ongoing basis, electronically submit and certify the business plan annually on or before the required due date.

Division : San Mateo County Environmental Health
Program : HMRRP
Source : CERS

Violation Date : 2022-10-03

Citation : HSC 6.95 25508(a)(3 - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(3

Description : Failure to report program data electronically.

Notes :

OBSERVATION: The business failed to electronically submit the Business Activities Page and/or Business Owner Operator Identification Page, or failed to report complete or accurate information on these forms. The primary emergency contact and environmental contact listed has since retired and requires updating. CORRECTIVE ACTION: Complete and electronically submit the Business Activities Page and/or Business Owner Operator Identification Page.

Division : San Mateo County Environmental Health

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

AST - CA ***(cont.)***

Program : HMRRP
Source : CERS

Violation Date : 2022-10-03

Citation : HSC 6.95 25505(a)(4) - California Health and Safety Code, Chapter 6.95, Section(s) 25505(a)(4)

Description : Failure to provide initial and annual training to all employees in safety procedures in the event of a release or threatened release of a hazardous material or failure to document and maintain training records for a minimum of three years.

Notes : OBSERVATION: The records of annual employee training were not reviewed during the inspection. CORRECTIVE ACTION: Ensure all employees receive the required training that includes: safe handling hazardous materials, emergency response procedures, and proper use of response equipment. Maintain records of training available for 3 years. Submit evidence of current training to the CUPA in 7 days.

Division : San Mateo County Environmental Health
Program : HMRRP
Source : CERS

Violation Date : 2022-10-03

Citation : HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple

Description : Business Plan Program - Release/Leaks/Spills - General

Notes : OBSERVATION: A small amount of liquid was observed in the day tank rupture basin. A large amount of absorbent material was on the floor below the generator. CORRECTIVE ACTION: Remove liquid from the secondary containment and properly manage if hazardous waste. Submit proof of correction to the CUPA in 7 days.

Division : San Mateo County Environmental Health
Program : HMRRP
Source : CERS

Chemicals
Chemical Name : DIESEL FUEL NO. 2
CAS Number : 68334-30-5
Hazard Type(s) : -

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

AST - CA ***(cont.)***

Max Daily Amount / Unit :	1200-2999 Gallons
Average Daily Amount / Unit :	1200-2999 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Pure

Chemical Name :	Oxygen
CAS Number :	7782-44-7
Hazard Type(s) :	-
Max Daily Amount / Unit :	0-2599 Cubic Feet
Average Daily Amount / Unit :	0-2599 Cubic Feet
Days Onsite :	0
Physical State(s) :	Gas, Pure

CALEPA SITES - CA

Facility Name :	CITY OF SOUTH SAN FRANCISCO FIRE STATION 63
Facility Address :	33 ARROYO DR, S SAN FRANCISCO, 94080

Site ID :	30253
EI ID :	10064140
EI Description :	Aboveground Petroleum Storage
Latitude :	37.655621
Longitude :	-122.436610
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Site ID :	30253
EI ID :	10064140
EI Description :	Chemical Storage Facilities
Latitude :	37.655621
Longitude :	-122.436610
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Facility Name :	CITY OF SSF FIRE STATION #63
Facility Address :	33 ARROYO DR, SOUTH SAN FRANCISCO, 94080

Site ID :	30253
EI ID :	10064140
EI Description :	Aboveground Petroleum Storage
Latitude :	37.655621
Longitude :	-122.436610
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Site ID :	30253
EI ID :	10064140
EI Description :	Chemical Storage Facilities
Latitude :	37.655621
Longitude :	-122.436610
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

HAZNET - CA

Facility Name :	CITY SOUTH SAN FRANCISCO/ENGINEERING
Facility Address :	33 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002100600
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000
Latitude :	37.65573837
Longitude :	-122.43696225
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1998: 512 - Other empty containers 30 gallons or more, 1 tons to CAD009466392

HIST AST - CA

Facility Name :	CITY OF SSF FIRE STATION #63
Facility Address :	33 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

CERS ID :	10064140
Facility ID :	N/R
EPA ID :	N/R
Business Name :	FIRE STATION #3

Map Id: D6
Direction: NNE
Distance: 0.063 mi., 331 ft.
Elevation: 64 ft.
Relative: Higher

Site Name : CITY OF SSF FIRE STATION #63 | CITY OF SOUTH SAN FRANCISCO FIRE STATION 63 | CITY SOUTH SAN FRANCISCO/ENGINEERING
33 ARROYO DR
SOUTH SAN FRANCISCO | S SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST AST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367916
EPA ID: N/R

HIST AST - CA ***(cont.)***

Phone :	6508778550
Fax :	N/R
Mailing Address :	P O BOX 711, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	CITY OF SOUTH SAN FRANCISCO
Owner Phone :	6508778555
Owner Mailing Address :	P O BOX 711, SOUTH SAN FRANCISCO, CA 94083
Property Owner Name :	N/R
Property Owner Phone :	N/R
Property Owner Mailing Address :	N/R
Operator Name :	CITY OF SOUTH SAN FRANCISCO
Operator Phone :	6508778550
CUPA :	N/R
Total Gallons :	N/R
Facility Latitude Measure :	37.655621
Facility Longitude Measure :	-122.436615
Last Date in Agency List :	2018-01-31

HWG - CA

Facility Name :	CITY SOUTH SAN FRANCISCO/ENGINEERING
Facility Address :	33 ARROYO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002100600
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000
Owner Name :	CITY SOUTH SAN FRANCISCO
Owner Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000
Operator Name :	FRED KAWAHARA-CIVIL ENGINEER
Operator Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000
Latitude :	37.656051
Longitude :	-122.436772

Map Id: B7
Direction: WNW
Distance: 0.063 mi., 333 ft.
Elevation: 73 ft.
Relative: Higher

Site Name : ALAN WONG
100 DEL MONTE AVENUE
SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN]

Envirosite ID: 54020596
EPA ID: CAC003246122

HWG - CA

Facility Name :	ALAN WONG
Facility Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
EPA ID :	CAC003246122
Status :	Active
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
Owner Name :	ALAN WONG
Owner Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
Operator Name :	ALAN WONG
Operator Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
Latitude :	37.654978
Longitude :	-122.439375

RCRA_NONGEN

Facility Name :	ALAN WONG
Facility Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
Date Form Received by Agency :	2023-08-09
EPA ID :	CAC003246122
Mailing Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
Contact :	ALAN WONG
Contact Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	408-888-2056
Contact Email :	ALANWONG68@GMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	ALAN WONG
Owner/Operator Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	408-888-2056
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	ALAN WONG
Owner/Operator Address :	100 DEL MONTE AVENUE, SAN FRANCISCO, CA 94080

Map Id: B7
Direction: WNW
Distance: 0.063 mi., 333 ft.
Elevation: 73 ft.
Relative: Higher

Site Name : ALAN WONG
100 DEL MONTE AVENUE
SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 54020596
EPA ID: CAC003246122

RCRA_NONGEN ***(cont.)***

Owner/Operator Country :	N/R
Owner/Operator Telephone :	408-888-2056
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: A8
Direction: NNW
Distance: 0.064 mi., 336 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : MIKE KENNY
66 ARROYO DR APT 1
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946917
EPA ID: CAC002671423

HAZNET - CA

Facility Name :	MIKE KENNY
Facility Address :	66 ARROYO DR APT 1, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002671423
Active :	Inactive
Category :	STATE

Map Id: A8
Direction: NNW
Distance: 0.064 mi., 336 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : MIKE KENNY
66 ARROYO DR APT 1
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946917
EPA ID: CAC002671423

HAZNET - CA ***(cont.)***

Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	66 ARROYO DR APT 1, SOUTH SAN FRANCISCO, CA 940803151
Latitude :	37.65569352
Longitude :	-122.43720036
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2011: 151 - Asbestos containing waste, 0.4 tons to CAD981382732

HWG - CA

Facility Name :	MIKE KENNY
Facility Address :	66 ARROYO DR APT 1, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002671423
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	66 ARROYO DR APT 1, SOUTH SAN FRANCISCO, CA 940803151
Owner Name :	MIKE KENNY
Owner Address :	66 ARROYO DR APT 1, SOUTH SAN FRANCISCO, CA 940803151
Operator Name :	MIKE KENNY
Operator Address :	66 ARROYO DR APT 1, SOUTH SAN FRANCISCO, CA 940803151
Latitude :	37.65563
Longitude :	-122.4377

Map Id: D9
Direction: ENE
Distance: 0.075 mi., 395 ft.
Elevation: 51 ft.
Relative: Lower

Site Name : PACIFIC SUPERMARKET
1015 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA]

Envirosite ID: 52367890
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	PACIFIC SUPERMARKET
Facility Address :	1015 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	411985
EI ID :	10714123
EI Description :	Chemical Storage Facilities
Latitude :	37.655010

Map Id: D9
Direction: ENE
Distance: 0.075 mi., 395 ft.
Elevation: 51 ft.
Relative: Lower

Site Name : PACIFIC SUPERMARKET
1015 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA] ***(cont.)***

Envirosite ID: 52367890
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Longitude :	-122.435547
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Map Id: D10
Direction: NE
Distance: 0.089 mi., 469 ft.
Elevation: 59 ft.
Relative: Higher

Site Name : O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.
1059 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN, SWRCY - CA]

Envirosite ID: 52367891
EPA ID: CAC000778880

CALEPA SITES - CA

Facility Name :	O'REILLY AUTO PARTS #2743
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	53018
EI ID :	10065352
EI Description :	Chemical Storage Facilities
Latitude :	37.655750
Longitude :	-122.435610
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Site ID :	53018
EI ID :	10065352
EI Description :	Hazardous Waste Generator
Latitude :	37.655750
Longitude :	-122.435610
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

HAZNET - CA

Facility Name :	1X BLOCKBUSTER VIDEO, INC.
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC000778880
Active :	Inactive
Category :	STATE

Map Id: D10
Direction: NE
Distance: 0.089 mi., 469 ft.
Elevation: 59 ft.
Relative: Higher

Site Name : O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.
1059 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 52367891
EPA ID: CAC000778880

HAZNET - CA ***(cont.)***

Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	4805 MURPHY CANYON ROAD, SAN DIEGO, CA 921230000
Latitude :	37.65582527
Longitude :	-122.43555368
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	O'REILLY AUTO PARTS #2473
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000187010
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	233 S PATTERSON AVE, SPRINGFIELD, MO 658020000
Latitude :	37.65582527
Longitude :	-122.43555368
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2013: 343 - Unspecified organic liquid mixture, 0.005 tons to CA0000084517
2013: 343 - Unspecified organic liquid mixture, 0.015 tons to CAD059494310
2013: 181 - Other inorganic solid waste, 0.1125 tons to UTD991301748
2011: 223 - Unspecified oil-containing waste, 0.025 tons to WIR000029751
2010: 221 - Waste oil and mixed oil, 0.1 tons to TXD077603371
2009: 223 - Unspecified oil-containing waste, 0.13 tons to WIR000029751
2008: 223 - Unspecified oil-containing waste, 0.0625 tons to WIR000029751
2007: 223 - Unspecified oil-containing waste, 0.0875 tons to WIR000029751
2006: 223 - Unspecified oil-containing waste, 0.025 tons to WIR000029751

Map Id: D10
Direction: NE
Distance: 0.089 mi., 469 ft.
Elevation: 59 ft.
Relative: Higher

Site Name : O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.
1059 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 52367891
EPA ID: CAC000778880

HAZNET - CA ***(cont.)***

2001: 223 - Unspecified oil-containing waste, 0.6255 tons to CAT080033681
1999: 223 - Unspecified oil-containing waste, 3.336 tons to CAT080013352

Facility Name :	O'REILLY AUTO PARTS STORE 2743
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000392590
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	233 S PATTERSON, SPRINGFIELD, MO 65802
Latitude :	37.65582525
Longitude :	-122.43555370
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

State Waste :

2019: 223 - Unspecified oil-containing waste, 0.13000 tons to CAD059494310
2019: 181 - Other inorganic solid waste, 0.10000 tons to CAD059494310
2019: 223 - Unspecified oil-containing waste, 0.15000 tons to NED981723513
2019: 214 - Unspecified solvent mixture, 0.05500 tons to CAD008364432
2019: 181 - Other inorganic solid waste, 0.50500 tons to UTD991301748
2019: 214 - Unspecified solvent mixture, 0.00800 tons to NVD980895338
2019: 141 - Off-specification, aged or surplus inorganics, 0.02850 tons to CAD008364432
2019: 791 - Liquids with pH <= 2, 0.01050 tons to CAD008364432
2018: 181 - Other inorganic solid waste, 1.03000 tons to CAD059494310
2018: 223 - Unspecified oil-containing waste, 0.12000 tons to NED981723513
2018: 343 - Unspecified organic liquid mixture, 0.00500 tons to UTD981552177
2018: 791 - Liquids with pH <= 2, 0.00750 tons to UTD991301748

Map Id: D10
Direction: NE
Distance: 0.089 mi., 469 ft.
Elevation: 59 ft.
Relative: Higher

Site Name : O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.
1059 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 52367891
EPA ID: CAC000778880

HAZNET - CA ***(cont.)***

2017: 343 - Unspecified organic liquid mixture, 0.005 tons to UTD981552177
2017: 181 - Other inorganic solid waste, 0.75 tons to CAD059494310
2017: 343 - Unspecified organic liquid mixture, 0.005 tons to UTD991301748
2017: 272 - Polymeric resin waste, 0.005 tons to UTD981552177
2016: 123 - Unspecified alkaline solution, 0.0025 tons to UTD991301748
2016: 343 - Unspecified organic liquid mixture, 0.0225 tons to UTD981552177
2016: 272 - Polymeric resin waste, 0.0125 tons to UTD981552177
2016: 181 - Other inorganic solid waste, 0.6875 tons to CAD059494310
2015: 181 - Other inorganic solid waste, 0.875 tons to CAD059494310
2015: 343 - Unspecified organic liquid mixture, 0.0025 tons to CAD059494310
2015: 343 - Unspecified organic liquid mixture, 0.0125 tons to UTD981552177
2015: 123 - Unspecified alkaline solution, 0.0025 tons to CAD980675276
2015: 272 - Polymeric resin waste, 0.005 tons to UTD981552177
2014: 791 - Liquids with pH <= 2, 0.005 tons to UTD991301748
2014: 343 - Unspecified organic liquid mixture, 0.015 tons to CAD980675276
2014: 343 - Unspecified organic liquid mixture, 0.005 tons to CAD044429835
2014: 352 - Other organic solids, 0.0025 tons to CAD980675276
2014: 343 - Unspecified organic liquid mixture, 0.01 tons to UTD981552177

HIST HAZNET - CA

Facility Name :	1X BLOCKBUSTER VIDEO, INC.
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
ID Number :	CAC000778880
Last Date in Agency List :	2014-11-17

HWG - CA

Facility Name :	1X BLOCKBUSTER VIDEO, INC.
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC000778880
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	4805 MURPHY CANYON ROAD, SAN DIEGO, CA 921230000
Owner Name :	BLOCKBUSTER VIDEO, INC.
Owner Address :	N/A

Map Id: D10
Direction: NE
Distance: 0.089 mi., 469 ft.
Elevation: 59 ft.
Relative: Higher

Site Name : O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.
1059 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 52367891
EPA ID: CAC000778880

HWG - CA ***(cont.)***

Operator Name :	JERRI BOWMAN/STORE OPENING COO
Operator Address :	N/A
Latitude :	37.655923
Longitude :	-122.435649
Facility Name :	O'REILLY AUTO PARTS #2473
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000187010
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	233 S PATTERSON AVE, SPRINGFIELD, MO 658020000
Owner Name :	O'REILLY AUTO ENTERPRISES, LLC
Owner Address :	233 S. PATTERSON AVE, SPRINGFIELD, MO 658020000
Operator Name :	JOHN BOUNDS
Operator Address :	233 S. PATTERSON AVE., SPRINGFIELD, MO 65802
Latitude :	37.655907
Longitude :	-122.43559
Facility Name :	O'REILLY AUTO PARTS STORE 2743
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000392590
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	233 S PATTERSON AVE, SPRINGFIELD, MO 658020000
Owner Name :	O'REILLY AUTO PARTS
Owner Address :	233 S PATTERSON AVE, SPRINGFIELD, MO 658020000
Operator Name :	JOHN BOUNDS
Operator Address :	233 S. PATTERSON AVE., SPRINGFIELD, MO 65802
Latitude :	37.655825
Longitude :	-122.435554

RCRA_NONGEN

Facility Name :	O'REILLY AUTO PARTS STORE 2743
Facility Address :	1059 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080-3206
County :	SAN MATEO

Map Id: D10
Direction: NE
Distance: 0.089 mi., 469 ft.
Elevation: 59 ft.
Relative: Higher

Site Name : O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.
1059 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 52367891
EPA ID: CAC000778880

RCRA_NONGEN ***(cont.)***

Date Form Received by Agency :	2014-01-09
EPA ID :	CAL000392590
Mailing Address :	233 S PATTERSON, SPRINGFIELD, MO 65802-0000
Contact :	JOHN BOUNDS
Contact Address :	233 S. PATTERSON AVE., SPRINGFIELD, MO 65802
Contact Country :	N/R
Contact Telephone :	417-520-4589
Contact Email :	JBOUNDS2@OREILLYAUTO.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	JOHN BOUNDS
Owner/Operator Address :	233 S. PATTERSON AVE., SPRINGFIELD, MO 65802
Owner/Operator Country :	N/R
Owner/Operator Telephone :	417-520-4589
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	O'REILLY AUTO PARTS
Owner/Operator Address :	233 S PATTERSON, SPRINGFIELD, MO 65802-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	417-862-3333
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N

Map Id: D10
Direction: NE
Distance: 0.089 mi., 469 ft.
Elevation: 59 ft.
Relative: Higher

Site Name : O'REILLY AUTO PARTS STORE 2743 | O'REILLY AUTO PARTS #2743 | 1X BLOCKBUSTER VIDEO, INC.
1059 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 52367891
EPA ID: CAC000778880

RCRA_NONGEN ***(cont.)***

Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

SWRCY - CA

Facility Name :	O'Reilly Auto Parts #2743
Facility Address :	1059 El Camino Real, South San Francisco, 94080
County :	N/R

Site Details

ID Number :	N/R
Activity Categories :	N/R
Activities :	N/R
Phone Number :	(650) 589-8102
Type :	UsedOil
Last Date in Agency List :	2023-06-27

Map Id: C11
Direction: ESE
Distance: 0.098 mi., 520 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : SUMMERVILLE SENIOR LIVING | WESTBOROUGH ROYALE INC
89 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946920
EPA ID: CAC002586453

HAZNET - CA

Facility Name :	SUMMERVILLE SENIOR LIVING
Facility Address :	89 WESTBOROUGH, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: C11
Direction: ESE
Distance: 0.098 mi., 520 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : SUMMERVILLE SENIOR LIVING | WESTBOROUGH ROYALE INC
89 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946920
EPA ID: CAC002586453

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002586453
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1940 OAKDALE AVE, SAN FRANCISCO, CA 94124
Latitude :	37.65419366
Longitude :	-122.43578568
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	WESTBOROUGH ROYALE INC
Facility Address :	89 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002639763
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	89 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940803162
Latitude :	37.65419366
Longitude :	-122.43578568
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	SUMMERVILLE SENIOR LIVING
Facility Address :	89 WESTBOROUGH, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002586453
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1940 OAKDALE AVE, SAN FRANCISCO, CA 94124
Owner Name :	SUMMERVILLE SENIOR LIVING
Owner Address :	1940 OAKDALE AVE, SAN FRANCISCO, CA 94124
Operator Name :	KURT LUTTER
Operator Address :	1940 OAKDALE AVE, SAN FRANCISCO, CA 94124
Latitude :	37.654754
Longitude :	-122.43485

Map Id: C11
Direction: ESE
Distance: 0.098 mi., 520 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : SUMMERVILLE SENIOR LIVING | WESTBOROUGH ROYALE INC
89 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946920
EPA ID: CAC002586453

HWG - CA ***(cont.)***

Facility Name :	WESTBOROUGH ROYALE INC
Facility Address :	89 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002639763
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	89 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940803162
Owner Name :	WESTBOROUGH ROYALE INC
Owner Address :	89 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940803162
Operator Name :	CHRIS VOGUE
Operator Address :	89 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940803162
Latitude :	37.65426
Longitude :	-122.435644

Map Id: 12
Direction: WSW
Distance: 0.102 mi., 537 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE
95 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 52367908
EPA ID: N/R

AST - CA

Facility Name :	California Golf Club
Facility Address :	95 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo County

Site Details

Site ID :	595565
Facility Identifer :	N/R
EPA Identifier :	CAL000463611
Facility Explorer ID :	595565
Dun and Bradsheet Number :	N/R
Regulatory Programs :	Aboveground Petroleum Storage, Chemical Storage Facilities, Hazardous Waste Generator
SIC :	N/R
NAICS :	N/R
Latitude :	37.654110

Map Id: 12
Direction: WSW
Distance: 0.102 mi., 537 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE
95 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367908
EPA ID: N/R

AST - CA ***(cont.)***

Longitude :	-122.436440
Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-02-24

Chemicals

Chemical Name :	Diesel Fuel No. 2
CAS Number :	68334-30-5
Hazard Type(s) :	-
Max Daily Amount / Unit :	600-1199 Gallons
Average Daily Amount / Unit :	120-599 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Pure

Chemical Name :	Gasoline
CAS Number :	86290-81-5
Hazard Type(s) :	-
Max Daily Amount / Unit :	600-1199 Gallons
Average Daily Amount / Unit :	120-599 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Pure

Chemical Name :	Petroleum Distillate
CAS Number :	N/R
Hazard Type(s) :	-
Max Daily Amount / Unit :	120-599 Gallons
Average Daily Amount / Unit :	60-119 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Mix

Chemical Name :	Waste Petroleum Distillate
CAS Number :	N/R
Hazard Type(s) :	-
Max Daily Amount / Unit :	12-59 Gallons
Average Daily Amount / Unit :	12-59 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Mix

CALEPA SITES - CA

Facility Name :	CALIFORNIA GOLF CLUB
Facility Address :	95 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, 94080

Site ID :	595565
EI ID :	10883212
EI Description :	Aboveground Petroleum Storage
Latitude :	37.654110

Map Id: 12
Direction: WSW
Distance: 0.102 mi., 537 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE
95 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367908
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Longitude :	-122.436440
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21
Site ID :	595565
EI ID :	10883212
EI Description :	Chemical Storage Facilities
Latitude :	37.654110
Longitude :	-122.436440
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21
Site ID :	595565
EI ID :	10883212
EI Description :	Hazardous Waste Generator
Latitude :	37.654110
Longitude :	-122.436440
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

HWG - CA

Facility Name :	CALIFORNIA GOLF CLUB OF SAN FRANCISCO
Facility Address :	95 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000463611
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	844 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	CALIFORNIA GOLF CLUB OF
Owner Address :	844 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	JEFFERSON LUMAQUIN
Operator Address :	95 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.654204
Longitude :	-122.435814

RCRA_NONGEN

Facility Name :	CALIFORNIA GOLF CLUB OF SAN FRANCISCO
Facility Address :	95 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2021-06-22
EPA ID :	CAL000463611
Mailing Address :	844 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080

Map Id: 12
Direction: WSW
Distance: 0.102 mi., 537 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE
95 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367908
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Contact :	JEFFERSON LUMAQUIN
Contact Address :	95 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	415-205-9521
Contact Email :	JEFF@CALCLUB.ORG
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	CALIFORNIA GOLF CLUB OF
Owner/Operator Address :	844 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-244-0108
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	JEFFERSON LUMAQUIN
Owner/Operator Address :	95 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-205-9521
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N

Map Id: 12
Direction: WSW
Distance: 0.102 mi., 537 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF SAN FRANCISCO - MAINTENANCE
95 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [AST - CA, CALEPA SITES - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367908
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS
849 W ORANGE AVE | 849 ORANGE
SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 52367907
EPA ID: CAC002832845

HAZNET - CA

Facility Name :	CLUB VIEW
Facility Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000032477
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1050 RALSTON AVE, BELMONT, CA 940022243
Latitude :	37.65316108
Longitude :	-122.43610308
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2014: 151 - Asbestos containing waste, 0.4 tons to CAD981382732 2013: 151 - Asbestos containing waste, 0.4 tons to CAD981382732

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS 849 W ORANGE AVE | 849 ORANGE SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

HAZNET - CA ***(cont.)***

2013: 151 - Asbestos containing waste, 0.8 tons to CAD982042475
2012: 151 - Asbestos containing waste, 0.4 tons to CAD981382732
2005: 151 - Asbestos containing waste, 2.5284 tons to CAD982042475
2000: 151 - Asbestos containing waste, 0.8428 tons to CAD981382732

Site Details

Generator EPA ID :	CAC002832845
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Latitude :	37.65316108
Longitude :	-122.43610308
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	CLUB VIEW APARTMENTS
Facility Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002858951
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Latitude :	37.65316108
Longitude :	-122.43610308
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2016: 151 - Asbestos containing waste, 0.69 tons to CAD981382732
Facility Name :	CLUB VIEW APARTMENTS
Facility Address :	849 W. ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS 849 W ORANGE AVE | 849 ORANGE SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002902032
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.65316108
Longitude :	-122.43610308
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2017: 151 - Asbestos containing waste, 0.23 tons to CAD981382732

Facility Name :	CLUBVIEW APTS. 2004
Facility Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC003076743
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65291898
Longitude :	-122.43549904
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	KORET FOUNDATION, DBA CLUBVIEW APARTMENTS
Facility Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

Site Details

Generator EPA ID :	CAC002997479
Active :	Inactive
Category :	STATE
Facility Types :	N/R

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS 849 W ORANGE AVE | 849 ORANGE SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

HAZNET - CA ***(cont.)***

Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Latitude :	37.65316108
Longitude :	-122.43610308
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2019: 151 - Asbestos containing waste, 0.23000 tons to CAD982042475

HWG - CA

Facility Name :	CLUB VIEW
Facility Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000032477
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1050 RALSTON AVE, BELMONT, CA 940022243
Owner Name :	KORET FOUNDATION
Owner Address :	1050 RALSTON AVE, BELMONT, CA 940022243
Operator Name :	KIRK OHLENDORF
Operator Address :	1050 RALSTON AVE, BELMONT, CA 940022243
Latitude :	37.652547
Longitude :	-122.436327

EPA ID :	CAC002832845
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Owner Name :	KORET FOUNDATION
Owner Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Operator Name :	KIRK OHLENDORF
Operator Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Latitude :	37.653161
Longitude :	-122.436103

Facility Name :	CLUB VIEW APARTMENTS
Facility Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS
849 W ORANGE AVE | 849 ORANGE
SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

HWG - CA ***(cont.)***

EPA ID :	CAC002858951
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Owner Name :	KORET FOUNDATION
Owner Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Operator Name :	KIRK OHLENDORF
Operator Address :	1050 RALSTON AVE, BELMONT, CA 940022210
Latitude :	37.653161
Longitude :	-122.436103

Facility Name :	CLUB VIEW APARTMENTS
Facility Address :	849 W. ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002902032
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Owner Name :	KORET FOUNDATION
Owner Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Operator Name :	KIRK OHLENDORF
Operator Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.653161
Longitude :	-122.436103

Facility Name :	CLUBVIEW APTS. 2004
Facility Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC003076743
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	RICK LATULIPPE
Owner Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	RICK LATULIPPE
Operator Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.652919
Longitude :	-122.435499

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS 849 W ORANGE AVE | 849 ORANGE SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

HWG - CA ***(cont.)***

Facility Name :	KORET FOUNDATION, DBA CLUBVIEW APARTMENTS
Facility Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
EPA ID :	CAC002997479
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Owner Name :	KORET FOUNDATION, DBA CLUBVIEW APTS
Owner Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Operator Name :	RICK LATULIPPE
Operator Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Latitude :	37.653161
Longitude :	-122.436103

RCRA_NONGEN

Facility Name :	CLUBVIEW APTS. 2004
Facility Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2020-07-28
EPA ID :	CAC003076743
Mailing Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Contact :	RICK LATULIPPE
Contact Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	650-583-7538
Contact Email :	RLATULIPPE@WRES.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	RICK LATULIPPE
Owner/Operator Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-583-7538
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS 849 W ORANGE AVE | 849 ORANGE SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

RCRA_NONGEN ***(cont.)***

Owner/Operator End Date :	N/R
Owner/Operator Name :	RICK LATULIPPE
Owner/Operator Address :	849 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-583-7538
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N
Facility Name :	KORET FOUNDATION, DBA CLUBVIEW APARTMENTS
Facility Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
Date Form Received by Agency :	2019-01-21
EPA ID :	CAC002997479
Mailing Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Contact :	RICK LATULIPPE
Contact Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	650-583-7538
Contact Email :	CLAUDIA.MIRANDA@ATIRESTORATION.COM

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS 849 W ORANGE AVE | 849 ORANGE SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

RCRA_NONGEN ***(cont.)***

EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	KORET FOUNDATION, DBA CLUBVIEW APTS
Owner/Operator Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-583-7538
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	RICK LATULIPPE
Owner/Operator Address :	849 W. ORANGE AVE, SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-583-7538
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: E13
Direction: SE
Distance: 0.102 mi., 537 ft.
Elevation: 74 ft.
Relative: Higher

Site Name : CLUBVIEW APTS. 2004 | KORET FOUNDATION, DBA CLUBVIEW APARTMENTS | CLUB VIEW APARTMENTS
849 W ORANGE AVE | 849 ORANGE
SOUTH SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367907
EPA ID: CAC002832845

RCRA_NONGEN ***(cont.)***

Notices of Violations Summary
Regulation Violated : N

Map Id: F14
Direction: NNE
Distance: 0.107 mi., 565 ft.
Elevation: 70 ft.
Relative: Higher

Site Name : GRAND AUTO | PACCAR AUTOMOTIVE, INC | CSK AUTO INC/KRAGEN AUTO PARTS #4047
1103 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 52367921
EPA ID: CAL000207795

HAZNET - CA

Facility Name : CSK AUTO INC/KRAGEN AUTO PARTS #4047
Facility Address : 1103 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

Site Details
Generator EPA ID : CAL000207795
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 645 E MISSOURI AVE STE 400, PHOENIX, AZ 850120000
Latitude : 37.65632661
Longitude : -122.43654342
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : GRAND AUTO
Facility Address : 1103 EL CAMINO REAL, S SAN FRANCISCO, CA 94080
County : SAN MATEO

Site Details
Generator EPA ID : CAL000015501
Active : Inactive
Category : STATE

Map Id: F14
Direction: NNE
Distance: 0.107 mi., 565 ft.
Elevation: 70 ft.
Relative: Higher

Site Name : GRAND AUTO | PACCAR AUTOMOTIVE, INC | CSK AUTO INC/KRAGEN AUTO PARTS #4047
1103 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367921
EPA ID: CAL000207795

HAZNET - CA ***(cont.)***

Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1103 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65632661
Longitude :	-122.43654342
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2000: 134 - Aqueous solution with total organic residues less than 10 percent, 0.2268 tons to CAT000613927
Facility Name :	PACCAR AUTOMOTIVE, INC
Facility Address :	1103 EL CAMINO REAL, SO SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAD981398415
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1400 N 4TH ST, RENTON, WA 980551535
Latitude :	37.65632661
Longitude :	-122.43654342
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

1999: 291 - Latex waste, 0.4587 tons to CAT080033681
1997: 214 - Unspecified solvent mixture, 0.0144 tons to CAD093459485
1997: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2293 tons to CAT080013352
1996: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2085 tons to CAT080013352
1995: 214 - Unspecified solvent mixture, 0.0144 tons to CAD093459485
1995: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2293 tons to CAT080013352

Map Id: F14
Direction: NNE
Distance: 0.107 mi., 565 ft.
Elevation: 70 ft.
Relative: Higher

Site Name : GRAND AUTO | PACCAR AUTOMOTIVE, INC | CSK AUTO INC/KRAGEN AUTO PARTS #4047
1103 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367921
EPA ID: CAL000207795

HWG - CA

Facility Name :	CSK AUTO INC/KRAGEN AUTO PARTS #4047
Facility Address :	1103 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000207795
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	645 E MISSOURI AVE STE 400, PHOENIX, AZ 850120000
Owner Name :	CSK AUTO INC
Owner Address :	645 E MISSOURI AVE STE 400, PHOENIX, AZ 850120000
Operator Name :	LORI BASKIND
Operator Address :	INACTIVE PER VQ00 - BMI, PHOENIX, AZ 850120000
Latitude :	37.656467
Longitude :	-122.436394

Facility Name :	GRAND AUTO
Facility Address :	1103 EL CAMINO REAL, S SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000015501
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1103 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	CORPORATION
Owner Address :	N/A
Operator Name :	INACT PER SURVEY
Operator Address :	N/A
Latitude :	37.656467
Longitude :	-122.436394

Facility Name :	PACCAR AUTOMOTIVE, INC
Facility Address :	1103 EL CAMINO REAL, SO SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAD981398415
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1400 N 4TH ST, RENTON, WA 980551535
Owner Name :	PACCAR AUTOMOTIVE, INC
Owner Address :	1400 N 4TH ST, RENTON, WA 980551535
Operator Name :	RAYMOND ELLIOTT/ENVIRO MGR
Operator Address :	INACTIVE PER VQ00 - BMI, RENTON, WA 980551535

Map Id: F14
Direction: NNE
Distance: 0.107 mi., 565 ft.
Elevation: 70 ft.
Relative: Higher

Site Name : GRAND AUTO | PACCAR AUTOMOTIVE, INC | CSK AUTO INC/KRAGEN AUTO PARTS #4047
1103 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367921
EPA ID: CAL000207795

HWG - CA ***(cont.)***

Latitude :	37.656467
Longitude :	-122.436394

Map Id: D15
Direction: NE
Distance: 0.115 mi., 610 ft.
Elevation: 61 ft.
Relative: Higher

Site Name : MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN
1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA]

Envirosite ID: 494861
EPA ID: CAC002927287

CALEPA SITES - CA

Facility Name :	MY CLEANERS (FORMER)
Facility Address :	1053 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080

Site ID :	240574
EI ID :	T10000003589
EI Description :	Cleanup Program Site
Latitude :	37.655354
Longitude :	-122.436189
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

Site ID :	671180
EI ID :	T10000003589
EI Description :	Cleanup Program Site
Latitude :	37.655354
Longitude :	-122.436189
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

HAZNET - CA

Facility Name :	DON NHAN
Facility Address :	1053 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: D15
Direction: NE
Distance: 0.115 mi., 610 ft.
Elevation: 61 ft.
Relative: Higher

Site Name : MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN
1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 494861
EPA ID: CAC002927287

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002927287
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	2900 ALEMANY BLVD, SAN FRANCISCO, CA 94112
Latitude :	37.65576578
Longitude :	-122.43546816
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2017: 151 - Asbestos containing waste, 0.23 tons to CAD981382732

Facility Name :	MY CLEANERS
Facility Address :	1053 EL CAMINO REAL STE F, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAD981655566
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1053 EL CAMINO REAL STE F, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65576578
Longitude :	-122.43546816
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	DON NHAN
Facility Address :	1053 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002927287
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R

Map Id: D15
Direction: NE
Distance: 0.115 mi., 610 ft.
Elevation: 61 ft.
Relative: Higher

Site Name : MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN
1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 494861
EPA ID: CAC002927287

HWG - CA ***(cont.)***

Mailing Address :	2900 ALEMANY BLVD, SAN FRANCISCO, CA 94112
Owner Name :	DON NHAN
Owner Address :	2900 ALEMANY BLVD, SAN FRANCISCO, CA 94112
Operator Name :	DON NHAN
Operator Address :	2900 ALEMANY BLVD, SAN FRANCISCO, CA 94112
Latitude :	37.655766
Longitude :	-122.435468

Facility Name :	MY CLEANERS
Facility Address :	1053 EL CAMINO REAL STE F, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAD981655566
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1053 EL CAMINO REAL STE F, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	SEO OK OH
Owner Address :	1053 EL CAMINO REAL STE F, SOUTH SAN FRANCISCO, CA 940800000
Operator Name :	SEO OK OH/OWNER
Operator Address :	1053 EL CAMINO REAL STE F, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65578
Longitude :	-122.43544

SLIC REG 2 - CA

Facility Name :	My Cleaners (Former)
Facility Address :	1053 El Camino Real, South San Francisco, CA 94080
County :	San Mateo

Site Details

Status Date :	2012-02-29
Status :	Open - Site Assessment
Begin Date :	2011-11-15
Global ID :	T10000003589
Region :	REGION 2
Site History :	Site opened 2/28/12
RB Case Number :	N/R
Potential Media Affected :	Aquifer used for drinking water supply, Indoor Air, Soil, Soil Vapor, Under Investigation
Potential Contaminants of Concern :	Tetrachloroethylene (PCE), Trichloroethylene (TCE), Vinyl chloride
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	559210
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	All Files are on GeoTracker or in the Local Agency Database

Map Id: D15
Direction: NE
Distance: 0.115 mi., 610 ft.
Elevation: 61 ft.
Relative: Higher

Site Name :	MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN 1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F SOUTH SAN FRANCISCO | South San Francisco, CA 94080
Database(s) :	[CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 494861
EPA ID: CAC002927287

SLIC REG 2 - CA ***(cont.)***

CUF Case :	NO
Caseworker :	JM
Case Type :	Cleanup Program Site
How Discovered :	Site Assessment/Site Investigation
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.655354
Longitude :	-122.43619
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T10000003589
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T10000003589
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2023-08-25
Global ID :	T10000003589
Action Type :	RESPONSE
Action :	Pilot Study/ Treatability Report

Map Id: D15
Direction: NE
Distance: 0.115 mi., 610 ft.
Elevation: 61 ft.
Relative: Higher

Site Name : MY CLEANERS (FORMER) | MY CLEANERS | DON NHAN
1053 EL CAMINO REAL | 1053 EL CAMINO REAL STE F
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 494861
EPA ID: CAC002927287

SLIC REG 2 - CA ***(cont.)***

Date : 2023-02-23
Global ID : T10000003589
Action Type : ENFORCEMENT
Action : Email Correspondence

Date : 2023-02-22
Global ID : T10000003589
Action Type : ENFORCEMENT
Action : Staff Letter

Date : 2022-05-16
Global ID : T10000003589
Action Type : RESPONSE
Action : Other Report / Document

Date : 2022-05-15
Global ID : T10000003589
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Status History
Status Date : 2012-02-29
Global ID : T10000003589
Status : Open - Site Assessment

Status Date : 2011-11-15
Global ID : T10000003589
Status : Open - Case Begin Date

Map Id: F16
Direction: NNW
Distance: 0.118 mi., 626 ft.
Elevation: 84 ft.
Relative: Higher

Site Name : FIONNOLA VILLAMEJOR
129 ALTA LOMA DR
SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946909
EPA ID: CAC002940669

HAZNET - CA

Facility Name : FIONNOLA VILLAMEJOR
Facility Address : 129 ALTA LOMA DR, SAN FRANCISCO, CA 94080
County : SAN FRANCISCO

Map Id: F16
Direction: NNW
Distance: 0.118 mi., 626 ft.
Elevation: 84 ft.
Relative: Higher

Site Name : FIONNOLA VILLAMEJOR
129 ALTA LOMA DR
SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946909
EPA ID: CAC002940669

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002940669
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	129 ALTA LOMA DR, SAN FRANCISCO, CA 94080
Latitude :	37.65669977
Longitude :	-122.43856984
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2017: 612 - Household waste, 0.075 tons to CAD982444481

HWG - CA

Facility Name :	FIONNOLA VILLAMEJOR
Facility Address :	129 ALTA LOMA DR, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
EPA ID :	CAC002940669
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	129 ALTA LOMA DR, SAN FRANCISCO, CA 94080
Owner Name :	FIONNOLA VILLAMEJOR
Owner Address :	129 ALTA LOMA DR, SAN FRANCISCO, CA 94080
Operator Name :	FIONNOLA VILLAMEJOR
Operator Address :	129 ALTA LOMA DR, SAN FRANCISCO, CA 94080
Latitude :	37.6567
Longitude :	-122.43857

Map Id: D17
Direction: ENE
Distance: 0.120 mi., 636 ft.
Elevation: 54 ft.
Relative: Lower

Site Name : CALTRANS DISTRICT 4 EA 04-0K6704
RTE 82 PM 19.8
SOUTH SAN FRANCISCO, CA 94083

Database(s) : [HWG - CA]

Envirosite ID: 48980763
EPA ID: CAL000468934

HWG - CA

Facility Name :	CALTRANS DISTRICT 4 EA 04-0K6704
Facility Address :	RTE 82 PM 19.8, SOUTH SAN FRANCISCO, CA 94083
County :	SAN MATEO

Map Id: D17
Direction: ENE
Distance: 0.120 mi., 636 ft.
Elevation: 54 ft.
Relative: Lower

Site Name : CALTRANS DISTRICT 4 EA 04-0K6704
RTE 82 PM 19.8
SOUTH SAN FRANCISCO, CA 94083

Database(s) : [HWG - CA] ***(cont.)***

Envirosite ID: 48980763
EPA ID: CAL000468934

HWG - CA ***(cont.)***

EPA ID :	CAL000468934
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	111 GRAND AVE FL 12, OAKLAND, CA 946123717
Owner Name :	CALTRANS
Owner Address :	1120 N STREET, SACRAMENTO, CA 95814
Operator Name :	JILL HOLLIS
Operator Address :	111 GRAND AVE, OAKLAND, CA 94612
Latitude :	37.655411
Longitude :	-122.434859

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN]

Envirosite ID: 52367937
EPA ID: CAC001257240

CALEPA SITES - CA

Facility Name :	AT&T MOBILITY - EL CAMINO REAL, WEST BURROUGH (USID24169)
Facility Address :	840 W ORANGE AVE, SOUTH SAN FRANCISCO, 94080
Site ID :	613266
EI ID :	10900153
EI Description :	Chemical Storage Facilities
Latitude :	37.652264
Longitude :	-122.436707
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Facility Name :	WEST ORANGE LIBRARY
Facility Address :	840 WEST ORANGE AVENUE, SOUTH SAN FRANCISCO, 94080
Site ID :	696989
EI ID :	T0608191183
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.653328
Longitude :	-122.436144

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

CALEPA SITES - CA ***(cont.)***

Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21
Site ID :	194858
EI ID :	T0608191183
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.653328
Longitude :	-122.436144
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

HAZNET - CA

Facility Name :	CITY OF SO SAN FRANCISCO
Facility Address :	840 WEST ORANGE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC001257240
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65284106
Longitude :	-122.43629898
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1996: 151 - Asbestos containing waste, 0.8428 tons to CAL000027741
Facility Name :	CITY OF SOUTH SAN FRANCISCO
Facility Address :	840 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002787855
Active :	Inactive

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

HAZNET - CA ***(cont.)***

Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PO BOX 711, SOUTH SAN FRANCISCO, CA 940830711
Latitude :	37.65284106
Longitude :	-122.43629898
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2014: N/R - Blank or unknown, 1.6856 tons to CAD981382732
Facility Name :	CLUB VIEW APARTMENTS
Facility Address :	840 W ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002971555
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.65284106
Longitude :	-122.43629898
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2018: 151 - Asbestos containing waste, 0.46000 tons to CAD981382732
Facility Name :	CLUBVIEW APARTMENTS
Facility Address :	840 W ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002956981
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.65284106
Longitude :	-122.43629898
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Generator EPA ID :	CAC002956984
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.65284106
Longitude :	-122.43629898
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2018: 151 - Asbestos containing waste, 0.92000 tons to CAD981382732

Facility Name :	WEST ORANGE LIBRARY
Facility Address :	840 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC001085408
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS 840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

HAZNET - CA ***(cont.)***

Latitude :	37.65284106
Longitude :	-122.43629898
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1999: 512 - Other empty containers 30 gallons or more, 5 tons to CAD009466392

HIST UST - CA

Facility Name :	WEST ORANGE LIBRARY
Facility Address :	840 WEST ORANGE, SOUTH SAN FRANCISCO, 94080
County :	San Mateo
PDF Link :	Click here for hyperlink provided by the agency.

HWG - CA

Facility Name :	CITY OF SO SAN FRANCISCO
Facility Address :	840 WEST ORANGE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC001257240
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	CITY OF SSF
Owner Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940800000
Operator Name :	FRED KAWAHARA
Operator Address :	+M, N/A
Latitude :	37.652581
Longitude :	-122.436332

Facility Name :	CITY OF SOUTH SAN FRANCISCO
Facility Address :	840 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

HWG - CA ***(cont.)***

EPA ID :	CAC002787855
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	PO BOX 711, SOUTH SAN FRANCISCO, CA 940830711
Owner Name :	CITY OF SOUTH SAN FRANCISCO
Owner Address :	PO BOX 711, SOUTH SAN FRANCISCO, CA 940830711
Operator Name :	MR. ROBERT HAHN
Operator Address :	PO BOX 711, SOUTH SAN FRANCISCO, CA 940830711
Latitude :	37.652841
Longitude :	-122.436299
Facility Name :	CLUB VIEW APARTMENTS
Facility Address :	840 W ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002971555
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Owner Name :	KORET FOUNDATION
Owner Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Operator Name :	KIRK OHLENDORF
Operator Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.652841
Longitude :	-122.436299
Facility Name :	CLUBVIEW APARTMENTS
Facility Address :	840 W ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002956984
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Owner Name :	KORET FOUNDATION
Owner Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Operator Name :	KIRK OHLENDORF
Operator Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.652841

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS 840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

HWG - CA ***(cont.)***

Longitude :	-122.436299

EPA ID :	CAC002956981
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Owner Name :	KORET FOUNDATION
Owner Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Operator Name :	KIRK OHLENDORF
Operator Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Latitude :	37.652841
Longitude :	-122.436299

Facility Name :	WEST ORANGE LIBRARY
Facility Address :	840 W ORANGE AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC001085408
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000
Owner Name :	CITY OF SOUTH SAN FRANCISCO
Owner Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000
Operator Name :	FRED KAWAHARA/CIVIL ENG
Operator Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 940830000
Latitude :	37.652581
Longitude :	-122.436332

LUST REG 2 - CA

Facility Name :	WEST ORANGE LIBRARY
Facility Address :	840 WEST ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2001-08-09
Status :	Completed - Case Closed
Begin Date :	1999-06-24
Global ID :	T0608191183
Region :	REGION 2

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS 840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

LUST REG 2 - CA ***(cont.)***

Site History :	N/R
RB Case Number :	41-1289
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Diesel
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550164
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.653328
Longitude :	-122.436144
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608191183
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608191183
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608191183
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

LUST REG 2 - CA ***(cont.)***

Organization Name : SAN MATEO COUNTY LOP
Address : 2000 ALAMEDA DE LAS PULGAS, Suite 100
City : SAN MATEO
Phone Number : 6503995959
Email : jmadden@smcgov.org

Regulatory Activities

Date : 2006-11-01
Global ID : T0608191183
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2001-07-20
Global ID : T0608191183
Action Type : RESPONSE
Action : Other Report / Document

Date : 1999-09-07
Global ID : T0608191183
Action Type : ENFORCEMENT
Action : Notice of Responsibility - #1

Date : 1999-06-24
Global ID : T0608191183
Action Type : Other
Action : Leak Reported

Status History

Status Date : 2001-08-09
Global ID : T0608191183
Status : Completed - Case Closed

Status Date : 1999-06-24
Global ID : T0608191183
Status : Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name : WEST ORANGE LIBRARY
Facility Address : 840 WEST ORANGE AVENUE, SOUTH SAN FRANCISCO, 94080
County : SAN MATEO

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Site Details

Status Date :	2001-08-09
Status :	COMPLETED - CASE CLOSED
Begin Date :	1999-06-24
Global ID :	T0608191183
Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-1289
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Diesel
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550164
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.653328
Longitude :	-122.436144
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608191183
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608191183
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Global ID :	T0608191183
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Regulatory Activities

Date :	2006-11-01
Global ID :	T0608191183
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2001-07-20
Global ID :	T0608191183
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	1999-09-07
Global ID :	T0608191183
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1

Date :	1999-06-24
Global ID :	T0608191183
Action Type :	Other
Action :	Leak Reported

Status History Summary

Status Date :	2001-08-09
Global ID :	T0608191183
Status :	Completed - Case Closed

Status Date :	1999-06-24
Global ID :	T0608191183
Status :	Open - Case Begin Date

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

RCRA_NONGEN

Facility Name :	CLUB VIEW APARTMENTS
Facility Address :	840 W ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2018-07-18
EPA ID :	CAC002971555
Mailing Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Contact :	KIRK OHLENDORF
Contact Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Contact Country :	N/R
Contact Telephone :	650-592-3960
Contact Email :	OLIVIA.LOPEZ@ATIRESTORATION.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	KIRK OHLENDORF
Owner/Operator Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-592-3960
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	KORET FOUNDATION
Owner/Operator Address :	1050 RALSTON AVENUE, BELMONT, CA 94002
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-592-3960
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: E18
Direction: SSE
Distance: 0.121 mi., 642 ft.
Elevation: 95 ft.
Relative: Higher

Site Name : WEST ORANGE LIBRARY | CLUB VIEW APARTMENTS | CLUBVIEW APARTMENTS
840 W ORANGE AVENUE | 840 WEST ORANGE AVENUE | 840 W ORANGE AVE-UNIT 1005
SOUTH SAN FRANCISCO | S. SAN FRANCISCO | SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367937
EPA ID: CAC001257240

RCRA_NONGEN ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: F19
Direction: N
Distance: 0.123 mi., 651 ft.
Elevation: 71 ft.
Relative: Higher

Site Name : WALTER & MILLIE 244 INC DBA KFC/LONG JOHN SILVER
1111 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA]

Envirosite ID: 52367919
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	WALTER & MILLIE 244 INC DBA KFC/LONG JOHN SILVER
Facility Address :	1111 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	365264
EI ID :	10661908
EI Description :	Chemical Storage Facilities
Latitude :	37.656384
Longitude :	-122.437218
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

Map Id: G20
Direction: ESE
Distance: 0.124 mi., 657 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : 1X G & K MANAGEMENT
77 WEST BOROUGH
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 52367911
EPA ID: CAC000908224

HAZNET - CA

Facility Name :	1X G & K MANAGEMENT
Facility Address :	77 WEST BOROUGH, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC000908224
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	5150 OVERLAND AVE, CULVER CITY, CA 902300000
Latitude :	37.65425315
Longitude :	-122.43553804
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X G & K MANAGEMENT
Facility Address :	77 WEST BOROUGH, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC000908224
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	5150 OVERLAND AVE, CULVER CITY, CA 902300000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	GLENN GLAZER (EXT 661)
Operator Address :	5150 OVERLAND AVE, CULVER CITY, CA 902300000
Latitude :	37.654253
Longitude :	-122.435538

Map Id: G21
Direction: ESE
Distance: 0.125 mi., 660 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : GOLDRICH KEST MANAGEMENT | FAIRWAY APARTMENTS
77 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 52367912
EPA ID: CAC002597676

HAZNET - CA

Facility Name :	FAIRWAY APARTMENTS

Map Id: G21
Direction: ESE
Distance: 0.125 mi., 660 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : GOLDRICH KEST MANAGEMENT | FAIRWAY APARTMENTS
77 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367912
EPA ID: CAC002597676

HAZNET - CA ***(cont.)***

Facility Address :	77 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002597676
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	77 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940803137
Latitude :	37.65425315
Longitude :	-122.43553804
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2005: 223 - Unspecified oil-containing waste, 0.417 tons to CAT080013352

HWG - CA

Facility Name :	FAIRWAY APARTMENTS
Facility Address :	77 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002597676
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	77 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940803137
Owner Name :	G & K MANAGEMENT
Owner Address :	5150 OVERLAND AVE, CULVER CITY, CA 902304914
Operator Name :	EMMANUEL ZUNIGA
Operator Address :	77 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940803137
Latitude :	37.654444
Longitude :	-122.435267
Facility Name :	GOLDRICH KEST MANAGEMENT
Facility Address :	77 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003214488
Status :	Active
Category :	STATE
Type :	TEMPORARY

Map Id: G21
Direction: ESE
Distance: 0.125 mi., 660 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : GOLDRICH KEST MANAGEMENT | FAIRWAY APARTMENTS
77 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367912
EPA ID: CAC002597676

HWG - CA ***(cont.)***

Facility Type :	N/R
Mailing Address :	5150 OVERLAND AVENUE, CULVER CITY, CA 902304914
Owner Name :	GOLDRICH KEST MANAGEMENT
Owner Address :	5150 OVERLAND AVENUE, CULVER CITY, CA 902304914
Operator Name :	SHAHLA ESHAGHIAN
Operator Address :	5150 OVERLAND AVENUE, CULVER CITY, CA 902304914
Latitude :	37.653552
Longitude :	-122.434809

RCRA_NONGEN

Facility Name :	GOLDRICH KEST MANAGEMENT
Facility Address :	77 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2023-01-26
EPA ID :	CAC003214488
Mailing Address :	5150 OVERLAND AVENUE, CULVER CITY, CA 90230-4914
Contact :	SHAHLA ESHAGHIAN
Contact Address :	5150 OVERLAND AVENUE, CULVER CITY, CA 90230-4914
Contact Country :	N/R
Contact Telephone :	408-296-1212
Contact Email :	SESHANGHIAN@GOLDRICHKEST.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	GOLDRICH KEST MANAGEMENT
Owner/Operator Address :	5150 OVERLAND AVENUE, CULVER CITY, CA 90230-4914
Owner/Operator Country :	N/R
Owner/Operator Telephone :	408-296-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	SHAHLA ESHAGHIAN
Owner/Operator Address :	5150 OVERLAND AVENUE, CULVER CITY, CA 90230-4914
Owner/Operator Country :	N/R
Owner/Operator Telephone :	408-296-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R

Map Id: G21
Direction: ESE
Distance: 0.125 mi., 660 ft.
Elevation: 53 ft.
Relative: Lower

Site Name : GOLDRICH KEST MANAGEMENT | FAIRWAY APARTMENTS
77 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367912
EPA ID: CAC002597676

RCRA_NONGEN ***(cont.)***

Owner/Operator End Date : N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated : N

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 52367889
EPA ID: CAX000047142

CALEPA SITES - CA

Facility Name :	WESTBOROUGH KWIK SERV
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, 94080
Site ID :	171142
EI ID :	10066147
EI Description :	Chemical Storage Facilities
Latitude :	37.654867
Longitude :	-122.434390

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

CALEPA SITES - CA ***(cont.)***

Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-04-07

Site ID : 171142
EI ID : 10066147
EI Description : Underground Storage Tank
Latitude : 37.654867
Longitude : -122.434390
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-04-07

Facility Name : WESTBOROUGH PETROLEUM INC
Facility Address : 1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, 94080

Site ID : 605350
EI ID : 10890004
EI Description : Chemical Storage Facilities
Latitude : 37.654923
Longitude : -122.434456
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-07-21

Site ID : 605350
EI ID : 10890004
EI Description : Underground Storage Tank
Latitude : 37.654923
Longitude : -122.434456
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-07-21

Site ID : 605350
EI ID : 10890004
EI Description : Hazardous Waste Generator
Latitude : 37.654923
Longitude : -122.434456
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-07-21

FID UST - CA

Facility Name : WESTBOROUGH KWIK SERV
Facility Address : 1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, 94080
County : San Mateo

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

FID UST - CA ***(cont.)***

Installation Date :	1983-01-01
Facility ID :	210515_017716
CERSID :	10066147
Permitting Agency :	San Mateo County Environmental Health
Latitude :	37.654867
Longitude :	-122.434392
Last Date in Agency List :	2023-09-22
Facility Name :	WESTBOROUGH PETROLEUM INC
Facility Address :	1 Westborough Blvd, South San Francisco, 94080
County :	San Mateo
Installation Date :	1983-01-01
Facility ID :	N/R
CERSID :	10890004
Permitting Agency :	San Mateo County Environmental Health
Latitude :	37.65468
Longitude :	-122.43441
Last Date in Agency List :	2023-09-22

HAZNET - CA

Facility Name :	1X CHEVRON STN #0381
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAX000047142
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	--, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65495406
Longitude :	-122.43437963
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	CHEVRON 90381
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000029690
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PO BOX 6004, SAN RAMON, CA 945830000
Latitude :	37.65495409
Longitude :	-122.43437963
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2003: 134 - Aqueous solution with total organic residues less than 10 percent, 0.42 tons to CAD009452657
2002: 134 - Aqueous solution with total organic residues less than 10 percent, 0.4704 tons to CAD009452657
2002: 134 - Aqueous solution with total organic residues less than 10 percent, 0.0714 tons to CAD009452657
2001: 134 - Aqueous solution with total organic residues less than 10 percent, 0.231 tons to CAD009452657
2000: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2752 tons to CAD009452657
1999: 133 - Aqueous solution with total organic residues 10 percent or more, 0.0458 tons to CAD009452657
1999: 133 - Aqueous solution with total organic residues 10 percent or more, 0.3502 tons to CAD009452657
1998: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.), 0.6046 tons to CAD009452657
1997: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.), 0.6672 tons to CAD009452657
1996: 513 - Empty containers less than 30 gallons, 0.25 tons to CAD009466392
1995: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.), 0.6672 tons to CAD009452657

Facility Name :	Chevron Station 90381
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAR000116624
Active :	Inactive
Category :	FEDERAL

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

HAZNET - CA ***(cont.)***

Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PO BOX 6004, SAN RAMON, CA 945830000
Latitude :	37.65495406
Longitude :	-122.43437963
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2004: 134 - Aqueous solution with total organic residues less than 10 percent, 0.2394 tons to CAD009452657 2004: 352 - Other organic solids, 0.015 tons to CAD982444481 2003: 133 - Aqueous solution with total organic residues 10 percent or more, 0.17931 tons to CAD009452657

Facility Name :	WESTBOROUGH LLC
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000223419
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65495409
Longitude :	-122.43437963
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2019: 223 - Unspecified oil-containing waste, 0.41700 tons to CAT080012602 2018: 352 - Other organic solids, 0.10000 tons to CAD097030993 2018: 223 - Unspecified oil-containing waste, 0.12510 tons to CAT080012602 2018: 223 - Unspecified oil-containing waste, 0.20850 tons to CAT080013352

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

HAZNET - CA ***(cont.)***

2017: 223 - Unspecified oil-containing waste, 0.7089 tons to CAT080012602
2016: 223 - Unspecified oil-containing waste, 0.2085 tons to CAT080012602
2015: 223 - Unspecified oil-containing waste, 0.1251 tons to CAT080013352
2015: 352 - Other organic solids, 0.0925 tons to CAD097030993
2014: 223 - Unspecified oil-containing waste, 0.1668 tons to CAT080012602
2013: 223 - Unspecified oil-containing waste, 0.27105 tons to CAT080012602
2010: 352 - Other organic solids, 0.0125 tons to CAD028409019
2010: 223 - Unspecified oil-containing waste, 0.22935 tons to CAD044003556
2009: 223 - Unspecified oil-containing waste, 0.22935 tons to NVD982358483
2007: 223 - Unspecified oil-containing waste, 0.22935 tons to CAL000161743
2005: 223 - Unspecified oil-containing waste, 0.68805 tons to CAL000161743

HIST UST - CA

Facility Name :	90381
Facility Address :	1 WESTBOROUGH BLVD, SO SAN FRANCISCO, 94080
County :	San Mateo
PDF Link :	Click here for hyperlink provided by the agency.

HWG - CA

Facility Name :	1X CHEVRON STN #0381
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAX000047142
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	AIDA GOMES
Operator Address :	N/A
Latitude :	37.655073
Longitude :	-122.43444

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

HWG - CA ***(cont.)***

Facility Name :	CHEVRON 90381
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000029690
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	PO BOX 6004, SAN RAMON, CA 945830000
Owner Name :	CHERVON PRODUCTS CO
Owner Address :	PO BOX 6004, SAN RAMON, CA 945830000
Operator Name :	KATHY NORRIS
Operator Address :	PO BOX 6004, SAN RAMON, CA 945830000
Latitude :	37.655073
Longitude :	-122.43444
Facility Name :	Chevron Station 90381
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAR000116624
Status :	Inactive
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	PO BOX 6004, SAN RAMON, CA 945830000
Owner Name :	CHEVRON
Owner Address :	PO BOX 6004, SAN RAMON, CA 945830000
Operator Name :	KATHY NORRIS-SLUSHER
Operator Address :	6101 BOLLINGER CANYON RD., SAN RAMON, CA 94583
Latitude :	37.65502
Longitude :	-122.43434
Facility Name :	WESTBOROUGH LLC
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000223419
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	WESTBOROUGH LLC
Owner Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 940800000

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

HWG - CA ***(cont.)***

Operator Name :	CHARLES ZANETTI - OWNER
Operator Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.655073
Longitude :	-122.43444

Facility Name :	WESTBROUGH PETROLEUM INC
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL000471177
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	6756 N WINTON WAY, WINTON, CA 95388
Owner Name :	EZ PETROLEUM
Owner Address :	6756 N WINTON WAY, WINTON, CA 95388
Operator Name :	HAMDI ALZGHOUL
Operator Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.654706
Longitude :	-122.434401

EPA ID :	CAC003177208
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	510 MYRTLE AVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	HAMDI ALZGHOUL
Owner Address :	510 MYRTLE AVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	HAMDI ALZGHOUL
Operator Address :	510 MYRTLE AVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.654706
Longitude :	-122.434401

RCRA_NONGEN

Facility Name :	CHEVRON STATION 90381
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080-3162
County :	SAN MATEO

Date Form Received by Agency :	2013-03-13
EPA ID :	CAR000116624
Mailing Address :	PO BOX 6004, SAN RAMON, CA 94583
Contact :	KATHY NORRIS SLUSHER
Contact Address :	PO BOX 6004, SAN RAMON, CA 94583
Contact Country :	US

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

RCRA_NONGEN ***(cont.)***

Contact Telephone :	877-386-6044
Contact Email :	NAWTDESK@CHEVRON.COM
EPA Region :	09
Land Type :	Private
Source Type :	Notification
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	CHEVRON USA
Owner/Operator Address :	PO BOX 6004, SAN RAMON, CA 94583
Owner/Operator Country :	US
Owner/Operator Telephone :	877-386-6044
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	2009-07-20
Owner/Operator End Date :	N/R

Owner/Operator Name :	KATHY NORRIS SLUSHER
Owner/Operator Address :	N/R
Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	2009-07-20
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

RCRA_NONGEN ***(cont.)***

Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Historical Generators

Date Form Received by Agency :	2002-05-16
Facility Name :	CHEVRON STATION 90381
Classification :	Small Quantity Generator

Notices of Violations Summary

Regulation Violated :	N

Facility Name :	WESTBOROUGH LLC
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080-0000
County :	SAN MATEO

Date Form Received by Agency :	2001-05-15
EPA ID :	CAL000223419
Mailing Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080-0000
Contact :	CHARLES ZANETTI - OWNER
Contact Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	650-952-5807
Contact Email :	CHEV702@AOL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	CHARLES ZANETTI - OWNER
Owner/Operator Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-952-5807
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

RCRA_NONGEN ***(cont.)***

Owner/Operator Name :	WESTBOROUGH LLC
Owner/Operator Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-952-5807
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Facility Name :	WESTBROUGH PETROLEUM INC
Facility Address :	1 WESTBOROUGH BLVD, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Date Form Received by Agency :	2022-06-08
EPA ID :	CAL000471177
Mailing Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Contact :	MOHAMMAD ALZGHOUL
Contact Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	650-634-8449
Contact Email :	ABED@CASYNERGY.COM
EPA Region :	09
Land Type :	Not Reported

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

RCRA_NONGEN ***(cont.)***

Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	MOHAMMAD ALZGHOUL
Owner/Operator Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-634-8449
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	WESTBROUGH PETROLEUM INC
Owner/Operator Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-634-8449
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

RCRA_NONGEN ***(cont.)***

Notices of Violations Summary

Regulation Violated :	N
Date Form Received by Agency :	2022-05-20
EPA ID :	CAC003177208
Mailing Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Contact :	HAMDI ALZGHOUL
Contact Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	650-634-8449
Contact Email :	ABED@CASYNERGY.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	HAMDI ALZGHOUL
Owner/Operator Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-634-8449
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	HAMDI ALZGHOUL
Owner/Operator Address :	510 MYRTLE AVE #209, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-634-8449
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N

Map Id: H22
Direction: E
Distance: 0.126 mi., 665 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : WESTBOROUGH KWIK SERV | WESTBOROUGH LLC | WESTBROUGH PETROLEUM INC
1 WESTBOROUGH BLVD
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, FID UST - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367889
EPA ID: CAX000047142

RCRA_NONGEN ***(cont.)***

Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: F23
Direction: N
Distance: 0.129 mi., 682 ft.
Elevation: 72 ft.
Relative: Higher

Site Name : CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)
1121 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO. SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA]

Envirosite ID: 52367920
EPA ID: CAD082444191

CALEPA SITES - CA

Facility Name :	CARRIAGE CLEANERS
Facility Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	458059
EI ID :	110010466995
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	37.656553
Longitude :	-122.436770
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21
Facility Name :	CARRIAGE CLEANERS (FORMER)
Facility Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080

Map Id: F23
Direction: N
Distance: 0.129 mi., 682 ft.
Elevation: 72 ft.
Relative: Higher

Site Name : CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)
1121 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO. SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367920
EPA ID: CAD082444191

CALEPA SITES - CA ***(cont.)***

Site ID :	246116
EI ID :	T10000005163
EI Description :	Cleanup Program Site
Latitude :	37.656597
Longitude :	-122.437031
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

Site ID :	642051
EI ID :	T10000005163
EI Description :	Cleanup Program Site
Latitude :	37.656597
Longitude :	-122.437031
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

HAZNET - CA

Facility Name :	CARRIAGE CLEANERS
Facility Address :	1121 EL CAMINO REAL, SO. SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

Site Details

Generator EPA ID :	CAD082444191
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1121 EL CAMINO REAL, SO.SAN FRANCISCO, CA 940800000
Latitude :	37.65652060
Longitude :	-122.43683776
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	CARRIAGE CLEANERS
Facility Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000265661
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT

Map Id: F23
Direction: N
Distance: 0.129 mi., 682 ft.
Elevation: 72 ft.
Relative: Higher

Site Name : CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)
1121 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO. SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367920
EPA ID: CAD082444191

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803207
Latitude :	37.65652060
Longitude :	-122.43683776
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Generator EPA ID :	CAL000013353
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803207
Latitude :	37.65652060
Longitude :	-122.43683776
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
2002: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.1251 tons to CAT080014079
2002: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, tons to CAT080014079
2002: 331 - Off-specification, aged or surplus organics, tons to CAT080014079
2001: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.3358 tons to CAT080014079

Facility Name :	CARRIAGE CLEANERS
Facility Address :	1121 EL CAMINO REAL, S SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000045526
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1121 EL CAMINO REAL, S SAN FRANCISCO, CA 940800000
Latitude :	37.65652060
Longitude :	-122.43683776

Map Id: F23
Direction: N
Distance: 0.129 mi., 682 ft.
Elevation: 72 ft.
Relative: Higher

Site Name : CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)
1121 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO. SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367920
EPA ID: CAD082444191

HAZNET - CA ***(cont.)***

Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	CARRIAGE CLEANERS
Facility Address :	1121 EL CAMINO REAL, SO. SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
EPA ID :	CAD082444191
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1121 EL CAMINO REAL, SO.SAN FRANCISCO, CA 940800000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	INACTIVE PER SURVEY 3-15-95LH
Operator Address :	N/A
Latitude :	37.656736
Longitude :	-122.436788

Facility Name :	CARRIAGE CLEANERS
Facility Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000013353
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803207
Owner Name :	KITWU HOM C
Owner Address :	N/A
Operator Name :	N/R
Operator Address :	INACT PER 98VQ FINAL NOTICE, N/A
Latitude :	37.656736
Longitude :	-122.436788

EPA ID :	CAL000265661
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803207
Owner Name :	SUK KIM
Owner Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803207
Operator Name :	ALEX YI

Map Id: F23
Direction: N
Distance: 0.129 mi., 682 ft.
Elevation: 72 ft.
Relative: Higher

Site Name : CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)
1121 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO. SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367920
EPA ID: CAD082444191

HWG - CA ***(cont.)***

Operator Address :	1121 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803207
Latitude :	37.656736
Longitude :	-122.436788
Facility Name :	CARRIAGE CLEANERS
Facility Address :	1121 EL CAMINO REAL, S SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000045526
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1121 EL CAMINO REAL, S SAN FRANCISCO, CA 940800000
Owner Name :	HOM KIT W C
Owner Address :	N/A
Operator Name :	INACTIVE PER SURVEY 3-15-95LH
Operator Address :	N/A
Latitude :	37.656736
Longitude :	-122.436788

SLIC REG 2 - CA

Facility Name :	Carriage Cleaners (Former)
Facility Address :	1121 El Camino Real, South San Francisco, CA 94080
County :	San Mateo

Site Details

Status Date :	2013-09-19
Status :	Open - Site Assessment
Begin Date :	2013-01-09
Global ID :	T10000005163
Region :	REGION 2
Site History :	Site opened 9/19/2013. Out of compliance. RP unresponsive.
RB Case Number :	N/R
Potential Media Affected :	Under Investigation
Potential Contaminants of Concern :	Tetrachloroethylene (PCE), Trichloroethylene (TCE), Vinyl chloride
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	559212
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	All Files are on GeoTracker or in the Local Agency Database
CUF Case :	NO
Caseworker :	JM
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R

Map Id: F23
Direction: N
Distance: 0.129 mi., 682 ft.
Elevation: 72 ft.
Relative: Higher

Site Name : CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)
1121 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO. SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367920
EPA ID: CAD082444191

SLIC REG 2 - CA ***(cont.)***

Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.656597
Longitude :	-122.437032
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T10000005163
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T10000005163
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2022-02-04
Global ID :	T10000005163
Action Type :	RESPONSE
Action :	Site Assessment Report

Date :	2021-10-14
Global ID :	T10000005163
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2021-09-07
Global ID :	T10000005163

Map Id: F23
Direction: N
Distance: 0.129 mi., 682 ft.
Elevation: 72 ft.
Relative: Higher

Site Name : CARRIAGE CLEANERS | CARRIAGE CLEANERS (FORMER)
1121 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO. SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367920
EPA ID: CAD082444191

SLIC REG 2 - CA ***(cont.)***

Action Type : ENFORCEMENT
Action : Voluntary Remedial Action Agreement

Date : 2021-08-18
Global ID : T10000005163
Action Type : ENFORCEMENT
Action : Email Correspondence

Date : 2021-07-16
Global ID : T10000005163
Action Type : RESPONSE
Action : Soil and Water Investigation Workplan - Regulator Responded

Status History
Status Date : 2013-09-19
Global ID : T10000005163
Status : Open - Site Assessment

Status Date : 2013-01-09
Global ID : T10000005163
Status : Open - Case Begin Date

Map Id: H24
Direction: E
Distance: 0.131 mi., 694 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : 1X 1ST NT'L BANK OF DALY CITY
975 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HIST HAZNET - CA, HWG - CA]

Envirosite ID: 52367887
EPA ID: CAC000694456

HAZNET - CA

Facility Name : 1X 1ST NT'L BANK OF DALY CITY
Facility Address : 975 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

Site Details
Generator EPA ID : CAC000694456
Active : Inactive
Category : STATE

Map Id: H24
Direction: E
Distance: 0.131 mi., 694 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : 1X 1ST NT'L BANK OF DALY CITY
975 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HIST HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367887
EPA ID: CAC000694456

HAZNET - CA ***(cont.)***

Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	--, COLMA, CA 941040000
Latitude :	37.65452225
Longitude :	-122.43382319
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HIST HAZNET - CA

Facility Name :	1X 1ST NT'L BANK OF DALY CITY
Facility Address :	975 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
ID Number :	CAC000694456
Last Date in Agency List :	2014-11-17

HWG - CA

Facility Name :	1X 1ST NT'L BANK OF DALY CITY
Facility Address :	975 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC000694456
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	COLMA, CA 941040000
Owner Name :	CORP
Owner Address :	N/A
Operator Name :	GROFT, JEANNE
Operator Address :	N/A
Latitude :	37.65491
Longitude :	-122.434231

Map Id: I25
Direction: W
Distance: 0.135 mi., 713 ft.
Elevation: 79 ft.
Relative: Higher

Site Name : ELIZABETH BARTHE
105 INDIO DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946902
EPA ID: CAC002568356

HAZNET - CA

Facility Name :	ELIZABETH BARTHE
Facility Address :	105 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: I25
Direction: W
Distance: 0.135 mi., 713 ft.
Elevation: 79 ft.
Relative: Higher

Site Name : ELIZABETH BARTHE
105 INDIO DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946902
EPA ID: CAC002568356

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002568356
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	105 INDIO DR, S SAN FRAN, CA 94080
Latitude :	37.65456151
Longitude :	-122.44059776
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2003: 151 - Asbestos containing waste, 0.8428 tons to CAD981382732

HWG - CA

Facility Name :	ELIZABETH BARTHE
Facility Address :	105 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002568356
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	105 INDIO DR, S SAN FRAN, CA 94080
Owner Name :	ELIZABETH BARTHE
Owner Address :	105 INDIO DR, S SAN FRAN, CA 94080
Operator Name :	ELIZABETH BARTHE
Operator Address :	105 INDIO DR, S SAN FRAN, CA 94080
Latitude :	37.654383
Longitude :	-122.440222

Map Id: D26
Direction: NE
Distance: 0.141 mi., 745 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL
1010 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRAN | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA]

Envirosite ID: 52367892
EPA ID: CAC003113979

CALEPA SITES - CA

Facility Name : 1010 EL CAMINO REAL
Facility Address : 1010 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080

Site ID : 600944
EI ID : T10000014438
EI Description : Cleanup Program Site
Latitude : 37.656040
Longitude : -122.435200
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-12-21

Site ID : 630136
EI ID : T10000014438
EI Description : Cleanup Program Site
Latitude : 37.656040
Longitude : -122.435200
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-07-21

Facility Name : COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC
Facility Address : 1010 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080

Site ID : 580713
EI ID : 879284
EI Description : Construction Storm Water
Latitude : 37.656050
Longitude : -122.435210
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-07-21

HAZNET - CA

Facility Name : CITY OF SOUTH SAN FRANCISCO
Facility Address : 1010 EL CAMINO REAL, S SAN FRAN, CA 94080
County : SAN MATEO

Site Details
Generator EPA ID : CAC002944175
Active : Inactive
Category : STATE
Facility Types : N/R
Type : TEMPORARY
Contact Name : N/R
Contact Phone : N/R

Map Id: D26
Direction: NE
Distance: 0.141 mi., 745 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL
1010 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRAN | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367892
EPA ID: CAC003113979

HAZNET - CA ***(cont.)***

Facility Mailing Address :	400 GRAND AVENUE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65588508
Longitude :	-122.43511547
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2018: 611 - Contaminated soil from site clean-up, 0.17000 tons to NVT330010000

HWG - CA

Facility Name :	CITY OF SOUTH SAN FRANCISCO
Facility Address :	1010 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003113979
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	550 N. CANAL STREET, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	JACOB GILCHRIST
Owner Address :	550 NORTH CANAL STREET, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	JACOB GILCHRIST
Operator Address :	550 NORTH CANAL STREET, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65599
Longitude :	-122.43514

Facility Name :	CITY OF SOUTH SAN FRANCISCO
Facility Address :	1010 EL CAMINO REAL, S SAN FRAN, CA 94080
County :	SAN MATEO
EPA ID :	CAC002944175
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	400 GRAND AVENUE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	CITY OF SOUTH SAN FRANISCO
Owner Address :	400 GRAND AVENUE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	MARIAN LEE
Operator Address :	400 GRAND AVENUE, SOUTH SAN FRANCISCO, CA 94080

Map Id: D26
Direction: NE
Distance: 0.141 mi., 745 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL
1010 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRAN | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367892
EPA ID: CAC003113979

HWG - CA ***(cont.)***

Latitude :	37.655885
Longitude :	-122.435115

RCRA_NONGEN

Facility Name :	CITY OF SOUTH SAN FRANCISCO
Facility Address :	1010 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2021-04-08
EPA ID :	CAC003113979
Mailing Address :	550 N. CANAL STREET, SOUTH SAN FRANCISCO, CA 94080
Contact :	JACOB GILCHRIST
Contact Address :	550 NORTH CANAL STREET, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	650-877-8552
Contact Email :	JACOB.GILCHRIST@SSF.NET
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	JACOB GILCHRIST
Owner/Operator Address :	550 NORTH CANAL STREET, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-877-8552
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	JACOB GILCHRIST
Owner/Operator Address :	550 NORTH CANAL STREET, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-877-8552
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: D26
Direction: NE
Distance: 0.141 mi., 745 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL
1010 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRAN | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367892
EPA ID: CAC003113979

RCRA_NONGEN ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

SLIC REG 2 - CA

Facility Name :	1010 El Camino Real
Facility Address :	1010 El Camino Real, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2020-06-10
Status :	Open - Long Term Management
Begin Date :	2020-04-21
Global ID :	T10000014438
Region :	REGION 2
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	Tetrachloroethylene (PCE)
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	559233
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	N/R
CUF Case :	NO
Caseworker :	JM
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R

Map Id: D26
Direction: NE
Distance: 0.141 mi., 745 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL
1010 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRAN | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367892
EPA ID: CAC003113979

SLIC REG 2 - CA ***(cont.)***

Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.65604
Longitude :	-122.4352
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T10000014438
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2021-12-15
Global ID :	T10000014438
Action Type :	RESPONSE
Action :	Other Report / Document - Regulator Responded

Date :	2021-05-15
Global ID :	T10000014438
Action Type :	RESPONSE
Action :	Other Workplan

Date :	2021-02-05
Global ID :	T10000014438
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2021-01-14
Global ID :	T10000014438
Action Type :	RESPONSE

Map Id: D26
Direction: NE
Distance: 0.141 mi., 745 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | COMMUNITY CIVIC CAMPUS PHASE II LIBRARY PARKS & REC | 1010 EL CAMINO REAL
1010 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRAN | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367892
EPA ID: CAC003113979

SLIC REG 2 - CA ***(cont.)***

Action : Well Destruction Workplan

Date : 2020-09-24
Global ID : T10000014438
Action Type : ENFORCEMENT
Action : Voluntary Remedial Action Agreement

Status History
Status Date : 2020-06-10
Global ID : T10000014438
Status : Open - Long Term Management

Status Date : 2020-04-22
Global ID : T10000014438
Status : Pending Review

Status Date : 2020-04-21
Global ID : T10000014438
Status : Open - Case Begin Date

Map Id: F27
Direction: N
Distance: 0.148 mi., 780 ft.
Elevation: 71 ft.
Relative: Higher

Site Name : LEUNG & ABAYA DENTAL OFFICE | MARILYN SY DDS | DR. EDEN JAOCHICO DENTAL SERVICES, INC
1133 EL CAMINO | 1133 EL CAMINO REAL | 1133 EL CAMINO REAL STE 3
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946905
EPA ID: CAL000139497

HAZNET - CA

Facility Name : DR. EDEN JAOCHICO DENTAL SERVICES, INC
Facility Address : 1133 EL CAMINO REAL STE 3, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

Map Id: F27
Direction: N
Distance: 0.148 mi., 780 ft.
Elevation: 71 ft.
Relative: Higher

Site Name : LEUNG & ABAYA DENTAL OFFICE | MARILYN SY DDS | DR. EDEN JAOCHICO DENTAL SERVICES, INC
1133 EL CAMINO | 1133 EL CAMINO REAL | 1133 EL CAMINO REAL STE 3
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946905
EPA ID: CAL000139497

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000139497
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1133 EL CAMINO REAL STE 3, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65664993
Longitude :	-122.43703399
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
1999: N/R - Blank or unknown, 0 tons to CAL000175030
1999: 343 - Unspecified organic liquid mixture, 0.0102 tons to CAL000175030
1999: 723 - Liquids with chromium (VI) >= 500 Mg./L, 0.0083 tons to CAL000175030
1998: 343 - Unspecified organic liquid mixture, 0.0136 tons to CAL000082530
1998: N/R - Blank or unknown, 0 tons to CAL000082530
1998: 541 - Photochemicals/photoprocessing waste, 0.0124 tons to CAL000082530

Facility Name :	LEUNG & ABAYA DENTAL OFFICE
Facility Address :	1133 EL CAMINO, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000140643
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1133 EL CAMINO, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65664993
Longitude :	-122.43703399
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
1999: 343 - Unspecified organic liquid mixture, 0.0068 tons to CAL000175030

Map Id: F27
Direction: N
Distance: 0.148 mi., 780 ft.
Elevation: 71 ft.
Relative: Higher

Site Name : LEUNG & ABAYA DENTAL OFFICE | MARILYN SY DDS | DR. EDEN JAOCHICO DENTAL SERVICES, INC
1133 EL CAMINO | 1133 EL CAMINO REAL | 1133 EL CAMINO REAL STE 3
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946905
EPA ID: CAL000139497

HAZNET - CA ***(cont.)***

1999: 343 - Unspecified organic liquid mixture, 0.0034 tons to CAL000082530
1999: N/R - Blank or unknown, 0 tons to CAL000175030
1999: N/R - Blank or unknown, 0 tons to CAL000082530

Facility Name :	MARILYN SY DDS
Facility Address :	1133 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000177316
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1133 EL CAMINO REAL STE 5, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65664993
Longitude :	-122.43703399
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	DR. EDEN JAOCHICO DENTAL SERVICES, INC
Facility Address :	1133 EL CAMINO REAL STE 3, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL000139497
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1133 EL CAMINO REAL STE 3, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	REDENCION JAOCHICO DMD
Owner Address :	1133 EL CAMINO REAL STE 3, SOUTH SAN FRANCISCO, CA 940800000
Operator Name :	REDENCION JAOCHICO -OWNER
Operator Address :	1133 EL CAMINO REAL STE 3, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.656615
Longitude :	-122.437068

Facility Name :	LEUNG & ABAYA DENTAL OFFICE
Facility Address :	1133 EL CAMINO, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: F27
Direction: N
Distance: 0.148 mi., 780 ft.
Elevation: 71 ft.
Relative: Higher

Site Name : LEUNG & ABAYA DENTAL OFFICE | MARILYN SY DDS | DR. EDEN JAOCHICO DENTAL SERVICES, INC
1133 EL CAMINO | 1133 EL CAMINO REAL | 1133 EL CAMINO REAL STE 3
SOUTH SAN FRANCISCO, CA 94080
Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946905
EPA ID: CAL000139497

HWG - CA ***(cont.)***

EPA ID :	CAL000140643
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1133 EL CAMINO, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	DR LEUNG & DR ABAYA
Owner Address :	1133 EL CAMINO REAL #4, SSF, CA 940800000
Operator Name :	SAM LEUNG-PARTNER
Operator Address :	1133 EL CAMINO, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.656915
Longitude :	-122.437051

Facility Name :	MARILYN SY DDS
Facility Address :	1133 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL000177316
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1133 EL CAMINO REAL STE 5, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	MARILYN SY DDS
Owner Address :	1133 EL CAMINO REAL STE 5, SOUTH SAN FRANCISCO, CA 940800000
Operator Name :	MARILYN SY
Operator Address :	1133 EL CAMINO REAL STE 5, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65668
Longitude :	-122.43703

Map Id: J28
Direction: WNW
Distance: 0.149 mi., 785 ft.
Elevation: 104 ft.
Relative: Higher

Site Name : FIKRET ASHKAR
127 CAMARITAS AVE
SOUTH SAN FRANCISCO, CA 94080
Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946908
EPA ID: CAC002617482

HAZNET - CA

Facility Name :	FIKRET ASHKAR
Facility Address :	127 CAMARITAS AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: J28
Direction: WNW
Distance: 0.149 mi., 785 ft.
Elevation: 104 ft.
Relative: Higher

Site Name : FIKRET ASHKAR
127 CAMARITAS AVE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946908
EPA ID: CAC002617482

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002617482
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	127 CAMARITAS AVE, SOUTH SAN FRANCISCO, CA 940803156
Latitude :	37.65594846
Longitude :	-122.44019077
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	FIKRET ASHKAR
Facility Address :	127 CAMARITAS AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002617482
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	127 CAMARITAS AVE, SOUTH SAN FRANCISCO, CA 940803156
Owner Name :	FIKRET ASHKAR
Owner Address :	127 CAMARITAS AVE, SOUTH SAN FRANCISCO, CA 940803156
Operator Name :	FIKRET ASHKAR
Operator Address :	127 CAMARITAS AVE, SOUTH SAN FRANCISCO, CA 940803156
Latitude :	37.655998
Longitude :	-122.44013

Map Id: H29
Direction: E
Distance: 0.155 mi., 820 ft.
Elevation: 47 ft.
Relative: Lower

Site Name : BANK OF AMERICA
955 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 52367901
EPA ID: CAC002615090

HAZNET - CA

Facility Name :	BANK OF AMERICA
Facility Address :	955 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002615090
Active :	Inactive

Map Id: H29
Direction: E
Distance: 0.155 mi., 820 ft.
Elevation: 47 ft.
Relative: Lower

Site Name : BANK OF AMERICA
955 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367901
EPA ID: CAC002615090

HAZNET - CA ***(cont.)***

Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1455 MARKET ST FL 14, SAN FRANCISCO, CA 92823
Latitude :	37.65413419
Longitude :	-122.43340819
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2007: 151 - Asbestos containing waste, 0.4 tons to CAD982042475

HWG - CA

Facility Name :	BANK OF AMERICA
Facility Address :	955 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002615090
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1455 MARKET ST FL 14, SAN FRANCISCO, CA 92823
Owner Name :	BANK OF AMERICA
Owner Address :	1455 MARKET ST FL 14, SAN FRANCISCO, CA 92823
Operator Name :	GERALD TUGEDE
Operator Address :	1455 MARKET ST FL 14, SAN FRANCISCO, CA 92823
Latitude :	37.654136
Longitude :	-122.433364

Map Id: I30
Direction: W
Distance: 0.156 mi., 823 ft.
Elevation: 76 ft.
Relative: Higher

Site Name : WININA MONTERO
102 ALTA MESA DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946901
EPA ID: CAC002753745

HAZNET - CA

Facility Name :	WININA MONTERO
Facility Address :	102 ALTA MESA DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: I30
Direction: W
Distance: 0.156 mi., 823 ft.
Elevation: 76 ft.
Relative: Higher

Site Name : WININA MONTERO
102 ALTA MESA DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946901
EPA ID: CAC002753745

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002753745
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	102 ALTA MESA DR, SOUTH SAN FRANCISCO, CA 940804152
Latitude :	37.65391148
Longitude :	-122.44103156
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	WININA MONTERO
Facility Address :	102 ALTA MESA DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002753745
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	102 ALTA MESA DR, SOUTH SAN FRANCISCO, CA 940804152
Owner Name :	WININA MONTERO
Owner Address :	102 ALTA MESA DR, SOUTH SAN FRANCISCO, CA 940804152
Operator Name :	WININA MONTERO
Operator Address :	102 ALTA MESA DR, SOUTH SAN FRANCISCO, CA 940804152
Latitude :	37.653911
Longitude :	-122.441032

Map Id: J31
Direction: WNW
Distance: 0.156 mi., 823 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : 4110009-015
37.655845, -122.44071
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 40228389
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	4110009-015
Dataset Name :	DDW
Well Category :	MUNICIPAL
Data Source :	DDW
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R

Map Id: J31
Direction: WNW
Distance: 0.156 mi., 823 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : 4110009-015
37.655845, -122.44071
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228389
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Alt Well ID1 :	CA4110009_015_015
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.655845
Longitude :	-122.44071
Last Date in Agency List :	2022-03-31

Chemicals

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 2 NG/L
Reporting Limit :	N/R

Map Id: J31
Direction: WNW
Distance: 0.156 mi., 823 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : 4110009-015
37.655845, -122.44071
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228389
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Chemical Name :	2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 3 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2818

Map Id: J31
Direction: WNW
Distance: 0.156 mi., 823 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : 4110009-015
37.655845, -122.44071
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228389
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 3 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2801
Source Well Depth (Ft) :	N/R

Map Id: J31
Direction: WNW
Distance: 0.156 mi., 823 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : 4110009-015
37.655845, -122.44071
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228389
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R

Map Id: J31
Direction: WNW
Distance: 0.156 mi., 823 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : 4110009-015
37.655845, -122.44071
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228389
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 2 NG/L
Reporting Limit :	N/R
Source Chemical Name :	2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Map Id: F32
Direction: NNW
Distance: 0.156 mi., 824 ft.
Elevation: 91 ft.
Relative: Higher

Site Name : CARMELA AND ART QUIAMBAO |
CARMELA AND ART QUIAMBAO 45-011217
136 ALTA LOMA DRIVE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 53946911
EPA ID: CAC003001123

HAZNET - CA

Facility Name :	CARMELA AND ART QUIAMBAO
Facility Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: F32
Direction: NNW
Distance: 0.156 mi., 824 ft.
Elevation: 91 ft.
Relative: Higher

Site Name : CARMELA AND ART QUIAMBAO | CARMELA AND ART QUIAMBAO 45-011217
136 ALTA LOMA DRIVE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 53946911
EPA ID: CAC003001123

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC003001123
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65688333
Longitude :	-122.43860001
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2019: 151 - Asbestos containing waste, 0.23000 tons to CAD981382732

HWG - CA

Facility Name :	CARMELA AND ART QUIAMBAO
Facility Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003001123
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	CARMELA AND ART QUIAMBAO
Owner Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	CARMELA AND ART QUIAMBAO
Operator Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.656883
Longitude :	-122.4386

RCRA_NONGEN

Facility Name :	CARMELA AND ART QUIAMBAO
Facility Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2019-02-14
EPA ID :	CAC003001123
Mailing Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Contact :	CARMELA AND ART QUIAMBAO
Contact Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	650-580-4694
Contact Email :	MARIAE@PWSEI.COM
EPA Region :	09

Map Id: F32
Direction: NNW
Distance: 0.156 mi., 824 ft.
Elevation: 91 ft.
Relative: Higher

Site Name : CARMELA AND ART QUIAMBAO | CARMELA AND ART QUIAMBAO 45-011217
136 ALTA LOMA DRIVE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 53946911
EPA ID: CAC003001123

RCRA_NONGEN ***(cont.)***

Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	CARMELA AND ART QUIAMBAO
Owner/Operator Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-580-4694
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	CARMELA AND ART QUIAMBAO
Owner/Operator Address :	136 ALTA LOMA DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-580-4694
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: F32
Direction: NNW
Distance: 0.156 mi., 824 ft.
Elevation: 91 ft.
Relative: Higher

Site Name : CARMELA AND ART QUIAMBAO | CARMELA AND ART QUIAMBAO 45-011217
136 ALTA LOMA DRIVE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 53946911
EPA ID: CAC003001123

RCRA_NONGEN ***(cont.)***

Notices of Violations Summary
Regulation Violated : N

Map Id: F33
Direction: NNW
Distance: 0.160 mi., 844 ft.
Elevation: 75 ft.
Relative: Higher

Site Name : NORGE VILLAGE CLEANERS (FORMER)
1155 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, SLIC REG 2 - CA]

Envirosite ID: 52367917
EPA ID: N/R

CALEPA SITES - CA

Facility Name : NORGE VILLAGE CLEANERS (FORMER)
Facility Address : 1155 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080

Site ID : 672183
EI ID : T10000007001
EI Description : Cleanup Program Site
Latitude : 37.657060
Longitude : -122.437970
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-07-21

Site ID : 277117
EI ID : T10000007001
EI Description : Cleanup Program Site
Latitude : 37.657060
Longitude : -122.437970
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-12-21

SLIC REG 2 - CA

Facility Name : Norge Village Cleaners (Former)
Facility Address : 1155 El Camino Real, South San Francisco, CA 94080
County : San Mateo

Site Details
Status Date : 2015-05-28
Status : Open - Site Assessment
Begin Date : 2015-05-28
Global ID : T10000007001
Region : REGION 2

Map Id: F33
Direction: NNW
Distance: 0.160 mi., 844 ft.
Elevation: 75 ft.
Relative: Higher

Site Name : NORGE VILLAGE CLEANERS (FORMER)
1155 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367917
EPA ID: N/R

SLIC REG 2 - CA ***(cont.)***

Site History :	Case opened 5/28/2015 under oversight of San Mateo County Groundwater Protection Program. The case was then transferred to the Regional Water Board on 7/18/2017. The responsible parties are currently exploring grant funding in order to begin the investigation.
RB Case Number :	41S0207
Potential Media Affected :	Aquifer used for drinking water supply, Under Investigation
Potential Contaminants of Concern :	Tetrachloroethylene (PCE), Trichloroethylene (TCE)
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN FRANCISCO BAY RWQCB (REGION 2)
File Location :	All Files are on GeoTracker or in the Local Agency Database
CUF Case :	YES
Caseworker :	KAW
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.65706
Longitude :	-122.43797
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T10000007001
Contact Name :	KIMBERLEE WEST
Contact Type :	Regional Board Caseworker - Primary Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 Clay Street
City :	OAKLAND
Phone Number :	5106222432
Email :	kimberlee.west@waterboards.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2023-04-21
Global ID :	T10000007001
Action Type :	ENFORCEMENT
Action :	Staff Letter
Date :	2023-03-03
Global ID :	T10000007001

Map Id: F33
Direction: NNW
Distance: 0.160 mi., 844 ft.
Elevation: 75 ft.
Relative: Higher

Site Name : NORGE VILLAGE CLEANERS (FORMER)
1155 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367917
EPA ID: N/R

SLIC REG 2 - CA ***(cont.)***

Action Type : RESPONSE
Action : Remedial Investigation Report - Regulator Responded

Date : 2023-01-31
Global ID : T10000007001
Action Type : ENFORCEMENT
Action : Staff Letter

Date : 2023-01-15
Global ID : T10000007001
Action Type : RESPONSE
Action : Soil Vapor Intrusion Investigation Report - Regulator Responded

Date : 2022-12-06
Global ID : T10000007001
Action Type : ENFORCEMENT
Action : Staff Letter

Status History

Status Date : 2015-05-28
Global ID : T10000007001
Status : Open - Case Begin Date

Status Date : 2015-05-28
Global ID : T10000007001
Status : Open - Site Assessment

Map Id: H34
Direction: E
Distance: 0.165 mi., 874 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR
998 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SAN FRANCISCO, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA]

Envirosite ID: 52367900
EPA ID: CAC002621663

CALEPA SITES - CA

Facility Name : SO CITY GAS & AUTO REPAIR
Facility Address : 998 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080

Map Id: H34
Direction: E
Distance: 0.165 mi., 874 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR
998 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SAN FRANCISCO, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367900
EPA ID: CAC002621663

CALEPA SITES - CA ***(cont.)***

Site ID :	494887
EI ID :	110001189071
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	37.654890
Longitude :	-122.433880
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

HAZNET - CA

Facility Name :	FRED BROVO
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002621663
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3015 BRITTAN AVE, SAN CARLOS, CA 94070
Latitude :	37.65516006
Longitude :	-122.43412595
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
2007: 551 - Laboratory waste chemicals, 0.031 tons to TXD982560294
2007: 221 - Waste oil and mixed oil, 0.8398 tons to NVD980895338
2007: 223 - Unspecified oil-containing waste, 0.006 tons to CAD982444481
2007: 343 - Unspecified organic liquid mixture, 1.122 tons to NVD980895338
2007: 512 - Other empty containers 30 gallons or more, 5.65 tons to CAD009466392

Facility Name :	PETRONBRAV
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002576173
Active :	Inactive

Map Id: H34
Direction: E
Distance: 0.165 mi., 874 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR
998 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SAN FRANCISCO, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367900
EPA ID: CAC002621663

HAZNET - CA ***(cont.)***

Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	775 CHESTNUT ST STE 26, SAN CARLOS, CA 94070
Latitude :	37.65516006
Longitude :	-122.43412595
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	SOUTH CITY GAS & AUTO REPAIR
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000122488
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803202
Latitude :	37.65516006
Longitude :	-122.43412595
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	UNION OIL STN #4523
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94005
County :	SAN MATEO

Site Details

Generator EPA ID :	CAX000219030
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	--, BRISBANE, CA 940050000
Latitude :	37.65500100
Longitude :	-122.43372750
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: H34
Direction: E
Distance: 0.165 mi., 874 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR
998 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SAN FRANCISCO, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367900
EPA ID: CAC002621663

HAZNET - CA ***(cont.)***

Facility Name :	UNOCAL SERVICE STATION #4523
Facility Address :	998 EL CAMINO REAL, S SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAD982056095
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PO BOX 25376, SANTA ANA, CA 927995376
Latitude :	37.65516006
Longitude :	-122.43412595
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1997: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2293 tons to CAD009452657 1996: 133 - Aqueous solution with total organic residues 10 percent or more, 0.5837 tons to CAD009452657 1995: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2293 tons to CAD009452657

HIST UST - CA

Facility Name :	UNION OIL SS 4523
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
County :	San Mateo
PDF Link :	Click here for hyperlink provided by the agency.

HWG - CA

Facility Name :	FRED BROVO
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002621663
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3015 BRITTAN AVE, SAN CARLOS, CA 94070

Map Id: H34
Direction: E
Distance: 0.165 mi., 874 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR
998 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SAN FRANCISCO, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367900
EPA ID: CAC002621663

HWG - CA ***(cont.)***

Owner Name :	FRED BROVO
Owner Address :	3015 BRITTAN AVE, SAN CARLOS, CA 94070
Operator Name :	JOHN MURPHY
Operator Address :	3015 BRITTAN AVE, SAN CARLOS, CA 94070
Latitude :	37.655124
Longitude :	-122.434207

Facility Name :	PETRONBRAV
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002576173
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	775 CHESTNUT ST STE 26, SAN CARLOS, CA 94070
Owner Name :	C PETROCCHI,SR/JR/FRED BRAVO
Owner Address :	775 CHESTNUT ST STE 26, SAN CARLOS, CA 94070
Operator Name :	CHARLES PETROCCHI SR/PARTNER
Operator Address :	775 CHESTNUT ST STE 26, SAN CARLOS, CA 94070
Latitude :	37.655269
Longitude :	-122.434419

Facility Name :	SOUTH CITY GAS & AUTO REPAIR
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL000122488
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803202
Owner Name :	TOM KOULOURIS
Owner Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803202
Operator Name :	TOM KOULOURIS
Operator Address :	998 EL CAMINO REAL, SSF, CA 940803202
Latitude :	37.655269
Longitude :	-122.434419

Facility Name :	UNION OIL STN #4523
Facility Address :	998 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94005
County :	SAN MATEO

Map Id: H34
Direction: E
Distance: 0.165 mi., 874 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SO CITY GAS & AUTO REPAIR | SOUTH CITY GAS | SOUTH CITY GAS & AUTO REPAIR
998 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SAN FRANCISCO, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367900
EPA ID: CAC002621663

HWG - CA ***(cont.)***

EPA ID :	CAX000219030
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	BRISBANE, CA 940050000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	DONALD TERRY
Operator Address :	N/A
Latitude :	37.667062
Longitude :	-121.783525

Facility Name :	UNOCAL SERVICE STATION #4523
Facility Address :	998 EL CAMINO REAL, S SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAD982056095
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	PO BOX 25376, SANTA ANA, CA 927995376
Owner Name :	UNION OIL COMPANY OF CALIFORNI
Owner Address :	DBA UNOCAL, EL SEGUNDO, CA 902450000
Operator Name :	CHRISTOPHER Z HILL
Operator Address :	PO BOX 25376 CANX VQ97 CC, SANTA ANA, CA 927995376
Latitude :	37.655269
Longitude :	-122.434419

Map Id: F35
Direction: NNW
Distance: 0.168 mi., 890 ft.
Elevation: 75 ft.
Relative: Higher

Site Name : GENIUS LEARNING | EDWARD V FOUCRAULT | GUARDIAN AMBULANCE SVC
1165 EL CAMINO REAL | 1165 EL CAMINO REAL STE B | 1165 EL CAMINO
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946907
EPA ID: CAC000771448

HAZNET - CA

Facility Name :	EDWARD V FOUCRAULT
Facility Address :	1165 EL CAMINO REAL STE B, SOUTH SAN FRANCISCO, CA 94080

Map Id: F35
Direction: NNW
Distance: 0.168 mi., 890 ft.
Elevation: 75 ft.
Relative: Higher

Site Name : GENIUS LEARNING | EDWARD V FOUCRAULT | GUARDIAN AMBULANCE SVC
1165 EL CAMINO REAL | 1165 EL CAMINO REAL STE B | 1165 EL CAMINO
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946907
EPA ID: CAC000771448

HAZNET - CA ***(cont.)***

County : SAN MATEO

Site Details

Generator EPA ID :	CAC000771448
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1165 EL CAMINO REAL STE B, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65698241
Longitude :	-122.43756589
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
1997: 352 - Other organic solids, 0.15 tons to CAD000088252
1997: 611 - Contaminated soil from site clean-up, 0.45 tons to CAD982444481
1997: 331 - Off-specification, aged or surplus organics, 0.1155 tons to CAD000088252
1995: 611 - Contaminated soil from site clean-up, 0.45 tons to CAD982444481
1995: 331 - Off-specification, aged or surplus organics, 0.1155 tons to CAD000088252
1995: 352 - Other organic solids, 0.15 tons to CAD000088252

HWG - CA

Facility Name :	EDWARD V FOUCRAULT
Facility Address :	1165 EL CAMINO REAL STE B, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC000771448
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1165 EL CAMINO REAL STE B, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	EDWARD FOUCRAULT
Owner Address :	1165 EL CAMINO REAL STE B, SOUTH SAN FRANCISCO, CA 940800000
Operator Name :	EDWARD
Operator Address :	1165 EL CAMINO REAL STE B, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.657404
Longitude :	-122.437755

Map Id: H36
Direction: E
Distance: 0.169 mi., 891 ft.
Elevation: 45 ft.
Relative: Lower

Site Name : PACIFIC BELL | PACIFIC BELL TELEPHONE CO DBA AT&T CALIF
965 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 245760
EPA ID: CAT080021264

HAZNET - CA

Facility Name :	PACIFIC BELL TELEPHONE CO DBA AT&T CALIF
Facility Address :	965 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAT080021264
Active :	Active
Category :	FEDERAL
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	308 S. AKARD ST. 17TH FLOOR, DALLAS, TX 752020000
Latitude :	37.65437981
Longitude :	-122.43367192
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	PACIFIC BELL TELEPHONE CO DBA AT&T CALIF
Facility Address :	965 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAT080021264
Status :	Active
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	311 S. AKARD ST., DALLAS, TX 752020000
Owner Name :	PACIFIC BELL TELEPHONE COMPANY
Owner Address :	430 BUSH ST, SAN FRANCISCO, CA 941080000
Operator Name :	EH&S WASTE MANAGER/TEAM
Operator Address :	311 S. AKARD ST., DALLAS, TX 75202
Latitude :	37.654296
Longitude :	-122.43352

Map Id: G37
Direction: ESE
Distance: 0.171 mi., 901 ft.
Elevation: 48 ft.
Relative: Lower

Site Name : MY CLEANERS
1053F EL CAMINO
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, DRYCLEANERS - CA]

Envirosite ID: 229939
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	MY CLEANERS

Map Id: G37
Direction: ESE
Distance: 0.171 mi., 901 ft.
Elevation: 48 ft.
Relative: Lower

Site Name : MY CLEANERS
1053F EL CAMINO
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, DRYCLEANERS - CA] ***(cont.)***

Envirosite ID: 229939
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Facility Address :	1053F EL CAMINO, SOUTH SAN FRANCISCO, 94080-3287
Site ID :	482348
EI ID :	110001197990
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	37.655262
Longitude :	-122.434920
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

DRYCLEANERS - CA

Property Name :	My Cleaners

Map Id: J38
Direction: NW
Distance: 0.172 mi., 910 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : NANCY LUATHATI
25 DEL PASO DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946914
EPA ID: CAC002664694

HAZNET - CA

Facility Name :	NANCY LUATHATI
Facility Address :	25 DEL PASO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

Site Details

Generator EPA ID :	CAC002664694
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	25 DEL PASO DR, SOUTH SAN FRANCISCO, CA 940802252
Latitude :	37.65688562
Longitude :	-122.44000696
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2011: 612 - Household waste, 0.1 tons to CAD982444481

Map Id: J38
Direction: NW
Distance: 0.172 mi., 910 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : NANCY LUATHATI
25 DEL PASO DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946914
EPA ID: CAC002664694

HWG - CA

Facility Name :	NANCY LUATHATI
Facility Address :	25 DEL PASO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
EPA ID :	CAC002664694
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	25 DEL PASO DR, SOUTH SAN FRANCISCO, CA 940802252
Owner Name :	NANCY LUATHATI
Owner Address :	25 DEL PASO DR, SOUTH SAN FRANCISCO, CA 940802252
Operator Name :	NANCY LUATHATI
Operator Address :	25 DEL PASO DR, SOUTH SAN FRANCISCO, CA 940802252
Latitude :	37.65645
Longitude :	-122.44044

Map Id: G39
Direction: ESE
Distance: 0.173 mi., 915 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : VISTA DENTAL CARE | COHEN DENTAL CARE | COHEN DENTAL CORP
931 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 52367906
EPA ID: CAL000181218

HAZNET - CA

Facility Name :	COHEN DENTAL CARE
Facility Address :	931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000181218
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65362847
Longitude :	-122.43296826
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: G39
Direction: ESE
Distance: 0.173 mi., 915 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : VISTA DENTAL CARE | COHEN DENTAL CARE | COHEN DENTAL CORP
931 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367906
EPA ID: CAL000181218

HAZNET - CA ***(cont.)***

Waste Generator Details

State Waste :
2006: 343 - Unspecified organic liquid mixture, 0.0136 tons to CAL000175030
2005: 343 - Unspecified organic liquid mixture, 0.0238 tons to CAL000175030
2004: 343 - Unspecified organic liquid mixture, 0.0391 tons to CAL000175030
2003: 343 - Unspecified organic liquid mixture, 0.0068 tons to CAL000175030
2003: 343 - Unspecified organic liquid mixture, 0.017 tons to CAL000212588
2003: N/R - Blank or unknown, tons to CAL000212588
2002: N/R - Blank or unknown, tons to CAL000212588
2002: 343 - Unspecified organic liquid mixture, 0.0136 tons to CAL000212588
2001: 343 - Unspecified organic liquid mixture, 0.0068 tons to CAL000212588
2001: N/R - Blank or unknown, 0 tons to CAL000212588

Facility Name : VISTA DENTAL CARE
Facility Address : 931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

Site Details

Generator EPA ID : CAL000322385
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Latitude : 37.65362847
Longitude : -122.43296826
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

HWG - CA

Facility Name : COHEN DENTAL CARE
Facility Address : 931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

EPA ID : CAL000181218
Status : Inactive
Category : STATE
Type : PERMANENT
Facility Type : N/R
Mailing Address : 931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Owner Name : HARRY COHEN DDS
Owner Address : 931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Operator Name : SHARON CHAO

Map Id: G39
Direction: ESE
Distance: 0.173 mi., 915 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : VISTA DENTAL CARE | COHEN DENTAL CARE | COHEN DENTAL CORP
931 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367906
EPA ID: CAL000181218

HWG - CA ***(cont.)***

Operator Address :	84 PERITA DR, DALY CITY, CA 94015
Latitude :	37.653644
Longitude :	-122.432912
Facility Name :	VISTA DENTAL CARE
Facility Address :	931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000322385
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	CATHERINE M VISTA DDS
Owner Address :	931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940802303
Operator Name :	NAKIDRA DOBSHINSKY
Operator Address :	931 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940802303
Latitude :	37.653644
Longitude :	-122.432912

Map Id: G40
Direction: ESE
Distance: 0.173 mi., 917 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : SOUTHWOOD CHIROPRACTIC
943 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 52367904
EPA ID: CAL000122840

HAZNET - CA

Facility Name :	SOUTHWOOD CHIROPRACTIC
Facility Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000122840
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803203
Latitude :	37.65388686
Longitude :	-122.43318171
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: G40
Direction: ESE
Distance: 0.173 mi., 917 ft.
Elevation: 49 ft.
Relative: Lower

Site Name : SOUTHWOOD CHIROPRACTIC
943 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367904
EPA ID: CAL000122840

HAZNET - CA ***(cont.)***

Waste Generator Details

State Waste : 1997: 541 - Photochemicals/photoprocessing waste, 0.0833 tons to CAL000121946
1995: 541 - Photochemicals/photoprocessing waste, 0.0833 tons to CAL000121946

Site Details

Generator EPA ID :	CAL000089832
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65388686
Longitude :	-122.43318171
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	SOUTHWOOD CHIROPRACTIC
Facility Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL000122840
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803203
Owner Name :	CHRISTIAN W. NASON
Owner Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803203
Operator Name :	CHRISTIAN W NASON
Operator Address :	INACTIVE PER VQ98 - BMI, SOUTH SAN FRANCISCO, CA 940803203
Latitude :	37.654479
Longitude :	-122.433727

EPA ID :	CAL000089832
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	DEACT PER VF96 -PH
Operator Address :	943 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.654479
Longitude :	-122.433727

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 52367898
EPA ID: CAC000679368

CALEPA SITES - CA

Facility Name :	988 EL CAMINO REAL
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	525179
EI ID :	869572
EI Description :	Construction Storm Water
Latitude :	37.655000
Longitude :	-122.433611
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-09-27
Facility Name :	SOUTH CITY CAR WASH INC
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	154885
EI ID :	10065007
EI Description :	Chemical Storage Facilities
Latitude :	37.654993
Longitude :	-122.433750
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-12-11
Site ID :	154885
EI ID :	10065007
EI Description :	Hazardous Waste Generator
Latitude :	37.654993
Longitude :	-122.433750
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-12-11

HAZNET - CA

Facility Name :	1X SOUTH CITY CAR WASH
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC000679368
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367898
EPA ID: CAC000679368

HAZNET - CA ***(cont.)***

Latitude :	37.65500287
Longitude :	-122.43390724
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	SHAC 988 ECR APARTMENTS, LLC
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC003038917
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3000 EXECUTIVE PARKWAY, SAN RAMON, CA 94583
Latitude :	37.65500287
Longitude :	-122.43390724
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2019: 134 - Aqueous solution with total organic residues less than 10 percent, 0.31500 tons to NVT330010000
Facility Name :	SHAC 988 ECR APARTMETNS, LLC
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC003025607
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3000 EXECUTIVE PARKWAY, SUITE 450, SAN RAMON, CA 94583
Latitude :	37.65500287
Longitude :	-122.43390724

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367898
EPA ID: CAC000679368

HAZNET - CA ***(cont.)***

Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details

State Waste : 2019: 611 - Contaminated soil from site clean-up, 152.28000 tons to CAT000646117

Facility Name : SOUTH CITY CAR WASH
Facility Address : 988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

Site Details

Generator EPA ID : CAL000094648
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803202
Latitude : 37.65500287
Longitude : -122.43390724
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details

State Waste : 1993: 541 - Photochemicals/photoprocessing waste, 0.0208 tons to CAD982524613

HIST HAZNET - CA

Facility Name : 1X SOUTH CITY CAR WASH
Facility Address : 988 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080

ID Number : CAC000679368
Last Date in Agency List : 2014-11-17

HWG - CA

Facility Name : 1X SOUTH CITY CAR WASH

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367898
EPA ID: CAC000679368

HWG - CA ***(cont.)***

Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC000679368
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	BASIL CAVALIER
Owner Address :	N/A
Operator Name :	BOB CAVALIERI/MANAGER
Operator Address :	N/A
Latitude :	37.655074
Longitude :	-122.43444

Facility Name :	SHAC 988 ECR APARTMENTS, LLC
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC003038917
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3000 EXECUTIVE PARKWAY, SAN RAMON, CA 94583
Owner Name :	SHAC 988 ECR APARTMENTS
Owner Address :	3000 EXECUTIVE PARKWAY, SAN RAMON, CA 94583
Operator Name :	JOHN PARKER
Operator Address :	777 S CALIFORNIA AVE, PALO ALTO, CA 94304
Latitude :	37.654647
Longitude :	-122.433161

Facility Name :	SHAC 988 ECR APARTMETNS, LLC
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC003025607
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3000 EXECUTIVE PARKWAY, SUITE 450, SAN RAMON, CA 94583
Owner Name :	SHAC 988 ECR APARTMENTS
Owner Address :	3000 EXECUTIVE PARKWAY, SUITE 450, SAN RAMON, CA 94583
Operator Name :	JOHN PARKER

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367898
EPA ID: CAC000679368

HWG - CA ***(cont.)***

Operator Address :	777 S CALIFORNIA AVE, PALO ALTO, CA 94304
Latitude :	37.655003
Longitude :	-122.433907
Facility Name :	SOUTH CITY CAR WASH
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000094648
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 940803202
Owner Name :	BASIL CAVALIERI
Owner Address :	28 CAMINO ALTO, MILLBRAE, CA 940302216
Operator Name :	BOB CAVALIERI MANAGER
Operator Address :	988 EL CAMINO REAL, SO SAN FRANCISCO, CA 940803202
Latitude :	37.654975
Longitude :	-122.434046

RCRA_NONGEN

Facility Name :	SHAC 988 ECR APARTMENTS, LLC
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080-3202
County :	SAN MATEO
Date Form Received by Agency :	2019-10-16
EPA ID :	CAC003038917
Mailing Address :	3000 EXECUTIVE PARKWAY SUITE 450, SAN RAMON, CA 94583
Contact :	JOHN PARKER
Contact Address :	777 S CALIFORNIA AVE, PALO ALTO, CA 94304
Contact Country :	N/R
Contact Telephone :	925-285-0813
Contact Email :	JPARKER@SHAPARTMENTS.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	JOHN PARKER
Owner/Operator Address :	777 S CALIFORNIA AVE, PALO ALTO, CA 94304
Owner/Operator Country :	N/R

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367898
EPA ID: CAC000679368

RCRA_NONGEN ***(cont.)***

Owner/Operator Telephone :	925-285-0813
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	SHAC 988 ECR APARTMENTS
Owner/Operator Address :	3000 EXECUTIVE PARKWAY SUITE 450, SAN RAMON, CA 94583
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-842-2206
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Facility Name :	SHAC 988 ECR APARTMETNS, LLC
Facility Address :	988 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080-3202
County :	SAN MATEO

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367898
EPA ID: CAC000679368

RCRA_NONGEN ***(cont.)***

Date Form Received by Agency :	2019-07-24
EPA ID :	CAC003025607
Mailing Address :	3000 EXECUTIVE PARKWAY, SUITE 450, SAN RAMON, CA 94583
Contact :	JOHN PARKER
Contact Address :	777 S CALIFORNIA AVE, PALO ALTO, CA 94304
Contact Country :	N/R
Contact Telephone :	925-285-0813
Contact Email :	JPARKER@SHAPARTMENTS.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	JOHN PARKER
Owner/Operator Address :	777 S CALIFORNIA AVE, PALO ALTO, CA 94304
Owner/Operator Country :	N/R
Owner/Operator Telephone :	925-285-0813
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	SHAC 988 ECR APARTMENTS
Owner/Operator Address :	3000 EXECUTIVE PARKWAY, SUITE 450, SAN RAMON, CA 94583
Owner/Operator Country :	N/R
Owner/Operator Telephone :	925-244-7500
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N

Map Id: H41
Direction: E
Distance: 0.181 mi., 954 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : SHAC 988 ECR APARTMENTS, LLC | SHAC 988 ECR APARTMETNS, LLC | 988 EL CAMINO REAL
988 EL CAMINO REAL
SOUTH SAN FRANCISCO | South San Francisco, CA

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367898
EPA ID: CAC000679368

RCRA_NONGEN ***(cont.)***

Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: K42
Direction: ENE
Distance: 0.189 mi., 1000 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : FORZA TELECOM-PH8 CHESTNUT HEAD END
955 ANTOINETTE LANE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA]

Envirosite ID: 797903
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	FORZA TELECOM-PH8 CHESTNUT HEAD END
Facility Address :	955 ANTOINETTE LANE, SOUTH SAN FRANCISCO, 94080
Site ID :	515370
EI ID :	110070059164
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	37.655809
Longitude :	-122.434550
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2020-02-19

Map Id: 43
Direction: SE
Distance: 0.193 mi., 1022 ft.
Elevation: 89 ft.
Relative: Higher

Site Name : NICOLETTE CIARDELLA
9 HILLCREST COURT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN]

Envirosite ID: 53946921
EPA ID: CAC003193552

HWG - CA

Facility Name :	NICOLETTE CIARDELLA
Facility Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003193552
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	NICOLETTE CIARDELLA
Owner Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	NICOLETTE CIARDELLA
Operator Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65195
Longitude :	-122.434924

RCRA_NONGEN

Facility Name :	NICOLETTE CIARDELLA
Facility Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2022-09-06
EPA ID :	CAC003193552
Mailing Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
Contact :	NICOLETTE CIARDELLA
Contact Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	415-310-3520
Contact Email :	GISELLE.ESPIRITU@SYNERGYCOMPANIES.ORG
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	NICOLETTE CIARDELLA
Owner/Operator Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-310-3520
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	NICOLETTE CIARDELLA
Owner/Operator Address :	9 HILLCREST COURT, SOUTH SAN FRANCISCO, CA 94080

Map Id: 43
Direction: SE
Distance: 0.193 mi., 1022 ft.
Elevation: 89 ft.
Relative: Higher

Site Name : NICOLETTE CIARDELLA
9 HILLCREST COURT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 53946921
EPA ID: CAC003193552

RCRA_NONGEN ***(cont.)***

Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-310-3520
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: K44
Direction: NE
Distance: 0.202 mi., 1067 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : PACIFIC GAS AND ELECTRIC COMPANY-I007B
LAT. 37.656875, LONG. -122.434623
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 33303198
EPA ID: CAC003061658

HAZNET - CA

Facility Name :	PACIFIC GAS AND ELECTRIC COMPANY-I007B
Facility Address :	LAT. 37.656875, LONG. -122.434623, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: K44
Direction: NE
Distance: 0.202 mi., 1067 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : PACIFIC GAS AND ELECTRIC COMPANY-I007B
LAT. 37.656875, LONG. -122.434623
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 33303198
EPA ID: CAC003061658

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC003061658
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PG&E - EPA ID'S, SAN FRANCISCO, CA 94120
Latitude :	37.70959805
Longitude :	-122.45886844
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	PACIFIC GAS AND ELECTRIC COMPANY-I007B
Facility Address :	LAT. 37.656875, LONG. -122.434623, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003061658
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	PO BOX 7640, SAN FRANCISCO, CA 941200000
Owner Name :	PG&E
Owner Address :	PO BOX 7640, SAN FRANCISCO, CA 941207640
Operator Name :	ANNA FEEHAN
Operator Address :	PO BOX 7640, SAN FRANCISCO, CA 94120
Latitude :	37.709598
Longitude :	-122.458868

RCRA_NONGEN

Facility Name :	PACIFIC GAS AND ELECTRIC COMPANY-I007B
Facility Address :	LAT. 37.656875, LONG. -122.434623, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2020-03-27
EPA ID :	CAC003061658
Mailing Address :	PG&E - EPA ID'S PO BOX 7640, SAN FRANCISCO, CA 94120
Contact :	ANDREW MATTHEW
Contact Address :	61111 BOLLINGER CANYON ROAD, SAN RAMON, CA 94583
Contact Country :	N/R
Contact Telephone :	925-412-2344
Contact Email :	A6M6@PGE.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Map Id: K44
Direction: NE
Distance: 0.202 mi., 1067 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : PACIFIC GAS AND ELECTRIC COMPANY-I007B
LAT. 37.656875, LONG. -122.434623
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 33303198
EPA ID: CAC003061658

RCRA_NONGEN ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	ANDREW MATTHEW
Owner/Operator Address :	61111 BOLLINGER CANYON ROAD, SAN RAMON, CA 94583
Owner/Operator Country :	N/R
Owner/Operator Telephone :	925-412-2344
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	PG&E - EPA ID'S
Owner/Operator Address :	PO BOX 7640, SAN FRANCISCO, CA 94120
Owner/Operator Country :	N/R
Owner/Operator Telephone :	925-412-2344
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: L45
Direction: ESE
Distance: 0.208 mi., 1097 ft.
Elevation: 47 ft.
Relative: Lower

Site Name : SOUTH SAN FRANCISCO FOOT CLINIC
927 EL CAMINO REAL
SAN FRANCISCO, CA

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 52367905
EPA ID: CAL000110314

HAZNET - CA

Facility Name :	SOUTH SAN FRANCISCO FOOT CLINIC
Facility Address :	927 EL CAMINO REAL, SAN FRANCISCO, CA
County :	SAN FRANCISCO

Site Details

Generator EPA ID :	CAL000110314
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	901 CAMPUS DR #311, DALY CITY, CA 940154930
Latitude :	37.60525416
Longitude :	-122.39612687
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1998: 541 - Photochemicals/photoprocessing waste, 0.0291 tons to CAL000121946 1997: 541 - Photochemicals/photoprocessing waste, 0.0625 tons to CAL000121946 1995: 541 - Photochemicals/photoprocessing waste, 0.0625 tons to CAL000121946

HWG - CA

Facility Name :	SOUTH SAN FRANCISCO FOOT CLINIC
Facility Address :	927 EL CAMINO REAL, SAN FRANCISCO, CA 00000
County :	SAN FRANCISCO

EPA ID :	CAL000110314
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	901 CAMPUS DR #311, DALY CITY, CA 940154930
Owner Name :	WILLIAM TARRAN DPM
Owner Address :	1216 SEVILLE DR, PACIFICA, CA
Operator Name :	WILLIAM TARRAN
Operator Address :	INACT PER 98 VQ FINAL NOTICE - HN, SOUTH SAN FRANCISCO, CA
Latitude :	37.605254
Longitude :	-122.396127

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA]

Envirosite ID: 52367894
EPA ID: CAC003058037

AST - CA

Facility Name :	SOUTH SAN FRANCISCO POLICE DEPARTMENT
Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo County

Site Details

Site ID :	627095
Facility Identifer :	FA0071602
EPA Identifier :	CAL000474811
Facility Explorer ID :	627095
Dun and Bradsheet Number :	N/R
Regulatory Programs :	Aboveground Petroleum Storage, Chemical Storage Facilities, Hazardous Waste Generator
SIC :	N/R
NAICS :	N/R
Latitude :	37.656250
Longitude :	-122.433563
Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-11-16

Chemicals

Chemical Name :	Diesel Fuel No. 2
CAS Number :	68476-34-6
Hazard Type(s) :	-
Max Daily Amount / Unit :	1200-2999 Gallons
Average Daily Amount / Unit :	0-11 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Pure

CALEPA SITES - CA

Facility Name :	COMMUNITY CIVIC CAMPUS PHASE 1 POLICE STATION
Facility Address :	1 CHESTNUT AVENUE, SOUTH SAN FRANCISCO, 94080
Site ID :	580712
EI ID :	876828
EI Description :	Construction Storm Water
Latitude :	37.656220
Longitude :	-122.433540
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-09-27
Facility Name :	RON PRICE MOTORS (FORMER)
Facility Address :	1 CHESTNUT AVENUE, SOUTH SAN FRANCISCO, 94080

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

CALEPA SITES - CA ***(cont.)***

Site ID :	680934
EI ID :	T10000013692
EI Description :	Cleanup Program Site
Latitude :	37.656220
Longitude :	-122.433540
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Site ID :	558298
EI ID :	T10000013692
EI Description :	Cleanup Program Site
Latitude :	37.656220
Longitude :	-122.433540
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

Facility Name :	SOUTH SAN FRANCISCO POLICE DEPARTMENT
Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, 94080

Site ID :	627095
EI ID :	10913206
EI Description :	Hazardous Waste Generator
Latitude :	37.656250
Longitude :	-122.433563
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Site ID :	627095
EI ID :	10913206
EI Description :	Aboveground Petroleum Storage
Latitude :	37.656250
Longitude :	-122.433563
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Site ID :	627095
EI ID :	10913206
EI Description :	Chemical Storage Facilities
Latitude :	37.656250
Longitude :	-122.433563
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

HAZNET - CA

Facility Name :	CITY OF SOUTH SAN FRANCISCO

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

HAZNET - CA ***(cont.)***

Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC003058037
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 940804691
Latitude :	37.65621600
Longitude :	-122.43348900
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	RON PRICE
Facility Address :	1 CHESTNUT AVE, S SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAD981441959
Active :	Inactive
Category :	FEDERAL
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940803228
Latitude :	37.65574040
Longitude :	-122.43352831
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2007: 223 - Unspecified oil-containing waste, 0.834 tons to CAD980887418
2005: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.15 tons to NVD980895338
2005: 221 - Waste oil and mixed oil, 0.171 tons to CAD980887418
2004: 134 - Aqueous solution with total organic residues less than 10 percent, 0.3108 tons to CA0000084517
2003: 222 - Oil/water separation sludge, 0.0417 tons to CAD059494310

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

HAZNET - CA ***(cont.)***

2003: 134 - Aqueous solution with total organic residues less than 10 percent, 0.5754 tons to CA0000084517
2003: 343 - Unspecified organic liquid mixture, 1.462 tons to CA0000084517
2003: 343 - Unspecified organic liquid mixture, 0.748 tons to CA0000084517
2002: 221 - Waste oil and mixed oil, 0.114 tons to CAD980887418
2000: 134 - Aqueous solution with total organic residues less than 10 percent, 1.344 tons to CAD982446874
1999: 134 - Aqueous solution with total organic residues less than 10 percent, 3.129 tons to CAD982446874
1998: 134 - Aqueous solution with total organic residues less than 10 percent, 4.326 tons to CAD980887418
1997: 221 - Waste oil and mixed oil, 0.19 tons to CAD980887418
1997: 214 - Unspecified solvent mixture, 0.0864 tons to CAD093459485
1997: 134 - Aqueous solution with total organic residues less than 10 percent, 0.63 tons to CAD980887418
1997: 134 - Aqueous solution with total organic residues less than 10 percent, 3.696 tons to CAD980887418
1996: 214 - Unspecified solvent mixture, 0.1152 tons to CAD093459485
1996: 221 - Waste oil and mixed oil, 0.247 tons to CAD980887418
1996: 134 - Aqueous solution with total organic residues less than 10 percent, 5.418 tons to CAD980887418
1995: 214 - Unspecified solvent mixture, 0.0864 tons to CAD093459485
1995: 134 - Aqueous solution with total organic residues less than 10 percent, 0.63 tons to CAD980887418
1995: 134 - Aqueous solution with total organic residues less than 10 percent, 3.696 tons to CAD980887418
1995: 221 - Waste oil and mixed oil, 0.19 tons to CAD980887418
1994: 134 - Aqueous solution with total organic residues less than 10 percent, 5.481 tons to CAD980887418
1993: N/R - Blank or unknown, 0 tons to CAD980887418
1993: 134 - Aqueous solution with total organic residues less than 10 percent, 2.688 tons to CAD980887418
1993: 134 - Aqueous solution with total organic residues less than 10 percent, 1.344 tons to CAD980887418
1993: 221 - Waste oil and mixed oil, 0.152 tons to CAD980887418

Facility Name :	RON PRICE MOTORS
Facility Address :	1 CHESTNUT AVE, SO. SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAD132029687
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940803228
Latitude :	37.65574040
Longitude :	-122.43352831
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details
State Waste :
1999: 343 - Unspecified organic liquid mixture, 0 tons to CAD009452657
1998: 343 - Unspecified organic liquid mixture, 0.255 tons to CAD009452657
1994: 221 - Waste oil and mixed oil, 0.076 tons to CAD980887418

HIST UST - CA

Facility Name :	RON PRICE MOTORS
Facility Address :	#1 CHESTNUT AVE., SOUTH SAN FRANCISCO, 94080
County :	San Mateo
PDF Link :	Click here for hyperlink provided by the agency.

HWG - CA

Facility Name :	CITY OF SOUTH SAN FRANCISCO
Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003058037
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 940804691
Owner Name :	CITY OF SOUTH SAN FRANCISCO
Owner Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 940804691
Operator Name :	JACOB GILCHRIST
Operator Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 940804691
Latitude :	37.656216
Longitude :	-122.433489
Facility Name :	RON PRICE
Facility Address :	1 CHESTNUT AVE, S SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

HWG - CA ***(cont.)***

EPA ID :	CAD981441959
Status :	Inactive
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940803228
Owner Name :	RON PRICE
Owner Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940803228
Operator Name :	DONNA SMITH
Operator Address :	INACT 99VQ FINAL NOTICE - BATCH, SOUTH SAN FRANCISCO, CA 940803228
Latitude :	37.655626
Longitude :	-122.433545
Facility Name :	RON PRICE MOTORS
Facility Address :	1 CHESTNUT AVE, SO. SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAD132029687
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940803228
Owner Name :	RONALD M PRICE
Owner Address :	240 EUCALYPTUS, HILLSBOROUGH, CA 940100000
Operator Name :	DONNA SMITH
Operator Address :	INACTIVE PER VQ98 - BMI, SAN FRANCISCO, CA 940303228
Latitude :	37.655169
Longitude :	-122.434292
Facility Name :	SOUTH SAN FRANCISCO POLICE DEPARTMENT
Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAL000474811
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	CITY OF SOUTH SAN FRANCISCO
Owner Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	MICHAEL TOSCANO
Operator Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.656214
Longitude :	-122.433521

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

RCRA_NONGEN

Facility Name :	CITY OF SOUTH SAN FRANCISCO
Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080-3228
County :	SAN MATEO
Date Form Received by Agency :	2020-02-28
EPA ID :	CAC003058037
Mailing Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 94080-4691
Contact :	JACOB GILCHRIST
Contact Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 94080-4691
Contact Country :	N/R
Contact Telephone :	650-877-8552
Contact Email :	JACOB.GILCHRIST@SSF.NET
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	CITY OF SOUTH SAN FRANCISCO
Owner/Operator Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 94080-4691
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-829-3809
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	JACOB GILCHRIST
Owner/Operator Address :	550 N CANAL ST, SOUTH SAN FRANCISCO, CA 94080-4691
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-877-8552
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

RCRA_NONGEN ***(cont.)***

Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Facility Name :	RON PRICE
Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Date Form Received by Agency :	1986-09-09
EPA ID :	CAD981441959
Mailing Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Contact :	ENVIRONMENTAL MANAGER
Contact Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	US
Contact Telephone :	415-555-1212
Contact Email :	N/R
EPA Region :	09
Land Type :	Not Reported
Source Type :	Notification
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	NOT REQUIRED
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

RCRA_NONGEN ***(cont.)***

Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	RON PRICE
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N
Facility Name :	SOUTH SAN FRANCISCO POLICE DEPARTMENT
Facility Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2022-11-23
EPA ID :	CAL000474811
Mailing Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Contact :	MICHAEL TOSCANO
Contact Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

RCRA_NONGEN ***(cont.)***

Contact Telephone :	650-877-8900
Contact Email :	PLANNINGSERGEANT@SSF.NET
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	CITY OF SOUTH SAN FRANCISCO
Owner/Operator Address :	400 GRAND AVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-877-8500
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	MICHAEL TOSCANO
Owner/Operator Address :	1 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	650-877-8900
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

RCRA_NONGEN ***(cont.)***

Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

SLIC REG 2 - CA

Facility Name :	Ron Price Motors (former)
Facility Address :	1 Chestnut Avenue, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2019-10-08
Status :	Open - Site Assessment
Begin Date :	2019-10-08
Global ID :	T10000013692
Region :	REGION 2
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	Tetrachloroethylene (PCE)
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	559231
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	N/R
CUF Case :	NO
Caseworker :	JM
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	N/R
DWR Groundwater Subbasin Name :	N/R
Disadvantaged Community :	N/R
Latitude :	37.65622
Longitude :	-122.43354
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T10000013692
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

SLIC REG 2 - CA ***(cont.)***

Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2023-07-14
Global ID :	T10000013692
Action Type :	RESPONSE
Action :	Soil Vapor Intrusion Investigation Report

Date :	2023-03-16
Global ID :	T10000013692
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2022-12-02
Global ID :	T10000013692
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly - Regulator Responded

Date :	2022-09-02
Global ID :	T10000013692
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2020-09-11
Global ID :	T10000013692
Action Type :	RESPONSE
Action :	Final Remedial Action Report / Corrective Action Report - Regulator Responded

Status History

Status Date :	2019-10-08
Global ID :	T10000013692
Status :	Open - Site Assessment

Map Id: K46
Direction: ENE
Distance: 0.211 mi., 1115 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : CITY OF SOUTH SAN FRANCISCO | SOUTH SAN FRANCISCO POLICE DEPARTMENT | RON PRICE
1 CHESTNUT AVE
SOUTH SAN FRANCISCO | South San Francisco | S SAN FRANCISCO, CA

Database(s) : [AST - CA, CALEPA SITES - CA, HAZNET - CA, HIST UST - CA, HWG - CA, RCRA_NONGEN, SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367894
EPA ID: CAC003058037

SLIC REG 2 - CA ***(cont.)***

Status Date :	2019-10-08
Global ID :	T10000013692
Status :	Open - Case Begin Date

Map Id: K47
Direction: ENE
Distance: 0.211 mi., 1116 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : RON PRICE MOTORS
1 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367893
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	RON PRICE MOTORS
Facility Address :	1 CHESTNUT, SOUTH SAN FRANCISCO, 94080
Site ID :	680933
EI ID :	T0608100429
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.655948
Longitude :	-122.433528
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21
Site ID :	210137
EI ID :	T0608100429
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.655948
Longitude :	-122.433528
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

LUST REG 2 - CA

Facility Name :	RON PRICE MOTORS
Facility Address :	1 CHESTNUT, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	1996-01-08
Status :	Completed - Case Closed

Map Id: K47
Direction: ENE
Distance: 0.211 mi., 1116 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : RON PRICE MOTORS
1 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367893
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Begin Date :	1991-05-07
Global ID :	T0608100429
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0453
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550087
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.655948
Longitude :	-122.433529
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608100429
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100429
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100429
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959

Map Id: K47
Direction: ENE
Distance: 0.211 mi., 1116 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : RON PRICE MOTORS
1 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367893
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Email : jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date : 1996-01-03
Global ID : T0608100429
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Date : 1996-01-01
Global ID : T0608100429
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 1993-12-31
Global ID : T0608100429
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Date : 1991-09-25
Global ID : T0608100429
Action Type : Other
Action : Leak Discovery

Date : 1991-08-14
Global ID : T0608100429
Action Type : ENFORCEMENT
Action : Notice of Responsibility - #1

Status History

Status Date : 1996-01-08
Global ID : T0608100429
Status : Completed - Case Closed

Status Date : 1991-05-07
Global ID : T0608100429
Status : Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name : RON PRICE MOTORS
Facility Address : 1 CHESTNUT, SOUTH SAN FRANCISCO, 94080
County : SAN MATEO

Map Id: K47
Direction: ENE
Distance: 0.211 mi., 1116 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : RON PRICE MOTORS
1 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367893
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Site Details

Status Date :	1996-01-08
Status :	COMPLETED - CASE CLOSED
Begin Date :	1991-05-07
Global ID :	T0608100429
Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-0453
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550087
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.655948
Longitude :	-122.433529
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608100429
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100429
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100429
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100

Map Id: K47
Direction: ENE
Distance: 0.211 mi., 1116 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : RON PRICE MOTORS
1 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367893
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

City : SAN MATEO
Phone Number : 6503995959
Email : jmadden@smcgov.org

Regulatory Activities

Date : 1996-01-03
Global ID : T0608100429
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Date : 1996-01-01
Global ID : T0608100429
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 1993-12-31
Global ID : T0608100429
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Date : 1991-09-25
Global ID : T0608100429
Action Type : Other
Action : Leak Discovery

Date : 1991-08-14
Global ID : T0608100429
Action Type : ENFORCEMENT
Action : Notice of Responsibility - #1

Date : 1991-05-07
Global ID : T0608100429
Action Type : Other
Action : Leak Reported

Status History Summary

Status Date : 1996-01-08
Global ID : T0608100429
Status : Completed - Case Closed

Status Date : 1991-05-07
Global ID : T0608100429
Status : Open - Case Begin Date

Map Id: K48
Direction: NE
Distance: 0.216 mi., 1139 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : BART CHESTNUT AVENUE VENTILATION STRUCTURE (CHS)
995 ANTOINETTE LN
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA]

Envirosite ID: 870430
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	BART CHESTNUT AVENUE VENTILATION STRUCTURE (CHS)
Facility Address :	995 ANTOINETTE LN, SOUTH SAN FRANCISCO, 94080
Site ID :	272638
EI ID :	10626898
EI Description :	Chemical Storage Facilities
Latitude :	37.657200
Longitude :	-122.436200
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367899
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	BURGER KING
Facility Address :	972 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	520788
EI ID :	10786036
EI Description :	Chemical Storage Facilities
Latitude :	37.654209
Longitude :	-122.432624
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

Facility Name :	CHEVRON, FORMER STANDARD OIL SUBSTATION
Facility Address :	972 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
Site ID :	218643
EI ID :	SL0608123509
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.654097
Longitude :	-122.432456
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Site ID :	645007
EI ID :	SL0608123509
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.654097
Longitude :	-122.432456
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

LUST REG 2 - CA

Facility Name :	CHEVRON, FORMER STANDARD OIL SUBSTATION
Facility Address :	972 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2012-03-30
Status :	Completed - Case Closed
Begin Date :	2007-03-29
Global ID :	SL0608123509
Region :	REGION 2

Site History :

Extracted from CRA's November 6, 2009 Work Plan for Well Installation, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site was originally developed in 1925 as a Standard Oil San Francisco Substation. The 1925 Sanborn Map1 depicts three aboveground storage tanks along the southwest perimeter of the site, and an oil storage and gasoline pump in the southeastern portion the property. The 1950, 1956, and 1970 Sanborn Maps depict construction/contractor's yards located on the property and these operations could also be a potential source. In 1984, the current Burger King restaurant was constructed. March 2007 Soil Boring Investigation: In March 2007, on behalf of the Estate of Frank Gigli, Professional Service Industries (PSI), Inc. advanced soil borings B-1 through B-4 to approximately 20 feet below grade (fbg) to investigate the recognized environmental conditions identified in PSI's February 27, 2007 Phase I Environmental Assessment (ESA) related to the Former Standard Oil Substation. No groundwater was encountered in any of the borings. No hydrocarbons were detected in soil from borings B-1 and B-2. The soil sample collected at 10 fbg in boring B-3 contained 1,300 milligrams per kilogram (mg/kg) total petroleum hydrocarbons as diesel (TPHd), 4,800 mg/kg total petroleum hydrocarbons as gasoline (TPHg), and 21 mg/kg benzene, but no methyl tertiary butyl ether (MTBE). The soil sample collected at 5 fbg in boring B-4 contained 370 mg/kg TPHd, 1,200 mg/kg TPHg, and no benzene or MTBE. Several other volatile organic compounds (VOCs) that are typically related to gasoline and diesel fuels were also detected in soil samples from both borings B-3 and B-4. April 2007 Remedial Action Agreement: On April 24, 2007, the San Mateo County Health System (SMCHS) issued two letters. The first letter was a Remedial Action Agreement with the former property owner, the Estate of Frank Gigli. The second letter requested further site characterization based on PSI's April 6, 2007 report. June 2007 SMCHS Correspondence: On June 21, 2007, the SMCHS issued a Notice of Responsibility to Chevron Environmental Management Company (Chevron). February 2008 Hank's Rentals Underground Storage Tank (UST) Removal: In February 2008, PSI removed one undocumented 800-gallon UST from the adjacent Hank's Rentals Property. On behalf of Chevron, CRA was onsite to observe the UST removal and collect soil samples. At the direction of the SMCHS, CRA staff collected two compliance soil samples at approximately 10 fbg beneath the western and eastern ends of the 800-gallon UST. All petroleum hydrocarbons and metal concentrations were below San Francisco Bay Region-Regional Water Quality Control Board environmental screening levels (ESLs) for soil. The UST is not associated with the former Standard Oil station that operated at 972 El Camino Real. The UST is likely

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

related to previous operations at the Hank's Rentals property. In addition, the manufacturer's plate on the UST, "Buehler Tank & Welding", was not identified as a brand historically associated with Standard Oil. The UST was located approximately five feet south of the property line between the former Standard Oil and Hank's Rental properties. May 2008 Unauthorized Release: On behalf of Chevron, CRA submitted the May 6, 2008 Unauthorized Contamination Site Report for the site as requested in the SMCHS's March 20, 2008 letter. July 2008 Work Plan: On behalf of Chevron, CRA submitted the July 1, 2008 Subsurface Investigation Work Plan and it was approved by the SMCHS in their letter dated January 16, 2009. The work plan proposed six soil borings to investigate hydrocarbons in soil and groundwater across the site. March 2009 Subsurface Investigation: On behalf of Chevron, CRA advanced soil borings B-7 through B-10 adjacent to and downgradient from the former ASTs and oil storage and gasoline dispenser to determine the lateral and vertical extent of hydrocarbon concentrations in soil and groundwater. Proposed borings B-5 and B-6 were abandoned due to extensive subsurface obstructions. The highest TPHd concentration detected in soil was 1,300 mg/kg in boring B-8 at 5 fbg. The maximum TPHg concentration detected was 3,700 mg/kg in boring B-7 at 4.5 fbg. Low or no TPHg concentrations were detected in borings B-8, B-9, and B-10. The only benzene concentration detected in soil was 0.16 mg/kg in boring B-7 at 4.5 fbg. The TPHd and TPHg concentrations are delineated onsite. No benzene was detected in groundwater. No MTBE was detected in soil or groundwater. The objectives of the proposed scope of work are to install a network of groundwater monitoring wells onsite to establish groundwater flow, gradient, and petroleum hydrocarbon concentration trend data.

RB Case Number :	N/R
Potential Media Affected :	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550196
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.654097
Longitude :	-122.432456
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	SL0608123509
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Global ID :	SL0608123509
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	SL0608123509
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2012-06-27
Global ID :	SL0608123509
Action Type :	RESPONSE
Action :	Well Destruction Report

Date :	2012-03-30
Global ID :	SL0608123509
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #20120330

Date :	2011-12-27
Global ID :	SL0608123509
Action Type :	ENFORCEMENT
Action :	Staff Letter - #20111227

Date :	2011-11-17
Global ID :	SL0608123509
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Date :	2011-11-16
Global ID :	SL0608123509
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Status History

Status Date :	2012-03-30
Global ID :	SL0608123509
Status :	Completed - Case Closed
Status Date :	2010-03-09
Global ID :	SL0608123509
Status :	Open - Verification Monitoring
Status Date :	2008-05-15
Global ID :	SL0608123509
Status :	Open - Site Assessment
Status Date :	2007-04-11
Global ID :	SL0608123509
Status :	Open - Site Assessment
Status Date :	2007-03-29
Global ID :	SL0608123509
Status :	Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name :	CHEVRON, FORMER STANDARD OIL SUBSTATION
Facility Address :	972 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	2012-03-30
Status :	COMPLETED - CASE CLOSED
Begin Date :	2007-03-29
Global ID :	SL0608123509
Facility Type :	LUST CLEANUP SITE
RB Case Number :	N/R
Potential Media Affected :	Other Groundwater (uses other than drinking water), Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550196
Lead Agency :	SAN MATEO COUNTY LOP

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.654097
Longitude :	-122.432456

Site History :

Extracted from CRA's November 6, 2009 Work Plan for Well Installation, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. The site was originally developed in 1925 as a Standard Oil San Francisco Substation. The 1925 Sanborn Map1 depicts three aboveground storage tanks along the southwest perimeter of the site, and an oil storage and gasoline pump in the southeastern portion the property. The 1950, 1956, and 1970 Sanborn Maps depict construction/contractor's yards located on the property and these operations could also be a potential source. In 1984, the current Burger King restaurant was constructed. March 2007 Soil Boring Investigation: In March 2007, on behalf of the Estate of Frank Gigli, Professional Service Industries (PSI), Inc. advanced soil borings B-1 through B-4 to approximately 20 feet below grade (fbg) to investigate the recognized environmental conditions identified in PSI's February 27, 2007 Phase I Environmental Assessment (ESA) related to the Former Standard Oil Substation. No groundwater was encountered in any of the borings. No hydrocarbons were detected in soil from borings B-1 and B-2. The soil sample collected at 10 fbg in boring B-3 contained 1,300 milligrams per kilogram (mg/kg) total petroleum hydrocarbons as diesel (TPHd), 4,800 mg/kg total petroleum hydrocarbons as gasoline (TPHg), and 21 mg/kg benzene, but no methyl tertiary butyl ether (MTBE). The soil sample collected at 5 fbg in boring B-4 contained 370 mg/kg TPHd, 1,200 mg/kg TPHg, and no benzene or MTBE. Several other volatile organic compounds (VOCs) that are typically related to gasoline and diesel fuels were also detected in soil samples from both borings B-3 and B-4. April 2007 Remedial Action Agreement: On April 24, 2007, the San Mateo County Health System (SMCHS) issued two letters. The first letter was a Remedial Action Agreement with the former property owner, the Estate of Frank Gigli. The second letter requested further site characterization based on PSI's April 6, 2007 report. June 2007 SMCHS Correspondence: On June 21, 2007, the SMCHS issued a Notice of Responsibility to Chevron Environmental Management Company (Chevron). February 2008 Hank's Rentals Underground Storage Tank (UST) Removal: In February 2008, PSI removed one undocumented 800-gallon UST from the adjacent Hank's Rentals Property. On behalf of Chevron, CRA was onsite to observe the UST removal and collect soil samples. At the direction of the SMCHS, CRA staff collected two compliance soil samples at approximately 10 fbg beneath the western and eastern ends of the 800-gallon UST. All petroleum hydrocarbons and metal concentrations were below San Francisco Bay Region-Regional Water Quality Control Board environmental screening levels (ESLs) for soil. The UST is not associated with the former Standard Oil station that operated at 972 El Camino Real. The UST is likely related to previous operations at the Hank's Rentals property. In addition, the manufacturer's plate on the UST, "Buehler Tank & Welding", was not identified as a brand historically associated with Standard Oil. The UST was located approximately five feet south of the property line between the former Standard Oil and Hank's Rental properties. May 2008 Unauthorized Release: On behalf of Chevron, CRA submitted the May 6, 2008 Unauthorized Contamination Site Report for the site as requested in the SMCHS's March 20, 2008 letter. July 2008 Work Plan: On behalf of Chevron, CRA submitted the July 1, 2008 Subsurface Investigation Work Plan and it was approved by the SMCHS in their letter dated January 16, 2009. The work plan proposed six soil borings to investigate hydrocarbons in soil and groundwater across the site. March 2009 Subsurface Investigation: On behalf of Chevron, CRA advanced soil borings B-7 through B-10 adjacent to and downgradient from the former ASTs and oil storage and gasoline dispenser to determine the lateral and vertical extent of hydrocarbon concentrations in soil and groundwater. Proposed borings B-5 and B-6 were abandoned due to extensive subsurface obstructions. The highest TPHd

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

concentration detected in soil was 1,300 mg/kg in boring B-8 at 5 fbg. The maximum TPHg concentration detected was 3,700 mg/kg in boring B-7 at 4.5 fbg. Low or no TPHg concentrations were detected in borings B-8, B-9, and B-10. The only benzene concentration detected in soil was 0.16 mg/kg in boring B-7 at 4.5 fbg. The TPHd and TPHg concentrations are delineated onsite. No benzene was detected in groundwater. No MTBE was detected in soil or groundwater. The objectives of the proposed scope of work are to install a network of groundwater monitoring wells onsite to establish groundwater flow, gradient, and petroleum hydrocarbon concentration trend data.

Agency URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-10-30

Contacts Summary

Global ID : SL0608123509
Contact Name : JACOB MADDEN
Contact Type : Local Agency Caseworker - Primary Caseworker
Organization Name : SAN MATEO COUNTY LOP
Address : 2000 ALAMEDA DE LAS PULGAS, Suite 100
City : SAN MATEO
Phone Number : 6503995959
Email : jmadden@smcgov.org

Global ID : SL0608123509
Contact Name : Regional Water Board
Contact Type : Regional Board Caseworker
Organization Name : SAN FRANCISCO BAY RWQCB (REGION 2)
Address : 1515 CLAY ST SUITE 1400
City : OAKLAND
Phone Number : N/R
Email : N/R

Global ID : SL0608123509
Contact Name : UUU
Contact Type : Regional Board Caseworker
Organization Name : SAN FRANCISCO BAY RWQCB (REGION 2)
Address : 1515 CLAY ST SUITE 1400
City : OAKLAND
Phone Number : N/R
Email : N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date : 2012-06-27
Global ID : SL0608123509

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Action Type : RESPONSE
Action : Well Destruction Report

Date : 2012-03-30
Global ID : SL0608123509
Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter - #20120330

Date : 2011-12-27
Global ID : SL0608123509
Action Type : ENFORCEMENT
Action : Staff Letter - #20111227

Date : 2011-11-17
Global ID : SL0608123509
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2011-11-16
Global ID : SL0608123509
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2011-06-30
Global ID : SL0608123509
Action Type : RESPONSE
Action : Request for Closure - Regulator Responded

Date : 2011-05-15
Global ID : SL0608123509
Action Type : RESPONSE
Action : Monitoring Report - Annually

Date : 2011-02-15
Global ID : SL0608123509
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Date : 2011-01-13
Global ID : SL0608123509
Action Type : ENFORCEMENT
Action : Staff Letter - #20110113

Map Id: H49
Direction: E
Distance: 0.216 mi., 1140 ft.
Elevation: 43 ft.
Relative: Lower

Site Name : CHEVRON, FORMER STANDARD OIL SUBSTATION | BURGER KING | CHEVRONNA FORMER STANDARD OIL SUBSTATION
972 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [CALEPA SITES - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367899
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date :	2010-11-15
Global ID :	SL0608123509
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly

Status History Summary

Status Date :	2012-03-30
Global ID :	SL0608123509
Status :	Completed - Case Closed
Status Date :	2010-03-09
Global ID :	SL0608123509
Status :	Open - Verification Monitoring
Status Date :	2008-05-15
Global ID :	SL0608123509
Status :	Open - Site Assessment
Status Date :	2007-04-11
Global ID :	SL0608123509
Status :	Open - Site Assessment
Status Date :	2007-03-29
Global ID :	SL0608123509
Status :	Open - Case Begin Date

Map Id: 50
Direction: ENE
Distance: 0.222 mi., 1175 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : COREY HANKS
10 CHESTNUT AVE BE: 199864
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 52367896
EPA ID: CAC003017534

HAZNET - CA

Facility Name :	COREY HANKS
Facility Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: 50
Direction: ENE
Distance: 0.222 mi., 1175 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : COREY HANKS
10 CHESTNUT AVE BE: 199864
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367896
EPA ID: CAC003017534

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC003017534
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65581788
Longitude :	-122.43283017
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	COREY HANKS
Facility Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003017534
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	COREY HANKS
Owner Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	COREY HANKS
Operator Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.655818
Longitude :	-122.43283

RCRA_NONGEN

Facility Name :	COREY HANKS
Facility Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2019-05-31
EPA ID :	CAC003017534
Mailing Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Contact :	COREY HANKS
Contact Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	480-220-4104
Contact Email :	RMARTINEZ@RMC.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Map Id: 50
Direction: ENE
Distance: 0.222 mi., 1175 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : COREY HANKS
10 CHESTNUT AVE BE: 199864
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 52367896
EPA ID: CAC003017534

RCRA_NONGEN ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	COREY HANKS
Owner/Operator Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	480-220-4104
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	COREY HANKS
Owner/Operator Address :	10 CHESTNUT AVE BE: 199864, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	480-220-4104
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	Y
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: 51
Direction: SSE
Distance: 0.223 mi., 1179 ft.
Elevation: 94 ft.
Relative: Higher

Site Name : DAVID DEZMAN
808 W. ORANGE AVE.
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946919
EPA ID: CAC002716460

HAZNET - CA

Facility Name :	DAVID DEZMAN
Facility Address :	808 W. ORANGE AVE., SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002716460
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	808 W. ORANGE AVE., SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65121262
Longitude :	-122.43543184
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2013: 151 - Asbestos containing waste, 1.2 tons to CAD982042475

HWG - CA

Facility Name :	DAVID DEZMAN
Facility Address :	808 W. ORANGE AVE., SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002716460
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	808 W. ORANGE AVE., SOUTH SAN FRANCISCO, CA 94080
Owner Name :	DAVID DEZMAN
Owner Address :	808 W. ORANGE AVE., SOUTH SAN FRANCISCO, CA 94080
Operator Name :	DAVID DEZMAN
Operator Address :	808 W. ORANGE AVE., SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65119
Longitude :	-122.43564

Map Id: M52
Direction: WNW
Distance: 0.226 mi., 1194 ft.
Elevation: 112 ft.
Relative: Higher

Site Name : JUAN FULGENCIO
207 DEL MONTE AVENUE
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946912
EPA ID: CAC002905857

HAZNET - CA

Facility Name :	JUAN FULGENCIO
Facility Address :	207 DEL MONTE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAC002905857
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	207 DEL MONTE AVENUE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65565111
Longitude :	-122.44157356
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2017: 151 - Asbestos containing waste, 0.23 tons to CAD981382732

HWG - CA

Facility Name :	JUAN FULGENCIO
Facility Address :	207 DEL MONTE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002905857
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	207 DEL MONTE AVENUE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	JUAN FULGENCIO
Owner Address :	207 DEL MONTE AVENUE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	JUAN FULGENCIO
Operator Address :	207 DEL MONTE AVENUE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	-90.0
Longitude :	180.0

Map Id: K53
Direction: NE
Distance: 0.227 mi., 1197 ft.
Elevation: 41 ft.
Relative: Lower

Site Name : PACIFIC GAS AND ELECTRIC
950 ANTOINETTE LN
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946924
EPA ID: CAC002670080

HAZNET - CA

Facility Name :	PACIFIC GAS AND ELECTRIC
Facility Address :	950 ANTOINETTE LN, SOUTH SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

Site Details

Generator EPA ID :	CAC002670080
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3401 CROW CANYON RD, SAN RAMON, CA 945830000
Latitude :	37.65640260
Longitude :	-122.43422812
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2011: 181 - Other inorganic solid waste, 33.712 tons to CAD980675276

HWG - CA

Facility Name :	PACIFIC GAS AND ELECTRIC
Facility Address :	950 ANTOINETTE LN, SOUTH SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

EPA ID :	CAC002670080
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3401 CROW CANYON RD, SAN RAMON, CA 945830000
Owner Name :	PG&E
Owner Address :	77 BEAL ST, SAN FRANCISCO, CA 941050000
Operator Name :	LARRY JEFFRIS
Operator Address :	50150 RD 426, OAKHURST, CA 936440000
Latitude :	37.657
Longitude :	-122.43426

Map Id: 54
Direction: W
Distance: 0.237 mi., 1252 ft.
Elevation: 113 ft.
Relative: Higher

Site Name : KRISTY HARDY
250 EL CAMPO DRIVE
SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 53946915
EPA ID: CAC002964506

HAZNET - CA

Facility Name :	KRISTY HARDY
Facility Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

Site Details

Generator EPA ID :	CAC002964506
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Latitude :	37.65394644
Longitude :	-122.44268440
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2018: 151 - Asbestos containing waste, 0.23000 tons to CAD982042475

HWG - CA

Facility Name :	KRISTY HARDY
Facility Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

EPA ID :	CAC002964506
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Owner Name :	TED DUANE & SUZANNE R MURRI
Owner Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Operator Name :	TED DUANE & SUZANNE R MURRI
Operator Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Latitude :	37.653946
Longitude :	-122.442684

RCRA_NONGEN

Facility Name :	KRISTY HARDY
Facility Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO

Date Form Received by Agency :	2018-06-01
EPA ID :	CAC002964506
Mailing Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Contact :	TED DUANE & SUZANNE R MURRI

Map Id: 54
Direction: W
Distance: 0.237 mi., 1252 ft.
Elevation: 113 ft.
Relative: Higher

Site Name : KRISTY HARDY
250 EL CAMPO DRIVE
SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 53946915
EPA ID: CAC002964506

RCRA_NONGEN ***(cont.)***

Contact Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	510-852-4192
Contact Email :	DANELLBAGBY@ALLIANCE-ENVIRO.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	TED DUANE & SUZANNE R MURRI
Owner/Operator Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	510-852-4192
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	TED DUANE & SUZANNE R MURRI
Owner/Operator Address :	250 EL CAMPO DRIVE, SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	510-852-4192
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: 54
Direction: W
Distance: 0.237 mi., 1252 ft.
Elevation: 113 ft.
Relative: Higher

Site Name : KRISTY HARDY
250 EL CAMPO DRIVE
SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 53946915
EPA ID: CAC002964506

RCRA_NONGEN ***(cont.)***

Notices of Violations Summary
Regulation Violated : N

Map Id: 55
Direction: ESE
Distance: 0.238 mi., 1255 ft.
Elevation: 51 ft.
Relative: Lower

Site Name : SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY | SFPUC SOUTHWOOD DR WELL & TREATEMENT FACILITY
608 SOUTHWOOD DRIVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HWG - CA, RCRA_SQG]

Envirosite ID: 991983
EPA ID: N/R

CALEPA SITES - CA

Facility Name : SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY
Facility Address : 608 SOUTHWOOD DR, SOUTH SAN FRANCISCO, 94080

Site ID : 437868
EI ID : 10762672
EI Description : Chemical Storage Facilities
Latitude : 37.652736
Longitude : -122.432836
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2023-07-21

HWG - CA

Facility Name : SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY
Facility Address : 608 SOUTHWOOD DR, SOUTH SAN FRANCISCO, CA 94080
County : SAN MATEO

EPA ID : CAR000337667
Status : Inactive
Category : FEDERAL
Type : PERMANENT
Facility Type : N/R
Mailing Address : 49 S VAN NESS AVE STE 600, SAN FRANCISCO, CA 94103
Owner Name : SFPUC SOUTHWOOD DRIVE WELL & TREATMENT
Owner Address : 608 SOUTHWOOD DR, SOUTH SAN FRANCISCO, CA 94080
Operator Name : HUMBERTO QUINONEZ
Operator Address : 49 S VAN NESS AVE STE 600, SAN FRANCISCO, CA 94103
Latitude : 37.652782
Longitude : -122.432698

Map Id: 55
Direction: ESE
Distance: 0.238 mi., 1255 ft.
Elevation: 51 ft.
Relative: Lower

Site Name : SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY | SFPUC SOUTHWOOD DR WELL & TREATEMENT FACILITY
608 SOUTHWOOD DRIVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 991983
EPA ID: N/R

RCRA_SQG

Facility Name :	SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY
Facility Address :	608 SOUTHWOOD DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
Date Form Received by Agency :	2022-04-22
EPA ID :	CAR000337667
Mailing Address :	49 SOUTH VAN NESS AVENUE, SUITE 600, SAN FRANCISCO, CA 94103
Contact :	HUMBERTO QUINONEZ
Contact Address :	49 SOUTH VAN NESS AVENUE, SUITE 600, SAN FRANCISCO, CA 94103
Contact Country :	US
Contact Telephone :	415-252-3977
Contact Email :	HUMBERTO.QUINONEZ@SFDPH.ORG
EPA Region :	09
Land Type :	County
Source Type :	Notification
Classification :	Small Quantity Generator
Description :	Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	SAN FRANCISCO PUBLIC UTILITIES COMMISSION
Owner/Operator Address :	1000 1000 EL CAMINO REAL, MILLBRAE, CA 94030
Owner/Operator Country :	US
Owner/Operator Telephone :	650-872-5900
Owner/Operator Email :	JJUNG@SFWATER.ORG
Owner/Operator Fax :	N/R
Legal Status :	County
Owner/Operator Type :	Owner
Owner/Operator Start Date :	1935-01-01
Owner/Operator End Date :	N/R

Owner/Operator Name :	SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY
Owner/Operator Address :	608 SOUTHWOOD DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	US
Owner/Operator Telephone :	415-252-3977
Owner/Operator Email :	HUMBERTO.QUINONEZ@SFDPH.ORG
Owner/Operator Fax :	N/R
Legal Status :	County
Owner/Operator Type :	Operator
Owner/Operator Start Date :	2017-11-01
Owner/Operator End Date :	N/R

Map Id: 55
Direction: ESE
Distance: 0.238 mi., 1255 ft.
Elevation: 51 ft.
Relative: Lower

Site Name : SFPUC SOUTHWOOD DRIVE WELL & TREATMENT FACILITY | SFPUC SOUTHWOOD DR WELL & TREATEMENT FACILITY
608 SOUTHWOOD DRIVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 991983
EPA ID: N/R

RCRA_SQG ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Hazardous Waste Summary

Waste Code / Name :
122 - Alkaline solution without metals (pH > 12.5)
331 - Off-specification, aged, or surplus organics
352 - Other organic solids
791 - Liquids with pH < 2
D001 - IGNITABLE WASTE
D002 - CORROSIVE WASTE

Notices of Violations Summary

Regulation Violated : N

Map Id: M56
Direction: WNW
Distance: 0.239 mi., 1261 ft.
Elevation: 103 ft.
Relative: Higher

Site Name : EMMA JEAN O'NIELL
208 INDIO DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 53946913
EPA ID: CAC002849690

HAZNET - CA

Facility Name :	EMMA JEAN O'NIELL
Facility Address :	208 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: M56
Direction: WNW
Distance: 0.239 mi., 1261 ft.
Elevation: 103 ft.
Relative: Higher

Site Name : EMMA JEAN O'NIELL
208 INDIO DR
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 53946913
EPA ID: CAC002849690

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002849690
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	208 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65521283
Longitude :	-122.44194761
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	EMMA JEAN O'NIELL
Facility Address :	208 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC002849690
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	208 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	EMMA JEAN O'NIELL
Owner Address :	208 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	EMMA JEAN O'NIELL
Operator Address :	208 INDIO DR, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.655213
Longitude :	-122.441948

Map Id: L57
Direction: E
Distance: 0.245 mi., 1292 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : ESTATE OF FRANK GIGLEY | HANKS RENTALS
932 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 52367902
EPA ID: CAC002626891

HAZNET - CA

Facility Name :	ESTATE OF FRANK GIGLEY
Facility Address :	932 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: L57
Direction: E
Distance: 0.245 mi., 1292 ft.
Elevation: 44 ft.
Relative: Lower

Site Name : ESTATE OF FRANK GIGLEY | HANKS RENTALS
932 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 52367902
EPA ID: CAC002626891

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002626891
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1777 BOREL PL STE 100, SAN MATEO, CA 944023510
Latitude :	37.65388232
Longitude :	-122.43276870
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2008: 512 - Other empty containers 30 gallons or more, 0.5 tons to CAD009466392

HWG - CA

Facility Name :	ESTATE OF FRANK GIGLEY
Facility Address :	932 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC002626891
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1777 BOREL PL STE 100, SAN MATEO, CA 944023510
Owner Name :	ESTATE OF FRANK GIGLEY
Owner Address :	1777 BOREL PL STE 100, SAN MATEO, CA 944023510
Operator Name :	RAY LAGUMARSINO
Operator Address :	1777 BOREL PL STE 100, SAN MATEO, CA 944023510
Latitude :	37.653869
Longitude :	-122.432712

Map Id: N58
Direction: ENE
Distance: 0.249 mi., 1316 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTECH AUTO | WESTBOROUGH PET HOSPITAL | AUTO STUDIO
45 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HIST UST - CA]

Envirosite ID: 52367924
EPA ID: N/R

HIST UST - CA

Facility Name :	AUTO STUDIO
Facility Address :	45 CHESTNUT, SOUTH SAN FRANCISCO, 94080
County :	San Mateo
PDF Link :	Click here for hyperlink provided by the agency.

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367925
EPA ID: CAC000649368

CALEPA SITES - CA

Facility Name :	ACUTEC AUTOS
Facility Address :	45 CHESTNUT AVENUE, SOUTH SAN FRANCISCO, 94080
Site ID :	245343
EI ID :	T0608151808
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.656265
Longitude :	-122.432844
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-12-21

Site ID :	631890
EI ID :	T0608151808
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	37.656265
Longitude :	-122.432844
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-07-21

HAZNET - CA

Facility Name :	1X ACUTECH AUTO INC
Facility Address :	45 CHESTNUT AVE, S SAN FRANCISCO, CA 94080
County :	SAN MATEO

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC000649368
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	--, SAN MATEO, CA 944040000
Latitude :	37.65627042
Longitude :	-122.43256477
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1996: 134 - Aqueous solution with total organic residues less than 10 percent, 0.336 tons to CAD980887418 1994: 223 - Unspecified oil-containing waste, 1.668 tons to CAD083166728
Facility Name :	ACUTECH AUTOS INC
Facility Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL920394851
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940800000
Latitude :	37.65636900
Longitude :	-122.43283200
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1996: 134 - Aqueous solution with total organic residues less than 10 percent, 0.294 tons to CAD980818645

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

HAZNET - CA ***(cont.)***

Facility Name :	AUTO STUDIO
Facility Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000064122
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940803228
Latitude :	37.65627042
Longitude :	-122.43256477
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	GREWALZ ANIMAL HOSPITAL DBA WESTBOROUGH PET HOSPITAL
Facility Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Site Details

Generator EPA ID :	CAL000425083
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.65636900
Longitude :	-122.43283200
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X ACUTECH AUTO INC
Facility Address :	45 CHESTNUT AVE, S SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAC000649368
Status :	Inactive
Category :	STATE

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

HWG - CA ***(cont.)***

Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	SAN MATEO, CA 944040000
Owner Name :	THE CORP
Owner Address :	N/A
Operator Name :	TERESA RIBEIRO OFF MNGR
Operator Address :	N/A
Latitude :	37.656285
Longitude :	-122.432414

Facility Name :	ACUTECH AUTOS INC
Facility Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL920394851
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940800000
Owner Name :	TAM NIKI
Owner Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940800000
Operator Name :	INACT PER 96 VQ AD
Operator Address :	N/A
Latitude :	37.655463
Longitude :	-122.433791

Facility Name :	AUTO STUDIO
Facility Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

EPA ID :	CAL000064122
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 940803228
Owner Name :	CRIS SANTIAGO/EDDIE M CHAN
Owner Address :	N/A
Operator Name :	N/R
Operator Address :	INACT PER NONDEL 98VQ FINAL, N/A
Latitude :	37.65627
Longitude :	-122.432565

Facility Name :	GREWALZ ANIMAL HOSPITAL DBA WESTBOROUGH PET HOSPITAL
Facility Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

HWG - CA ***(cont.)***

County :	SAN MATEO
EPA ID :	CAL000425083
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	GREWALZ ANIMAL HOSPITAL
Owner Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	SARABJEET GREWAL
Operator Address :	45 CHESTNUT AVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.656369
Longitude :	-122.432832

LUST REG 2 - CA

Facility Name :	ACUTEC AUTOS
Facility Address :	45 CHESTNUT AVENUE, South San Francisco, CA 94080
County :	San Mateo

Site Details

Status Date :	2003-05-13
Status :	Completed - Case Closed
Begin Date :	1991-11-21
Global ID :	T0608151808
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0007
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550089
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency Warehouse
CUF Case :	YES
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.656265
Longitude :	-122.432844
Agency URL :	Click here for hyperlink provided by the agency.

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

LUST REG 2 - CA ***(cont.)***

Last Date in Agency List : 2023-08-25

Contacts Summary

Global ID : T0608151808
Contact Name : Regional Water Board
Contact Type : Regional Board Caseworker
Organization Name : SAN FRANCISCO BAY RWQCB (REGION 2)
Address : 1515 CLAY ST SUITE 1400
City : OAKLAND
Phone Number : N/R
Email : N/R

Global ID : T0608151808
Contact Name : UUU
Contact Type : Regional Board Caseworker
Organization Name : SAN FRANCISCO BAY RWQCB (REGION 2)
Address : 1515 CLAY ST SUITE 1400
City : OAKLAND
Phone Number : N/R
Email : N/R

Global ID : T0608151808
Contact Name : JACOB MADDEN
Contact Type : Local Agency Caseworker - Primary Caseworker
Organization Name : SAN MATEO COUNTY LOP
Address : 2000 ALAMEDA DE LAS PULGAS, Suite 100
City : SAN MATEO
Phone Number : 6503995959
Email : jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date : 2007-05-15
Global ID : T0608151808
Action Type : ENFORCEMENT
Action : Other Report

Date : 2004-01-17
Global ID : T0608151808
Action Type : ENFORCEMENT

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

LUST REG 2 - CA ***(cont.)***

Action : Technical Correspondence / Assistance / Other

Date : 2004-01-13
Global ID : T0608151808
Action Type : RESPONSE
Action : Soil and Water Investigation Report

Date : 2003-11-06
Global ID : T0608151808
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2003-05-13
Global ID : T0608151808
Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter - #2

Status History

Status Date : 2003-05-13
Global ID : T0608151808
Status : Completed - Case Closed

Status Date : 1991-11-21
Global ID : T0608151808
Status : Open - Case Begin Date

Status Date : 1991-11-21
Global ID : T0608151808
Status : Open - Verification Monitoring

LUST_SAN MATEO COUNTY - CA

Facility Name : ACUTEC AUTOS
Facility Address : 45 CHESTNUT AVENUE, SOUTH SAN FRANCISCO, 94080
County : SAN MATEO

Site Details

Status Date : 2003-05-13
Status : COMPLETED - CASE CLOSED
Begin Date : 1991-11-21
Global ID : T0608151808
Facility Type : LUST CLEANUP SITE

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

LUST_SAN MATEO COUNTY - CA ***(cont.)***

RB Case Number :	41-0007
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550089
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency Warehouse
CUF Case :	YES
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.656265
Longitude :	-122.432844
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608151808
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608151808
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608151808
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Phone Number :	6503995959
Email :	jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2007-05-15
Global ID :	T0608151808
Action Type :	ENFORCEMENT
Action :	Other Report

Date :	2004-01-17
Global ID :	T0608151808
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2004-01-13
Global ID :	T0608151808
Action Type :	RESPONSE
Action :	Soil and Water Investigation Report

Date :	2003-11-06
Global ID :	T0608151808
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2003-05-13
Global ID :	T0608151808
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #2

Date :	2001-11-27
Global ID :	T0608151808
Action Type :	ENFORCEMENT
Action :	Clean Up Fund - Letter to RP

Date :	1998-02-07
Global ID :	T0608151808
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Map Id: N59
Direction: ENE
Distance: 0.249 mi., 1317 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : ACUTEC AUTOS | 1X ACUTECH AUTO INC | ACUTECH AUTOS INC
45 CHESTNUT AVE
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [CALEPA SITES - CA, HAZNET - CA, HWG - CA, LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367925
EPA ID: CAC000649368

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date :	1991-11-21
Global ID :	T0608151808
Action Type :	Other
Action :	Leak Discovery
Date :	1991-11-21
Global ID :	T0608151808
Action Type :	Other
Action :	Leak Reported
Date :	1991-11-21
Global ID :	T0608151808
Action Type :	ENFORCEMENT
Action :	* Historical Enforcement - #1

Status History Summary

Status Date :	2003-05-13
Global ID :	T0608151808
Status :	Completed - Case Closed
Status Date :	1991-11-21
Global ID :	T0608151808
Status :	Open - Case Begin Date
Status Date :	1991-11-21
Global ID :	T0608151808
Status :	Open - Verification Monitoring

Map Id: M60
Direction: WNW
Distance: 0.250 mi., 1320 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : JOHN LIM | JULIE KHOLMEISTER
210 INDIO DR
SAN FRANCISCO | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN]

Envirosite ID: 44388229
EPA ID: CAC003222146

HWG - CA

Facility Name :	JOHN LIM
Facility Address :	210 INDIO DR, SAN FRANCISCO, CA 94080

Map Id: M60
Direction: WNW
Distance: 0.250 mi., 1320 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : JOHN LIM | JULIE KHOLMEISTER
210 INDIO DR
SAN FRANCISCO | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44388229
EPA ID: CAC003222146

HWG - CA ***(cont.)***

County :	SAN FRANCISCO
EPA ID :	CAC003222146
Status :	Active
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
Owner Name :	JOHN LIM
Owner Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
Operator Name :	JOHN LIM
Operator Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
Latitude :	37.655551
Longitude :	-122.442752
Facility Name :	JULIE KHOLMEISTER
Facility Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO
EPA ID :	CAC003148650
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner Name :	JULIE KHOLMEISTER
Owner Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Operator Name :	JULIE KHOLMEISTER
Operator Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Latitude :	37.655551
Longitude :	-122.442752

RCRA_NONGEN

Facility Name :	JOHN LIM
Facility Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
County :	SAN FRANCISCO
Date Form Received by Agency :	2023-03-13
EPA ID :	CAC003222146
Mailing Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
Contact :	JOHN LIM
Contact Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	724-833-4128
Contact Email :	LAURA@8884ABATEMENT.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Map Id: M60
Direction: WNW
Distance: 0.250 mi., 1320 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : JOHN LIM | JULIE KHOLMEISTER
210 INDIO DR
SAN FRANCISCO | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44388229
EPA ID: CAC003222146

RCRA_NONGEN ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	JOHN LIM
Owner/Operator Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	724-833-4128
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	JOHN LIM
Owner/Operator Address :	210 INDIO DR, SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	724-833-4128
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Facility Name :	JULIE KHOLMEISTER
Facility Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
County :	SAN MATEO

Date Form Received by Agency :	2021-11-16
EPA ID :	CAC003148650

Map Id: M60
Direction: WNW
Distance: 0.250 mi., 1320 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : JOHN LIM | JULIE KHOLMEISTER
210 INDIO DR
SAN FRANCISCO | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44388229
EPA ID: CAC003222146

RCRA_NONGEN ***(cont.)***

Mailing Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Contact :	JULIE KHOLMEISTER
Contact Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Contact Country :	N/R
Contact Telephone :	408-799-4458
Contact Email :	TIFFANY.RELIANCE@GMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2023-11-16

Owner/Operator Summary

Owner/Operator Name :	JULIE KHOLMEISTER
Owner/Operator Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	408-799-4458
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	JULIE KHOLMEISTER
Owner/Operator Address :	210 INDIO DRIVE, SOUTH SAN FRANCISCO, CA 94080
Owner/Operator Country :	N/R
Owner/Operator Telephone :	408-799-4458
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N

Map Id: M60
Direction: WNW
Distance: 0.250 mi., 1320 ft.
Elevation: 105 ft.
Relative: Higher

Site Name : JOHN LIM | JULIE KHOLMEISTER
210 INDIO DR
SAN FRANCISCO | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44388229
EPA ID: CAC003222146

RCRA_NONGEN ***(cont.)***

Used Oil Transporter : N

Notices of Violations Summary
Regulation Violated : N

Map Id: N61
Direction: ENE
Distance: 0.276 mi., 1457 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_015_015
37.655849, -122.431968
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 49933012
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	CA4110009_015_015
Dataset Name :	DDW
Well Category :	MUNICIPAL
Data Source :	DDW
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R
Alt Well ID1 :	4110009-015
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.655849
Longitude :	-122.431968
Last Date in Agency List :	2023-10-12

Chemicals

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorododecanoic acid

Map Id: N61
Direction: ENE
Distance: 0.276 mi., 1457 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_015_015
37.655849, -122.431968
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 49933012
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Chemical Valid Value :	PFDOA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA

Map Id: N61
Direction: ENE
Distance: 0.276 mi., 1457 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_015_015
37.655849, -122.431968
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 49933012
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 2 NG/L

Map Id: N61
Direction: ENE
Distance: 0.276 mi., 1457 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_015_015
37.655849, -122.431968
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 49933012
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Reporting Limit :	2
Source Chemical Name :	2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 2 NG/L
Reporting Limit :	2

Map Id: N61
Direction: ENE
Distance: 0.276 mi., 1457 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_015_015
37.655849, -122.431968
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 49933012
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Chemical Name :	2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2021-09-21 13:00:00
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2816

Map Id: N61
Direction: ENE
Distance: 0.276 mi., 1457 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_015_015
37.655849, -122.431968
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 49933012
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: 62
Direction: E
Distance: 0.284 mi., 1503 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : SOUTH SF GROUNDWATER INVESTIGATION
EAST OF EL CAMINO REAL
South San Francisco | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST_SAN MATEO COUNTY - CA, SWRCB CLEANUP - CA]

Envirosite ID: 916360
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA

Facility Name :	SOUTH SF GROUNDWATER INVESTIGATION
Facility Address :	EAST OF EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	N/R
Status :	OPEN - SITE ASSESSMENT
Begin Date :	N/R
Global ID :	T10000004143
Facility Type :	LUST CLEANUP SITE
RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	N/R
Loc Case Number :	N/R
Lead Agency :	N/R
File Location :	N/R
CUF Case :	N/R
Caseworker :	N/R
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	N/R
DWR Groundwater Subbasin Name :	N/R
Disadvantaged Community :	N/R
Latitude :	N/R
Longitude :	N/R
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2015-01-15

Map Id: 62
Direction: E
Distance: 0.284 mi., 1503 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : SOUTH SF GROUNDWATER INVESTIGATION
EAST OF EL CAMINO REAL
South San Francisco | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST_SAN MATEO COUNTY - CA, SWRCB CLEANUP - CA] ***(cont.)***

Envirosite ID: 916360
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Contacts Summary

Global ID :	T10000004143
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	N/R
Global ID :	T10000004143
Action Type :	N/R
Action :	N/R

Status History Summary

Status Date :	N/R
Global ID :	T10000004143
Status :	N/R

SWRCB CLEANUP - CA

Facility Name :	South SF Groundwater Investigation
Facility Address :	east of El Camino Real, South San Francisco, CA 94080
County :	San Mateo

Site Details

Status Date :	2018-03-28
Status :	Active
Begin Date :	2012-06-18
Global ID :	T10000004143
Site History :	N/R
RB Case Number :	41-1311
Potential Media Affected :	Aquifer used for drinking water supply, Other Groundwater (uses other than drinking water), Under Investigation, Well used for drinking water supply
Potential Contaminants of Concern :	Tetrachloroethylene (PCE), Gasoline, MTBE / TBA / Other Fuel Oxygenates, Total Petroleum Hydrocarbons (TPH)
Local Agency :	DEPARTMENT OF PUBLIC HEALTH
Local Case Number :	N/R
Lead Agency :	SAN FRANCISCO BAY RWQCB (REGION 2)
File Location :	N/R

Map Id: 62
Direction: E
Distance: 0.284 mi., 1503 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : SOUTH SF GROUNDWATER INVESTIGATION
EAST OF EL CAMINO REAL
South San Francisco | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST_SAN MATEO COUNTY - CA, SWRCB CLEANUP - CA] ***(cont.)***

Envirosite ID: 916360
EPA ID: N/R

SWRCB CLEANUP - CA ***(cont.)***

CUF Case :	NO
Caseworker :	KAW
Case Type :	Project
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.655218
Longitude :	-122.431576
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-24

Contacts Summary

Global ID :	T10000004143
Contact Name :	KIMBERLEE WEST
Contact Type :	Regional Board Caseworker - Primary Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 Clay Street
City :	OAKLAND
Phone Number :	5106222432
Email :	kimberlee.west@waterboards.ca.gov

Regulatory Activities

Date :	2013-07-18
Global ID :	T10000004143
Action Type :	ENFORCEMENT
Action :	Site Visit / Inspection / Sampling
Date :	2013-04-30
Global ID :	T10000004143
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2012-06-29
Global ID :	T10000004143
Action Type :	RESPONSE
Action :	Site Assessment Report
Date :	2012-06-13
Global ID :	T10000004143
Action Type :	ENFORCEMENT
Action :	File review

Map Id: 62
Direction: E
Distance: 0.284 mi., 1503 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : SOUTH SF GROUNDWATER INVESTIGATION
EAST OF EL CAMINO REAL
South San Francisco | SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST_SAN MATEO COUNTY - CA, SWRCB CLEANUP - CA] ***(cont.)***

Envirosite ID: 916360
EPA ID: N/R

SWRCB CLEANUP - CA ***(cont.)***

Date :	2012-06-12
Global ID :	T10000004143
Action Type :	ENFORCEMENT
Action :	Meeting

Status History

Status Date :	2018-03-28
Global ID :	T10000004143
Status :	Active
Status Date :	2012-06-18
Global ID :	T10000004143
Status :	Open - Case Begin Date
Status Date :	2012-06-18
Global ID :	T10000004143
Status :	Informational Item / Review Complete

Map Id: L63
Direction: E
Distance: 0.293 mi., 1548 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : STAN THE ROOF MAN | 1X STAN THE ROOF MAN INC
103 1ST | 103 FIRST STREET | 103 1ST ST.
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367927
EPA ID: N/R

LUST REG 2 - CA

Facility Name :	STAN THE ROOF MAN
Facility Address :	103 1ST, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2000-08-10
Status :	Completed - Case Closed
Begin Date :	1992-08-09
Global ID :	T0608100696
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0736
Potential Media Affected :	Soil

Map Id: L63
Direction: E
Distance: 0.293 mi., 1548 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : STAN THE ROOF MAN | 1X STAN THE ROOF MAN INC
103 1ST | 103 FIRST STREET | 103 1ST ST.
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367927
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550118
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.65341
Longitude :	-122.431412
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608100696
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100696
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100696
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Map Id: L63
Direction: E
Distance: 0.293 mi., 1548 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : STAN THE ROOF MAN | 1X STAN THE ROOF MAN INC
103 1ST | 103 FIRST STREET | 103 1ST ST.
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367927
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Regulatory Activities

Date :	2006-11-01
Global ID :	T0608100696
Action Type :	RESPONSE
Action :	Other Report / Document
Date :	2006-11-01
Global ID :	T0608100696
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	1997-07-31
Global ID :	T0608100696
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1
Date :	1992-08-09
Global ID :	T0608100696
Action Type :	Other
Action :	Leak Discovery
Date :	1992-08-09
Global ID :	T0608100696
Action Type :	Other
Action :	Leak Reported

Status History

Status Date :	2000-08-10
Global ID :	T0608100696
Status :	Completed - Case Closed
Status Date :	1992-08-09
Global ID :	T0608100696
Status :	Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name :	STAN THE ROOF MAN
Facility Address :	103 1ST, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	2000-08-10
Status :	COMPLETED - CASE CLOSED
Begin Date :	1992-08-09
Global ID :	T0608100696

Map Id: L63
Direction: E
Distance: 0.293 mi., 1548 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : STAN THE ROOF MAN | 1X STAN THE ROOF MAN INC
103 1ST | 103 FIRST STREET | 103 1ST ST.
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367927
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-0736
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550118
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.65341
Longitude :	-122.431412
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608100696
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100696
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100696
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Map Id: L63
Direction: E
Distance: 0.293 mi., 1548 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : STAN THE ROOF MAN | 1X STAN THE ROOF MAN INC
103 1ST | 103 FIRST STREET | 103 1ST ST.
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367927
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Regulatory Activities

Date :	2006-11-01
Global ID :	T0608100696
Action Type :	RESPONSE
Action :	Other Report / Document
Date :	2006-11-01
Global ID :	T0608100696
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	1997-07-31
Global ID :	T0608100696
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1
Date :	1992-08-09
Global ID :	T0608100696
Action Type :	Other
Action :	Leak Discovery
Date :	1992-08-09
Global ID :	T0608100696
Action Type :	Other
Action :	Leak Reported

Status History Summary

Status Date :	2000-08-10
Global ID :	T0608100696
Status :	Completed - Case Closed
Status Date :	1992-08-09
Global ID :	T0608100696
Status :	Open - Case Begin Date

Map Id: N64
Direction: ENE
Distance: 0.295 mi., 1559 ft.
Elevation: 39 ft.
Relative: Lower

Site Name : 100879
N/R
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 10010556
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	100879
Dataset Name :	GAMA_SP-STUDY
Well Category :	MUNICIPAL
Data Source :	LLNL
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R
Alt Well ID1 :	3S/11W-26E05S
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.656446
Longitude :	-122.431923
Last Date in Agency List :	2023-01-10

Chemicals

Sample Collection Date :	2020-03-24
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 0 NG/L
Reporting Limit :	5
Source Chemical Name :	C2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1

Map Id: N64
Direction: ENE
Distance: 0.295 mi., 1559 ft.
Elevation: 39 ft.
Relative: Lower

Site Name : 100879
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 10010556
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R

Map Id: N64
Direction: ENE
Distance: 0.295 mi., 1559 ft.
Elevation: 39 ft.
Relative: Lower

Site Name : 100879
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 10010556
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Map Id: N64
Direction: ENE
Distance: 0.295 mi., 1559 ft.
Elevation: 39 ft.
Relative: Lower

Site Name : 100879
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 10010556
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Map Id: N64
Direction: ENE
Distance: 0.295 mi., 1559 ft.
Elevation: 39 ft.
Relative: Lower

Site Name : 100879
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 10010556
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Map Id: N65
Direction: ENE
Distance: 0.298 mi., 1573 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_014_014 | 4110009-014
37.656342, -122.4318
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 40228390
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	CA4110009_014_014

Map Id: N65
Direction: ENE
Distance: 0.298 mi., 1573 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_014_014 | 4110009-014
37.656342, -122.4318
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228390
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Dataset Name :	DDW
Well Category :	MUNICIPAL
Data Source :	DDW
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R
Alt Well ID1 :	4110009-014
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.656342
Longitude :	-122.4318
Last Date in Agency List :	2023-10-12

Chemicals

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: N65
Direction: ENE
Distance: 0.298 mi., 1573 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_014_014 | 4110009-014
37.656342, -122.4318
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228390
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: N65
Direction: ENE
Distance: 0.298 mi., 1573 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_014_014 | 4110009-014
37.656342, -122.4318
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228390
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: N65
Direction: ENE
Distance: 0.298 mi., 1573 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_014_014 | 4110009-014
37.656342, -122.4318
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228390
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: N65
Direction: ENE
Distance: 0.298 mi., 1573 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_014_014 | 4110009-014
37.656342, -122.4318
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228390
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 14:05:00
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: O66
Direction: NE
Distance: 0.317 mi., 1673 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : CA4110009_013_013 | 4110009-013
37.658103, -122.43319
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 40228391
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	CA4110009_013_013

Map Id: O66
Direction: NE
Distance: 0.317 mi., 1673 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : CA4110009_013_013 | 4110009-013
37.658103, -122.43319
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228391
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Dataset Name :	DDW
Well Category :	MUNICIPAL
Data Source :	DDW
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R
Alt Well ID1 :	4110009-013
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.658103
Longitude :	-122.43319
Last Date in Agency List :	2023-10-12

Chemicals

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: O66
Direction: NE
Distance: 0.317 mi., 1673 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : CA4110009_013_013 | 4110009-013
37.658103, -122.43319
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228391
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: O66
Direction: NE
Distance: 0.317 mi., 1673 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : CA4110009_013_013 | 4110009-013
37.658103, -122.43319
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228391
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: O66
Direction: NE
Distance: 0.317 mi., 1673 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : CA4110009_013_013 | 4110009-013
37.658103, -122.43319
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228391
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: O66
Direction: NE
Distance: 0.317 mi., 1673 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : CA4110009_013_013 | 4110009-013
37.658103, -122.43319
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 40228391
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:40:00
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: N67
Direction: ENE
Distance: 0.321 mi., 1695 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_007_007 | 4110009-007
37.656582, -122.431481
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 23674691
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	CA4110009_007_007

Map Id: N67
Direction: ENE
Distance: 0.321 mi., 1695 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_007_007 | 4110009-007
37.656582, -122.431481
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674691
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Dataset Name :	DDW
Well Category :	MUNICIPAL
Data Source :	DDW
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	380
Bottom Depth of Screen (Ft) :	580
CAS Number :	N/R
Alt Well ID1 :	4110009-007
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.656582
Longitude :	-122.431481
Last Date in Agency List :	2023-10-12

Chemicals

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2813
Source Well Depth (Ft) :	N/R

Map Id: N67
Direction: ENE
Distance: 0.321 mi., 1695 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_007_007 | 4110009-007
37.656582, -122.431481
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674691
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluoro-4-methoxybutanoic acid (PFMBA)
Chemical Valid Value :	PFMBA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2825
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluoro(2-ethoxyethane) sulfonic acid (PFEESA)
Chemical Valid Value :	PFEESA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2826
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Nonafluoro-3,6-dioxaheptanoic acid (NFDHA)
Chemical Valid Value :	NFDHA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2827
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R

Map Id: N67
Direction: ENE
Distance: 0.321 mi., 1695 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_007_007 | 4110009-007
37.656582, -122.431481
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674691
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	6:2 Fluorotelomer sulfonic acid (1H,1H,2H,2H-Perfluorooctanesulfonic acid)
Chemical Valid Value :	6:2FTS
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2820
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluoropentanoicacid
Chemical Valid Value :	PFPA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2824
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	8:2 Fluorotelomer sulfonic acid (1H, 1H, 2H, 2H-Perfluorodecanesulfonic acid)
Chemical Valid Value :	8:2FTS
Result :	< 2 NG/L
Reporting Limit :	2

Map Id: N67
Direction: ENE
Distance: 0.321 mi., 1695 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_007_007 | 4110009-007
37.656582, -122.431481
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674691
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Chemical Name :	2822
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluoropentanesulfonoicacid
Chemical Valid Value :	PFPES
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2828
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	4:2 Fluorotelomer sulfonic acid (1H, 1H, 2H, 2H-Perfluorohexanesulfonic acid)
Chemical Valid Value :	4:2FTS

Map Id: N67
Direction: ENE
Distance: 0.321 mi., 1695 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_007_007 | 4110009-007
37.656582, -122.431481
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674691
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2821
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluoro-3-methoxypropanoic acid (PFMPA)
Chemical Valid Value :	PFMPA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2823
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluorobutyric acid
Chemical Valid Value :	PFBTA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2819
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 2 NG/L

Map Id: N67
Direction: ENE
Distance: 0.321 mi., 1695 ft.
Elevation: 37 ft.
Relative: Lower

Site Name : CA4110009_007_007 | 4110009-007
37.656582, -122.431481
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674691
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Reporting Limit :	2
Source Chemical Name :	2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2023-04-27 11:30:00
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 2 NG/L
Reporting Limit :	2
Source Chemical Name :	2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 533
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367936
EPA ID: N/R

LUST REG 2 - CA

Facility Name :	CALIFORNIA GOLF CLUB
Facility Address :	844 WEST ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2000-10-04
Status :	Completed - Case Closed
Begin Date :	1986-04-22
Global ID :	T0608100653
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0687

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Potential Media Affected :	Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550111
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.654008
Longitude :	-122.439052
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608100653
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100653
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100653
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Email : N/R

Regulatory Activities

Date : 2006-11-01
Global ID : T0608100653
Action Type : RESPONSE
Action : Other Report / Document

Date : 2006-11-01
Global ID : T0608100653
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 1993-01-14
Global ID : T0608100653
Action Type : ENFORCEMENT
Action : Notice of Responsibility - #1

Date : 1993-01-14
Global ID : T0608100653
Action Type : Other
Action : Leak Discovery

Date : 1986-04-22
Global ID : T0608100653
Action Type : Other
Action : Leak Reported

Status History

Status Date : 2000-10-04
Global ID : T0608100653
Status : Completed - Case Closed

Status Date : 1986-04-22
Global ID : T0608100653
Status : Open - Case Begin Date

Facility Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO
Facility Address : 844 WEST ORANGE AVENUE, SOUTH SAN FRANCISCO, CA 94080
County : San Mateo

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Site Details

Status Date :	2022-10-11
Status :	Completed - Case Closed
Begin Date :	2005-10-03
Global ID :	T0608140024
Region :	REGION 2
Site History :	Site reopened to confirm tank removal soil data due to potential lab issues (caltech labs)
RB Case Number :	N/R
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550190
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	All Files are on GeoTracker or in the Local Agency Database
CUF Case :	NO
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.649438
Longitude :	-122.439501
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608140024
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608140024
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Phone Number :	N/R
Email :	N/R
Global ID :	T0608140024
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2022-02-16
Global ID :	T0608140024
Action Type :	RESPONSE
Action :	Site Assessment Report
Date :	2022-01-06
Global ID :	T0608140024
Action Type :	ENFORCEMENT
Action :	Notice of Violation
Date :	2020-10-15
Global ID :	T0608140024
Action Type :	RESPONSE
Action :	Site Assessment Report
Date :	2020-06-04
Global ID :	T0608140024
Action Type :	ENFORCEMENT
Action :	Staff Letter
Date :	2020-01-21
Global ID :	T0608140024
Action Type :	ENFORCEMENT
Action :	Warning Letter

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Status History

Status Date :	2022-10-11
Global ID :	T0608140024
Status :	Completed - Case Closed
Status Date :	2018-11-20
Global ID :	T0608140024
Status :	Open - Reopen Case
Status Date :	2018-11-20
Global ID :	T0608140024
Status :	Open - Verification Monitoring
Status Date :	2006-08-17
Global ID :	T0608140024
Status :	Completed - Case Closed
Status Date :	2006-06-05
Global ID :	T0608140024
Status :	Open - Verification Monitoring

LUST_SAN MATEO COUNTY - CA

Facility Name :	CALIFORNIA GOLF CLUB
Facility Address :	844 WEST ORANGE AVENUE, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	2000-10-04
Status :	COMPLETED - CASE CLOSED
Begin Date :	1986-04-22
Global ID :	T0608100653
Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-0687
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550111
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.654008
Longitude :	-122.439052
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608100653
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100653
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100653
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	2006-11-01
Global ID :	T0608100653
Action Type :	RESPONSE
Action :	Other Report / Document

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date :	2006-11-01
Global ID :	T0608100653
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	1993-01-14
Global ID :	T0608100653
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1
Date :	1993-01-14
Global ID :	T0608100653
Action Type :	Other
Action :	Leak Discovery
Date :	1986-04-22
Global ID :	T0608100653
Action Type :	Other
Action :	Leak Reported

Status History Summary

Status Date :	2000-10-04
Global ID :	T0608100653
Status :	Completed - Case Closed
Status Date :	1986-04-22
Global ID :	T0608100653
Status :	Open - Case Begin Date
Facility Name :	CALIFORNIA GOLF CLUB OF SAN FRANCISCO
Facility Address :	844 WEST ORANGE AVENUE, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	2022-10-11
Status :	COMPLETED - CASE CLOSED
Begin Date :	2005-10-03
Global ID :	T0608140024
Facility Type :	LUST CLEANUP SITE
RB Case Number :	N/R
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550190
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	All Files are on GeoTracker or in the Local Agency Database
CUF Case :	NO
Caseworker :	JM
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.649438
Longitude :	-122.439501
Site History :	Site reopened to confirm tank removal soil data due to potential lab issues (caltech labs)
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608140024
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608140024
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608140024
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2022-02-16
Global ID :	T0608140024
Action Type :	RESPONSE
Action :	Site Assessment Report

Date :	2022-01-06
Global ID :	T0608140024
Action Type :	ENFORCEMENT
Action :	Notice of Violation

Date :	2020-10-15
Global ID :	T0608140024
Action Type :	RESPONSE
Action :	Site Assessment Report

Date :	2020-06-04
Global ID :	T0608140024
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2020-01-21
Global ID :	T0608140024
Action Type :	ENFORCEMENT
Action :	Warning Letter

Date :	2019-01-25
Global ID :	T0608140024
Action Type :	RESPONSE
Action :	Soil and Water Investigation Workplan - Regulator Responded

Date :	2018-11-20
Global ID :	T0608140024
Action Type :	ENFORCEMENT
Action :	Staff Letter

Map Id: 68
Direction: SSW
Distance: 0.324 mi., 1711 ft.
Elevation: 120 ft.
Relative: Higher

Site Name : CALIFORNIA GOLF CLUB OF SAN FRANCISCO | CALIFORNIA GOLF CLUB | CALIFORNIA GOLF CLUB OF S F
844 WEST ORANGE AVENUE | 844 W ORANGE AVE | 844 ORANGE AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367936
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date : 2018-09-14
Global ID : T0608140024
Action Type : RESPONSE
Action : Verbal Communication

Date : 2018-08-16
Global ID : T0608140024
Action Type : ENFORCEMENT
Action : Staff Letter

Date : 2006-08-24
Global ID : T0608140024
Action Type : RESPONSE
Action : Soil and Water Investigation Report

Status History Summary

Status Date : 2022-10-11
Global ID : T0608140024
Status : Completed - Case Closed

Status Date : 2018-11-20
Global ID : T0608140024
Status : Open - Reopen Case

Status Date : 2018-11-20
Global ID : T0608140024
Status : Open - Verification Monitoring

Status Date : 2006-08-17
Global ID : T0608140024
Status : Completed - Case Closed

Status Date : 2006-06-05
Global ID : T0608140024
Status : Open - Verification Monitoring

Map Id: O69
Direction: NE
Distance: 0.334 mi., 1763 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : 100883
N/R
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 9311138
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	100883
Dataset Name :	GAMA_SP-STUDY
Well Category :	MUNICIPAL
Data Source :	LLNL
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R
Alt Well ID1 :	2S/12W-07J03S
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.658444
Longitude :	-122.43325
Last Date in Agency List :	2023-01-10

Chemicals

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 0 NG/L
Reporting Limit :	2

Map Id: O69
Direction: NE
Distance: 0.334 mi., 1763 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : 100883
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311138
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Chemical Name :	C2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2808

Map Id: O69
Direction: NE
Distance: 0.334 mi., 1763 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : 100883
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311138
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 0 NG/L
Reporting Limit :	5
Source Chemical Name :	C2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2804
Source Well Depth (Ft) :	N/R

Map Id: O69
Direction: NE
Distance: 0.334 mi., 1763 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : 100883
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311138
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R

Map Id: O69
Direction: NE
Distance: 0.334 mi., 1763 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : 100883
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311138
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-04-29
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2019-09-26
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 0 NG/L
Reporting Limit :	1.7
Source Chemical Name :	C2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R

Map Id: O69
Direction: NE
Distance: 0.334 mi., 1763 ft.
Elevation: 42 ft.
Relative: Lower

Site Name : 100883
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311138
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Analytical Method :	EPA 537 Ver 1.1,mod
Source Datum :	N/R
Source Lab Note :	N/R
Sample Collection Date :	2019-09-26
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 0 NG/L
Reporting Limit :	1.7
Source Chemical Name :	C2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537 Ver 1.1,mod
Source Datum :	N/R
Source Lab Note :	N/R

Map Id: P70
Direction: ENE
Distance: 0.391 mi., 2063 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : 100880
N/R
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 9311112
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	100880
Dataset Name :	GAMA_SP-STUDY
Well Category :	MUNICIPAL
Data Source :	LLNL
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R
Alt Well ID1 :	3S/11W-26E06S
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.656072
Longitude :	-122.429848
Last Date in Agency List :	2023-01-10

Chemicals

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2805

Map Id: P70
Direction: ENE
Distance: 0.391 mi., 2063 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : 100880
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311112
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2808
Source Well Depth (Ft) :	N/R

Map Id: P70
Direction: ENE
Distance: 0.391 mi., 2063 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : 100880
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311112
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R

Map Id: P70
Direction: ENE
Distance: 0.391 mi., 2063 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : 100880
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311112
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 0 NG/L
Reporting Limit :	5
Source Chemical Name :	C2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R

Map Id: P70
Direction: ENE
Distance: 0.391 mi., 2063 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : 100880
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311112
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1

Map Id: P70
Direction: ENE
Distance: 0.391 mi., 2063 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : 100880
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311112
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Datum :	N/R
Source Lab Note :	N/R
Sample Collection Date :	2020-03-24
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Map Id: Q71
Direction: N
Distance: 0.393 mi., 2077 ft.
Elevation: 52 ft.
Relative: Lower

Site Name : GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO
1086 GRAND AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367940
EPA ID: N/R

LUST REG 2 - CA

Facility Name :	Grand Avenue Gas
Facility Address :	1086 Grand Avenue, South San Francisco, CA 94080
County :	San Mateo

Site Details

Status Date :	2022-06-24
Status :	Completed - Case Closed
Begin Date :	2011-07-05
Global ID :	T10000003112
Region :	REGION 2
Site History :	Site Opened 7/5/2011, based on soil contamination (10,000 ppm TPH-G) detected in saturated soil.
RB Case Number :	N/R
Potential Media Affected :	Soil, Under Investigation
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550207
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	State Records Center

Map Id: Q71
Direction: N
Distance: 0.393 mi., 2077 ft.
Elevation: 52 ft.
Relative: Lower

Site Name : GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO
1086 GRAND AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367940
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

CUF Case :	YES
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Tank Closure
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.660357
Longitude :	-122.43723
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T10000003112
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T10000003112
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2022-06-25
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Letter - Notice

Date :	2022-06-24
Global ID :	T10000003112
Action Type :	ENFORCEMENT

Map Id: Q71
Direction: N
Distance: 0.393 mi., 2077 ft.
Elevation: 52 ft.
Relative: Lower

Site Name : GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO
1086 GRAND AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367940
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Action : Closure/No Further Action Letter

Date : 2022-06-03
Global ID : T10000003112
Action Type : RESPONSE
Action : Well Destruction Report

Date : 2022-03-02
Global ID : T10000003112
Action Type : ENFORCEMENT
Action : Staff Letter

Date : 2022-02-18
Global ID : T10000003112
Action Type : RESPONSE
Action : Well Destruction Workplan - Regulator Responded

Status History

Status Date : 2022-06-24
Global ID : T10000003112
Status : Completed - Case Closed

Status Date : 2021-10-07
Global ID : T10000003112
Status : Open - Eligible for Closure

Status Date : 2011-07-05
Global ID : T10000003112
Status : Open - Site Assessment

Status Date : 2011-07-05
Global ID : T10000003112
Status : Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name : GRAND AVENUE GAS
Facility Address : 1086 GRAND AVENUE, SOUTH SAN FRANCISCO, 94080
County : SAN MATEO

Site Details

Status Date : 2022-06-24
Status : COMPLETED - CASE CLOSED

Map Id: Q71
Direction: N
Distance: 0.393 mi., 2077 ft.
Elevation: 52 ft.
Relative: Lower

Site Name : GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO
1086 GRAND AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367940
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Begin Date :	2011-07-05
Global ID :	T10000003112
Facility Type :	LUST CLEANUP SITE
RB Case Number :	N/R
Potential Media Affected :	Soil, Under Investigation
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550207
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	State Records Center
CUF Case :	YES
Caseworker :	JM
How Discovered :	Tank Closure
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.660357
Longitude :	-122.43723
Site History :	Site Opened 7/5/2011, based on soil contamination (10,000 ppm TPH-G) detected in saturated soil.
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T10000003112
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T10000003112
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Map Id: Q71
Direction: N
Distance: 0.393 mi., 2077 ft.
Elevation: 52 ft.
Relative: Lower

Site Name : GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO
1086 GRAND AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367940
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2022-06-25
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Letter - Notice

Date :	2022-06-24
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2022-06-03
Global ID :	T10000003112
Action Type :	RESPONSE
Action :	Well Destruction Report

Date :	2022-03-02
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2022-02-18
Global ID :	T10000003112
Action Type :	RESPONSE
Action :	Well Destruction Workplan - Regulator Responded

Date :	2021-12-09
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2021-12-09
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Notification - Public Notice of Case Closure

Date :	2021-12-08
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Closure Summary

Map Id: Q71
Direction: N
Distance: 0.393 mi., 2077 ft.
Elevation: 52 ft.
Relative: Lower

Site Name : GRAND AVENUE GAS | GRAND AVE OLYMPIC | LIOUSE BRUSCO
1086 GRAND AVE
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367940
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date :	2021-10-07
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Email Correspondence
Date :	2021-02-24
Global ID :	T10000003112
Action Type :	ENFORCEMENT
Action :	Notice of Violation

Status History Summary

Status Date :	2022-06-24
Global ID :	T10000003112
Status :	Completed - Case Closed
Status Date :	2021-10-07
Global ID :	T10000003112
Status :	Open - Eligible for Closure
Status Date :	2011-07-05
Global ID :	T10000003112
Status :	Open - Site Assessment
Status Date :	2011-07-05
Global ID :	T10000003112
Status :	Open - Case Begin Date

Map Id: Q72
Direction: N
Distance: 0.400 mi., 2113 ft.
Elevation: 56 ft.
Relative: Lower

Site Name : CONTRERAS PAINTING
1090 GRAND
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [SLIC REG 2 - CA]

Envirosite ID: 52367939
EPA ID: N/R

SLIC REG 2 - CA

Facility Name :	CONTRERAS PAINTING
Facility Address :	1090 GRAND, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Map Id: Q72
Direction: N
Distance: 0.400 mi., 2113 ft.
Elevation: 56 ft.
Relative: Lower

Site Name : CONTRERAS PAINTING
1090 GRAND
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367939
EPA ID: N/R

SLIC REG 2 - CA ***(cont.)***

Site Details

Status Date :	2011-06-23
Status :	Completed - Case Closed
Begin Date :	2002-09-26
Global ID :	T0608106763
Region :	REGION 2

Site History :

Extracted from GEI's August 19, 2008 Report on Second Quarter 2008 Quarterly Groundwater Monitoring, San Mateo County does not take responsibility for the accuracy of the statements made or any professional interpretations made in the referenced report. In December 2002, GEI collected soil samples in a paint-spattered area along the northeast side of the building at 1090 Grand Avenue. This area had allegedly been impacted by unauthorized discharges of paint and solvent onto the exposed ground surface. Shallow soil samples were collected in the paint-spattered area from ground surface to a maximum 1.33 feet below ground surface (feet bgs). The soil samples were analyzed for total extractable petroleum hydrocarbons as mineral spirits (TEPHms) by Environmental Protection Agency (EPA) Method 8015M, and volatile organic compounds (VOCs) by EPA Method 8260B. Analytical results indicated up to 7,300 milligrams per kilogram (mg/kg) of TEPHms in the soil samples. The following VOCs were detected in the soil samples: acetone, naphthalene, 1,2,4-trimethylbenzene (1,2,4-TMB), 1,3,5-trimethylbenzene (1,3,5-TMB), n-butylbenzene (n-BB), sec-butylbenzene (sec-BB), ethylbenzene, iso-propylbenzene (iso-PB), toluene, n-propylbenzene (n-PB), trichloroethene (TCE) and xylenes.Remedial excavation of the paint spattered area was performed in September and October 2003. Confirmation soil samples were collected from the floor and sidewalls of the excavated trench. The results of confirmation sampling indicated that VOC-impacted soil remained around and below the south segment of the over-excavated trench. Residual VOC-impacted soil was identified below 5 feet depth extending into first encountered groundwater at approximately 16 feet bgs. In the south segment of the trench, confirmation soil analytical results indicated up to 4,900 mg/kg TEPHms, 7,500 micrograms per kilogram (ìg/kg) 1,2,4-TMB, 2,500 ìg/kg 1,3,5-TMB, 520 ìg/kg naphthalene, 250 ìg/kg n-BB, 150 ìg/kg n-PB, 100 ìg/kg xylenes, 91 ìg/kg sec-BB, 90 ìg/kg ethylbenzene and 66 ìg/kg iso-PB. The analytical results of a grab groundwater sample taken from below the floor of the south segment of the trench indicated 43,000 micrograms per liter (ìg/L) TEPHms, 130 ìg/L naphthalene, 110 ìg/L 1,3,5-TMB, and 94 ìg/L 1,2,4-TMB. To further evaluate the extent of soil and groundwater impact, GEI conducted in November 2004 a subsurface investigation that included the drilling of 8 soil borings, B1 to B8, respectively. Borings B1 to B4 were completed on the neighboring property at 1082 Grand Avenue, east to northeast of the trench. Borings B5 to B8 were completed on-site southeast to southwest of the trench. Soil and groundwater samples collected from the borings were analyzed for TEPHms by EPA Method 8015M and VOCs by EPA Method 8260B. Laboratory analyses results indicated no detectable levels of TEPHms or VOCs in the set of 22 soil samples collected from 2.5 to 15 feet depth from borings B1 to B8. However, laboratory analytical results of grab groundwater samples from borings B4 and B5 near the south end of the trench indicated up to 48,000 ìg/L TEPHms, 180 ìg/L 1,2,4-TMB, 75 ìg/L naphthalene, 61 ìg/L 1,3,5-TMB, 52 ìg/L xylenes, 12 ìg/L ethylbenzene, 9.7 ìg/L iso-PB, 8.9 ìg/L sec-BB , 8.2 ìg/L n-PB and 3.8 ìg/L n-BB. In February 2005 GEI supervised the backfilling of the excavated trench with clean backfill. During backfilling, GEI applied Oxygen Release Compound (ORC) manufactured by Regenesis, LTD. of Pleasant Hill, California to facilitate natural attenuation and degradation of residual petroleum hydrocarbons. In 2006, GEI performed further groundwater investigation as documented in GEI report dated May 8, 2007, "Report on Continuing Subsurface Investigation and 2006 Groundwater Monitoring, Contreras Painting, 1090 Grand Avenue, South San Francisco, CA." Two borings (B9 and B10) were completed in June 2006 on 1082 Grand Avenue, and four (4) groundwater monitoring wells (MW-1 to MW-4) were installed on-site. Except for traces of tetrachloroethene (PCE), the analytical results indicated no detectable levels of petroleum hydrocarbons or volatile organics in the grab groundwater samples from off-site borings B9 and B10. Laboratory analyses indicated 12 ìg/L and 6.2 ìg/L of PCE in groundwater sampled from borings B9 and B10, respectively.

RB Case Number :	N/R
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Stoddard solvent / Mineral Spriits / Distillates
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	559177
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency

Map Id: Q72
Direction: N
Distance: 0.400 mi., 2113 ft.
Elevation: 56 ft.
Relative: Lower

Site Name : CONTRERAS PAINTING
1090 GRAND
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367939
EPA ID: N/R

SLIC REG 2 - CA ***(cont.)***

CUF Case :	NO
Caseworker :	JM
Case Type :	Cleanup Program Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	apparent illegal disposal
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.66053
Longitude :	-122.437002
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608106763
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608106763
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608106763
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2011-06-23
Global ID :	T0608106763

Map Id: Q72
Direction: N
Distance: 0.400 mi., 2113 ft.
Elevation: 56 ft.
Relative: Lower

Site Name : CONTRERAS PAINTING
1090 GRAND
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [SLIC REG 2 - CA] ***(cont.)***

Envirosite ID: 52367939
EPA ID: N/R

SLIC REG 2 - CA ***(cont.)***

Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter - #20110623

Date : 2011-05-13
Global ID : T0608106763
Action Type : RESPONSE
Action : Well Destruction Report

Date : 2011-04-08
Global ID : T0608106763
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2011-02-15
Global ID : T0608106763
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2011-01-05
Global ID : T0608106763
Action Type : ENFORCEMENT
Action : Staff Letter - #20110105

Status History

Status Date : 2011-06-23
Global ID : T0608106763
Status : Completed - Case Closed

Status Date : 2005-01-07
Global ID : T0608106763
Status : Open - Remediation

Status Date : 2004-05-11
Global ID : T0608106763
Status : Open - Site Assessment

Status Date : 2002-09-26
Global ID : T0608106763
Status : Open - Site Assessment

Status Date : 2002-09-26
Global ID : T0608106763
Status : Open - Case Begin Date

Map Id: 73
Direction: ENE
Distance: 0.419 mi., 2214 ft.
Elevation: 57 ft.
Relative: Higher

Site Name : FINLEY CONSTRUCTION CO
125 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367941
EPA ID: N/R

LUST REG 2 - CA

Facility Name :	FINLEY CONSTRUCTION CO
Facility Address :	125 CHESTNUT, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	1992-07-09
Status :	Completed - Case Closed
Begin Date :	1989-06-22
Global ID :	T0608100215
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0226
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550046
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.658641
Longitude :	-122.430928
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608100215
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100215
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Map Id: 73
Direction: ENE
Distance: 0.419 mi., 2214 ft.
Elevation: 57 ft.
Relative: Higher

Site Name : FINLEY CONSTRUCTION CO
125 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367941
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Global ID :	T0608100215
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2006-11-01
Global ID :	T0608100215
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2006-11-01
Global ID :	T0608100215
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	1992-07-09
Global ID :	T0608100215
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1

Date :	1992-05-06
Global ID :	T0608100215
Action Type :	RESPONSE
Action :	Monitoring Report - Other

Date :	1989-06-22
Global ID :	T0608100215
Action Type :	Other
Action :	Leak Discovery

Status History

Status Date :	1992-07-09
Global ID :	T0608100215
Status :	Completed - Case Closed

Status Date :	1989-06-22
Global ID :	T0608100215

Map Id: 73
Direction: ENE
Distance: 0.419 mi., 2214 ft.
Elevation: 57 ft.
Relative: Higher

Site Name : FINLEY CONSTRUCTION CO
125 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367941
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Status :	Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name :	FINLEY CONSTRUCTION CO
Facility Address :	125 CHESTNUT, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	1992-07-09
Status :	COMPLETED - CASE CLOSED
Begin Date :	1989-06-22
Global ID :	T0608100215
Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-0226
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550046
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.658641
Longitude :	-122.430928
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608100215
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100215
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100

Map Id: 73
Direction: ENE
Distance: 0.419 mi., 2214 ft.
Elevation: 57 ft.
Relative: Higher

Site Name : FINLEY CONSTRUCTION CO
125 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367941
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org
Global ID :	T0608100215
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	2006-11-01
Global ID :	T0608100215
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2006-11-01
Global ID :	T0608100215
Action Type :	RESPONSE
Action :	Other Report / Document
Date :	1992-07-09
Global ID :	T0608100215
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1
Date :	1992-05-06
Global ID :	T0608100215
Action Type :	RESPONSE
Action :	Monitoring Report - Other
Date :	1989-06-22
Global ID :	T0608100215
Action Type :	Other
Action :	Leak Discovery
Date :	1989-06-22
Global ID :	T0608100215
Action Type :	Other
Action :	Leak Reported

Map Id: 73
Direction: ENE
Distance: 0.419 mi., 2214 ft.
Elevation: 57 ft.
Relative: Higher

Site Name : FINLEY CONSTRUCTION CO
125 CHESTNUT
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367941
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Status History Summary

Status Date :	1992-07-09
Global ID :	T0608100215
Status :	Completed - Case Closed
Status Date :	1989-06-22
Global ID :	T0608100215
Status :	Open - Case Begin Date

Map Id: R74
Direction: ESE
Distance: 0.425 mi., 2246 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL
710 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367946
EPA ID: N/R

LUST REG 2 - CA

Facility Name :	SHELL
Facility Address :	710 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2005-06-24
Status :	Completed - Case Closed
Begin Date :	1987-06-02
Global ID :	T0608100490
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0514
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550018
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency Warehouse
CUF Case :	YES
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)

Map Id: R74
Direction: ESE
Distance: 0.425 mi., 2246 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL
710 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367946
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Disadvantaged Community :	N/R
Latitude :	37.6516
Longitude :	-122.4302
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608100490
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100490
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100490
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2022-06-28
Global ID :	T0608100490
Action Type :	RESPONSE
Action :	Tank Removal Report / UST Sampling Report

Map Id: R74
Direction: ESE
Distance: 0.425 mi., 2246 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL
710 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367946
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Date : 2008-09-30
Global ID : T0608100490
Action Type : RESPONSE
Action : Phase II Environmental Site Investigation Report

Date : 2008-07-02
Global ID : T0608100490
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2007-09-28
Global ID : T0608100490
Action Type : RESPONSE
Action : Other Report / Document

Date : 2006-11-01
Global ID : T0608100490
Action Type : RESPONSE
Action : Other Report / Document

Status History

Status Date : 2005-06-24
Global ID : T0608100490
Status : Completed - Case Closed

Status Date : 1987-06-02
Global ID : T0608100490
Status : Open - Case Begin Date

Status Date : 1987-06-02
Global ID : T0608100490
Status : Open - Site Assessment

LUST_SAN MATEO COUNTY - CA

Facility Name : SHELL
Facility Address : 710 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
County : SAN MATEO

Site Details

Status Date : 2005-06-24
Status : COMPLETED - CASE CLOSED
Begin Date : 1987-06-02
Global ID : T0608100490

Map Id: R74
Direction: ESE
Distance: 0.425 mi., 2246 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL
710 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367946
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-0514
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550018
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency Warehouse
CUF Case :	YES
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.6516
Longitude :	-122.4302
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608100490
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100490
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100490
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Map Id: R74
Direction: ESE
Distance: 0.425 mi., 2246 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL
710 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367946
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2022-06-28
Global ID :	T0608100490
Action Type :	RESPONSE
Action :	Tank Removal Report / UST Sampling Report

Date :	2008-09-30
Global ID :	T0608100490
Action Type :	RESPONSE
Action :	Phase II Environmental Site Investigation Report

Date :	2008-07-02
Global ID :	T0608100490
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2007-09-28
Global ID :	T0608100490
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	2006-11-01
Global ID :	T0608100490
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	2006-11-01
Global ID :	T0608100490
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2005-06-24
Global ID :	T0608100490
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #20050624

Date :	2005-02-15
Global ID :	T0608100490
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly

Map Id: R74
Direction: ESE
Distance: 0.425 mi., 2246 ft.
Elevation: 67 ft.
Relative: Higher

Site Name : SOUTH CITY SHELL AUTO SERVICE | ORANGE AVE SHELL | SHELL
710 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | South San Francisco, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367946
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date :	2004-08-17
Global ID :	T0608100490
Action Type :	ENFORCEMENT
Action :	Email Correspondence
Date :	2004-08-15
Global ID :	T0608100490
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly

Status History Summary

Status Date :	2005-06-24
Global ID :	T0608100490
Status :	Completed - Case Closed
Status Date :	1987-06-02
Global ID :	T0608100490
Status :	Open - Case Begin Date
Status Date :	1987-06-02
Global ID :	T0608100490
Status :	Open - Site Assessment

Map Id: P75
Direction: ENE
Distance: 0.431 mi., 2279 ft.
Elevation: 35 ft.
Relative: Lower

Site Name : CA4110009_006_006 | 4110009-006
37.656491, -122.429236
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 23674690
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	CA4110009_006_006
Dataset Name :	DDW
Well Category :	MUNICIPAL
Data Source :	DDW
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	0
Bottom Depth of Screen (Ft) :	312
CAS Number :	N/R
Alt Well ID1 :	4110009-006
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R

Map Id: P75
Direction: ENE
Distance: 0.431 mi., 2279 ft.
Elevation: 35 ft.
Relative: Lower

Site Name : CA4110009_006_006 | 4110009-006
37.656491, -122.429236
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674690
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Latitude :	37.656491
Longitude :	-122.429236
Last Date in Agency List :	2023-10-12

Chemicals

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R

Map Id: P75
Direction: ENE
Distance: 0.431 mi., 2279 ft.
Elevation: 35 ft.
Relative: Lower

Site Name : CA4110009_006_006 | 4110009-006
37.656491, -122.429236
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674690
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R

Map Id: P75
Direction: ENE
Distance: 0.431 mi., 2279 ft.
Elevation: 35 ft.
Relative: Lower

Site Name : CA4110009_006_006 | 4110009-006
37.656491, -122.429236
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674690
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2809
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R

Map Id: P75
Direction: ENE
Distance: 0.431 mi., 2279 ft.
Elevation: 35 ft.
Relative: Lower

Site Name : CA4110009_006_006 | 4110009-006
37.656491, -122.429236
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674690
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES
Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R

Map Id: P75
Direction: ENE
Distance: 0.431 mi., 2279 ft.
Elevation: 35 ft.
Relative: Lower

Site Name : CA4110009_006_006 | 4110009-006
37.656491, -122.429236
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 23674690
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2803
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Sample Collection Date :	2020-05-07 13:15:00
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 3 NG/L
Reporting Limit :	3
Source Chemical Name :	2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	N/R
Source Datum :	N/R
Source Lab Note :	BSK ANALYTICAL LABORATORIES

Map Id: P76
Direction: ENE
Distance: 0.436 mi., 2301 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : 100881
N/R
CA

Database(s) : [PFAS GAMA - CA]

Envirosite ID: 9311113
EPA ID: N/R

PFAS GAMA - CA

Well Details

Well ID :	100881
Dataset Name :	GAMA_SP-STUDY
Well Category :	MUNICIPAL
Data Source :	LLNL
Well Depth (Ft) :	N/R
Top Depth of Screen (Ft) :	N/R
Bottom Depth of Screen (Ft) :	N/R
CAS Number :	N/R
Alt Well ID1 :	2S/12W-07J01S
Alt Well ID2 :	N/R
Alt Well ID3 :	N/R
Latitude :	37.656508

Map Id: P76
Direction: ENE
Distance: 0.436 mi., 2301 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : 100881
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311113
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Longitude :	-122.429161
Last Date in Agency List :	2023-01-10

Chemicals

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	4,8-Dioxa-3H-perfluorononanoic acid
Chemical Valid Value :	ADONA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2818
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorobutanesulfonic acid
Chemical Valid Value :	PFBSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2801
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 0 NG/L

Map Id: P76
Direction: ENE
Distance: 0.436 mi., 2301 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : 100881
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311113
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Reporting Limit :	2
Source Chemical Name :	C2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	N-Methyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NMEFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2808
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	N-Ethyl perfluorooctane sulfonamidoacetic acid
Chemical Valid Value :	NETFOSAA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2807
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorotetradecanoic acid
Chemical Valid Value :	PFTEDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2812
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorononanoic acid
Chemical Valid Value :	PFNA
Result :	< 0 NG/L
Reporting Limit :	2

Map Id: P76
Direction: ENE
Distance: 0.436 mi., 2301 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : 100881
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311113
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Chemical Name :	C2804
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorotridecanoic acid
Chemical Valid Value :	PFTRIDA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2813
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	9-Chlorohexadecafluoro-3-oxanonane-1-sulfonic acid
Chemical Valid Value :	9ClPF3ONS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2816
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorooctanoic sulfonate
Chemical Valid Value :	PFOS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2805
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorodecanoic acid
Chemical Valid Value :	PFNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2809

Map Id: P76
Direction: ENE
Distance: 0.436 mi., 2301 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : 100881
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311113
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	2,3,3,3-tetrafluoro-2-(1,1,2,2,3,3,3-heptafluoropropoxy) propanoic acid
Chemical Valid Value :	HFPA-DA
Result :	< 0 NG/L
Reporting Limit :	5
Source Chemical Name :	C2815
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorododecanoic acid
Chemical Valid Value :	PFDOA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2810
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	11-Chloroeicosafluoro-3-oxaundecane-1-sulfonic acid
Chemical Valid Value :	11ClPF3OUDS
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2817
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorohexanesulfonic acid
Chemical Valid Value :	PFHXSA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2803
Source Well Depth (Ft) :	N/R

Map Id: P76
Direction: ENE
Distance: 0.436 mi., 2301 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : 100881
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311113
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluoroundecanoic acid
Chemical Valid Value :	PFUNDCA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2814
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2020-07-08
Chemical Name :	Perfluorohexanoic acid
Chemical Valid Value :	PFHA
Result :	< 0 NG/L
Reporting Limit :	2
Source Chemical Name :	C2811
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537.1
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2019-04-08
Chemical Name :	Perfluorooctanoic acid
Chemical Valid Value :	PFOA
Result :	< 0 NG/L
Reporting Limit :	.91
Source Chemical Name :	C2806
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R
Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537 Ver 1.1,mod
Source Datum :	N/R
Source Lab Note :	N/R

Sample Collection Date :	2019-04-08
Chemical Name :	Perfluoroheptanoic acid
Chemical Valid Value :	PFHPA
Result :	< 0 NG/L
Reporting Limit :	.91
Source Chemical Name :	C2802
Source Well Depth (Ft) :	N/R
Source Top Depth of Screen (Ft) :	N/R

Map Id: P76
Direction: ENE
Distance: 0.436 mi., 2301 ft.
Elevation: 33 ft.
Relative: Lower

Site Name : 100881
N/R
CA

Database(s) : [PFAS GAMA - CA] ***(cont.)***

Envirosite ID: 9311113
EPA ID: N/R

PFAS GAMA - CA ***(cont.)***

Source Bottom Depth of Screen (Ft) :	N/R
Source Analytical Method :	EPA 537 Ver 1.1,mod
Source Datum :	N/R
Source Lab Note :	N/R

Map Id: R77
Direction: SE
Distance: 0.448 mi., 2365 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : CHEVRON 9-0248
687 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367948
EPA ID: N/R

LUST REG 2 - CA

Facility Name :	CHEVRON 9-0248
Facility Address :	687 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2001-12-19
Status :	Completed - Case Closed
Begin Date :	1991-08-02
Global ID :	T0608100144
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0152
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550088
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.649968
Longitude :	-122.430739
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Map Id: R77
Direction: SE
Distance: 0.448 mi., 2365 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : CHEVRON 9-0248
687 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367948
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Contacts Summary

Global ID :	T0608100144
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100144
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100144
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	2006-11-01
Global ID :	T0608100144
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2001-12-12
Global ID :	T0608100144
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	1991-08-29
Global ID :	T0608100144
Action Type :	Other
Action :	Leak Discovery

Date :	1991-08-20
Global ID :	T0608100144
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1

Map Id: R77
Direction: SE
Distance: 0.448 mi., 2365 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : CHEVRON 9-0248
687 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367948
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Date :	1991-08-02
Global ID :	T0608100144
Action Type :	Other
Action :	Leak Reported

Status History

Status Date :	2001-12-19
Global ID :	T0608100144
Status :	Completed - Case Closed

Status Date :	1991-08-02
Global ID :	T0608100144
Status :	Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name :	CHEVRON 9-0248
Facility Address :	687 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	2001-12-19
Status :	COMPLETED - CASE CLOSED
Begin Date :	1991-08-02
Global ID :	T0608100144
Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-0152
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550088
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.649968
Longitude :	-122.430739
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Map Id: R77
Direction: SE
Distance: 0.448 mi., 2365 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : CHEVRON 9-0248
687 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367948
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Contacts Summary

Global ID :	T0608100144
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100144
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100144
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	2006-11-01
Global ID :	T0608100144
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2001-12-12
Global ID :	T0608100144
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	1991-08-29
Global ID :	T0608100144
Action Type :	Other
Action :	Leak Discovery

Date :	1991-08-20
Global ID :	T0608100144
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility - #1

Map Id: R77
Direction: SE
Distance: 0.448 mi., 2365 ft.
Elevation: 68 ft.
Relative: Higher

Site Name : CHEVRON 9-0248
687 EL CAMINO REAL
SOUTH SAN FRANCISCO, CA 94080

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367948
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date :	1991-08-02
Global ID :	T0608100144
Action Type :	Other
Action :	Leak Reported

Status History Summary

Status Date :	2001-12-19
Global ID :	T0608100144
Status :	Completed - Case Closed

Status Date :	1991-08-02
Global ID :	T0608100144
Status :	Open - Case Begin Date

Map Id: R78
Direction: ESE
Distance: 0.469 mi., 2477 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669
698 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA]

Envirosite ID: 52367947
EPA ID: N/R

LUST REG 2 - CA

Facility Name :	CHEVRON 9-5669
Facility Address :	698 EL CAMINO REAL, SOUTH SAN FRANCISCO, CA 94080
County :	San Mateo

Site Details

Status Date :	2007-04-09
Status :	Completed - Case Closed
Begin Date :	1989-02-27
Global ID :	T0608100145
Region :	REGION 2
Site History :	N/R
RB Case Number :	41-0153
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Local Case Number :	550010
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency Warehouse

Map Id: R78
Direction: ESE
Distance: 0.469 mi., 2477 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669
698 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367947
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

CUF Case :	YES
Caseworker :	JM
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.6504
Longitude :	-122.4294
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-08-25

Contacts Summary

Global ID :	T0608100145
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Global ID :	T0608100145
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100145
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Map Id: R78
Direction: ESE
Distance: 0.469 mi., 2477 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669
698 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367947
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2009-07-17
Global ID :	T0608100145
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2007-04-09
Global ID :	T0608100145
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #20070409
Date :	2007-01-03
Global ID :	T0608100145
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2006-12-14
Global ID :	T0608100145
Action Type :	RESPONSE
Action :	Unknown
Date :	2006-11-29
Global ID :	T0608100145
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Status History

Status Date :	2007-04-09
Global ID :	T0608100145
Status :	Completed - Case Closed
Status Date :	2005-11-02
Global ID :	T0608100145
Status :	Open - Verification Monitoring
Status Date :	1998-03-26
Global ID :	T0608100145
Status :	Open - Site Assessment

Map Id: R78
Direction: ESE
Distance: 0.469 mi., 2477 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669
698 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367947
EPA ID: N/R

LUST REG 2 - CA ***(cont.)***

Status Date :	1989-02-27
Global ID :	T0608100145
Status :	Open - Case Begin Date

LUST_SAN MATEO COUNTY - CA

Facility Name :	CHEVRON 9-5669
Facility Address :	698 EL CAMINO REAL, SOUTH SAN FRANCISCO, 94080
County :	SAN MATEO

Site Details

Status Date :	2007-04-09
Status :	COMPLETED - CASE CLOSED
Begin Date :	1989-02-27
Global ID :	T0608100145
Facility Type :	LUST CLEANUP SITE
RB Case Number :	41-0153
Potential Media Affected :	Other Groundwater (uses other than drinking water)
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN MATEO COUNTY LOP
Loc Case Number :	550010
Lead Agency :	SAN MATEO COUNTY LOP
File Location :	Local Agency Warehouse
CUF Case :	YES
Caseworker :	JM
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	N/R
Calwater Watershed Name :	South Bay - San Mateo Bayside (204.40)
DWR Groundwater Subbasin Name :	Westside (2-035)
Disadvantaged Community :	N/R
Latitude :	37.6504
Longitude :	-122.4294
Site History :	N/R
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-30

Contacts Summary

Global ID :	T0608100145
Contact Name :	JACOB MADDEN
Contact Type :	Local Agency Caseworker - Primary Caseworker
Organization Name :	SAN MATEO COUNTY LOP
Address :	2000 ALAMEDA DE LAS PULGAS, Suite 100
City :	SAN MATEO
Phone Number :	6503995959
Email :	jmadden@smcgov.org

Map Id: R78
Direction: ESE
Distance: 0.469 mi., 2477 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669
698 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367947
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Global ID :	T0608100145
Contact Name :	UUU
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Global ID :	T0608100145
Contact Name :	Regional Water Board
Contact Type :	Regional Board Caseworker
Organization Name :	SAN FRANCISCO BAY RWQCB (REGION 2)
Address :	1515 CLAY ST SUITE 1400
City :	OAKLAND
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2009-07-17
Global ID :	T0608100145
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2007-04-09
Global ID :	T0608100145
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #20070409

Date :	2007-01-03
Global ID :	T0608100145
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2006-12-14
Global ID :	T0608100145
Action Type :	RESPONSE
Action :	Unknown

Map Id: R78
Direction: ESE
Distance: 0.469 mi., 2477 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669
698 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367947
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Date : 2006-11-29
Global ID : T0608100145
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2006-11-21
Global ID : T0608100145
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2006-11-01
Global ID : T0608100145
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2006-11-01
Global ID : T0608100145
Action Type : RESPONSE
Action : Other Report / Document

Date : 2006-09-07
Global ID : T0608100145
Action Type : ENFORCEMENT
Action : Staff Letter - #20060907

Date : 2006-08-21
Global ID : T0608100145
Action Type : RESPONSE
Action : Other Workplan

Status History Summary

Status Date : 2007-04-09
Global ID : T0608100145
Status : Completed - Case Closed

Status Date : 2005-11-02
Global ID : T0608100145
Status : Open - Verification Monitoring

Status Date : 1998-03-26
Global ID : T0608100145
Status : Open - Site Assessment

Map Id: R78
Direction: ESE
Distance: 0.469 mi., 2477 ft.
Elevation: 66 ft.
Relative: Higher

Site Name : CAMINO PETROLEUM | ANDREW S JUNER DBA CAMINO PETROLEUM | CHEVRON 9-5669
698 EL CAMINO REAL
SOUTH SAN FRANCISCO | S SAN FRANCISCO | SO SAN FRANCISCO, CA

Database(s) : [LUST REG 2 - CA, LUST_SAN MATEO COUNTY - CA] ***(cont.)***

Envirosite ID: 52367947
EPA ID: N/R

LUST_SAN MATEO COUNTY - CA ***(cont.)***

Status Date :	1989-02-27
Global ID :	T0608100145
Status :	Open - Case Begin Date

Map Id: 79
Direction: E
Distance: 0.635 mi., 3351 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : MANTEGANI SITE
735 COMMERCIAL AVENUE
South San Francisco | SOUTH SAN FRANCISCO, CA

Database(s) : [ENVIROSTOR - CA]

Envirosite ID: 52367942
EPA ID: N/R

ENVIROSTOR - CA

Facility Name :	Mantegani Site
Facility Address :	735 Commercial Avenue, South San Francisco, CA 94080
County :	SAN MATEO

Site Details

Cleanup Date :	2007-02-20
Cleanup Status :	Certified
Site Type :	Voluntary Cleanup
Site Type Detailed :	Voluntary Agreement
Acreage :	0.81
APN :	014-022-0460, 014-022-0470, 014-022-0480, 014-022-0490, 014-022-0500, 014022490
National Priorities List :	NO
Regulatory Agencies Involved :	DTSC - Site Cleanup Program; RWQCB 2 - San Francisco Bay; SAN MATEO COUNTY
Lead Agency :	DTSC - Site Cleanup Program
Project Manager :	N/R
Supervisor :	Denise Tsuji
Office :	Cleanup Berkeley
Envirostor ID :	70000073
Site Code :	201499
Assembly :	21
Senate :	13
Congressional District :	15
Special Program :	Voluntary Agreement - Standard Voluntary Agreement
Past Uses :	NURSERY
Potential COC :	DDD; Dieldrin; DDT; DDE
Confirmed COC :	DDD; Dieldrin; DDT; DDE
Potential Media Affected :	Soil

Map Id: 79
Direction: E
Distance: 0.635 mi., 3351 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : MANTEGANI SITE
735 COMMERCIAL AVENUE
South San Francisco | SOUTH SAN FRANCISCO, CA

Database(s) : [ENVIROSTOR - CA] ***(cont.)***

Envirosite ID: 52367942
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Restricted Use :	NO
Site Management Req :	N/R
Funding :	Responsible Party
Latitude :	37.656075
Longitude :	-122.425015
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2023-10-06

Alias :
APN - 014-022-0460
APN - 014-022-0470
APN - 014-022-0480
APN - 014-022-0490
APN - 014-022-0500
APN - 014022490
Alternate Name - 735 Commercial Avenue
EPA (FRS #) - 110033608585
Envirostor ID Number - 70000073
GeoTracker Global ID - SL0608169862
Project Code (Site Code) - 201499

Completed Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Completed Date :	2007-02-20
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Removal Action Completion Report
Comments :	Report documents the nexts undertaken to breakdown dieldrin and DDT/DDE/DDD.

Completed Date :	2007-02-20
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Certification
Comments :	Documents the in-situ bioremediation of soil impacted with dieldrin and DDT. Soil remediation results indicate Site cleanup reached the goal of a 10 ^(-6) risk factor.

Completed Date :	2007-01-09
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Fieldwork

Map Id: 79
Direction: E
Distance: 0.635 mi., 3351 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : MANTEGANI SITE
735 COMMERCIAL AVENUE
South San Francisco | SOUTH SAN FRANCISCO, CA

Database(s) : [ENVIROSTOR - CA] ***(cont.)***

Envirosite ID: 52367942
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Comments :

Fieldwork completed. Confirmation sampling indicates the bioremediation technique has successfully degraded the total DDT concentrations at the Site to levels below the Site specific cleanup goal. However, it was unable to completely degrade the dieldrin concentrations at the Site. The dieldrin site cleanup goal has been revised to a 95% UCL of 125 parts per billion from 30 ppb. The new cleanup represents a risk of 5 x 10^-6.

Completed Date :	2007-01-05
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Other Report
Comments :	Realized project costs have gone over the estimated project cost. A letter was prepared by DTSC to explain the cost overrun.
Completed Date :	2006-12-20
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Removal Action Completion Report
Comments :	The December 20, 2006 sampling indicates that the dieldrin concentrations are dropping. Only one the eleven samples collect had a dieldrin concentration higher than the cleanup goal. Additional soil samples will be collected in the area of that sample the week of January 5, 2006.
Completed Date :	2006-10-30
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Removal Action Completion Report
Comments :	Dieldrin concentrations are is still elevated above the site cleanup goal. Further sampling is required. Soil pH has dropped again, the soil pH will be adjusted upward with lime.
Completed Date :	2006-09-27
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Removal Action Completion Report
Comments :	Dieldrin still above the site cleanup goal. It was determined that soil pH is too low and needs to be adjusted upward. Lime was added.
Completed Date :	2006-09-13
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Removal Action Completion Report

Map Id: 79
Direction: E
Distance: 0.635 mi., 3351 ft.
Elevation: 31 ft.
Relative: Lower

Site Name : MANTEGANI SITE
735 COMMERCIAL AVENUE
South San Francisco | SOUTH SAN FRANCISCO, CA

Database(s) : [ENVIROSTOR - CA] ***(cont.)***

Envirosite ID: 52367942
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Comments :	The bioremediation process is working in reducing the pesticide concentrations in the soil. However, the process is taking longer than anticipated. The process requires more fertilizer, lime, and time than estimated. Site will be re-evaluated in approximately two to three weeks.
Completed Date :	2006-08-09
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Letter - Demand
Comments :	N/R
Completed Date :	2006-08-01
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Removal Action Completion Report
Comments :	Soil dieldrin concentration is still above the Site Cleanup goal

No unmappable sites reported.

FEDERAL RCRA NON-CORRACTS TSD FACILITIES LIST

ARCHIVED RCRA TSDF: Resource Conservation and Recovery Act hazardous waste transportation storage disposal and treatment facilities

Agency Version Date: 09/01/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 11/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 09/01/2023

RCRA_TSDF: Resource Conservation and Recovery Act hazardous waste transportation storage disposal and treatment facilities

Agency Version Date: 09/01/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 11/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 09/01/2023

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS

FEMA UST: FEMA underground storage tank listing

Agency Version Date: 06/07/2023
Agency Update Frequency: Varies
Planned Next Contact: 11/28/2023
Agency: FEMA
Agency Contact: 202-212-5283
Most Recent Contact: 09/01/2023

INDIAN UST R9: Underground Storage Tanks on Indian Land in EPA Region 9

Agency Version Date: 09/20/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/15/2023
Agency: U.S. Environmental Protection Agency Region 9
Agency Contact: 855-246-3642
Most Recent Contact: 09/20/2023

AST - CA: Listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act

Agency Version Date: 09/04/2023
Agency Update Frequency: No update
Planned Next Contact: 11/29/2023
Agency: California Environmental Protection Agency Unified Program Section
Agency Contact: 916-327-5092
Most Recent Contact: 09/04/2023

FID UST - CA: The State Water Resource Control Board's Facility Inventory Database underground storage tank locations listing

Agency Version Date: 08/08/2023
Agency Update Frequency: Varies
Planned Next Contact: 01/29/2024
Agency: California Environmental Protection Agency
Agency Contact: 916-341-5791
Most Recent Contact: 11/02/2023

HIST AST - CA: Historical listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act

Agency Version Date: 07/19/2019
Agency Update Frequency: Quarterly
Planned Next Contact: 12/04/2023
Agency: California Environmental Protection Agency Unified Program Section
Agency Contact: 916-327-5092
Most Recent Contact: 09/07/2023

HIST UST - CA: Historical UST listing

Agency Version Date: 12/23/2021
Agency Update Frequency: Varies
Planned Next Contact: 02/14/2024
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 11/20/2023

FEDERAL CERCLIS LIST

CERCLIS NFRAP: The CERCLIS sites with No Further Remedial Action Planned from the CERCLIS program database. The Environmental Protection Agency decommissioned the CERCLIS data in 2014. The last update was November 12, 2013.

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 10/03/2023

CERCLIS-HIST: The CERCLIS program database contains information on the assessment and remediation of federal hazardous waste sites. The Environmental Protection Agency decommissioned the CERCLIS data in 2014. The last update was November 12, 2013.

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 10/03/2023

FEDERAL FACILITY: Sites where Federal Facilities Restoration and Reuse Office (FFRRO) arranged cleanup for Base Closure and Property Transfer at Federal Facilities

Agency Version Date: 10/03/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8712
Most Recent Contact: 10/03/2023

FEDERAL RCRA CORRACTS FACILITIES LIST

CORRACTS: List of facilities where Resource Conservation and Recovery Act Corrective Action Program used to investigate and remediate hazardous releases

Agency Version Date: 09/01/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 11/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-1667
Most Recent Contact: 09/01/2023

HIST CORRACTS 2: List of facilities where Resource Conservation and Recovery Act Corrective Action Program used to investigate and remediate hazardous releases that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/19/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-1667
Most Recent Contact: 10/25/2023

FEDERAL DELISTED NPL SITE LIST

DELISTED NPL: National Priority List of sites that were delisted and no longer require action

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 10/03/2023

FEDERAL ERNS LIST

ERNS: Emergency Response Notification System records of reported spills

Agency Version Date: 09/27/2023
Agency Update Frequency: Annually
Planned Next Contact: 12/22/2023
Agency: National Response Center United States Coast Guard
Agency Contact: N/R
Most Recent Contact: 09/27/2023

FEDERAL INSTITUTIONAL CONTROLS / ENGINEERING CONTROLS REGISTRIES

FED E C: Federal listing of remediation sites with engineering controls

Agency Version Date: 10/25/2023
Agency Update Frequency: Varies
Planned Next Contact: 01/19/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 10/25/2023

FED I C: Federal listing of remediation sites with institutional controls

Agency Version Date: 10/25/2023
Agency Update Frequency: Varies
Planned Next Contact: 01/19/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 10/25/2023

RCRA IC_EC: Sites with institutional or engineering controls related to Resource Conservation and Recovery Act

Agency Version Date: 10/09/2023
Agency Update Frequency: Varies
Planned Next Contact: 01/03/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 10/09/2023

FEDERAL RCRA GENERATORS LIST

HIST RCRA_CESQG: List of Resource Conservation and Recovery Act licensed conditionally exempt small quantity generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/19/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 10/25/2023

HIST RCRA_LQG: List of Resource Conservation and Recovery Act licensed large quantity generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/22/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 10/26/2023

HIST RCRA_NONGEN: List of Resource Conservation and Recovery Act licensed non-generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/19/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 10/25/2023

HIST RCRA_SQG: List of Resource Conservation and Recovery Act licensed small quantity generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/19/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 10/25/2023

RCRA_NONGEN: Resource Conservation and Recovery Act listing of licensed non-generators

Agency Version Date: 09/01/2023
Agency Update Frequency: Varies
Planned Next Contact: 11/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 09/01/2023

RCRA_SQG: Resource Conservation and Recovery Act listing of licensed small quantity generators

Agency Version Date: 09/01/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 11/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 09/01/2023

FEDERAL RCRA GENERATORS LIST (cont.)

RCRA_VSQG: Resource Conservation and Recovery Act listing of licensed very small quantity generators.

Agency Version Date: 09/01/2023
Agency Update Frequency: Varies
Planned Next Contact: 11/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 09/01/2023

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land in EPA Region 9

Agency Version Date: 09/20/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/14/2023
Agency: U.S. Environmental Protection Agency Region 9
Agency Contact: 855-246-3642
Most Recent Contact: 09/20/2023

LUST REG 2 - CA: Leaking underground storage tanks in Region 2: Alameda Contra Costa San Francisco Santa Clara (north of Morgan Hill) San Mateo Marin Sonoma Napa Solano counties

Agency Version Date: 07/04/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/25/2023
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 09/28/2023

LUST_SAN MATEO COUNTY - CA: San Mateo county leaking underground storage tank listing

Agency Version Date: 09/28/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/25/2023
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 09/28/2023

SLIC REG 2 - CA: List of Region 2 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 07/04/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/25/2023
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 09/28/2023

FEDERAL NPL SITE LIST

NPL: List of priority contaminated sites among identified releases or threatened releases of hazardous substances pollutants or contaminants nationally

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 10/03/2023

NPL EPA R9 GIS: Geospatial data for the Environmental Protection Agency Region 9 National Priority List subject to environmental regulation

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-2132
Most Recent Contact: 10/03/2023

SEMS_FINAL NPL: All Included National Priority List Sites

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 10/03/2023

SEMS_PROPOSED NPL: All Proposed National Priority List Sites

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 10/03/2023

STATE- AND TRIBAL - EQUIVALENT CERCLIS

ENVIROSTOR - CA: Department of Toxic Substances Controls

Agency Version Date: 08/28/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 02/16/2024
Agency: Department of Toxic Substances Control
Agency Contact: 916-327-1077
Most Recent Contact: 11/22/2023

OIL & GAS CLEANUP - CA: List of SWRCB Oil & Gas Cleanup Sites from GeoTracker Site Cleanup Program database.

Agency Version Date: 07/04/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/25/2023
Agency: California Regional Water Quality Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 09/28/2023

SWRCB CLEANUP - CA: List of SWRCB Cleanups from Geotracker including CAF, Sampling Points, and Projects.

Agency Version Date: 07/04/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/25/2023
Agency: California Regional Water Quality Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 09/28/2023

TOXIC PITS - CA: Listing of Toxic Pit Cleanup Act sites

Agency Version Date: 06/16/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/07/2023
Agency: State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 09/12/2023

STATE RCRA GENERATORS LIST

HWG - CA: Hazardous waste generator listing

Agency Version Date: 08/21/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 02/09/2024
Agency: Department of Toxic Substances Control
Agency Contact: N/R
Most Recent Contact: 11/15/2023

STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

SWF/LF - CA: Solid Waste Information System's facility listing of solid waste facilities and landfills

Agency Version Date: 08/16/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 02/06/2024
Agency: Department of Resources Recycling and Recovery
Agency Contact: 916-341-6066
Most Recent Contact: 11/10/2023

STATE AND TRIBAL BROWNFIELD SITES

TRIBAL BROWNFIELDS: Tribal brownfield remediation site listing

Agency Version Date: 02/10/2017
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 02/12/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 11/16/2023

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES

CDL - CA: Listing of Meth and clandestine drug labs maintained by the Department of Toxic Substances Control

Agency Version Date: 09/06/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/01/2023
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 09/06/2023

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES (cont.)

SCH - CA: Listing of possible hazardous material contamination sites on existing school properties

Agency Version Date: 07/03/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/25/2023
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 09/28/2023

LOCAL BROWNFIELD LISTS

FED BROWNFIELDS: Federal brownfield remediation sites

Agency Version Date: 07/03/2023
Agency Update Frequency: Semi Annually
Planned Next Contact: 12/25/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 09/28/2023

LOCAL LAND RECORDS

LIENS 2: Comprehensive Environmental Response Compensation and Liability Act sites with liens

Agency Version Date: 05/11/2017
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 02/13/2024
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 11/17/2023

HIST LIENS - CA: The Department of Toxic Substances Control's listing of property locations with environmental liens that is no longer in current agency list.

Agency Version Date: 12/04/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/04/2024
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 10/10/2023

LIENS - CA: The Department of Toxic Substances Control's listing of property locations with environmental liens

Agency Version Date: 08/16/2023
Agency Update Frequency: Varies
Planned Next Contact: 02/06/2024
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 11/10/2023

RECORDS OF EMERGENCY RELEASE REPORTS

HMIRS (DOT): Hazardous Material spills reported by the Department of Transportation

Agency Version Date: 08/24/2023
Agency Update Frequency: Varies
Planned Next Contact: 02/14/2024
Agency: U.S. Department of Transportation
Agency Contact: (202) 366-4996
Most Recent Contact: 11/20/2023

LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES

TRIBAL ODI: Indian land open dump inventory for all regions

Agency Version Date: 08/01/2023
Agency Update Frequency: Varies
Planned Next Contact: 01/22/2024
Agency: Indian Health Service
Agency Contact: 301-443-3593
Most Recent Contact: 10/26/2023

SWRCY - CA: Listing of facilities which perform recycled material processing activities

Agency Version Date: 04/27/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 01/16/2024
Agency: California Department of Resources Recycling and Recovery (CalRecycle)
Agency Contact: 916-341-6066
Most Recent Contact: 10/20/2023

OTHER ASCERTAINABLE RECORDS

COAL GAS: Manufactured Gas Plant locations

Agency Version Date: 09/07/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/04/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 09/07/2023

CORRECTIVE ACTIONS_2020: In 2009 the EPA created the 2020 Corrective Action Baseline list of contaminated or potentially contaminated sites with a cleanup goal to complete 95% by the year 2020. The names on the list indicate the facility owners who may or may not have caused the contamination.

Agency Version Date: 12/21/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 12/19/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: N/R
Most Recent Contact: 09/22/2023

DOD: Department of Defense sites from the Protected Areas Database (PAD-US)

Agency Version Date: 10/03/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/28/2023
Agency: United States Geologic Survey (USGS)
Agency Contact: 1-888-275-8747
Most Recent Contact: 10/03/2023

ECHO: ECHO is EPA Enforcement and Compliance History Online website to search for facilities in your community to assess their compliance with environmental regulations related to CAA, CWA, RCRA, & SDWA.

Agency Version Date: 06/02/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 11/23/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-1667
Most Recent Contact: 08/29/2023

FUDS: Defense sites that require cleanup

Agency Version Date: 07/18/2023
Agency Update Frequency: Varies
Planned Next Contact: 01/08/2024
Agency: US Army Corps of Engineering
Agency Contact: (202) 761-0011
Most Recent Contact: 10/12/2023

HIST DOD: Department of Defense historical sites

Agency Version Date: 10/03/2023
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 12/28/2023
Agency: Environmental Protection Agency
Agency Contact: (800) 424-9346
Most Recent Contact: 10/03/2023

HIST PCS ENF: List of permitted facilities to discharge wastewater (Federal equivalent to NPDES) that are no longer in current agency list.

Agency Version Date: 12/08/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/12/2024
Agency: Environmental Protection Agency
Agency Contact: (202) 564-6582
Most Recent Contact: 10/18/2023

ICIS: Comprised of all Federal Administrative and Judicial enforcement information [intended to replace PCS] by tracking enforcement and compliance information (also contains what used to be known as FFTS)

Agency Version Date: 06/06/2023
Agency Update Frequency: Varies
Planned Next Contact: 11/27/2023
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 08/31/2023

LUCIS: Land Use Control Information Systems

Agency Version Date: 03/08/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 11/24/2023
Agency: Department of the Navy: BRAC PMO
Agency Contact: (619) 532-0900
Most Recent Contact: 08/30/2023

OTHER ASCERTAINABLE RECORDS (cont.)

LUCIS 2: Land Use Control Information Systems

Agency Version Date: 01/17/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 01/01/2024
Agency: Department of the Navy: BRAC PMO
Agency Contact: (619) 532-0900
Most Recent Contact: 10/05/2023

NPL AOC: Areas of Concern related to NPL remediation sites

Agency Version Date: 10/03/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/28/2023
Agency: Environmental Protection Agency
Agency Contact: N/R
Most Recent Contact: 10/03/2023

NPL LIENS: National Priority List of sites with Liens

Agency Version Date: 10/03/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/28/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 10/03/2023

PADS: Listing of generators transporters commercial store/ brokers and disposers of PCB

Agency Version Date: 10/02/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/27/2023
Agency: Environmental Protection Agency
Agency Contact: (703) 308-8404
Most Recent Contact: 10/02/2023

PCB TRANSFORMER: Disposal and Storage of Polychlorinated Biphenyl (PCB) Waste

Agency Version Date: 10/16/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 01/10/2024
Agency: Environmental Protection Agency
Agency Contact: (703) 308-8404
Most Recent Contact: 10/16/2023

PFAS NPL: List of NPL sites with PFAS or PFOA contamination

Agency Version Date: 06/20/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/11/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 09/14/2023

PFAS TRIS: List of TRIS sites where PFAS or PFOA are used/manufactured/ treated/ transported/released.

Agency Version Date: 08/31/2023
Agency Update Frequency: Varies
Planned Next Contact: 11/27/2023
Agency: U.S. Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 08/31/2023

CALEPA SITES - CA: CalEPA Regulated Sites from the Certified Unified Program Agencies (CUPA).

Agency Version Date: 06/08/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 11/28/2023
Agency: California Environmental Protection Agency Unified Program Section
Agency Contact: 916-327-5092
Most Recent Contact: 09/01/2023

CIWQS - CA: California Integrated Water Quality System database facilities listing which includes owner information, violations, inspections, and other regulatory matters

Agency Version Date: 05/26/2023
Agency Update Frequency: Varies
Planned Next Contact: 02/12/2024
Agency: CA State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 11/16/2023

OTHER ASCERTAINABLE RECORDS (cont.)

CIWQS 2 - CA: California Integrated Water Quality System database facilities listing which includer owner information violations inspections and other regulatory matters

Agency Version Date: 06/16/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/07/2023
Agency: CA State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 09/12/2023

DRYCLEANERS - CA: Listing of drycleaning facilities

Agency Version Date: 09/09/2014
Agency Update Frequency: Quarterly
Planned Next Contact: 02/14/2024
Agency: California EPA Air Resources Board
Agency Contact: 916-324-3013
Most Recent Contact: 11/20/2023

FA - CA: Listing of the Department of Toxic Substance Control's Financial Assurance report sites and facilities

Agency Version Date: 07/03/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/22/2023
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 09/27/2023

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters

Agency Version Date: 04/05/2021
Agency Update Frequency: Annually
Planned Next Contact: 02/14/2024
Agency: California Environmental Protection Agency
Agency Contact: 916-341-5791
Most Recent Contact: 11/20/2023

HIST HAZNET - CA: List of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters that are no longer in current agency list.

Agency Version Date: 10/10/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/12/2024
Agency: California Environmental Protection Agency
Agency Contact: 916-341-5791
Most Recent Contact: 10/18/2023

HIST HWP - CA: List of the Department of Toxic Substance Control's hazardous waste transporters and corrective action that are no longer in current agency list.

Agency Version Date: 01/18/2019
Agency Update Frequency: Annually
Planned Next Contact: 12/20/2023
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 09/25/2023

HIST LDS - CA: List of areas of land on or in which hazardous waste is placed or the largest area in which there is significant likelihood of mixing hazardous waste constituents in the same area that are no longer in current agency list.

Agency Version Date: 05/20/2018
Agency Update Frequency: Annually
Planned Next Contact: 01/18/2024
Agency: State Water Qualilty Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 10/24/2023

HIST MCS - CA: List of the State Water Resources Control Boards investigation and remediation of water quality issues at military facilities that is no longer in current agency list.

Agency Version Date: 09/24/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 02/12/2024
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 11/16/2023

HIST NFA - CA: Historical No further action cleanup sites listing

Agency Version Date: 03/21/2019
Agency Update Frequency: Quarterly
Planned Next Contact: 01/09/2024
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 10/13/2023

OTHER ASCERTAINABLE RECORDS (cont.)

HWM COMMERCIAL FACILITIES - CA: Listing of all commercial hazardous waste permitted off-site transfer recycling treatment storage and disposal facilities

Agency Version Date: 09/21/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/18/2023
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-5308
Most Recent Contact: 09/21/2023

HWP - CA: Facility listing of the Department of Toxic Substance Control's hazardous waste transporters and corrective action

Agency Version Date: 10/02/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/27/2023
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 10/02/2023

HWT - CA: Listing of registered hazardous waste transporters

Agency Version Date: 10/09/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 01/03/2024
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 10/09/2023

LDS - CA: List of Land Disposal Cleanup Sites from Geotracker

Agency Version Date: 07/04/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/25/2023
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 09/28/2023

MCS - CA: List of Military Cleanup Sites from Geotracker

Agency Version Date: 07/04/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/25/2023
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 09/28/2023

MWMP - CA: Listing of treatment and transfer stations that properly handle and dispose of medical waste that are permitted and inspected by the Medical Waste Management Program

Agency Version Date: 07/10/2023
Agency Update Frequency: Varies
Planned Next Contact: 12/29/2023
Agency: California-Health Human Services Department of Public Health
Agency Contact: 916-449-5661
Most Recent Contact: 10/04/2023

MWMP 2 - CA: Listing of facilities that generate permitted medical waste and are inspected by the Medical Waste Management Program

Agency Version Date: 01/13/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 12/19/2023
Agency: California-Health Human Services Department of Public Health
Agency Contact: 916-449-5661
Most Recent Contact: 09/22/2023

NFA - CA: No further action cleanup sites listing

Agency Version Date: 08/28/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 02/16/2024
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 11/22/2023

NFE - CA: Unconfirmed contaminated properties listing

Agency Version Date: 08/28/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 02/16/2024
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 11/22/2023

OTHER ASCERTAINABLE RECORDS (cont.)

NPDES - CA: Listing of facilities with wastewater and NPDES permits including stormwater

Agency Version Date: 10/19/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 01/15/2024
Agency: State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 10/19/2023

PERCHLORATE 2 - CA: Listing of contaminated sites where the primary known chemical is perchlorate

Agency Version Date: 08/24/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 02/14/2024
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 11/20/2023

PFAS - CA: List of PFAS sites and areas of interest

Agency Version Date: 09/11/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/07/2023
Agency: California State Water Resources Control Board
Agency Contact: N/R
Most Recent Contact: 09/11/2023

PFAS DOD - CA: List of DoD facilities conducting PFAS investigations

Agency Version Date: 09/11/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/07/2023
Agency: California State Water Resources Control Board
Agency Contact: N/R
Most Recent Contact: 09/11/2023

PFAS GAMA - CA: PFOS & PFAS GAMA Well Sampling program

Agency Version Date: 09/06/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/01/2023
Agency: California State Water Resources Control Board
Agency Contact: N/R
Most Recent Contact: 09/06/2023

RFR - CA: State Water Resources Control Board Regulated Facility Report database listing which includes program agency type and their permit status

Agency Version Date: 05/15/2023
Agency Update Frequency: Varies
Planned Next Contact: 01/30/2024
Agency: CA State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 11/03/2023

WDR - CA: List of Waste Discharge Requirement Sites.

Agency Version Date: 05/30/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 02/14/2024
Agency: State Water Resources Control Board
Agency Contact: N/R
Most Recent Contact: 11/20/2023

WDS - CA: Listing of waste discharge system reporting facilities

Agency Version Date: 06/28/2023
Agency Update Frequency: Quarterly
Planned Next Contact: 12/19/2023
Agency: State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 09/22/2023

SUBJECT PROPERTY ADDRESS:

South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA 94080

SUBJECT PROPERTY COORDINATES:

Latitude(North):	37.654462 - 37°39'16.1"
Longitude(West):	-122.437419 - -122°26'14.7"
Universal Transverse Mercator:	Zone 10N
UTM X (Meters):	549624.19
UTM Y (Meters):	4167626.78
State Plane Coordinates:	0403 - California Zone 3 (US Survey Feet)
X Coordinate (Feet):	6000842.573 E
Y Coordinate (Feet):	2066572.156 N

ELEVATION:

Elevation:	60 ft. above sea level

USGS TOPOGRAPHIC MAP:

Subject Property Map:	37122-F4 San Francisco South, CA
Most Recent Revision:	2018

GEOHYDROLOGY DATA:

SUBJECT PROPERTY TOPOGRAPHY:

Topographic Gradient: South

DFIRM FLOOD ZONE:

	DFIRM Flood
Subject Property County:	Electronic Data:
SAN MATEO	Yes - refer to the PROPERTY PROXIMITY MAP and AREA MAP
Flood Plain Panel at Subject Property:	06081C0043F (Eff. date 4/5/2019) 06081C0039F (Eff. date 4/5/2019)
Additional Panels in search area:	06081C0037E (Eff. date 10/16/2012) 06081C0041E (Eff. date 10/16/2012)

FEMA FLOOD ZONE:

	FEMA Flood
Subject Property County:	Electronic Data:
SAN MATEO	Yes - refer to the PROPERTY PROXIMITY MAP and AREA MAP
Flood Plain Panel at Subject Property:	0650620001B

Additional Panels in search area:	0650620002B 0650620008B 0650620007B 0603170000B 0603110025B 0603160000B 0603110012B


NATIONAL WETLAND INVENTORY:


	NWI Electronic
NWI Quad at Subject Property:	Data Coverage:
San Francisco South	Yes - refer to the Geological Findings Map

LITHOSTRATIGRAPHIC INFORMATION:

ROCK STRATIGRAPHIC UNIT:		GEOLOGIC AGE IDENTIFICATION
Era:	Cenozoic	Category: 4 Q Quaternary
System:	Quaternary	
Series:	Quaternary	
Code:	Q	


SURROUNDING ELEVATION PROFILES:





SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 9...
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: November 22, 2023



Subject Property — SSURGO — STATSGO

SOIL COMPOSITION IN GENERAL AREA OF SUBJECT PROPERTY:

Agency source: Soil Conservation Service, US Department of Agriculture

SOIL MAP ID 1	SSURGO
USDA Soil Name	Urban land,Miscellaneous area
USDA Soil Texture	No data
Hydrologic Soil Group	Not Reported
Soil Drainage Class	Not Reported
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Not Reported

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-15	No data	No data	No data	0-0.01	0-0

SOIL MAP ID 2	SSURGO
USDA Soil Name	Orthents,Taxon above family
USDA Soil Texture	Not Reported
Hydrologic Soil Group	Not Reported
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Not Reported

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-152		No data	No data	0-0	0-0

SOIL MAP ID 3	SSURGO
USDA Soil Name	Orthents,Taxon above family
USDA Soil Texture	Not Reported
Hydrologic Soil Group	Not Reported
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Not Reported

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-152		No data	No data	0-0	0-0

SOIL MAP ID 4 **SSURGO**

USDA Soil Name	Urban land,Miscellaneous area
USDA Soil Texture	No data
Hydrologic Soil Group	Not Reported
Soil Drainage Class	Not Reported
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Not Reported

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-15	No data	No data	No data	0-0.01	0-0

SOIL MAP ID 5 **SSURGO**

USDA Soil Name	Urban land,Miscellaneous area
USDA Soil Texture	No data
Hydrologic Soil Group	Not Reported
Soil Drainage Class	Not Reported
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Not Reported

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-15	No data	No data	No data	0-0.01	0-0

SOIL MAP ID 6 **SSURGO**

USDA Soil Name	Urban land,Miscellaneous area
USDA Soil Texture	No data
Hydrologic Soil Group	Not Reported
Soil Drainage Class	Not Reported
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Not Reported

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-15	No data	No data	No data	0-0.01	0-0

SOIL MAP ID A **STATSGO**

USDA Soil Name	Urban land,Miscellaneous area
USDA Soil Texture	Not Reported
Hydrologic Soil Group	Not Reported
Soil Drainage Class	Not Reported
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Not Reported

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-6		No data	No data	No data	No data

WATER AGENCY DATA:

WATER AGENCY SEARCH DISTANCES:

DATABASE:	SEARCH DISTANCE (MILES):
NWIS	1.000
OIL & GAS WELLS - CA	1.000
PWS	1.000
WELLS - GAMA - CA	0.000

DISTANCE TO NEAREST:	DISTANCE:
NWIS	0.566 mi / 2986 ft
OIL & GAS WELLS - CA	N/A
PWS	0.780 mi / 4121 ft
WELLS - GAMA - CA	N/A

FEDERAL WATER AGENCY DATA SUMMARY:

MAP ID:	WELL ID:	LOCATION FROM SP:
4	11162720	1/2 - 1 Mile E
8	MAUREEN BROWN | CA3200054	1/2 - 1 Mile SE
15	11162722	1/2 - 1 Mile ESE


Note: PWS System location is not always the same as well location.

STATE/LOCAL WATER AGENCY DATA SUMMARY:

MAP ID:	WELL ID:	LOCATION FROM SP:
No Wells Found	N/R	N/R

SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 9...
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: November 22, 2023



Subject Property
NWI
Basins (No Data)
NWIS
Geologic Cluster
Oil & Gas Wells (No Data)
Geological Site

Map Id: 1
Direction: ESE
Distance: 0.062 mi., 327 ft.
Elevation: 57 ft.
Relative: Lower

Site Name : BLDG
37.653811, -122.435797
SAN FRANCISCO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 43160606
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2021-04-09
Action :	Add
FAA Study Number :	2020AWP12785OE
OBS Number :	06-236030
Obstacle Type :	BLDG
City Name :	SAN FRANCISCO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00050
Above Mean Sea Level Height (Feet) :	00110
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	37 39 13.72N
Longitude :	122 26 08.87W

Map Id: 2
Direction: ENE
Distance: 0.133 mi., 703 ft.
Elevation: 57 ft.
Relative: Lower

Site Name : BLDG
37.655833, -122.435
SOUTH SAN FRANCI, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 50133346
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2022-05-31
Action :	Add
FAA Study Number :	2021AWP01705OE
OBS Number :	06-242736
Obstacle Type :	BLDG
City Name :	SOUTH SAN FRANCI
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00054
Above Mean Sea Level Height (Feet) :	00116
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	37 39 21.00N
Longitude :	122 26 06.00W

Map Id: 3
Direction: ENE
Distance: 0.213 mi., 1125 ft.
Elevation: 40 ft.
Relative: Lower

Site Name : BLDG
37.656, -122.433331
SAN FRANCISCO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 50129076
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2022-05-27
Action :	Add
FAA Study Number :	2020AWP08046OE
OBS Number :	06-242737
Obstacle Type :	BLDG
City Name :	SAN FRANCISCO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00082
Above Mean Sea Level Height (Feet) :	00122
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	37 39 21.60N
Longitude :	122 25 59.99W

Map Id: 4
Direction: E
Distance: 0.566 mi., 2987 ft.
Elevation: 27 ft.
Relative: Lower

Site Name : 11162720
37.653823, -122.426361
CA

Database(s) : [NWIS]

Envirosite ID: 9125855
EPA ID: N/R

NWIS

Site Identification Number :	11162720
Site Type :	Stream
Station Name :	COLMA C A SOUTH SAN FRANCISCO CA
Agency :	U.S. Geological Survey
District :	N/R
State :	CA
County :	San Mateo County
Country :	USA
Land Net Location :	N/R
Name of Location Map :	N/R
Scale of Location Map :	N/R
Altitude of Gage/Land Surface :	12.53
Method Altitude Determined :	Level or other surveyed method.
Altitude Accuracy :	.01
Altitude Datum :	National Geodetic Vertical Datum of 1929
Hydrologic Unit :	San Francisco Bay
Drainage Basin :	N/R
Topographic Setting :	N/R
Flags for the Type of Data Collected:	NNNNNNNNNNNNNNNNNNNNNNNNNNNNI
Flags for Instruments at Site :	NNNNNNNNNNNNNNNNNNNNNNNNNNNNN
Date of First Construction :	N/R
Date Site Established or Inventoried:	N/R
Drainage Area :	10.8
Contributing Drainage Area :	N/R

Map Id: 4
Direction: E
Distance: 0.566 mi., 2987 ft.
Elevation: 27 ft.
Relative: Lower

Site Name : 11162720
37.653823, -122.426361
CA

Database(s) : [NWIS] ***(cont.)***

Envirosite ID: 9125855
EPA ID: N/R

NWIS ***(cont.)***

Data Reliability :	N/R
Data-Other GW Files :	NNNNNNNN
National Aquifer :	N/R
Local Aquifer :	N/R
Local Aquifer Type :	N/R
Well Depth :	N/R
Hole Depth :	N/R
Source of Depth Data :	N/R
Project Number :	N/R
Real-Time Data Flag :	0
Peak-Streamflow Data Begin Date :	1964-01-20
Peak-Streamflow Data End Date :	1996-01-31
Peak-Streamflow Data Count :	32
Water-Quality Data Begin Date :	1965-11-17
Water-Quality Data End Date :	1982-03-01
Water-Quality Data Count :	155
Field Water-Level Measurements Begin Date:	N/R
Field Water-level Measurements End Date:	N/R
Field Water-Level Measurements Count:	0
Site-Visit Data Begin Date :	1986-10-21
Site-Visit Data End Date :	1994-03-15
Site-Visit Data Count :	33
Latitude :	37.653823
Longitude :	-122.426361
Last Date in Agency List :	2023-09-22

Map Id: 5
Direction: SE
Distance: 0.725 mi., 3827 ft.
Elevation: 84 ft.
Relative: Higher

Site Name : TOWER
37.645189, -122.430261
S. SAN FRANCISCO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 812911
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2011-09-05
Action :	Add
FAA Study Number :	2011AWP03946OE
OBS Number :	06-021690
Obstacle Type :	TOWER
City Name :	S. SAN FRANCISCO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Verified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00055
Above Mean Sea Level Height (Feet) :	00139
Horizontal Accuracy :	+-20'

Map Id: 5
Direction: SE
Distance: 0.725 mi., 3827 ft.
Elevation: 84 ft.
Relative: Higher

Site Name : TOWER
37.645189, -122.430261
S. SAN FRANCISCO, CA

Database(s) : [DIGITAL OBSTACLE] ***(cont.)***

Envirosite ID: 812911
EPA ID: N/R

DIGITAL OBSTACLE ***(cont.)***

Vertical Accuracy :	+-3'
Latitude :	37 38 42.68N
Longitude :	122 25 48.94W

Map Id: 6
Direction: W
Distance: 0.766 mi., 4043 ft.
Elevation: 231 ft.
Relative: Higher

Site Name : T-L TWR
37.654392, -122.452303
SAN FRANCISCO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 809326
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2013-10-16
Action :	Add
FAA Study Number :	N/R
OBS Number :	06-034183
Obstacle Type :	T-L TWR
City Name :	SAN FRANCISCO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	Unknown
Verification Status :	Verified
Quantity :	1
Mark Indicator :	Unknown
Above Ground Level Height (Feet) :	00105
Above Mean Sea Level Height (Feet) :	00335
Horizontal Accuracy :	+-20'
Vertical Accuracy :	+-3'
Latitude :	37 39 15.81N
Longitude :	122 27 08.29W

Map Id: 7
Direction: SSW
Distance: 0.771 mi., 4073 ft.
Elevation: 157 ft.
Relative: Higher

Site Name : UTILITY POLE
37.643194, -122.439839
SAN BRUNO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 51510994
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2022-08-31
Action :	Add
FAA Study Number :	2020AWP07479OE
OBS Number :	06-259307
Obstacle Type :	UTILITY POLE
City Name :	SAN BRUNO

Map Id: 7
Direction: SSW
Distance: 0.771 mi., 4073 ft.
Elevation: 157 ft.
Relative: Higher

Site Name : UTILITY POLE
37.643194, -122.439839
SAN BRUNO, CA

Database(s) : [DIGITAL OBSTACLE] ***(cont.)***

Envirosite ID: 51510994
EPA ID: N/R

DIGITAL OBSTACLE ***(cont.)***

State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00036
Above Mean Sea Level Height (Feet) :	00193
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	37 38 35.50N
Longitude :	122 26 23.42W

Map Id: 8
Direction: SE
Distance: 0.780 mi., 4121 ft.
Elevation: 80 ft.
Relative: Higher

Site Name : MAUREEN BROWN | CA3200054
217 COUNTRY CLUB DR.
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [PWS, PWS ENF]

Envirosite ID: 840437
EPA ID: N/R

PWS

Facility Address :	217 Country Club Dr., South San Francisco, CA 94080
PWS ID :	CA3200054
PWS Type :	Transient non-community system
PWS Name :	BIG MEADOWS SUBDIVISION
Activity Status :	Changed from public to non-public
Primary Source :	Ground water
Submission Year :	2023
Submission Year Quarter :	2023Q2
Population Served Count :	11
Service Connections Count :	18
Population Category 2 :	<10,000
Population Category 3 :	<=3300
Population Category 4 :	<10K
Population Category 5 :	<=500
Population Category 11 :	<=100
Submission Quarter :	2
Submission Status Code :	Y
First Reported Date :	1984-01-21
Last Reported Date :	2023-07-03
Deactivation Date :	2015-01-06
GW or SW :	Groundwater
Is Grant Eligible :	N
Is Outstanding Performer :	N/R
Is School or Daycare :	N
Is Source Water Protected :	N/R
Primacy Agency :	California
Primacy Type :	State

Map Id: 8
Direction: SE
Distance: 0.780 mi., 4121 ft.
Elevation: 80 ft.
Relative: Higher

Site Name : MAUREEN BROWN | CA3200054
217 COUNTRY CLUB DR.
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [PWS, PWS ENF] ***(cont.)***

Envirosite ID: 840437
EPA ID: N/R

PWS ***(cont.)***

Org Name :	BIG MEADOWS SUBDIVISION
EPA Region :	Region 9
Admin Name :	Ron Brown
Owner Type :	Private
Phone Number :	6505833386
Phone Ext Number :	N/R
Alt Phone Number :	N/R
Email Address :	rondo378@astound.net
Fax Number :	N/R
Is Wholesaler :	N
LT2 Schedule Category :	N/R
NPM Candidate :	N
CDS ID :	N/R
DBPR Schedule Category :	N/R
Outstanding Performer Date :	N/R
Season Begin Date :	01-01
Season End Date :	12-31
Source Water Protection Date :	N/R
Seasonal Startup System :	N/R
Reduced Monitoring Begin Date :	N/R
Reduced Monitoring End Date :	N/R
Reduced RTCR Monitoring :	N/R
Last Date in Agency List :	2023-09-13

PWS ENF

Facility Address :	217 Country Club Dr., South San Francisco, CA 94080

Site Details

PWS ID :	CA3200054
PWS Name :	BIG MEADOWS SUBDIVISION
EPA Region :	Region 9
Primacy Agency :	California
PWS Type :	Transient non-community system
Primacy Type :	State
Primary Source :	Ground water
Activity Status :	Changed from public to non-public
Deactivation Date :	2015-01-06
Owner Type :	Private
Phone Number :	6505833386
Last Date in Agency List :	2023-09-20

Violation Details

RTC Enforcement ID :	N/R
Violation ID :	8463399
Submission Year :	2023
Violation First Reported Date :	1984-09-30
Contaminant Name :	N/R
Rule Family :	Miscellaneous
Rule Group :	Other
Rule Name :	Miscellaneous
Violation Type :	Notification, Public

Map Id: 8
Direction: SE
Distance: 0.780 mi., 4121 ft.
Elevation: 80 ft.
Relative: Higher

Site Name : MAUREEN BROWN | CA3200054
217 COUNTRY CLUB DR.
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [PWS, PWS ENF] ***(cont.)***

Envirosite ID: 840437
EPA ID: N/R

PWS ENF ***(cont.)***

Is Health Based :	N
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	3
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	N/R
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	8463397
Submission Year :	2023
Violation First Reported Date :	1984-09-30
Contaminant Name :	N/R
Rule Family :	Miscellaneous
Rule Group :	Other
Rule Name :	Miscellaneous
Violation Type :	Notification, Public
Is Health Based :	N
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	3
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	N/R
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	8318241
Submission Year :	2023
Violation First Reported Date :	1983-09-30
Contaminant Name :	N/R
Rule Family :	Miscellaneous
Rule Group :	Other
Rule Name :	Miscellaneous
Violation Type :	Notification, Public
Is Health Based :	N
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	3
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	N/R
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

Map Id: 8
Direction: SE
Distance: 0.780 mi., 4121 ft.
Elevation: 80 ft.
Relative: Higher

Site Name : MAUREEN BROWN | CA3200054
217 COUNTRY CLUB DR.
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [PWS, PWS ENF] ***(cont.)***

Envirosite ID: 840437
EPA ID: N/R

PWS ENF ***(cont.)***

RTC Enforcement ID :	N/R
Violation ID :	302003
Submission Year :	2023
Violation First Reported Date :	2004-09-11
Contaminant Name :	Coliform (TCR)
Rule Family :	Total Coliform Rules
Rule Group :	Microbials
Rule Name :	Total Coliform Rule
Violation Type :	Maximum Contaminant Level Violation, Monthly (TCR)
Is Health Based :	Y
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	2
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	State Formal Notice of Violation issued
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	900001
Submission Year :	2023
Violation First Reported Date :	2010-02-26
Contaminant Name :	Coliform (TCR)
Rule Family :	Total Coliform Rules
Rule Group :	Microbials
Rule Name :	Total Coliform Rule
Violation Type :	Maximum Contaminant Level Violation, Monthly (TCR)
Is Health Based :	Y
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	2
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	State Violation/Reminder Notice
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	102001
Submission Year :	2023
Violation First Reported Date :	2001-12-01
Contaminant Name :	Coliform (TCR)
Rule Family :	Total Coliform Rules
Rule Group :	Microbials
Rule Name :	Total Coliform Rule
Violation Type :	Maximum Contaminant Level Violation, Monthly (TCR)
Is Health Based :	Y
Is Major Violation :	N/R
Severity Indicator Count :	N/R

Map Id: 8
Direction: SE
Distance: 0.780 mi., 4121 ft.
Elevation: 80 ft.
Relative: Higher

Site Name : MAUREEN BROWN | CA3200054
217 COUNTRY CLUB DR.
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [PWS, PWS ENF] ***(cont.)***

Envirosite ID: 840437
EPA ID: N/R

PWS ENF ***(cont.)***

Public Notification Tier :	2
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	State Violation/Reminder Notice
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	8318239
Submission Year :	2023
Violation First Reported Date :	1983-09-30
Contaminant Name :	N/R
Rule Family :	Miscellaneous
Rule Group :	Other
Rule Name :	Miscellaneous
Violation Type :	Notification, Public
Is Health Based :	N
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	3
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	N/R
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	900002
Submission Year :	2023
Violation First Reported Date :	2010-02-26
Contaminant Name :	Coliform (TCR)
Rule Family :	Total Coliform Rules
Rule Group :	Microbials
Rule Name :	Total Coliform Rule
Violation Type :	Maximum Contaminant Level Violation, Monthly (TCR)
Is Health Based :	Y
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	2
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	State Violation/Reminder Notice
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	8463401

Map Id: 8
Direction: SE
Distance: 0.780 mi., 4121 ft.
Elevation: 80 ft.
Relative: Higher

Site Name : MAUREEN BROWN | CA3200054
217 COUNTRY CLUB DR.
SOUTH SAN FRANCISCO | South San Francisco, CA 94080

Database(s) : [PWS, PWS ENF] ***(cont.)***

Envirosite ID: 840437
EPA ID: N/R

PWS ENF ***(cont.)***

Submission Year :	2023
Violation First Reported Date :	1984-09-30
Contaminant Name :	N/R
Rule Family :	Miscellaneous
Rule Group :	Other
Rule Name :	Miscellaneous
Violation Type :	Notification, Public
Is Health Based :	N
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	3
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	N/R
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

RTC Enforcement ID :	N/R
Violation ID :	8318243
Submission Year :	2023
Violation First Reported Date :	1983-09-30
Contaminant Name :	N/R
Rule Family :	Miscellaneous
Rule Group :	Other
Rule Name :	Miscellaneous
Violation Type :	Notification, Public
Is Health Based :	N
Is Major Violation :	N/R
Severity Indicator Count :	N/R
Public Notification Tier :	3
Address Line 1 :	217 Country Club Dr., South San Francisco, 94080
Address Line 2 :	N/R
Compliance Status :	System Inactive
RTC Date :	2015-01-06
Enforcement Action Description :	N/R
Admin Name :	Ron Brown
Email Address :	rondo378@astound.net

Map Id: 9
Direction: WSW
Distance: 0.788 mi., 4162 ft.
Elevation: 311 ft.
Relative: Higher

Site Name : BLDG
37.651192, -122.45205
DALY CITY, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 821314
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2013-10-16

Map Id: 9
Direction: WSW
Distance: 0.788 mi., 4162 ft.
Elevation: 311 ft.
Relative: Higher

Site Name : BLDG
37.651192, -122.45205
DALY CITY, CA

Database(s) : [DIGITAL OBSTACLE] ***(cont.)***

Envirosite ID: 821314
EPA ID: N/R

DIGITAL OBSTACLE ***(cont.)***

Action :	Change
FAA Study Number :	2010AWP03159OE
OBS Number :	06-020717
Obstacle Type :	BLDG
City Name :	DALY CITY
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Verified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00040
Above Mean Sea Level Height (Feet) :	00351
Horizontal Accuracy :	+-20'
Vertical Accuracy :	+-10'
Latitude :	37 39 04.29N
Longitude :	122 27 07.38W

Map Id: 10
Direction: SW
Distance: 0.843 mi., 4451 ft.
Elevation: 190 ft.
Relative: Higher

Site Name : BLDG
37.645556, -122.448611
SAN FRANCISCO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 821313
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2014-06-01
Action :	Change
FAA Study Number :	N/R
OBS Number :	06-001421
Obstacle Type :	BLDG
City Name :	SAN FRANCISCO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Verified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00202
Above Mean Sea Level Height (Feet) :	00380
Horizontal Accuracy :	+-50'
Vertical Accuracy :	+-3'
Latitude :	37 38 44.00N
Longitude :	122 26 55.00W

Map Id: 11
Direction: W
Distance: 0.895 mi., 4728 ft.
Elevation: 353 ft.
Relative: Higher

Site Name : T-L TWR
37.651367, -122.45415
DALY CITY, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 817921
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2016-05-16
Action :	Add
FAA Study Number :	2011AWP08606OE
OBS Number :	06-038759
Obstacle Type :	T-L TWR
City Name :	DALY CITY
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00080
Above Mean Sea Level Height (Feet) :	00433
Horizontal Accuracy :	N/R
Vertical Accuracy :	N/R
Latitude :	37 39 04.92N
Longitude :	122 27 14.94W

Map Id: A12
Direction: S
Distance: 0.939 mi., 4958 ft.
Elevation: 156 ft.
Relative: Higher

Site Name : UTILITY POLE
37.640778, -122.434822
SAN BRUNO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 52134220
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2022-10-24
Action :	Add
FAA Study Number :	2020AWP11506OE
OBS Number :	06-259309
Obstacle Type :	UTILITY POLE
City Name :	SAN BRUNO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00024
Above Mean Sea Level Height (Feet) :	00180
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	37 38 26.80N
Longitude :	122 26 05.36W

Map Id: A13
Direction: S
Distance: 0.953 mi., 5035 ft.
Elevation: 160 ft.
Relative: Higher

Site Name : UTILITY POLE
37.640583, -122.434689
SAN BRUNO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 52135224
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2022-10-24
Action :	Add
FAA Study Number :	2020AWP11505OE
OBS Number :	06-259308
Obstacle Type :	UTILITY POLE
City Name :	SAN BRUNO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00024
Above Mean Sea Level Height (Feet) :	00183
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	37 38 26.10N
Longitude :	122 26 04.88W

Map Id: 14
Direction: S
Distance: 0.958 mi., 5059 ft.
Elevation: 122 ft.
Relative: Higher

Site Name : UTILITY POLE
37.64035, -122.436719
SAN BRUNO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 52133556
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2022-10-31
Action :	Add
FAA Study Number :	2020AWP07204OE
OBS Number :	06-259286
Obstacle Type :	UTILITY POLE
City Name :	SAN BRUNO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00049
Above Mean Sea Level Height (Feet) :	00170
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	37 38 25.26N
Longitude :	122 26 12.19W

Map Id: 15
Direction: ESE
Distance: 0.991 mi., 5236 ft.
Elevation: 21 ft.
Relative: Lower

Site Name : 11162722
37.646045, -122.421917
CA

Database(s) : [NWIS]

Envirosite ID: 9126314
EPA ID: N/R

NWIS

Site Identification Number :	11162722
Site Type :	Stream
Station Name :	SPRUCE BRANCH A SOUTH SAN FRANCISCO CA
Agency :	U.S. Geological Survey
District :	N/R
State :	CA
County :	San Mateo County
Country :	USA
Land Net Location :	N/R
Name of Location Map :	SAN FRANCISCO SOUTH
Scale of Location Map :	N/R
Altitude of Gage/Land Surface :	5.50
Method Altitude Determined :	Interpolated from topographic map.
Altitude Accuracy :	12.
Altitude Datum :	National Geodetic Vertical Datum of 1929
Hydrologic Unit :	San Francisco Bay
Drainage Basin :	N/R
Topographic Setting :	N/R
Flags for the Type of Data Collected:	NNNNNNNNNNNNNNNNNNNNNNNNNNNNI
Flags for Instruments at Site :	NNNNNNNNNNNNNNNNNNNNNNNNNNNNN
Date of First Construction :	N/R
Date Site Established or Inventoried:	N/R
Drainage Area :	0.70
Contributing Drainage Area :	N/R
Data Reliability :	N/R
Data-Other GW Files :	NNNNNNNN
National Aquifer :	N/R
Local Aquifer :	N/R
Local Aquifer Type :	N/R
Well Depth :	N/R
Hole Depth :	N/R
Source of Depth Data :	N/R
Project Number :	N/R
Real-Time Data Flag :	0
Peak-Streamflow Data Begin Date :	1965-11-13
Peak-Streamflow Data End Date :	1969-01-26
Peak-Streamflow Data Count :	4
Water-Quality Data Begin Date :	1965-11-17
Water-Quality Data End Date :	1969-02-24
Water-Quality Data Count :	30
Field Water-Level Measurements Begin Date:	N/R
Field Water-level Measurements End Date:	N/R
Field Water-Level Measurements Count:	0
Site-Visit Data Begin Date :	N/R
Site-Visit Data End Date :	N/R
Site-Visit Data Count :	0
Latitude :	37.646045
Longitude :	-122.421917
Last Date in Agency List :	2023-09-22

RADON DATA:

STATE SOURCE: CA

Radon Test Results:

Zip:	Total Sites:	Cnt >=4 pCi/L:	Pct >= 4 pCi/L:	Max Result (pCi/L):
94080	96	2	2.083	15.2

FEDERAL AREA RADON INFORMATION FOR: 94080

NUMBER OF SAMPLE SITES: 3

Area:	Average Activity:	% <4 pCi/L:	% 4-20 pCi/L:	% >20 pCi/L:
first floor	0.35 pCi/L	100%	0%	0%
unknown	1.3 pCi/L	100%	0%	0%

FEDERAL EPA RADON ZONE FOR SAN MATEO COUNTY: Zone = 2

Note: Zone 1 indoor average level > 4 pCI/L

: Zone 2 indoor average level > = 2 pCI/L and <= 4 pCI/L

: Zone 3 indoor average < 2 pCI/L

HIST PWS ENF
Historical Public Water Supply locations with Enforcement Violations
Environmental Protection Agency
(800) 426-4791
List of Safe Drinking Water Information Systems (SDWIS) with enforcement violations that are no longer in current agency list.

NWIS
National Water Information Systems
United States Geological Society
(703) 648-5953
Information on all water resources for the United States. This database contains all current and historical data for the nation.

PWS
Public Water Supply
Environmental Protection Agency
(800) 426-4791
Safe drinking water information Systems

PWS ENF
Public Water Supply locations with Enforcement Violations
Environmental Protection Agency
(800) 426-4791
Safe drinking water information Systems with enforcememnt violations

WELLS - GAMA - CA
California Groundwater Ambient Monitoring Assessment
State Water Resources Control Board
916-341-5791
Brings together datasets from California state agencies including: Public Health Water Resources and Pesticide Regulation as well as from the US Geological Survey Lawrence Livermore National Laboratory and the Water Boards. It shows results for untreated raw water in different types of wells for naturally-occurring and man-made chemicals.

FLOOD Q3
Flood data
Environmental Protection Agency
(202) 566-1667
Q3 Flood Data

HYDROLOGIC UNIT
Hydrologic Unit Maps
USGS
The United States Geological Survey created a hierarchical system of hydrologic units originally called regions, sub-regions, accounting units, and cataloging units. Each unit was assigned a unique Hydrologic Unit Code (HUC). As first implemented the system had 21 regions, 221 subregions, 378 accounting units, and 2,264 cataloging units. Over time the system was changed and expanded. As of 2010 there are six levels in the hierarchy, represented by hydrologic unit codes from 2 to 12 digits long, called regions, subregions, basins, subbasins, watersheds, and subwatersheds. The table below describes the system's hydrologic unit levels and their characteristics, along with example names and codes.

WETLANDS NWI
National Wetland Inventory
U.S. Fish and Wildlife Service
(703) 358-2171
Wetland Inventory for the United States

SSURGO
Detailed Soil Data Map
Natural Resources Conservation Service: U.S. Department of Agriculture
(202) 690-4985
Detailed Soil Data Map

STATSGO & MUI
General Soil Data Map
Natural Resources Conservation Service: U.S. Department of Agriculture
(202) 690-4985
General Soil Data Map

USGS GEOLOGIC AGE
USGS Digital Data Series DDS
Natural Resources Conservation Service: U.S. Department of Agriculture
(202) 690-4985
USGS Digital Data Series DDS: Geologic Age and Rock Stratigraphic Unit

OIL & GAS WELLS - CA
Oil and Gas Well Data
State of California Department of Conservation
916-327-1042
Oil and gas well locations and detail for all 6 districts

RADON
National Radon Database
U.S. Environmental Protection Agency
215-814-2469
A study of the EPA/State Residential Radon Survey and the National Residential Radon Survey.

RADON - CA
Radon tested locations in California
California Department of Health Services
(916) 449-5674
A table of long term and short term indoor radon measurments

RADON EPA
RADON EPA
U.S. Environmental Protection Agency
215-814-2469
EPA list of Radon zones

BASINS
Better Assessment Science Integrating point & Non-point Sources
U.S. Environmental Protection Agency
855-246-3642
Integrated geographical information system national watershed data and environmental assessment known as Better Assessment Science Integrating point & Non-point Sources

DIGITAL OBSTACLE
Obstacles of interest to aviation users
Federal Aviation Administration
855-379-6518
The Digital Obstacle File describes all known obstacles of interest to aviation users in the U.S. with limited coverage of the Pacific the Caribbean Canada and Mexico. The obstacles are assigned unique numerical identifiers; accuracy codes and listed in order of ascending latitude within each state or area by FAA Region.

EPICENTERS
National Geographical Data Center
National Geographical Data Center
303-497-6826
List of recent and historic earthquakes and information.

FLOOD DFIRM
National Flood Hazard Layer Database
Federal Emergency Management Agency
The National Flood Hazard Layer Database (NFHL) is a computer database that contains the flood hazard map information from FEMAs Flood Map Modernization program. These map data are from Digital Flood Insurance Rate Map (DFIRM) databases and Letters of Map Revision.

APPENDIX C

Historical Research Documentation

Historical Aerial Photo Report | 2023

Order Number: 92757
Report Generated: 11/25/2023

Project Name: South San Francisco Fire Station #63
Project Number: 3818.0008ES114B

South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA, 94080

Contact us at:
(866) 211-2028
envirositecorp.com

Historical Aerial Photo Report 2023

Envirosite's Historical Aerial Photo Report is designed to assist in evaluating a subject property resulting from past activities. Envirosite's Historical Aerial Photo Report includes a search of available historical aerial photographs, dating back to the 1930s, or earliest available photographs.

ENVIROSITE SEARCHED SOURCES

SUBJECT PROPERTY:

South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA, 94080

YEAR:	***SCALE:***	***SOURCE:***
1941	1" = 500'	U.S.D.A
1943	1" = 500'	U.S.D.A
1946	1" = 500'	U.S.D.A
1956	1" = 500'	U.S.D.A
1960	1" = 1,000'	U.S.G.S
1965	1" = 500'	U.S.D.A
1967	1" = 1,000'	U.S.G.S
1968	1" = 500'	U.S.G.S
1970	1" = 1,000'	U.S.G.S
1971	1" = 1,000'	U.S.G.S
1974	1" = 500'	U.S.G.S
1975	1" = 1,000'	U.S.G.S
1977	1" = 1,000'	U.S.G.S
1982	1" = 1,000'	NHAP
1983	1" = 1,000'	U.S.G.S
1985	1" = 1,000'	U.S.G.S
1987	1" = 500'	U.S.D.A
1988	1" = 1,000'	NAPP
1991	1" = 1,000'	U.S.G.S
1993	1" = 500'	DOQ
1995	1" = 1,000'	U.S.G.S
1998	1" = 500'	U.S.D.A
2000	1" = 500'	U.S.D.A
2001	1" = 500'	U.S.D.A
2005	1" = 500'	NAIP
2009	1" = 500'	NAIP
2010	1" = 500'	NAIP
2012	1" = 500'	NAIP
2014	1" = 500'	NAIP
2016	1" = 500'	NAIP
2018	1" = 500'	NAIP
2020	1" = 500'	NAIP
2022	1" = 500'	NAIP

Disclaimer - Copyright and Trademark Notice

All information contained in this report are based on data available from various public, government and other sources and are based upon the best data available from those sources. The information available in this report may be available from other sources and is not exclusive or the exclusive property of Envirosite Corporation.

NO WARRANTY EXPRESSED OR IMPLIED, IS MADE IN CONNECTION WITH THIS REPORT, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. ALL RISK IS ASSUMED BY USER AND Envirosite assumes no liability for faulty or inaccurate information. The Reports may utilize a variety of public and other sources reasonably available to Envirosite. Envirosite cannot, and does not assure, warrant, guarantee or assume any liability for the correctness, comprehensiveness, timeliness or completeness of any of such information, nor is the information in any Report to be construed as legal advice with respect to environmental risks associated with any property. Envirosite shall not be liable to anyone for any claims, causes of action, suits, damages, losses, costs and expenses (including, without limitation, attorneys' fees and costs) arising out of or caused by this report regardless of the acts, errors or omissions, or negligence of Envirosite. Any damages shall be limited to the purchase price of the report.

Purchaser of the report accepts the report "As Is". The report is intended only to provide information only and should not be considered as providing any legal advice, prediction, forecast, or fact as to the environmental risk for any specific property. Reports are proprietary to Envirosite, and contain copyrighted material and trademarks of Envirosite. All other trademarks used herein are the property of their respective owners. All rights of Envirosite as to the Reports are reserved.

FLIGHT YEAR:
1941

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1943

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1946

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1956

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1960

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1965

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1967

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1968

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1970

Subject Cannot Be Centered

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1971

Subject Cannot Be Centered

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1974

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1975

N
W E
S

Scale: 1" = 1,000'




FLIGHT YEAR:
1977

Best Quality Available

Cloud Cover on Photo

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1982

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1983

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1985

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1987

N
W E
S

Scale: 1" = 500'




FLIGHT YEAR:
1988

Subject Cannot Be Centered

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1991

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1993

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
1995

Subject Cannot Be Centered

N
W E
S

Scale: 1" = 1,000'



FLIGHT YEAR:
1998

N
W E
S


Scale: 1" = 500'



FLIGHT YEAR:
2000

N
W E
S


Scale: 1" = 500'



FLIGHT YEAR:
2001

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
2005

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
2009

N
W E
S


Scale: 1" = 500'



FLIGHT YEAR:
2010

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
2012

N
W E
S


Scale: 1" = 500'



FLIGHT YEAR:
2014

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
2016

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
2018

N
W E
S


Scale: 1" = 500'



FLIGHT YEAR:
2020

N
W E
S

Scale: 1" = 500'



FLIGHT YEAR:
2022

N
W E
S

Scale: 1" = 500'



Historical Topographic Map Report | 2023

Order Number: 92757

Report Generated: 11/22/2023

Project Name: South San Francisco Fire Station #63

Project Number: 3818.0008ES114B

South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA 94080

Contact us at:
(866) 211-2028
envirositecorp.com

Envirosite's Historical Topographic Map Report is designed to assist in evaluating a subject property resulting from past activities. Envirosite's Historical Topographic Map Report includes a search of USGS historical topographic maps, dating back to the early 1900s.

TOPOGRAPHIC MAPS FOUND:

	Map Name:	Year:	Revision Year:	Scale:
1.	San Mateo	1892	N/R	1 : 62500
2.	San Mateo	1896	N/R	1 : 62500
3.	San Mateo	1899	N/R	1 : 62500
4.	San Mateo	1915	N/R	1 : 62500
5.	San Mateo	1939	N/R	1 : 62500
6.	San Mateo	1943	N/R	1 : 62500
7.	San Francisco South	1947	N/R	1 : 24000
8.	San Francisco South	1950	N/R	1 : 24000
9.	San Francisco South	1956	1968	1 : 24000
10.	San Francisco South	1956	1973	1 : 24000
11.	San Francisco South	1956	1980	1 : 24000
12.	San Francisco South	1956	N/R	1 : 24000
13.	San Francisco South	1993	N/R	1 : 24000
14.	San Francisco South	1995	N/R	1 : 24000
15.	San_Francisco_South	2012	N/R	1 : 24000
16.	San_Francisco_South	2015	N/R	1 : 24000
17.	San_Francisco_South	2018	N/R	1 : 24000
18.	San_Francisco_South	2021	N/R	1 : 24000

The USGS 7.5 minute series includes scales 1:24,000 / 1:25,000 / 1:31,680. The USGS 15 minute series includes scales 1:48,000 / 1:62,500 / 1:63,360. The USGS 30x60 minute series scale is 1:100,000.

Disclaimer - Copyright and Trademark Notice

All information contained in this report are based on data available from various public, government and other sources and are based upon the best data available from those sources. The information available in this report may be available from other sources and is not exclusive or the exclusive property of Envirosite Corporation.

NO WARRANTY EXPRESSED OR IMPLIED, IS MADE IN CONNECTION WITH THIS REPORT, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. ALL RISK IS ASSUMED BY USER AND Envirosite assumes no liability for faulty or inaccurate information. The Reports may utilize a variety of public and other sources reasonably available to Envirosite. Envirosite cannot, and does not assure, warrant, guarantee or assume any liability for the correctness, comprehensiveness, timeliness or completeness of any of such information, nor is the information in any Report to be construed as legal advice with respect to environmental risks associated with any property. Envirosite shall not be liable to anyone for any claims, causes of action, suits, damages, losses, costs and expenses (including, without limitation, attorneys' fees and costs) arising out of or caused by this report regardless of the acts, errors or omissions, or negligence of Envirosite. Any damages shall be limited to the purchase price of the report.


Purchaser of the report accepts the report "As Is". The report is intended only to provide information only and should not be considered as providing any legal advice, prediction, forecast, or fact as to the environmental risk for any specific property. Reports are proprietary to Envirosite, and contain copyrighted material and trademarks of Envirosite. All other trademarks used herein are the property of their respective owners. All rights of Envirosite as to the Reports are reserved.

SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Mateo	MAP YEAR:	1892	REVISION YEAR:	N/R
SCALE:	1 : 62500	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Mateo	MAP YEAR:	1896	REVISION YEAR:	N/R
SCALE:	1 : 62500	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Mateo	MAP YEAR:	1899	REVISION YEAR:	N/R
SCALE:	1 : 62500	Part	1		



SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Mateo	MAP YEAR:	1915	REVISION YEAR:	N/R
SCALE:	1 : 62500	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Mateo	MAP YEAR:	1939	REVISION YEAR:	N/R
SCALE:	1 : 62500	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Mateo	MAP YEAR:	1943	REVISION YEAR:	N/R
SCALE:	1 : 62500	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1947	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1950	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1956	REVISION YEAR:	1968
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1956	REVISION YEAR:	1973
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1956	REVISION YEAR:	1980
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1956	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1993	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San Francisco South	MAP YEAR:	1995	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San_Francisco_South	MAP YEAR:	2012	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San_Francisco_South	MAP YEAR:	2015	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San_Francisco_South	MAP YEAR:	2018	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		




SUBJECT NAME: South San Francisco Fire Station #63
ADDRESS: 71 Camaritas Ave, South San Francisco, CA, 94080
LAT/LONG: 37.654462 / -122.437419

PREPARED FOR: Cameron-Cole - Alameda
ORDER #: 92757
REPORT DATE: 11/22/2023

SUBJECT QUAD:

MAP NAME:	San_Francisco_South	MAP YEAR:	2021	REVISION YEAR:	N/R
SCALE:	1 : 24000	Part	1		



City Directory Report | 2023

Order Number: 92757

Report Generated: November 28, 2023

South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA 94080

---

56 Broome Corporate Parkway
Conklin, NY 13748

Toll Free: 866-211-2028
www.envirositecorp.com

Prepared for Envirosite Corporation By:

Property Archives

City Directory Report

Envirosite's Standard City Directory Report is a screening tool designed to assist in historical use determination of a subject property and adjacent properties. It includes a search of Property Archives digital datasets and national book collections including the Library of Congress and/or the Allen County Public Library at five year intervals or the closest available intervals.

RESEARCH SUMMARY:

The following research sources were consulted in the preparation of this report:

SOURCE:	***YEAR:***
Property Archives	2018, 2015, 2010, 2006, 2001, 1998, 1993
San Mateo County Criss Cross Directory	1988
San Mateo Street Address Directory	1983, 1978, 1973, 1968, 1963, 1959

Property Archives is a proprietary and comprehensive dataset of over 1.5 billion commercial, industrial and residential records, business names and uses and occupant records for every city and town in the United States, from recent years to the early 1990s. Property Archives dataset is wholly owned and operated by Property Archives, LLC

This report was prepared by Property Archives, LLC for Envirosite Corporation

Property Archives

SUBJECT PROPERTY:

71 Camaritas Ave , South San Francisco, CA 94080

ADJOINING PROPERTIES:

1-105 Camaritas Ave, South San Francisco, CA, 94080

Disclaimer - Copyright and Trademark Notice

All information contained in this report is based on data available from various public, government and other sources and are based upon the best data available from those sources. The information available in this report may be available from other sources and is not exclusive or the exclusive property of Property Archives, LLC

NO WARRANTY EXPRESSED OR IMPLIED, IS MADE IN CONNECTION WITH THIS REPORT, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. ALL RISK IS ASSUMED BY USER AND Property Archives, LLC assumes no liability for faulty or inaccurate information. The Reports may utilize a variety of public and other sources reasonably available to Property Archives. Property Archives cannot, and does not assure, warrant, guarantee or assume any liability for the correctness, comprehensiveness, timeliness or completeness of any of such information, nor is the information in any Report to be construed as legal advice with respect to environmental risks associated with any property. Property Archives shall not be liable to anyone for any claims, causes of action, suits, damages, losses, costs and expenses (including, without limitation, attorneysâ€™ fees and costs) arising out of or caused by this report regardless of the acts, errors or omissions, or negligence of Property Archives. Any damages shall be limited to the purchase price of the report.

Purchaser of the report accepts the report "As Is". The report is intended only to provide information only and should not be considered as providing any legal advice, prediction, forecast, or fact as to the environmental risk for any specific property. Reports are proprietary to Property Archives, and contain copyrighted material and trademarks of Property Archives. All other trademarks used herein are the property of their respective owners. All rights of Property Archives,LLC as to the Reports are reserved.

2018 **1-105 Camaritas Ave, South San Francisco, CA, 94080**

BURI BURI LIQUOR	71 CAMARITAS AVE
ONGPIN NOODLES	73 CAMARITAS AVE
DA VITA SOUTH SAN FRANCISCO	74 CAMARITAS AVE
DAVITA SOUTH SAN FRANCISCO	74 CAMARITAS AVE
DOMENIC MARRETTA	105 CAMARITAS AVE
LINDA MARRETTA	105 CAMARITAS AVE
JANICE ALIBAYAN	106 CAMARITAS AVE
RODRIGO ALIBAYAN	106 CAMARITAS AVE
HOT ROD LIMOUSINE SVC LLC	106 CAMARITAS AVE
KATSUKO EISENMAN	107 CAMARITAS AVE
MARIA ROQUE	108 CAMARITAS AVE
GORDON VALLEDOR	109 CAMARITAS AVE

2015 **1-105 Camaritas Ave, South San Francisco, CA, 94080**

BURI BURI LIQUOR	71 CAMARITAS AVE
ONGPIN NOODLES	73 CAMARITAS AVE
DAVITA SOUTH SAN FRANCISCO	74 CAMARITAS AVE
DOMENIC MARRETTA	105 CAMARITAS AVE
LINDA MARRETTA	105 CAMARITAS AVE
STEPHANIE MARRETTA	105 CAMARITAS AVE
JANICE ALIBAYAN	106 CAMARITAS AVE
MARIVIC ALIBAYAN	106 CAMARITAS AVE
RODRIGO ALIBAYAN	106 CAMARITAS AVE
HOT ROD LIMOUSINE SVC LLC	106 CAMARITAS AVE
KATSUKO EISENMAN	107 CAMARITAS AVE
MARIA ROQUE	108 CAMARITAS AVE
SALVADOR ROQUE	108 CAMARITAS AVE
GORDON VALLEDOR	109 CAMARITAS AVE
MARIA VALLEDOR	109 CAMARITAS AVE

2010 **1-105 Camaritas Ave, South San Francisco, CA, 94080**

BURI BURI	71 CAMARITAS AVE
HARRY PATEL	71 CAMARITAS AVE
EDGAR ELAZIGUE	73 CAMARITAS AVE
MARIVIC ALIBAYAN	106 CAMARITAS AVE
REGINA ALIBAYAN	106 CAMARITAS AVE
RODRIGO ALIBAYAN	106 CAMARITAS AVE
KATSUKO EISENMAN	107 CAMARITAS AVE
MARIA ROQUE	108 CAMARITAS AVE
GORDON VALLEDOR	109 CAMARITAS AVE
MARIA VALLEDOR	109 CAMARITAS AVE
MIKE THOMPSON	110 CAMARITAS AVE
ROBERTA PETIT	110 CAMARITAS AVE
ROBERTA THOMPSON	110 CAMARITAS AVE

2006 **1-105 Camaritas Ave, South San Francisco, CA, 94080**

Harry Patel	71 CAMARITAS AVE
Edgar Elazigue	73 CAMARITAS AVE
Joseph So	74 CAMARITAS AVE
Salvador Roque	108 Camaritas Ave

2001 **1-105 Camaritas Ave, South San Francisco, CA, 94080**

Salvador Roque	108 Camaritas Ave
Ligia R Calvillo	109 Camaritas Ave
Robert A Thompson	110 Camaritas Ave

1998 **1-105 Camaritas Ave, South San Francisco, CA, 94080**

Buri Buri Liquor	71 Camaritas Ave
Ongpin Noodles	73 Camaritas Ave

Blockbuster Video	74 Camaritas Ave
Fantasy Comics	75 Camaritas Ave
Salvador Roque	108 Camaritas Ave

1993 **1-105 Camaritas Ave, South San Francisco, CA, 94080**

BURI BURI LIQUOR	71 CAMARITAS AVE
DOHERTY & DUNNE INC	74 CAMARITAS AVE
FIRST NATIONAL BANK OF DALY CI	74 CAMARITAS AVE
AFFILIATED AIR SERV	75 CAMARITAS AVE
COSENTINO FRANK F	75 CAMARITAS AVE
WEBSTER DIANE	103 CAMARITAS AVE
EISENMAN FRANCIS J	107 CAMARITAS AVE
ROQUE STEVE	108 CAMARITAS AVE

SOURCE: San Mateo County Criss Cross Directory

STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080

YEAR: 1988

INFO:

71 *BURI BURI LIQUOR
73 *BURI BUM DELI
74 *FIRST NIL BNK BURI
75 COSENTINO Frank F
*STATE FARM INS CO
76 *DOHERTYADUNNE
103 WEBSTER D
WEBSTER T
106 SILVIA Ronald
SILVIA Susan
107 EISENMAN F J
108 ROGUE Salvador
109 XXXX
111 THOMASSEN Paul R
112 GARDINI John L
113 XXXX
114 SMITH Jamas R
115 LOCKE Edward FA
116 NAKAGAWA Solids
117 XXXX
118 XXXX
119 XXXX
120 MARTIN Mark
121 CASAGRANDE Frank A
122 XXXX
123 XXXX
126 GRISSOM C A Mrs
127 XXXX
130 PAGAN Stephan




IMAGE: 1 of 2

SOURCE: San Mateo Street Address Directory

STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080

YEAR: 1983



CAMARITAS AV (CONT'D) 94080

74 First National Bank 583-8450
74 Doherty And Dunne Sporting Goods 952-6060
75 Cosentino Frank F 589-0800
75 Affiliated Air Services 952-5179
75 Cosentino Frank F 761-7600
103 Machado L S 873-5294
106 Hurlock Billie 588-2344
107 Eisenman F J 871-4317
108 Roque Salvador 583-6865
111 Thomassen Paul R 589-6203
112 Gardini John L 588-7125
113 Snyder Marvin M 583-1554
114 Smith Jas R 583-0602
115 Locke Edw M 589-6835
116 Nakagawa Seiichi 873-2337
119 Peters Richard 871-9324
120 Martin Mark 583-7964
121 Casagrande Frank A 588-4754
122 Bowler Alfred F 583-5028
123 Cornejo Denise 589-1495
126 Grissom Clifford A Mrs 583-8913
130 Pagan Stephen 583-2917
130 Pagan Lynn 588-7894
201 Darwish Sadet 952-6643
203 Wise Gertrude Mrs 871-8362
204 Healy Wm 588-3469
209 McKay Jas P 588-8192
210 Cruse Bazil C 588-4671
212 Dunlop L E 588-8298
213 Graham L C 588-8904
214 Galyean Willard E 761-0687

IMAGE: 2 of 2
SOURCE: San Mateo Street Address Directory
STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080
YEAR: 1983





IMAGE: 1 of 2
SOURCE: San Mateo Street Address Directory
STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080
YEAR: 1978



CAMARITAS AV (CONT'D)


119 Peters Richard
120 Martin Mark
121 Casagrande Frank A
122 Bowler Alfred F
126 Grissom Clifford A Mrs
130 Pagan Stephen
131 Cocciolone A
203 Wise Gertrude Mrs
204 Healy Wm
207 Altube Bernard
208 Bullentini Alvin J
209 McKay Jas P
210 Cruse Bazil C
212 Dunlop L E
213 Graham L C
214 Galyean Willard E
216 Ormando Richard M
217 Dieckelt Hans
221 Braschi R J
223 Shaughnessy Mary E
224 Miller Catura R
228 Bayer Alfred J Jr
229 Wimberley Jas A
230 Waskey Anthony J Jr
300 Malaney Frank
305 Panattoni H P

IMAGE:	2 of 2
SOURCE:	San Mateo Street Address Directory
STREET:	1-105 Camaritas Ave, South San Francisco, CA, 94080
YEAR:	1978

CAMARITAS AV 94080

71 Buri Buri Liquor.....583-6898
73 Buri-Buri Delicatessen.....588-9449
75 Armanino Gun Shop 588-0245
103 Henslee Louis C.....588-2651
106 Hurlock Billie 588-2344
108 Roque Salvador.....583-6865
109 Colletta A S.....871-5525
111 Thomassen Paul R 589-6203
112 Gardini John L.....588-7125
113 Cardon Guy A.....761-3512
114 Smith Jas R 583-0602
115 Locke Edw M.....589-6835
116 Mitchell Dan C 589-5759
117 Alfano Giuseppe 873-5584
119 Peters Richard.....761-2218
120 Martin Mark.....583-7964
121 Casagrande Frank A.....588-4754
122 Bowler Alfred F 583-5028
123 Preciado David 871-7694
126 Grissom Clifford A Mrs 583-6041
127 Milhorn Donald R 588-5256
130 Pagan Stephen 583-2917
131 Thomas John 589-1807
203 Wise Gertrude Mrs 871-8362
204 Guerrero Thos R 871-5730
207 Altube Bernard 589-5218
208 Bullentini Alvin J 588-8278
209 McKay Jas P 588-8192
210 Cruse Bazil C.....588-4671
212 Dunlop L E 588-8298
213 Graham L C 588-8904
214 Galyean Willard E 761-0687
215 Gonzales Victor 583-8108
216 Ormando Richard M 873-1920

IMAGE: 1 of 1
SOURCE: San Mateo Street Address Directory
STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080
YEAR: 1973



CAMARITAS AV


1	BURI BURI CHEVRON SVC	583-9495
11	BURI BURI DELICATESSN	588-9449
13	BURI BURI LIQUOR	583-6898
103	HENSLEE L C	588-2651
106	HURLOCK BILLIE	588-2344
108	ROQUE S	583-6865
109	COLLETTA PHYLLIS	589-3783
111	THOMASSEN P R	589-6203
112	GARDINI J L	588-7125
113	SERRANO ARLENE M	588-5045
115	WAGNER DORIS E	589-6835
116	MITCHELL D C	589-5759
118	WISTUBA E	588-2168
118	GARNER E	588-4931
119	PETERS R	871-9351
120	MARTIN M	583-7964
121	CASAGRANDE F A	588-4754
122	BOWLER A F	583-5028
126	GRISSOM C A MRS	583-6041
127	CARLSON C O	589-7818
129	SOURIS P	589-3349
130	PAGAN S	583-2917
131	AKKALAEFF N	589-7116
203	SERIO S J	588-0272
204	GUERRERO T R	871-5730
205	GAY S P	589-0903
207	ALTUBE B	589-5218
208	MC LEOD D	589-4597
209	MC KAY J P	588-8192
210	CRUSE B C	588-4671
211	ESCOBAR M D	583-6695
212	DUNLOP L E	588-8298
213	GRAHAM L C	588-8904
215	GONZALES V	583-8108
216	RUIZ E	589-9177
217	DIECKELT H	589-9045
220	LARSON M	588-8481
221	BRASCHI R J	588-8882
223	SHAUGHNESSY MARY E	583-7009
227	HESSELBARTH V L	873-7461
228	BAYER A J JR	588-6465
229	WIMBERLEY J A	588-5334
230	SUE F Y	588-0386
231	POWERS JULIA O	588-8370
300	ARROYO F	871-6962
305	PANATTONI H P	583-2327
309	FERRIGNO IONE	871-7313
310	TRUJILLO DORIS	589-0509
311	LASKY R	583-1359
313	KRAVCHENKO J T	583-3739
315	SULLIVAN C	588-7636
317	KNOBLAU B R	583-1537
318	MASON L	583-2485
319	NICHOLS ISAAC	588-4734
323	STEELE R S	583-4303
326	VIERA V	589-6204
327	LORENZINI R J	583-1438
329	WORLEY R S	871-9554
400	O FARRELL T	871-5950
403	MORAN J	589-9149

IMAGE: 1 of 1

SOURCE: San Mateo Street Address Directory

STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080

YEAR: 1968



CAMARITAS AV


1	BURI BURI CHEVRON SVC	583-9495
11	BURI BURI DELICATESSN	588-9449
13	BURI BURI LIQUOR	583-6898
105	PILANT W	583-2616
106	HURLOCK BILLIE	588-2344
107	BULLERDICK EVELYN T	588-6264
108	ROQUE S	583-6865
109	COLLETTA PHYLLIS	589-3783
111	THOMASSEN P R	589-6203
112	GARDINI J L	588-9137
113	SERRANO ARLENE M	588-5045
114	SMITH J R	583-2603
116	CENTER W M	588-7620
117	CHISHOLM D	583-1925
118	WISTUBA E	588-2168
119	HULGAN J A	583-3627
120	MARTIN M	583-7964
121	CASAGRANDE F A	588-4754
122	BOWLER A F	583-5028
123	KELLY W	583-6651
123	NIEBUHR H	588-6537
125	STADEL H	583-7270
126	GRISSOM C A MRS	583-6041
127	GRUSSI E	583-1060
129	SOURIS P	589-3349
130	PAGAN S	583-2917
131	KEBODEAUX V A	583-0747
201	TEDESCO MARIAN	583-9252
203	SERIO S J	588-0272
206	ROYAL ERNEST L	588-4976
207	CARSON P	589-5322
208	MC LEOD D	589-4597
209	MC KAY J P	588-8192
210	CRUSE B C	588-4671
212	DUNLOP L E	588-8298
213	GRAHAM CATHERINE	588-8904
215	GONZALES V	583-8108
216	RUIZ MARIE A	589-8147
219	MEGAS GEORGE P	588-7490
220	LARSON M	588-8481
221	BRASCHI R J	588-8882
222	SANDERS E J	583-7058
223	SHAUGHNESSY MARY E	583-7009
224	SHERRATT ESTELLE M	588-4151
227	SCHAEFFER R MRS	589-8519
228	BAYER A J JR	588-6465
229	WIMBERLEY J A	588-5334
230	KEMPTON MILDRED	583-2133
231	BIRD PENNY	588-8370
304	FOUST E L	583-6340
305	PANATTONI H P	583-2327
307	CLARKE R A	588-5558
309	CHICCA R P	589-7976
310	TRUJILLO DORIS	589-0509
311	LASKY R	583-1359

IMAGE: 1 of 1

SOURCE: San Mateo Street Address Directory

STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080

YEAR: 1963



CAMARITAS AV


1	BURI BURI CHEVRON SVC	JU3-9495
11	BURI BURI DELICATESSN	JU8-9628
13	BURI BURI LIQUOR	JU3-6898
74	BANK OF AMERICA	JU3-7040
103	COLYER C H CHAPLAIN	JU3-3591
105	WILKENS GLADYS A	JU8-5881
105	SCHROEDER C L	JU8-8095
106	HURLOCK BILLIE	JU8-2344
107	BULLERDICK EVELYN T	JU8-6264
109	COLLETTA A S	JU3-8274
111	THOMASSEN PAUL R	JU8-8193
112	GARDINI J L	JU8-9137
113	SERRANO JOAN G	JU8-5045
114	SMITH J R	JU3-2603
115	WAGNER F E	JU8-7275
116	CENTER W M	JU8-7620
117	CHISHOLM D	JU3-1925
118	WISTUBA E	JU3-5288
119	HULGAN J A	JU3-3627
120	MARTIN M	JU3-7964
121	CASAGRANDE FRANK A	JU8-4754
122	MIFSUD C	JU3-9497
125	NOTARO D J	JU9-0658
126	GRISSOM C A MRS	JU3-6041
129	WATROBA J	JU9-3961
130	PAGAN S	JU3-2917
201	TEDESCO MARIAN	JU3-9252
203	KESENHEIMER A	JU3-8719
204	MC DAVID C H	JU9-3366
205	WEINROB ALBERT M	JU8-4454
206	ROYAL ERNEST L	JU8-4976
207	CARSON P	JU9-5322
208	PALMIERI L MRS	JU9-3854
209	MC KAY J P	JU8-8192
210	CRUSE B C	JU8-4671
211	MC FARLANE W J	JU3-9534
212	DUNLOP L E	JU8-8298
213	GRAHAM CATHERINE	JU8-8904
214	GALYEAN W E	JU8-8421
217	DOLGOFF R N	JU8-8372
218	MYERS J H	JU9-4021
219	MEGAS GEORGE P	JU8-7490
220	LARSON M	JU8-8481
221	BRASCHI R J	JU8-8882
222	SANDERS E J	JU3-7058
223	SHAUGHNESSY J P	JU3-7009
224	SHERRATT ESTELLE M	JU8-4151
225	MEYER A C	JU9-1122
227	WYCKOFF J	JU8-1891
228	IMBECK E H	JU8-7740
229	WIMBERLEY J A	JU8-5334
230	KEMPTON A H	JU3-2133
231	POWERS OTHELLA	JU8-2958
300	PELUSO L	JU8-8615
304	FOUST E L	JU3-6340
305	PANATTONI H P	JU3-2327
307	GOULD J S	JU8-6631
309	RYDER E F	JU3-2004
310	TRUJILLO DORIS	JU9-0509
311	LASKY R	JU3-1359
313	ELKIN B J	JU3-0587
315	LEAR J H	JU8-6121
317	KNOBLAU B R	JU3-1537
319	NICHOLS ISAAC	JU8-4734
321	ATWOOD L	JU3-9198
323	HENRY H L JR	JU8-0819
325	CAMPBELL M	JU3-5119
327	LORENZINI R J	JU3-1438
329	HARA KAY	JU9-2248
330	HUMPHREY I F	JU9-5061
400	PETTY C JR	JU3-2987
403	HACKLEY C R	JU3-1371

IMAGE: 1 of 1


SOURCE: San Mateo Street Address Directory

STREET: 1-105 Camaritas Ave, South San Francisco, CA, 94080

YEAR: 1959



Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: South San Francisco, CA Base Map Date: April 1925 Revised Date: 1970 Republished Date: Sheet Number: 39	**1970**	Requested by: Envirosite Corporation South San Francisco Fire Station #63 71 Camaritas Ave South San Francisco, CA 94080 Client Project # 92757 HIG Project # 2078730 www.historicalinfo.com	HIG



Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: South San Francisco, CA Base Map Date: April 1925 Revised Date: 1956 Republished Date: Sheet Number: 39	**1956**	Requested by: Envirosite Corporation South San Francisco Fire Station #63 71 Camaritas Ave South San Francisco, CA 94080 Client Project # 92757 HIG Project # 2078730 www.historicalinfo.com	HIG



Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: South San Francisco, CA Base Map Date: April 1925 Revised Date: September 1950 Republished Date: Sheet Number: 28	**1950**	Requested by: Envirosite Corporation South San Francisco Fire Station #63 71 Camaritas Ave South San Francisco, CA 94080 Client Project # 92757 HIG Project # 2078730 www.historicalinfo.com



Map Type: Fire Insurance Publisher: Sanborn Map Co. Publication Name: South San Francisco, CA Base Map Date: April 1925 Revised Date: Republished Date: Sheet Number: 28	**1925**	Requested by: Envirosite Corporation South San Francisco Fire Station #63 71 Camaritas Ave South San Francisco, CA 94080 Client Project # 92757 HIG Project # 2078730 www.historicalinfo.com

HIG Research Summary

Site Location
South San Francisco Fire Station #63
71 Camaritas Ave
South San Francisco, CA

Requested by
Envirosite Corporation
2 Corporate Drive
Shelton, CT

HIG Project #
2078730
Client Project #
92757
Date Created
11/27/2023

Historical Information Gatherers

This Research Summary identifies the products and services provided by Historical Information Gatherers, Inc. (HIG) for the above referenced site location. All products are provided as PDFs unless otherwise noted.

FIM+ Maps

The HIG Historical Map Collection and the United States Library of Congress Map Collection were searched for fire insurance maps (FIMs), real estate atlases and similar maps for the site location and adjoining properties. These maps were used to create a multi-page file named FIM+Maps. The maps have title blocks that include the map publisher, year the map was created and, if applicable, the year the map was last updated. The years provided are:

1925, 1950, 1956, 1970

Disclaimer & Limitation of Liability

This Research Summary and the related documents and images provided by Historical Information Gatherers (hereafter referred to as the "Site Specific HIG Data") contain information obtained from a variety of public and private sources. Additional information for the site and surrounding properties may exist. Accordingly, there can be no guaranty or warranty that the information provided is complete for its particular intended purpose. No warranty expressed or implied, is made whatsoever in connection with the Site Specific HIG Data. Historical Information Gatherers specifically disclaims the making of any such warranties, including without limitation, merchantability or fitness for a particular purpose. Historical Information Gatherers, its officers, employees and independent contractors cannot be held liable to anyone for any loss or damage, whether arising out of errors or omissions, negligence, accident or any other cause, resulting directly or indirectly from any information provided or any information not provided in the Site Specific HIG Data. Any liability on the part of Historical Information Gatherers is strictly limited to a refund equal to the amount paid for the Site Specific HIG Data.

HIG Copyright Notice

This Research Summary and the selection, arrangement and compilation of Site Specific HIG Data are the property of Historical Information Gatherers. © Copyright 2023 by Historical Information Gatherers, Inc. All rights reserved. The person or entity that ordered and paid for the Site Specific HIG Data is granted a personal, non-assignable, limited license to reproduce the Site Specific HIG Data solely for purposes of providing supporting documentation for reports produced for the site location which is noted on page one of this Research Summary. Any other reproduction or other use of the Site Specific HIG Data in any media or format, in whole or in part, is expressly prohibited without prior written permission from Historical Information Gatherers, and the person or entity that ordered and paid for the Site Specific HIG Data assumes all liability for the making of any such reproductions.

Licensing Agreement

The licensing agreement between Historical Information Gatherers and infoGroup provides that Historical Information Gatherers may create photocopies or reproductions of portions of Polk City Directories, Hill-Donnelley Criss-Cross Directories and other directories under infoGroup copyright. The licensing agreement also permits the person or entity that ordered and paid for the Site Specific HIG Data to include photocopies or reproductions of portions of Polk City Directories, Hill-Donnelley Criss-Cross Directories and other directories under infoGroup copyright as supporting documents for reports produced for the site which is the subject of the Site Specific HIG Data.

infogroup

APPENDIX D

Interview Documentation

Interview with Local officials

Date: October 24th, 2023

Name: City of South San Francisco

Title: N/A

Interviewed by: Ryan Barry, Cameron-Cole, LLC

Cameron-Cole contacted the City of South San Francisco on October 24th, 2023, requesting records regarding environmental violations, releases, or hazardous material or petroleum product storage, storage tanks, or other environmental concerns associated with the subject property and a reported state hazardous waste database listing associated with the subject property. A response was received on November 14th, 2023, no records pertaining to hazardous substances, or petroleum products were located,

Date: April 17th, 2023

Name: San Mateo County Department of Environmental Health

Title: N/A

Interviewed by: Ryan Barry, Cameron-Cole, LLC

Cameron-Cole contacted the San Mateo County Department of Environmental Health on October 24th, 2023, requesting records regarding environmental violations, releases, or hazardous material or petroleum product storage, storage tanks, or other environmental concerns associated with the subject property and a reported state hazardous waste database listing associated with the subject property. A response was received from the Department of Environmental Health including multiple subsurface drilling permits.

Date: October 24th, 2023

Name: Carl Rose

Title: Regional Records Coordinator

Interviewed by: Ryan Barry, Cameron-Cole, LLC

Cameron-Cole contacted the California Department of Toxic Substances Control on October 24th, 2023, requesting records regarding environmental violations, releases, or hazardous material or petroleum product storage, storage tanks, or other environmental concerns associated with the subject property and a reported state hazardous waste database listing associated with the subject property. A response was received on October 24th. 2023, indicating that no such records had been found.

APPENDIX E

Professional Qualifications

Ryan Barry, Environmental Scientist I

Ryan Barry has one year of professional experience in environmental field sampling, groundwater monitoring, and water level contouring. He has collected surface and subsurface soil samples, as well as groundwater samples from monitoring wells, and conducted well tests. Additionally, Mr. Barry is well versed in topographic mapping and the use of geographic information systems (GIS) for analysis of various environmental topics. He has assisted in analyzing data, developing presentations, and preparing draft reports with tables, charts, and graphs. He has acted as the primary author under the direct supervision of someone who means the definition of an Environmental Professional, of numerous Phase I ESA for a wide variety of facilities. These facilities include but are not limited to residential developments, educational facilities, agricultural land, industrial properties, and commercial development.

Education:

- Bachelor of Science, Environmental Science and Management, California Polytechnic State University - Humboldt, Arcata, CA, 2021

Certifications:

- 40-hour Hazardous Waste Operations and Emergency Response Training

Michael Stephenson – Principal Scientist – Western Region Manager

Michael Stephenson, MBA, ERM, has more than 28 years of project management, site assessment, and remediation experience gained from working on various projects, including large and complex industrial development, for both private and municipal clients. Mr. Stephenson's expertise includes risk management, environmental liability estimation, database management, and statistical data analysis. He has conducted human health and ecological risk assessments, Remedial Investigations/Feasibility Studies, soil, and groundwater characterizations; provided technical support for site closures; and managed several soil and groundwater remediation, monitoring, and investigation for projects involving human health and ecologically based risk analysis.

Education:

- Master of Business Administration, Saint Mary's College, Moraga, CA, 2002
- Bachelor of Arts, Environmental Studies, University of California, Santa Barbara, CA, 1994.

Certifications:

- Environmental Risk Manager, Environmental Risk Strategies Institute, 2007
- 40-hour and 8-hour 29 CFR 1910.120 Training, Department of Labor
- 8-hour 29 CFR 1910.120 Supervisor Training, Department of Labor

THIS PAGE INTENTIONALLY LEFT BLANK