

SOUTH SAN FRANCISCO-SAN BRUNO WATER QUALITY CONTROL PLANT SODIUM HYPOCHLORITE FACILITY REHABILITATION



Replacement of (2) Double-Contained Sodium Hypochlorite Supply Feed Lines to Disinfection Tanks

Removal and Replacement of Sodium Hypochlorite Tanks 1-3

New Concrete Pad and Replacement of ALL Sodium Hypochlorite Secondary Containment Piping, Valves, Safety Apparatus, & Equipment

Replacement of ALL Sodium Hypochlorite Pumps, Flow Meters, Conduit, PLC, SCADA System, and associated electrical equipment in the Hypo Building.