

ATTACHMENT 2 – CONSTRUCTION PHOTOS

Page 1 of 7



Photo 1: Demolition of the island at the southeast corner of E Grand/Grand Ave



Photo 2: Construction of the new biofiltration area, sidewalk, and curb/gutter at the southeast corner of E Grand/Grand Ave

ATTACHMENT 2 – CONSTRUCTION PHOTOS

Page 2 of 7



Photo 3: Construction of the new biofiltration area at the southeast corner of E Grand/Grand Ave



Photo 4: Completion of the new sidewalk and corner extension at the southeast corner of E Grand/Grand Ave

ATTACHMENT 2 – CONSTRUCTION PHOTOS

Page 3 of 7



Photo 5: Encountering large amount of water intrusion during the traffic signal foundation installation



Photo 6: Encountering large amount of water intrusion during the traffic signal foundation installation

ATTACHMENT 2 – CONSTRUCTION PHOTOS

Page 4 of 7



Photo 7: Installation of a steel casing for the traffic signal foundation



Photo 8: Installation of the rebar cage for the traffic signal foundation

ATTACHMENT 2 – CONSTRUCTION PHOTOS

Page 5 of 7



Photo 9: Construction of concrete sidewalk and curb ramp at the southwest corner of E Grand/Grand Ave



Photo 10: Construction of street paving to conform with new curb ramp and sidewalk at the southwest corner of E Grand/Grand Ave

ATTACHMENT 2 – CONSTRUCTION PHOTOS

Page 6 of 7



Photo 11: Installation of new dual high-visibility crosswalk and bicyclist crossing at the south leg of the E Grand/Grand Ave intersection



Photo 12: Installation of new protected bicycle lane with delineators along E Grand Ave

ATTACHMENT 2 – CONSTRUCTION PHOTOS

Page 7 of 7



Photo 13: Installation of new enhanced pedestrian and bicyclist crossing at the west leg of the E Grand/Grand Ave intersection



Photo 14: Installation of new green bicyclist box at northwest corner of E Grand/Grand Ave